

123456789

ASS. REC. BY:

Assigner: Kenneth

REF:

CS/SMD19019ASS/KYD3N2

Special Instruction:

ASSIGNMENT (Office)

From (Person): Yong Keng Melvin of SMO

Date/Time: 11/11/19 @ 3.24pm

Estimated Cost: Bill to:

OP / PD / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLW 424Y

Insured: FBM 6111G

at Workshop n/s: LH Express Motor

Tel: 9008 9959

of Blk 5038 Amk Ave 3 #01-405

Policy No:

Claim No: CMTD1905224 / THE

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 7/11/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 3.41pm 11/11/19

Person Contacted:

Dick

Vehicle IN / OUT

Date/Time

Action/Instruction

SLW 424Y - X

FBM 6111G - CS/SMD18004865/KYD3N2

DOA: 13/3/2018

15/11/19

Sent Preli by email

28/11

Call & 27od email & LCA form (Red \$4020-88, 59%)

SMO

ASSIGNMENT

From: Date: 12/11/19

Estimated Cost:

OT / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLW 424Y

at Workshop n/s: LH Express Motor

of: Blk 5038 AMK Ave 3 #01-405

Insured:

Policy No:

Claims No:


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 05 days Res: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS ^{Imp}

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLW 424Y Regn: 05 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / Std / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal:

L/Bal:

D.O.A:

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

C/S Rec

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal:

L/Bal:

D.O.A:

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

C/S Rec

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 03 DEC 2019

Date/Time: File Pass to?



: Prel. Report

1)



: Final Report

Date/Time: File Return to?

3/12/19 Typist

Report Format:

Comp Sum / U/C: \$2700/-

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee:



Site Insp: 15



Interview: 15



Tech. Insp: 15



Wash & Dry: 15

Survey Fee:

Transportation:

3 - 15.00

Parking:

Office:

Total:

250

250



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref:

Date: 15 Nov 2019

Our Ref: CS/SMO19019955/Kyd3

The Motor Claims Department
SOMPO INSURANCE SINGAPORE PL

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLW424Y .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 12/11/2019 at the premises of M/s LH EXPRESS MOTOR and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 6,720.88</u> .
Revised Estimate Amount	: <u>S\$ 2,619.90</u> .
"Check" Items Amount	: <u>S\$ 500.00</u> .
Market Value	: <u>S\$ -</u> .
LTA Reimbursement Value	: <u>S\$ -</u> .
Nett Value	: <u>S\$ -</u> .

Description of Damage:

The vehicle sustained damages at the rear o/s body.



Yours faithfully

Kenneth Kong
Licensed Appraiser

Yvonne Wong (LKK Auto)

From: Yvonne Wong (LKK Auto)
Sent: Friday, November 15, 2019 6:10 PM
To: Ye, Yong Kang Melvin; SUR
Subject: Arrangement for PRS for the vehicle SLW 424 Y. Our ref : CMTD1905224/THE
Attachments: SLW424Y PRELI ADVISE.pdf

Dear Sir/ Madam

Enclosed preliminary revised of vehicle SLW424Y
Date of survey : 12/11/2019
Number of days : 5 days

Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonne.wong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonne.wong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ye, Yong Kang Melvin [mailto:melvin.ye@sompo.com.sg]
Sent: Monday, November 11, 2019 3:21 PM
To: SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>
Cc: LH Motor Trading <dyeo.lhmotortrading@gmail.com>
Subject: RE: Arrangement for PRS for the vehicle SLW 424 Y. Our ref : CMTD1905224/THE

Dear LKK Auto,

Please make arrangement to conduct the survey for SLW424Y.

Best Regards

Melvin Ye

Nivitha (LKK Auto)

From: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>
Sent: Monday, 11 November 2019 3:21 PM
To: SUR; assignments
Cc: LH Motor Trading
Subject: RE: Arrangement for PRS for the vehicle SLW 424 Y. Our ref : CMTD1905224/THE

Dear LKK Auto,

Please make arrangement to conduct the survey for SLW424Y.

Best Regards

Melvin Ye

Claims Division

D: 6322 4667 | T: 6461 6555 | F: 6221 3302



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG



Download now @

or

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: LH Motor Trading <dyeo.lhmotortrading@gmail.com>

Sent: Monday, 11 November, 2019 2:08 PM

To: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>

Subject: Re: Arrangement for PRS for the vehicle SLW 424 Y. Our ref : CMTD1905224/THE

Dear Sir/Mdm,

We would like LKK Consultants Pte Ltd (Kenneth Kong) to survey this case, thank you.

Regards,

Dick

On Mon, Nov 11, 2019 at 11:17 AM Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg> wrote:

Our Reference: CMTD1905224/THE

Your Reference: SLK424Y

Without Prejudice

Date: 08 November 2019

Attention:

LH EXPRESS MOTOR TRADING

Dear Sir / Mdm,

ACCIDENT INVOLVING SLW424Y & FBM6111G ON 07.11.2019

We refer to your Notice of Accident dated 09/11/2019.

The handler for this case is Ms Thelma Choo.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	

2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	In House surveyor	Teo See Ling	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert

Best Regards

Melvin Ye

Claims Division

D: 6322 4667 | T: 6461 6555 | F: 6221 3302



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @



or



¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential

and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: LH Motor Trading <dyeo.lhmotortrading@gmail.com>

Sent: Saturday, 9 November, 2019 11:27 AM

To: Claims - Motor Survey <MotorSurvey@sompo.com.sg>

Subject: Arrangement for PRS for the vehicle SLW 424 Y.

Dear Sir/Mdm,

We attached a letter of PRS for the vehicle SLW 424 Y, please kindly let us have the your list of your surveyors.

Regards,

Dick

LH Express Motor Trading

Blk 5038 Ang Mo Kio Ave 3 #01-405 Ang Mo
Kio Industrial Park 2 Singapore 569541.
Email: dyeo.lhmotortrading@gmail.com
Fax: 64816131 Tel : 64817221

Yeo Choon Huan Eugene
Blk 314A Anchovale Link
#12- 147
Singapore 541314.

Vehicle No : SLW 424 Y
Chassis No : MRHDD4870FP000100
Make : Honda Mobilio 1.5L
Year : 2015

Not Notarial
11 Sep @ 2700h
Heavy After Rain
5 days

LH Express Motor Trading hereby notify the Repairer of the following:
• To remove damaged parts from vehicle
• To display damaged parts from vehicle
• Parts prices are subject to market rate
• Third party survey is at a "Market Rate" to
• No legal involvement is allowed
• Supplementary survey must be submitted and
• It subject to final approval from Insurance Company

Authorised by Dealer

QTY	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1	Rear Bumper
1	Rear Bumper Side Retainer RH
1	Rear Fender RH
1	Rear Fender Inner shield RH
1 set	Rear Fender Inner Shield Clips
1	Rear Bumper ^{Side} Lower Garnish
1	Tail Lamp assy RH
1	Rear Door Assy RH
1	Rear Door Outer Handle RH
1	Rear Door Lock RH
1	Rear Shock Absorber RH
1	Rear Wheel Hup RH

<i>Red/cm</i>	\$563.70	✓
<i>Ln</i>	\$41.20	X
<i>Ry</i>	\$856.70	✓
<i>Ln</i>	\$50.20	X
<i>Ln</i>	\$25.00	X
<i>1/2 p</i>	\$168.30	X
<i>Ln</i>	\$235.70	✓
<i>Ln</i>	\$825.40	X
<i>Ln</i>	\$86.20	X
<i>Ln</i>	\$156.20	X
<i>Ln</i>	\$180.00	X
<i>Ln</i>	\$250.00	✓
	<u>\$3,438.60</u>	
Less 20%	\$687.72	
	\$2,750.88	

Special Nett

1	Rear Windscreen Sealant
1	Rear Reverse Sensor
1	Tail Lamp Seal
1	Rear Sport Rim RH
1	<i>Bumper lower sticker</i>

<i>Ln</i>	\$60.00	<i>40sm</i>
<i>Ln</i>	\$300.00	X
<i>Ln</i>	\$35.00	X
<i>Ln</i>	\$600.00	<i>280sm</i>
<i>Ln</i>	\$280.00	
	<i>150sm</i>	

1 Rear Tyre RH

\$300.00 ~~8~~

Labour Charges

To remove and replaced damaged parts including straightening repositioning replacement parts.

\$1,000.00 700

Supply Paint Material and necessary items. To respray replaced and other affected panels

\$1,200.00 600

Reconnect wiring at the damage section and check for proper functions.

\$75.00 20

To install reverse sensors, control unit. Re-connect wires harness. Check function.

\$100.00 50

To remove/refit rear windscreen and check water leakage.

\$200.00 80

To carry out antirust treatment on affected panels.

\$100.00 30

Grand Total :

\$6,720.88

7000.88



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO19019955/Kyd3n2		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 04-12-2019		
		Code : SMO		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	FBM 6111G	Veh. Inspected	SLW 424Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD1905224/THE	Excess (\$)	0.00	
Assign From	YONG KANG MELVIN	Assign Date	11/11/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA MOBILIO (A)	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	MRHDD4870FP000100	Colour	METALLIC SILVER	
Odometer	100266	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/50 R16	YOKOHAMA	9 mm	
L/H Front Tyre	205/50 R16	YOKOHAMA	9 mm	
R/H Rear Tyre	205/50 R16	YOKOHAMA	9 mm	
L/H Rear Tyre	205/50 R16	YOKOHAMA	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/11/2019	Inspection Date	12/11/2019	
Survey held at	LH EXPRESS MOTOR TRADING BLK 5038 ANG MO KIO AVE 3 #01-405 ANG MO KIO IND. PARK 2 SINGAPORE 569541			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLW 424Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DENTED / CRACKED	563.70	563.70
1	REAR BUMPER SIDE RETAINER RH	SERVICEABLE	41.20	-
1	REAR FENDER RH	BENT	856.70	856.70
1	REAR FENDER INNER SHIELD RH	SERVICEABLE	50.20	-
1	SET REAR FENDER INNER SHIELD CLIPS	NOT NECESSARY	25.00	-
1	REAR BUMPER SIDE GARNISH	NO SUCH PARTS	168.30	-
1	TAIL LAMP ASSY RH	CUT	235.70	235.70
1	REAR DOOR ASSY RH	TO REPAIR SEE LABOUR	825.40	-
1	REAR DOOR OUTER HANDLE RH	SERVICEABLE	86.20	-
1	REAR DOOR LOCK RH	TO REPAIR SEE LABOUR	156.20	-
1	REAR SHOCK ABSORBER RH	SERVICEABLE	180.00	-
1	REAR WHEEL HUP RH	JAMMED	250.00	250.00
	LESS 20% DISCOUNT		-687.72	-381.22
			2,750.88	1,524.88
SPECIAL NETT ITEMS				
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	60.00	40.00
1	REAR REVERSE SENSOR (SN)	SERVICEABLE	300.00	-
1	TAIL LAMP SEAL (SN)	NOT NECESSARY	35.00	-
1	REAR SPORT RIM RH (SN)	DENTED	600.00	280.00
1	BUMPER LOWER STICKER (SN)	NECESSARY	280.00	150.00
1	REAR TYRE RH (SN)	SERVICEABLE	300.00	-
			1,575.00	470.00
LABOUR				
	TO REMOVE AND REPLACED DAMAGED PARTS INCLUDING STRAIGHTENING REPOSITIONING REPLACEMENT PARTS.INCLUSIVE OF THE REPAIR OF REAR DOOR ASSY RH AND REAR DOOR LOCK RH.		1,000.00	700.00
	SUPPLY PAINT MATERIAL AND NECESSARY ITEMS.TO RESPRAY REPLACED AND OTHER AFFECTED PANELS.		1,200.00	600.00

Report Ref No. CS/SMO19019955/Kyd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	RECONNECT WIRING AT THE DAMAGE SECTION AND CHECK FOR PROPER FUNCTIONS.		75.00	20.00
	TO INSTALL REVERSE SENSORS,CONTROL UNIT.RE-CONNECT WIRES HARNES.CHECK FUNCTION.		100.00	50.00
	TO REMOVE/REFIT REAR WINDSCREEN AND CHECK WATER LEAKAGE.		200.00	80.00
	TO CARRY OUT ANTIRUST TREATMENT ON AFFECTED PANELS.		100.00	30.00
			2,675.00	1,480.00
GRAND TOTAL			7,000.88	3,474.88
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,700.00

Report Ref No. CS/SMO19019955/Kyd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.