

ASS. REC. BY:

REF: CS/CTI 19019956/kyf302

Special Instruction:

Survivor: Kenneth

ASSIGNMENT (Office)From (Person): Tran Tay Hui Ping of CTI Date/Time: 11.11.19 16:21pm

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLA 470XJ Insured: GBB 8834Zat Workshop m/s Messrs V6 Motor Tel: 9729 0880of BK 9 901-44 San Ming Industrial Est Sector CPolicy No: DMCVSN 19262219000 Claim No: SMM 19D 205294COR

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 6.11.2019  
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 11.11.19 4:42pm Person Contacted: Mr Chang Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLA 470XJ - NA/CTI 17/01/2017
	GBB 8834Z - CS/CTI 19/11/2019 R/H
21/11/19 @ 3.54pm	Mr Chang will check on estimate & let us know.
11/12/19 @ 11.42am	checked with Mr Chang, the status of estimate.
03/01/20 @ 12pm	re-send email to Mr Chang to check status of estimate.

ASS. REC. BY:

REF: 0121

Kenneth

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SLA 47021 Yr Regn: 02.09

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Axiom 1.6 cc 1598

Colour: M. Blue A/C: Insured / Std / NI / NA

Sp. Reading: - T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: MR0538EE406139039

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/R/m / STD A/R/m or

Tyre Size: Continental 195/65R15

Rivestake

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal: 4 mm

L/Bal: 4 mm

D.O.A: 8/11/19

Survey held at

Rear

R/Bal: 8 mm

L/Bal: 8 mm

D.O.A: 11/11/19

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S Rear &amp; UIC

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

11/11 File sent to No Key  
EST not ready

5/3 L1 Sup &amp; 5800 email

10/3/20 @ 7.28pm confirmed with Mr Chang LG 55800. (Lad \$14069.20, 71%)

RECEIVED 12 MAR 2020

Date/Time, File Pass to?

11/03/20

Date/Time, File Return to?

☐ : Prell. Report☐ : Final Report

Days Of Repair: 10

Resurvey No. of Trlp: 1

Survey Fee:

Transportation:

S + RS. \$

Fuel:

Others:

TOTAL

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format:

Lump Sum / I.B.F. (\$

MER-TP

5800

220

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Nov 2019		11 Nov 2019 16:21 Assign				<b>New Assignment</b> Cancel Case

Main

Reference

Claim Details

Documents

Show All

## CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	CLOUD CAR RENTAL PTE LTD		
Vehicle Reg. No.:	SLA4702J	Date of Loss:	06/11/2019 15:00 - :59
Claim Type:	TP / SNM19D205294C02	Policy/Cover Note No.:	DMCVSN19267719000
Vehicle Reg. No. (Insured):	GBB8834Z	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Messrs V8 Motor Werkz Pte Ltd (HQ) Blk 9, #01-44 Sin Ming Industrial Est Sector C, 575630 Sin Ming - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 20/11/2019]		
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT		

## ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.

## ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Nivitha (LKK Auto)

---

**From:** Irene Tay <irene.tay@sg.cntaiping.com>  
**Sent:** Monday, 11 November 2019 4:00 PM  
**To:** Elaine Toh; assignments; Admin A  
**Subject:** FW: OUR REF: SNM19D205294-GBB8834Z-THP- PRE-REPAIR SURVEY --- YOUR REF: GBB 8834 Z --- ACCIDENT INVOLVING SLA 4702 J AND GBB 8834 Z AND SKQ 4716 Y ON 6 NOVEMBER 2019 ALONG JALAN BUKIT MERAH AT ABOUT 1530 HOURS  
**Attachments:** image001.emz; image003.emz  
**Importance:** High

WITHOUT PREJUDICE

Dear Sir/Mdm(LKK),

We refer to the above captioned matter.

Please get your surveyors to liaise with Messrs V8 Motor Werkz Pte Ltd to conduct PRS.

Thank You.

Regards,

**Irene Tay**  
Executive  
Claims Department (Motor Division)

**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #15-00 Springleaf Tower Singapore 079909  
DID: (65) 63896192 | F:(65) 62247478/62247175

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

---

**From:** Elaine Toh [mailto:Elainetoh@visionlawllc.com]  
**Sent:** Monday, November 11, 2019 3:06 PM  
**To:** Irene Tay <irene.tay@sg.cntaiping.com>  
**Subject:** RE: OUR REF: SNM19D205294-GBB8834Z-THP- PRE-REPAIR SURVEY --- YOUR REF: GBB 8834 Z --- ACCIDENT INVOLVING SLA 4702 J AND GBB 8834 Z AND SKQ 4716 Y ON 6 NOVEMBER 2019 ALONG JALAN BUKIT MERAH AT ABOUT 1530 HOURS  
**Importance:** High

**Our Ref:** SLA 4702 J (et)  
**WITHOUT PREJUDICE**

Dear Sir/Madam,

We refer to your email of even date informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment of **KENNETH KONG - LKK AUTO CONSULTANTS PTE LTD** as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

Venue: Messrs V8 Motor Werkz Pte Ltd  
Block 7 #01-92  
Sin Ming Industrial Estate Sector C  
Singapore 575642

Contact: Mr. Chang – HP 9725 0880 (Please call before going)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Thank you.

Regards,  
Elaine Toh  
Vision Law LLC  
Tel: 65342811 (Ext. 122)  
Fax: 65356802



**FOR SURVEYOR**

Please initial here after completion of pre-repair inspection.  
Thank you.

Appointed surveyor :  
(Name & Signature)

Date & Time of Inspection :

cc: SLA 4702 J – By email only

**From:** Irene Tay [mailto:[irene.tay@sg.cntaiping.com](mailto:irene.tay@sg.cntaiping.com)]

**Sent:** Monday, 11 November, 2019 12:38 PM

**To:** Elaine Toh

**Subject:** RE: OUR REF: SNM19D205294-GBB8834Z-THP- PRE-REPAIR SURVEY --- YOUR REF: GBB 8834 Z --- ACCIDENT INVOLVING SLA 4702 J AND GBB 8834 Z AND SKQ 4716 Y ON 6 NOVEMBER 2019 ALONG JALAN BUKIT MERAH AT ABOUT 1530 HOURS

**WITHOUT PREJUDICE**

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

LKK / LBS / STA

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards,

**Irene Tay**

Executive

Claims Department (Motor Division)

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896192 | F: (65) 62247478/62247175

W: [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | FB: [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | WeChat: 太平獅城 Taiping SG

**Irene Tay**

Executive

Claims Department (Motor Division)

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896192 | F: (65) 62247478/62247175

W: [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | FB: [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | WeChat: 太平獅城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

---

**From:** Claims Dept of CTI

**Sent:** Friday, November 8, 2019 5:02 PM

**To:** Elaine Toh <[Elainetoh@visionlawllc.com](mailto:Elainetoh@visionlawllc.com)>; Irene Tay <[irene.tay@sg.cntaiping.com](mailto:irene.tay@sg.cntaiping.com)>; Chee So Chow <[sochow.chee@sg.cntaiping.com](mailto:sochow.chee@sg.cntaiping.com)>

**Subject:** OUR REF: SNM19D205294-GBB8834Z-THP- PRE-REPAIR SURVEY --- YOUR REF: GBB 8834 Z --- ACCIDENT INVOLVING SLA 4702 J AND GBB 8834 Z AND SKQ 4716 Y ON 6 NOVEMBER 2019 ALONG JALAN BUKIT MERAH AT ABOUT 1530 HOURS

Dear Irene,

Please conduct PRS for SLA4702J.

Note : officer in charge – Irene Tay 63896192.

Thank you

Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896116 | F: (65) 62247175

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

---

**From:** Elaine Toh [<mailto:Elainetoh@visionlawllc.com>]

**Sent:** Friday, November 08, 2019 2:08 PM

**To:** Claims Dept of CTI

**Cc:** Chong Boon Sen; Ong Chin Kiat; Chee So Chow; Elaine Cheong; Alfred Toh; Tan Kah Leong; Irene Tay; Angie Foo

**Subject:** PRE-REPAIR SURVEY --- YOUR REF: GBB 8834 Z --- ACCIDENT INVOLVING SLA 4702 J AND GBB 8834 Z AND SKQ 4716 Y ON 6 NOVEMBER 2019 ALONG JALAN BUKIT MERAH AT ABOUT 1530 HOURS

**Importance:** High

**Our Ref:** SLA 4702 J (et)

**WITHOUT PREJUDICE**

Dear Sir/Madam,

We are instructed by **CLOUD CAR RENTAL PTE LTD** to notify you of a road traffic accident on 6 November 2019 at about 1530 hours along Jalan Bukit Merah involving our client's motor vehicle registration number SLA 4702 J and motor vehicle registration number GBB 8834 Z driven by you/your insured at the material time.

As a result of the accident, our client's motor vehicle has been damaged. Before our client proceed to repair the damaged motor vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the motor vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the motor vehicle without further reference to you.

Thank you.

Regards,

Elaine Toh (Secretary)

Vision Law LLC

Tel: 65342811 (Ext. 122)

Fax: 65356802

cc: SLA 4702 J – By email only

---

**VISION LAW LLC**

Advocates & Solicitors

(Incorporated with limited liability)

Unique Entity No. 200721148H

Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

---

**DISCLAIMER:**

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email

by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

---

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

---

VISION LAW LLC  
Advocates & Solicitors  
(Incorporated with limited liability)  
Unique Entity No. 200721148H  
Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413  
Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

---

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

---

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	07/11/2019 14:35
Date Of Accident	06/11/2019 15:30
Exact Location Of Accident	ALONG JALAN BUKIT MERAH
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLA4702J
<b>Insured/Policyholder</b>	
Name Of Registered Owner	CLOUD CAR RENTAL PTE. LTD.
Co Reg No	201818019M
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-82983472
<b>Vehicle Particulars</b>	
Manufacturer	TOYOTA
Model	COROLLA ALTIS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
<b>Insurance Company</b>	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	5110232360
Cover Note Number	
<b>Driver</b>	
Name of Driver	AHMAD MARICAN S/O RAZACK MARICAN
NRIC No	S69186888
Date Of Birth	02/06/1969
Occupation	OUTDOOR
Date Of Driving Pass	06/02/1995
Driving Experience	24 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82983472
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	APT BLK 280 TAMPINES STREET 22 #08-248
Postcode	520280
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4

Passenger 1	NAME: : PASSENGER	GENDER: : MALE
Passenger 2	NAME: : PASSENGER	GENDER: : FEMALE
Passenger 3	NAME: : PASSENGER	GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBB8834Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	

Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SKQ4716Y  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category PRIVATE CAR  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

### Accident Sketch Plan

### IMPORTANT NOTICE

CLOUD CAR RENTAL, PTE. LTD.  
1000, SINGAPORE

### Accident Sketch Plan

### SKETCH PLAN

Dec 29/14

7/1/00  
 10/1/00  
 10/1/00

X - 60888342  
B - 5K24716Y  
C - 5L247327

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

## DECLARATION

CLOUD GAS HEATING, FTS LTD  
100, BRISTOL ST  
GLASGOW G1 1HT

1999, 2000, 2001, 2002, 2003, 2004, 2005, 2006, 2007, 2008, 2009, 2010, 2011, 2012, 2013, 2014, 2015, 2016, 2017, 2018, 2019, 2020, 2021, 2022, 2023, 2024, 2025, 2026, 2027, 2028, 2029, 2030, 2031, 2032, 2033, 2034, 2035, 2036, 2037, 2038, 2039, 2040, 2041, 2042, 2043, 2044, 2045, 2046, 2047, 2048, 2049, 2050, 2051, 2052, 2053, 2054, 2055, 2056, 2057, 2058, 2059, 2060, 2061, 2062, 2063, 2064, 2065, 2066, 2067, 2068, 2069, 2070, 2071, 2072, 2073, 2074, 2075, 2076, 2077, 2078, 2079, 2080, 2081, 2082, 2083, 2084, 2085, 2086, 2087, 2088, 2089, 2090, 2091, 2092, 2093, 2094, 2095, 2096, 2097, 2098, 2099, 2100, 2101, 2102, 2103, 2104, 2105, 2106, 2107, 2108, 2109, 2110, 2111, 2112, 2113, 2114, 2115, 2116, 2117, 2118, 2119, 2120, 2121, 2122, 2123, 2124, 2125, 2126, 2127, 2128, 2129, 2130, 2131, 2132, 2133, 2134, 2135, 2136, 2137, 2138, 2139, 2140, 2141, 2142, 2143, 2144, 2145, 2146, 2147, 2148, 2149, 2150, 2151, 2152, 2153, 2154, 2155, 2156, 2157, 2158, 2159, 2160, 2161, 2162, 2163, 2164, 2165, 2166, 2167, 2168, 2169, 2170, 2171, 2172, 2173, 2174, 2175, 2176, 2177, 2178, 2179, 2180, 2181, 2182, 2183, 2184, 2185, 2186, 2187, 2188, 2189, 2190, 2191, 2192, 2193, 2194, 2195, 2196, 2197, 2198, 2199, 2200, 2201, 2202, 2203, 2204, 2205, 2206, 2207, 2208, 2209, 2210, 2211, 2212, 2213, 2214, 2215, 2216, 2217, 2218, 2219, 2220, 2221, 2222, 2223, 2224, 2225, 2226, 2227, 2228, 2229, 2230, 2231, 2232, 2233, 2234, 2235, 2236, 2237, 2238, 2239, 2240, 2241, 2242, 2243, 2244, 2245, 2246, 2247, 2248, 2249, 2250, 2251, 2252, 2253, 2254, 2255, 2256, 2257, 2258, 2259, 2260, 2261, 2262, 2263, 2264, 2265, 2266, 2267, 2268, 2269, 2270, 2271, 2272, 2273, 2274, 2275, 2276, 2277, 2278, 2279, 2280, 2281, 2282, 2283, 2284, 2285, 2286, 2287, 2288, 2289, 2290, 2291, 2292, 2293, 2294, 2295, 2296, 2297, 2298, 2299, 2300, 2301, 2302, 2303, 2304, 2305, 2306, 2307, 2308, 2309, 2310, 2311, 2312, 2313, 2314, 2315, 2316, 2317, 2318, 2319, 2320, 2321, 2322, 2323, 2324, 2325, 2326, 2327, 2328, 2329, 2330, 2331, 2332, 2333, 2334, 2335, 2336, 2337, 2338, 2339, 2340, 2341, 2342, 2343, 2344, 2345, 2346, 2347, 2348, 2349, 2350, 2351, 2352, 2353, 2354, 2355, 2356, 2357, 2358, 2359, 2360, 2361, 2362, 2363, 2364, 2365, 2366, 2367, 2368, 2369, 2370, 2371, 2372, 2373, 2374, 2375, 2376, 2377, 2378, 2379, 2380, 2381, 2382, 2383, 2384, 2385, 2386, 2387, 2388, 2389, 2390, 2391, 2392, 2393, 2394, 2395, 2396, 2397, 2398, 2399, 2400, 2401, 2402, 2403, 2404, 2405, 2406, 2407, 2408, 2409, 2410, 2411, 2412, 2413, 2414, 2415, 2416, 2417, 2418, 2419, 2420, 2421, 2422, 2423, 2424, 2425, 2426, 2427, 2428, 2429, 2430, 2431, 2432, 2433, 2434, 2435, 2436, 2437, 2438, 2439, 2440, 2441, 2442, 2443, 2444, 2445, 2446, 2447, 2448, 2449, 2450, 2451, 2452, 2453, 2454, 2455, 2456, 2457, 2458, 2459, 2460, 2461, 2462, 2463, 2464, 2465, 2466, 2467, 2468, 2469, 2470, 2471, 2472, 2473, 2474, 2475, 2476, 2477, 2478, 2479, 2480, 2481, 2482, 2483, 2484, 2485, 2486, 2487, 2488, 2489, 2490, 2491, 2492, 2493, 2494, 2495, 2496, 2497, 2498, 2499, 2500, 2501, 2502, 2503, 2504, 2505, 2506, 2507, 2508, 2509, 2510, 2511, 2512, 2513, 2514, 2515, 2516, 2517, 2518, 2519, 2520, 2521, 2522, 2523, 2524, 2525, 2526, 2527, 2528, 2529, 2530, 2531, 2532, 2533, 2534, 2535, 2536, 2537, 2538, 2539, 2540, 2541, 2542, 2543, 2544, 2545, 2546, 2547, 2548, 2549, 2550, 2551, 2552, 2553, 2554, 2555, 2556, 2557, 2558, 2559, 2560, 2561, 2562, 2563, 2564, 2565, 2566, 2567, 2568, 2569, 2570, 2571, 2572, 2573, 2574, 2575, 2576, 2577, 2578, 2579, 2580, 2581, 2582, 2583, 2584, 2585, 2586, 2587, 2588, 2589, 2590, 2591, 2592, 2593, 2594, 2595, 2596, 2597, 2598, 2599, 2600, 2601, 2602, 2603, 2604, 2605, 2606, 2607, 2608, 2609, 2610, 2611, 2612, 2613, 2614, 2615, 2616, 2617, 2618, 2619, 2620, 2621, 2622, 2623, 2624, 2625, 2626, 2627, 2628, 2629, 2630, 2631, 2632, 2633, 2634, 2635, 2636, 2637, 2638, 2639, 2640, 2641, 2642, 2643, 2644, 2645, 2646, 2647, 2648, 2649, 2650, 2651, 2652, 2653, 2654, 2655, 2656, 2657, 2658, 2659, 2660, 2661, 2662, 2663, 2664, 2665, 2666, 2667, 2668, 2669, 2670, 2671, 2672, 2673, 2674, 2675, 2676, 2677, 2678, 2679, 2680, 26

**STUDY DESIGN:** Cohort study.

[illegible]

© 2000 Blackwell Science Ltd  
Journal of Internal Medicine 247: 111–117



# V8 MOTOR WERKZ PRIVATE LIMITED

7 #01-92 SIN MING INDUSTRIAL ESTATE SINGAPORE 575644

TEL NO : 91442977

EMAIL : [V8MOTORWERKZ@GMAIL.COM](mailto:V8MOTORWERKZ@GMAIL.COM)

ROC NO. : 201622378N

DATE :13/12/19

MAKE / MODEL : TOYOTA ALTIS

VEHICLE PLATE NUM : SLA4702J

ESTIMATED COST :

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

No.	Description	QTY	Amount
1	REAR BUMPER <i>Dis/bn</i>	1PCS	\$520.00
2	REAR BUMPER RETAINER <i>105.40</i>	2PCS	\$115.40
3	REAR BUMPER BRACKET <i>R</i>	2PCS	\$119.50
4	TAILLAMP LH <i>281.80 CM</i>	1PCS	\$515.00
5	TAILLAMP LH LOWER BRACKET <i>R</i>	1PCS	\$116.00
6	TAILLAMP PANEL LH <i>R</i>	1PCS	\$195.00
7	LH SIDE SKIRT <i>m/crm</i>	1PCS	\$459.50
8	REAR FENDER LH <i>R</i>	1PCS	\$980.00
9	REAR LH FENDER INNER TRIM <i>R</i>	1PCS	\$490.00
10	REAR FENDER INNER COWLING <i>Dis</i>	1PCS	\$130.00
11	REAR FENDER AIR VENT LH <i>R</i>	1PCS	\$60.00
12	REAR DOOR LH <i>1056.40 R</i>	1PCS	\$1250.00
13	REAR DOOR INNER TRIM LH <i>R</i>	1PCS	\$695.00
14	REAR DOOR INNER LOCK LH <i>R</i>	1PCS	\$480.00
15	REAR DOOR WEATHER STRIP LH <i>R</i>	1PCS	\$160.00
16	REAR DOOR PROTECTOR LH <i>158.60 R</i>	1PCS	\$175.00
17	REAR WINDSCREEN MOULDING <i>R</i>	1PCS	\$155.00
18	REAR SHOCK ABSORBER RH <i>R</i>	1PCS	\$461.80

258

7077.70

Not Authorised  
L/Smp 858-001  
Resurvey After Paint

10 days

19	REAR AXLE BEAM	SL	1PCS	\$2017.10	X
20	REAR WHEEL HUB BEARING 561.60	me	1PCS	\$591.70	✓
21	REAR SPORT WHEEL - RH	del	1PCS	\$1250.00	2801n
22	FRONT BUMPER 53040	Bex	1PCS	\$747.80	✓
23	RADIATOR GRILLE 381.45	Dig	1PCS	\$521.20	✓
24	FRONT BUMPER LOWER GRILLE 105	Dig	1PCS	\$151.20	✓
25	FRONT BUMPER REINFORCEMENT	re	1PCS	\$843.70	X
26	FRONT NUMBER PLATE	in	1PCS	\$50.00	X
27	FRONT BUMPER CLIP	me	1PCS	\$50.00	✓
28	TAILLAMP CLIP(SET)	me	1PCS	\$60.00	X
29	TAILLAMP PANEL SEALANT LH	me	1PCS	\$60.00	X
30	REAR DOOR INNER TRIM CLIP	me	1PCS	\$100.00	✓
31	REAR FENDER SEALANT LH	me	1PCS	\$80.00	301n
32	REAR FENDER COWLING CLIPS	me	1PCS	\$60.00	✓
33	REAR FENDER INNER TRIM CLIPS	me	1PCS	\$60.00	X
34	REAR WINDSCREEN SEALANT	me	1PCS	\$80.00	401n
35	REAR WINDSCREEN INNER SEAL	me	1PCS	\$80.00	301n
36	REAR TYRE	in	1PCS	\$450.00	701n
	PANEL BEATING, REMOVAL AND REPLACING PARTS			\$2200.00	1200
	TO SPRAY PAINT AFFECTED AREA			\$2000.00	1100
	TUFF COAT			\$150.00	601
	WIRING CHECK			\$100.00	301
	REMOVE AND REFIX UPHOLSTERY FACILITATE REPAIR			\$160.00	1001
	REMOVE AND REFIX REVERSE SENSOR			\$120.00	501
	CONDUCT WATER LEAKAGE TEST			\$60.00	201
	REMOVE AND REFIX FUEL TANK FENDER REPLACEMENT			\$150.00	601
	REMOVE AND REFIX REAR WINDSCREEN			\$150.00	1201
	TRANSFER REAR DOOR MECHANISM			\$200.00	601
	REAR CHASSIS ALIGNMENT			\$250.00	601

2022.20  
12792.72  
19869.92






























## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Nov 2019		11 Nov 2019 16:21 <a href="#">Edit Adj Rpt</a>	<b>S\$5,800.00</b> <a href="#">Edit Estimates</a>	<b>S\$5,800.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	<b>CLOUD CAR RENTAL PTE LTD</b>								
Vehicle Reg. No.:	<b>SLA4702J</b>	Date of Loss:	06/11/2019 15:00 - :59 [129 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / SNM19D205294C02</b>	Policy/Cover Note No.:	DMCVSN19267719000						
Vehicle Reg. No. (Insured):	<b>GBB8834Z</b>	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	<b>Messrs VB Motor Werkz Pte Ltd (HQ)</b> Blk 9, #01-44 Sin Ming Industrial Est Sector C, 575630 Sin Ming - Tel:								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Irene Tay Hui Ping</b> - 638986192]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KENNETH KONG</b> ] ... <b>[Final Rpt due 20/11/2019]</b>								
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SLA4702J (SNM19D205294C02)  
[GBB8834Z]  
TP  
CLOUD CAR RENTAL PTE LTD  
Nov 6 2019 3:00PM  
[-]  
Messrs V8 Motor Werkz Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images						3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	10/03/20 17:24	General View					Load JPG	<input checked="" type="checkbox"/>	
2	10/03/20 17:24	General View					Load JPG	<input checked="" type="checkbox"/>	
3	10/03/20 17:24	General View					Load JPG	<input checked="" type="checkbox"/>	
4	10/03/20 17:24	General View					Load JPG	<input checked="" type="checkbox"/>	
5	10/03/20 17:24	General View					Load JPG	<input checked="" type="checkbox"/>	
6	10/03/20 17:24	General View					Load JPG	<input checked="" type="checkbox"/>	
7	10/03/20 17:24	General View					Load JPG	<input checked="" type="checkbox"/>	
8	10/03/20 17:24	General View					Load JPG	<input checked="" type="checkbox"/>	
9	10/03/20 17:24	General View					Load JPG	<input checked="" type="checkbox"/>	
10	10/03/20 17:24	General View					Load JPG	<input checked="" type="checkbox"/>	
11	10/03/20 17:24	General View					Load JPG	<input checked="" type="checkbox"/>	
12	10/03/20 17:24	General View					Load JPG	<input checked="" type="checkbox"/>	
13	10/03/20 17:24	General View					Load JPG	<input checked="" type="checkbox"/>	
14	10/03/20 17:24	General View					Load JPG	<input checked="" type="checkbox"/>	
15	10/03/20 17:24	General View					Load JPG	<input checked="" type="checkbox"/>	
16	10/03/20 17:24	General View					Load JPG	<input checked="" type="checkbox"/>	
17	10/03/20 17:24	General View					Load JPG	<input checked="" type="checkbox"/>	
18	10/03/20 17:24	General View					Load JPG	<input checked="" type="checkbox"/>	
19	10/03/20 17:24	General View					Load JPG	<input checked="" type="checkbox"/>	
20	10/03/20 17:24	General View					Load JPG	<input checked="" type="checkbox"/>	
21	10/03/20 17:24	General View					Load JPG	<input checked="" type="checkbox"/>	
22	10/03/20 17:27	Photo After Spray					Load JPG	<input checked="" type="checkbox"/>	
23	10/03/20 17:27	Photo After Spray					Load JPG	<input checked="" type="checkbox"/>	
24	10/03/20 17:27	Photo After Spray					Load JPG	<input checked="" type="checkbox"/>	
25	10/03/20 17:27	Photo After Spray					Load JPG	<input checked="" type="checkbox"/>	
Documentation						1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)					Thumbnail	Print	
1	19/12/19 15:24	REPORT OF SLA4702J					Load PDF		
2	19/12/19 15:25	Singapore Accident Statement					Load PDF		

## Documents Checklist

<a href="#">Reset</a> <a href="#">Save</a> <a href="#">Print</a>
<p><b>DOCUMENTS CHECKLIST</b></p> <p>There are no document checklists configured.</p>

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

	^ v
--	--------

**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:196607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19019956/KQF3E2

Date: 23/03/2020

## REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMCVSN19267719000

Claimant Vehicle  
No : SLA4702JInsured Vehicle  
No : GBB8834Z

Date of Loss: 06/11/2019

Nature of Claim: TP

Claim  
No: SNM19D205294C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLA4702J

Make &amp; Model: TOYOTA COROLLA ALTIS, 1.6 (A)

Engine No: HIDDEN

Reg. Date: 03/02/2009 (Man. Year: 2009)

Chassis No: MR053ZEE106139039

Colour: Metallic Blue

Odometer: 0 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Continental 4 mm

Rear Left Side: West Lake 8 mm

Front Right Side: Continental 4 mm

Rear Right Side: West Lake 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,329.90	4,670.44	9,659.46	67.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,540.00	2,860.00	2,680.00	48.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>19,869.90</b>	<b>7,530.44</b>	<b>12,339.46</b>	<b>62.10</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,800.00</b>		
<b>Nett Amount (S\$)</b>	<b>19,869.90</b>	<b>5,800.00</b>	<b>14,069.90</b>	<b>70.81</b>

## INSPECTION

Date of Assignment: 11/11/2019

Date Inspected: 11/11/2019 Inspected At:

Messrs V8 Motor Werkz Pte Ltd (HQ)  
Blk 9, #01-44 Sin Ming Industrial Est  
Sector C  
Singapore 575630

Estimated Period of Repair: 10.0 days

**Adjuster:** KENNETH KONG

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 23 Mar 2020)
<b>Parts:</b>	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLA4702J)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted / Buckled	520.00 F	*520.00 FL
2	1		*REAR BUMPER RETAINER	N/S Cracked	115.40 F	*57.70 FL
3	2		*REAR BUMPER BRACKET	Repair	119.50 F	*- FL
4	1		*TAILLAMP LH	Cracked	515.00 F	*281.90 FL
5	1		*TAILLAMP LH LOWER BRACKET	Serviceable	116.00 F	*- FL
6	1		*TAILLAMP PANEL LH	Repair	195.00 F	*- FL
7	1		*LH SIDE SKIRT	Mtg Cracked	459.50 F	*459.50 FL
8	1		*REAR FENDER LH	Bent	980.00 F	*980.00 FL
9	1		*REAR LH FENDER INNER TRIM	Serviceable	490.00 F	*- FL
10	1		*REAR FENDER INNER COWLING	Distorted	130.00 F	*130.00 FL
11	1		*REAR FENDER AIR VENT LH	Serviceable	60.00 F	*- FL
12	1		*REAR DOOR LH	Bent	1,250.00 F	*1,056.40 FL
13	1		*REAR DOOR INNER TRIM LH	Serviceable	695.00 F	*- FL
14	1		*REAR DOOR INNER LOCK LH	Repair	480.00 F	*- FL
15	1		*REAR DOOR WEATHER STRIP LH	Serviceable	160.00 F	*- FL
16	1		*REAR DOOR PROTECTOR LH	Necessary	175.00 F	*158.60 FL
17	1		*REAR WINDSCREEN MOULDING	Necessary	155.00 F	*155.00 FL
18	1		*REAR SHOCK ABSORBER RH	Serviceable	461.80 F	*- FL
19	1		*REAR AXLE BEAM	Serviceable	2,017.10 F	*- FL
20	1		*REAR WHEEL HUB BEARING	Necessary	591.70 F	*561.60 FL
21	1		*REAR SPORT WHEEL - RH	Dented	1,250.00 FS	*280.00 FS
22	1		*FRONT BUMPER	Buckled	747.80 F	*530.10 FL
23	1		*RADIATOR GRILLE	Distorted	521.20 F	*381.45 FL
24	1		*FRONT BUMPER LOWER GRILLE	Distorted	151.20 F	*105.00 FL
25	1		*FRONT BUMPER REINFORCEMENT	Repair	843.70 F	*- FL
26	1		*FRONT NUMBER PLATE	Serviceable	50.00 F	*- FL
27	1		*FRONT BUMPER CLIP	Necessary	50.00 F	*50.00 FL
28	1		*SET TAILLAMP CLIP	Not Necessary	60.00 F	*- FL
29	1		*TAILLAMP PANEL SEALANT LH	Not Necessary	60.00 F	*- FL
30	1		*REAR DOOR INNER TRIM CLIP	Not Necessary	100.00 F	*- FL
31	1		*REAR FENDER SEALANT LH	Necessary	80.00 FS	*30.00 FS
32	1		*REAR FENDER COWLING CLIPS	Necessary	60.00 F	*60.00 FL
33	1		*REAR FENDER INNER TRIM CLIPS	Not Necessary	60.00 F	*- FL
34	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
35	1		*REAR WINDSCREEN INNER SEAL	Necessary	80.00 FS	*30.00 FS
36	1		*REAR TYRE (\$250.00) (70%)	Torn	450.00 FS	*175.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>14,329.90</b>	<b>6,042.25</b>
<b>- List Item Discount on L Items 0.00/25.00% (S\$)</b>	<b>0.00</b>	<b>1,371.81</b>

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)					14,329.90	4,670.44

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	New	2,200.00	1,200.00
2	TO SPRAY PAINT AFFECTED AREA	New	2,000.00	1,100.00
3	TUFF COAT	New	150.00	60.00
4	WIRING CHECK	New	100.00	30.00
5	REMOVE AND REFIX UPHOLSTERY FACILITATE REPAIR	New	160.00	100.00
6	REMOVE AND REFIX REVERSE SENSOR	New	120.00	50.00
7	CONDUCT WATER LEAKAGE TEST	New	60.00	20.00
8	REMOVE AND REFIX FUEL TANK FENDER REPLACEMENT	New	150.00	60.00
9	REMOVE AND REFIX REAR WINDSCREEN	New	150.00	120.00
10	TRANSFER REAR DOOR MECHANISM	New	200.00	60.00
11	REAR CHASSIS ALIGNMENT	New	250.00	60.00
Gross Labour Cost (S\$)			<b>5,540.00</b>	<b>2,860.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >