Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)

Sent: Wednesday, 13 November 2019 5:36 pm

To: Sbk E Cc: SUR

Subject: FBL 8813G OD Date of Loss: 07/11/2019

Dear All,

As instructed by our client, please proceed to repair the insured vehicle FBL 8813G (Excess \$ 1.300/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Kindly refer to the below AIG comments.

Front shock absorber to be under repair basic.

To arrange photo taking for check, suppl & after repair.

Thanks

Regards, Thaddaeus Ng AlG

Motor Claims Surveyor

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>Sur@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)