

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Nadaraja, Deeban

Date: 17 Dec 2019

Preliminary Advice

Vehicle No	: FBL8813G	Accident Date	: 07/11/2019
Make	: YAMAHA MT-10	Policy No.	: 1800023006
Assignment Date	: 12/11/2019	Excess	: S\$1,300.00
Date of Inspection	: 11/11/2019	Est. Duration of Repair	: 4 days
Inspection At	: Bike Production (HQ) No 610 Serangoon Road Singapore 218216		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,450.60 (inclusive supp)
Revised Amount	:S\$	6,972.60 (inclusive supp)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,972.60
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	25,000.00
COE / PARF Rebate	:S\$	4,728.00
Salvage Value	:S\$	
Margin for Repair	:S\$	20,272.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Supplementary amount is \$ 523.60.