

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : HOC TRADING
BLK 295 PUNGGOL CENTRAL
#05-517
SINGAPORE 820295

Estimate No: MC1900792
Date: 30 Oct 2019
Policy No: P1953808
Veh Reg No: SGG8203J
Make/Model: TOYOTA WISH 1.8A

ATTN:

Your Ref No: SGG8203J
Claim Type: Third Party
Accident Date: 29/10/2019
TP Veh Reg No: SLE9372Z

Not Withdrawn
LLP & ?
Returning After Paint

4-5 days

Estimate Repair Cost to Vehicle No :SGG8203J

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 REAR WINDSCREEN M/SIDE/LOWEROULDING TOP	1 PC	70.20	✓
2 TAILGATE	1 PC	1,472.30	✓
3 TAILGATE EMBLEM	1 PC	68.50	✓
4 TAILGATE INNER LOCK	1 PC	490.40	X
5 TAILGATE RUBBER	1 PC	362.30	X
6 TAILAMP RH	1 PC	SVC 524.70	X
7 REAR BUMPER	1 PC	Bu 524.30	✓
8 REAR BUMPER SIDE RETAINER RH	1 PC	DIT 69.60	✓
9 REAR BUMPER CLIPS	15 PC	Bu 58.35	✓
10 REAR BUMPER REFLECTOR RH	1 PC	Bu 57.60	X
11 REAR END PANEL	1 PC	SVC 568.70	X
12 REAR END PANEL TOP GARNISH	1 PC	Bu 265.30	X
13 REAR EXHAUST PIPE	1 PC	Bu 790.15	X
		5,322.40	
	Less 25%	1,330.60	3,991.80
Special Nett			
14 NUMBER PLATE	1 PC	Bu 35.00	X
15 REVERSE SENSOR	1 SET	Bu 200.00	X
16 INNER SEAL	1 PC	Bu 20.00	✓
17 WINDSCREEN SEALANT	1 PC	Bu 40.00	✓
		295.00	295.00
LABOUR			
18 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	15/
19 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.	1 PC	120.00	✓
20 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	80.00	50/
21 TO SPRY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	30/
22 TO REALIGN, DISMANTLE AND REINSTALL/REPLACE EXHAUST PIPE.	1 PC	60.00	X
23 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD END PANEL.TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	800.00	500/
24 TO SPRAY TAILGATE,REAR BUMPER,END PANEL.	1 PC	800.00	600/
		1,960.00	1,960.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : HOC TRADING
BLK 295 PUNGGOL CENTRAL
#05-517
SINGAPORE 820295

Estimate No: MC1900792
Date: 30 Oct 2019
Policy No: P1953808
Veh Reg No: SGG8203J
Make/Model: TOYOTA WISH 1.8A

ATTN:
Your Ref No: SGG8203J
Claim Type: Third Party
Accident Date: 29/10/2019
TP Veh Reg No: SLE9372Z

Estimate Repair Cost to Vehicle No :SGG8203J

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
		Total	S\$ 6,246.80
		Add GST @ 7%	437.28
		Total Amount Payable	<u>S\$ 6,684.08</u>

TOTAL: SINGAPORE DOLLAR SIX THOUSAND SIX HUNDRED EIGHTY FOUR AND CENTS EIGHT ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY

AUTHORISED SIGNATURE