

JIN AUTO SERVICES PTE LTD: *Asher*

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62894656 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

10/12/2019

M/S AIG *e*

DEAR SIR
ESTIMATED REPAIR COST FOR VEHICLE GBD9074H

net Net Items

- 1 REAR DOOR *o/s*
- 1 REAR DOOR PILLAR *o/s*
- 1 REAR RH LAMP
- 2 REAR ~~REVERSE~~ STOPPER
- 1 RH MUDGUARD
- 1 REAR RH MUDFLAP
- 1 ARTWORK
- 1 SPRAY PAINTING
- LABOUR CHARGE
- WIRING

102

S.NETT ITEMS

<i>20/3/19</i>	\$	1,850.00	<i>1000 s.n</i>
<i>20/3/19</i>	\$	480.00	<i>420 s.n</i>
<i>5/10</i>	\$	174.80	<i>✓</i>
<i>7/11</i>	\$	30.00	<i>✓</i>
<i>12</i>	\$	129.60	<i>α</i>
<i>8/11</i>	\$	51.50	<i>α</i>
<i>11/11</i>	\$	480.00	<i>380 s.n</i>
	\$	680.00	<i>300</i>
	\$	580.00	<i>500</i>
	\$	30.00	<i>20</i>
	\$	<u>4,485.90</u>	

net Amount
11/12/19
Take the. 4485.90
1/5 \$2400
4/11

P-204.80
102
P-184.32
S.N-1800.00
L-1070.00
3004.32
2003.

Jin Auto Consultants hence notify the Repairer of the following:

1. The vehicle must be resurveyed after spray painting

2. The vehicle must be resurveyed (if any) during resurvey

3. The vehicle must be resurveyed to confirmation

4. The vehicle must be resurveyed on a "Without Prejudice" basis

5. The vehicle must be resurveyed and

6. The vehicle must be resurveyed and

7. The vehicle must be resurveyed and

8. The vehicle must be resurveyed and

9. The vehicle must be resurveyed and

10. The vehicle must be resurveyed and

Acknowledged by Repairer

Signature