

Kd

RICARDO AUTO CENTRE PTE LTD

GST: M2-0053787-4 RCB NO: 198102182M

160 SIN MING DRIVE #02-02/03 SIN MING AUTOCITY SINGAPORE 575722

TEL: 6475 2112 FAX: 6475 4666

WEBSITE: <http://www.ricardo.com.sg>

QUOTATION

M/S: NG HUA KUAN

BLK 416 CHOA CHU KANG AVE 4
#10-362 S(680416)

H/P: 91088546

NO:

WQT0801015

DATE:

07 Nov 2019

A/C CODE:

C015382

YOUR REF:

SLJ3328R

VEH REG NO:

SLJ3328R

MAKE/MODEL:

TOYOTA WISH 1.8 CVT

SALESMAN:

Description	Quantity	Unit Price	%	Amount
		SS		SS

WE SUBMIT HERewith OUR ESTIMATED COST OF REPAIRED TO ABOVE MENTIONED VEHICLE.

DOA: 07/11/2019 @0730 HRS

ACCIDENT INVOLVING: SLJ3328R, GBC4416T, SHC459A & GBG8502E

CLAIM TYPE: 3RD PARTY CLAIM AGAINST GBC4416T (INSURED WITH AIG)

1	TAILGATE	1 PC	1,615.90	Ry	1,615.90	—
2	TAILGATE TOYOTA LOGO	1 PC	66.15	Ry	66.15	—
3	TAILGATE PLATE - "VALVE MATIC"	1 PC	45.00	Ry	45.00	—
4	TAILGATE OUTER GARNISH (CHROME)	1 PC	298.70	CM	298.70	—
5	REAR LAMP LH & RH	2 PC	365.70	Sn	731.40	X
6	BACK DOOR TRIM BOARD	1 PC	375.40	Sn	375.40	X
7	BACK DOOR LOCK	1 PC	402.60	DR	402.60	—
8	BACK DOOR OPENER	1 PC	149.80	Sn	149.80	X
9	BACK DOOR HINGES LH & RH	2 PC	68.70	R	137.40	X
10	REAR END PANEL	1 PC	580.20	Ry	580.20	—
11	BACK DOOR SCUFF PLATE	1 PC	278.66	MJD	278.66	—
12	REAR BUMPER	1 PC	688.90	Ry	688.90	—
13	REAR BUMPER CLIPS	10 PC	4.00	Ry	40.00	—
14	REAR BUMPER REFLECTOR LH	1 PC	54.70	CM Ry	54.70	—
15	REAR BUMPER ARM LH	1 PC	97.66	DR	97.66	—
16	REAR BUMPER SIDE SUPPORT LH & RH	2 PC	95.00		190.00	—
17	REAR BUMPER SIDE RETAINER LH & RH	2 PC	93.10		186.20	—
18	REAR FENDER LH	1 PC	898.50	R	898.50	X
19	REAR COMBINATION LAMP LH	1 PC	289.70	Sn	289.70	X
20	BACK DOOR WEATHERSTRIP	1 PC	381.10	MJD	381.10	—
21	REAR FENDER INNER TRIM LH	1 PC	679.40	Ry	679.40	—
22	BACK WINDSCREEN MOULDING LH & RH	2 PC	70.20	Ry	140.40	—
23	BACK WINDSCREEN MOULDING TOP	1 PC	68.00	Ry	68.00	—
24	BACK WINDSCREEN MOULDING BOTTOM	1 PC	70.20	Ry	70.20	—
25	REAR NO. PLATE WITH HOLDER (NETT ITEM)	1 PC	45.00	DR	45.00	—
26	SUPPLY WINDSCREEN SEALANT.	1 LOT	40.00	Ry	40.00	—

259

RICARDO AUTO CENTRE PTE LTD

GST: M2-0053787-4 RCB NO: 198102182M
160 SIN MING DRIVE #02-02/03 SIN MING AUTOCITY SINGAPORE 575722
TEL: 6475 2112 FAX: 6475 4666
WEBSITE: <http://www.ricardo.com.sg>



QUOTATION

M/S : NG HUA KUAN

NO: WQT0801015
DATE: 07 Nov 2019

PAGE: 2

Description	Quantity	Unit Price	%	Amount
		SS		SS
WE SUBMIT HERewith OUR ESTIMATED COST OF REPAIRED TO ABOVE MENTIONED VEHICLE.				
DOA: 07/11/2019 @0730 HRS				
ACCIDENT INVOLVING: SLJ3328R, GBC4416T, SHC459A & GBG8502E				
CLAIM TYPE: 3RD PARTY CLAIM AGAINST GBC4416T (INSURED WITH AIG)				
27 TO REMOVE & REPLACE REAR WINDSCREEN GLASS ENABLE TO REPLACE NEW BACK DOOR.	1 SVC	100.00		100.00 ✓
28 TO TUFF COAT REPAIRED AREA.	1 SVC	100.00	60%	100.00
29 TO REMOVE INNER TRIM AND ATTACHED PARTS ENABLE TO REPLACE LH REAR INNER TRIM BOARD & FIX SAME.	1 SVC	300.00	80%	300.00
30 TO CUT, WELD & STRAIGHTEN REAR PORTION OF CAR CAUSED BY ACCIDENT. ADJUST & REPLACE DAMAGE PARTS.	1 SVC	1,400.00		1,400.00 900%
31 TO RESPRAY ON REPAIRED AREAS.	1 SVC	1,200.00		1,200.00 1000%
32 COMPUTERIZED WHEEL ALIGNMENT.	1 SVC	60.00	~	60.00 X
33 TO REPAIR EXHAUST TAIL PIPE.	1 SVC	80.00	~	80.00 X
Total				SS 11,790.97
Add GST @ 7%				825.37
Grand Total				SS 12,616.34

TOTAL: SINGAPORE DOLLAR TWELVE THOUSAND SIX HUNDRED SIXTEEN AND CENTS THIRTY FOUR ONLY

NG HUA KUAN

For RICARDO AUTO CENTRE PTE LTD

CONFIRMED & ACCEPTED BY

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following: • To resurvey - before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey - on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____

RICARDO AUTO CENTRE PTE LTD

GST: M2-0053787-4 RCB NO: 198102182M
160 SIN MING DRIVE #02-02/03 SIN MING AUTOCITY SINGAPORE 575722
TEL: 6475 2112 FAX: 6475 4666
WEBSITE: <http://www.ricardo.com.sg>



QUOTATION

M/S: NG HUA KUAN

BLK 416 CHOA CHU KANG AVE 4
#10-362 S(680416)

H/P: 91088546

NO: WQT0801017

DATE: 15 Nov 2019

A/C CODE: C015382

YOUR REF: SLJ3328R

VEH REG NO: SLJ3328R

MAKE/MODEL: TOYOTA WISH 1.8 CVT

SALESMAN:

Description				PAGE:1	
	Quantity	Unit Price	%	Amount	
				SS	SS
WE SUBMIT HERewith OUR SUPPLEMENTARY ITEMS TO ABOVE MENTIONED VEHICLE.					
DOA: 07/11/2019 @0730 HRS					
ACCIDENT INVOLVING: SLJ3328R, GBC4416T, SHC459A & GBG8502E					
CLAIM TYPE: 3RD PARTY CLAIM AGAINST GBC4416T (INSURED WITH AIG)					
1 EXHAUST MOUNTING	1 PC	48.70		48.70	X
2 REAR BUMPER SENSOR (ORIGINAL)(NETT ITEM)	1 SET	201.70		201.70	SN
3 REAR BUMPER ARM RH	1 PC	97.66		97.66	CM
4 ANTENNA ELECTRICAL KEY	1 PC	161.70		161.70	CM
Total				SS 509.76	
Add GST @ 7%				35.68	
Grand Total				SS 545.44	

TOTAL: SINGAPORE DOLLAR FIVE HUNDRED FORTY FIVE AND CENTS FORTY FOUR ONLY

NG HUA KUAN

For RICARDO AUTO CENTRE PTE LTD

CONFIRMED & ACCEPTED BY

AUTHORISED SIGNATURE

Pls take pictures flw:

Rear bumper reflector LH

Rear fender inner trim LH

Rear bumper arm LH

05352-62



Part 8 4014.47

S.net 8 24670

Labour 8 2140

6401.17