

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Lionel Tan

Date: 19 Nov 2019

Preliminary Advice

Insured Vehicle No : FBD1995C

TP Vehicle No : SMD1864S

Make : BMW 316I

Date of Inspection : 18/11/2019

Inspection At : Hock Wah Motor Workshop Pte Ltd
BLK9006 TAMPINES ST 93 #01-204
Singapore 528840

Accident Date : 26/10/2019

Assignment Date : 11/11/2019

Est. Duration of Repair : 2 days

Point of Impact / General Description of Damages

The vehicle sustained impact / damagesN/S front... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,307.25
Revised Amount	:S\$	1,440.35
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,440.35

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : We have not authorized repairs.