

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 9006 TAMPINES ST 93 #01-204
SINGAPORE 528840
TEL : 67853933 FAX: 67883933
R.O.C No. 200104141D GST Reg No. 20-0104141-D

TO : S8620232H

CHING HAN MING, JONATHAN (QIAN HANMING)
NO 515 BEDOK RESERVOIR ROAD #01-43

SINGAPORE 479272

TEL : FAX :
PH : 96202135
ATTN :

ESTIMATE BILL

Number : EBK0000295
Date : 09/11/2019
Case No : ADK0000369
Vehicle No : SMD1864S
Chassis : WBA3A12010J720413
Year of Mfr : 2013
Policy No :
Model : BMW 316I

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	FRT BUMPER <i>one ✓</i>	1.0	1,037.05	0	1,037.05
2	FRT BUMPER SIDE RETAINER LH RH <i>1-1 X</i>	2.0	20.10	0	40.20
3	FRT BUMPER CLIPS <i>per ✓</i>	10.0	3.00	0	30.00
List Price - Parts Sub Total					1,107.25
Parts Total					1,107.25
4	FRT FENDER LH REPAIR <i>1-1</i>	1.0			
5	FRT RIM LH REPAIR <i>cut 1-1 X</i>	1.0			
6	SPRAY PAINT ON THE AFFECTED AREAS	1.0	600.00	0	300 600.00
7	LABOUR TO REMOVE AND REFIT NECESSARY PARTS	1.0	600.00	0	180 600.00
Labour 1 Sub Total					1,200.00
SINGAPORE DOLLARS : TWO THOUSAND FOUR HUNDRED SIXTY-EIGHT AND CENTS SEVENTY-SIX ONLY					
Less Excess					0.00
SUBTOTAL					2,307.25
GST 7.00%					161.51
TOTAL					2,468.76

*not added
all
1/53
2019
18/11/19
the price after repair*

Date of accident : 26/10/2019 06:40 PM. Place : KEPPEL ROAD 1 TOWARDS VIVO CITY

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE