


ASSIGNMENT

From: _____ Date: 8/11/19
 Estimated Cost: _____
 OD: TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SHB1246X
 at Workshop with: SMRT
 of: Woodlands
 Insured: SJZ 4609M
 Policy No: 5108727014 (25/05/2019 - 27/05/2020)
 Claims No: MT/1070321-003
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SHB1246X Yr Regn: 08/04/2016
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Toyota Prius C.C: 1798
 Colour: Maroon A/C: Insured / Std / NI / NA
 Sp. Reading: 602399 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JTDKN36U105767865
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or _____

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 11 days Res: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS up
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT



Tyre Size: F: 195/65 R15
 R: 195/65 R15
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Firenza
 Front: _____ Rear: _____
 R/Bal. 5 mm L/Bal. 5 mm
 L/Bal. 5 mm R/Bal. 5 mm
 D.O.A. 07/11/2019 D.O.I. 08/11/2019
 Survey held at SMRT
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SJZ 4609M - X
	SHB 1246X NA/CY12VU1R4U/24 D/O 07/11/2019
	TP TAX/11/19/2019 SJZ 4609 M GBE 5586 T
RECEIVED 20 DEC 2019	

Confirm with Pohsuan
 Finalize \$7750 @ 11 days (LIS) (Red \$29351.81, 79.1%)

: Prel. Report
 : Final Report
 Days Of Repair: 11
 Resurvey No. of Trip: 2
 Survey Fee: 160
 Add Fee: Site Insp (\$) Interview (\$) Tech. Insp (\$) Wheel stud (\$)

Report Fined: TP
 Final Sum: 7750

TP Claims against NTUC Income: Follow-Through Survey

Date : 19/12/2019

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate
1	MT/1070321-003	SMRT TAXI PTE LTD	SHB 1246X	SJZ 4609M	07/11/2019	7:45	\$ 37,101.81
2	MT/1076107-002	COMFORT TRANSPORTATION PTE LTD	SHA 6956C	SLR 3535S	15/12/2019	3:10	\$ 1,949.26
3	MT/1075678-002	CITYCAB PTE LTD	SHD 8582T	SKG 5918C	13/12/2019	17:40	\$ 1,490.00

eBaoTech

GeneralClaim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)My Desktop
Notice of Loss

Policy Query

Policy No. Date of Accident
 Vehicle No. (For Motor) Certificate Number

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	S108727014		PENG TONG VAN NIGEL	S7710430E	GPC	drive CLASSIC	S1Z4609M	S1Z4609M	28/05/2019	27/05/2020

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	369K
Vehicle Details	
Vehicle No.:	SHB1246X
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Nov 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2015
Engine No.:	2ZR6591575
Chassis No.:	JTDKN36U105767865
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$29,508.00
Original Registration Date:	08 Apr 2016
First Registration Date:	08 Apr 2016
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Apr 2024
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	07 Apr 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$36,862.00
COE Rebate Amount:	\$20,304.00
Total Rebate Amount:	\$24,054.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 11 Nov 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/11/2019 10:03
Date Of Accident	07/11/2019 07:45
Exact Location Of Accident	SOMAPAH ROAD TOWARDS CHANGI BUSINESS PARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB1246X
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-19093197MFSH
Cover Note Number	

Driver

Name of Driver	IDRIS BIN SUKI
NRIC No	S1569895J
Date Of Birth	18/07/1962
Occupation	OUTDOOR
Date Of Driving Pass	20/05/1983
Driving Experience	36 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address	165
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS STOPPING ALONG SOMAPAH ROAD AT THE CENTRE LANE WITH A PASSENGER ON BOARD DUE TO TRAFFIC CONGESTED AHEAD. WHILE STATIONARY SUDDENLY THE VEHICLE SJZ4609M FROM BEHIND COLLIDED ONTO THE REAR PORTION OF MY TAXI. DUE TO THE GREAT IMPACT, IT CAUSED MY TAXI TO PUSH FORWARD AND HIT ONTO THE REAR OF THE VEHICLE GBE5586T IN FRONT OF ME.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJZ4609M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	NIGEL PENG
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number GBE5586T
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE
Name of Driver MUHD RAIHAN
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name IDRIS BIN SUKI
Approximate Age
Injuries Sustain
Injured person in which vehicle? SHB1246X
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Case Details

Case Reference Number :

TAX/11/19/2019

Type of Repair : Accident Repair

Vehicle Registration Number : SHB1246X

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-9240-ID

Assigned By : Taxi Claims Manager Team

Insurance Company Name : NTUC Income Insurance Co-operative Ltd

Accident Date and Time : 06/11/2019 11:45 PM

Vehicle Age(In Months) : 43

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation				Repair/ Replace	Surveyor Quantity	Surveyor Approval		Remarks
						List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)			Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			BRACKET, FR BUMPER	1	110.40	110.40	25.00	82.80	Replace	0	0.00	Not Give	* X SUC
One Time Key In	Main			NUMBER PLATE FRAME	1	15.00	15.00	0.00	15.00	Replace	1	15.00	Replace	* / BT
One Time Key In	Main			NUMBER PLATE	1	12.00	12.00	0.00	12.00	Replace	1	12.00	Replace	* / BT
One Time Key In	Main			COVER, FR BUMPER HOLE LH	1	18.50	18.50	25.00	13.88	Replace	1	13.88	Replace	* / SCR
One Time Key In	Main			COVER, FR BUMPER HOLE RH	1	18.50	18.50	25.00	13.88	Replace	0	0	Not Give	* X SUC
One Time Key In	Main			EMBLEM FRONT	1	86.50	86.50	25.00	64.88	Replace	1	64.88	Replace	* / Nec
One Time Key In	Main			SUPPORT SUB-ASSY	1	1,460.40	1,460.40	25.00	1,095.30	Replace	0	0.00	Not Give	* X SUC
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace	* / Nec
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.0	Replace	* / Nec
One Time Key In	Main			ANTENNA,ELECTRICAL LOWER REAR	1	157.40	157.40	10.00	141.66	Replace	1	141.66	Replace	* / BR
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	1	180.0	Replace	* / short
One Time Key In	Main			BUMPER SEAL, RR LH	1	88.90	88.90	25.00	66.68	Replace	1	66.68	Replace	* / Nec

777320

Total Spare Part Cost	19,877.16	Surveyor Total	6,150.20
Lump Sum Discount (%)	20.00	Lump Sum Dis (%)	20
Final Spare Part Cost	15,901.73	Final Sur Total	4,920.16

SMRT Recommendation

Surveyor Approval

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			UNDER COVER CENTER REAR	1	514.50	514.50	25.00	385.88	Replace	0	0.00	Check	* X SVC
One Time Key In	Main			END PANEL COVER, DECK TRIM HOLE	1	46.10	46.10	25.00	34.58	Replace	1	34.58	Replace	* MIS
One Time Key In	Main			END PANEL COVER, DECK TRIM, RR	1	121.10	121.10	25.00	90.82	Replace	1	90.82	Replace	* BR
One Time Key In	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	1	37.00	Replace	* Nec
One Time Key In	Main			BOX, DECK FLOOR, RR	1	649.70	649.70	25.00	487.28	Replace	0	0.00	Check	* X SVC
One Time Key In	Main			BOX RR FLOOR, BOARD	1	679.60	679.60	25.00	509.70	Replace	0	0.00	Check	* X SVC
One Time Key In	Main			BOARD, RR FLOOR	1	392.30	392.30	25.00	294.23	Replace	0	0.00	Check	* X SVC
One Time Key In	Main			BOX, DECK FLOOR, COVER LH	1	230.10	230.10	25.00	172.57	Replace	0	0.00	Check	* X SVC
One Time Key In	Main			BOX, DECK FLOOR, LH	1	196.80	196.80	25.00	147.60	Replace	0	0.00	Check	* X SVC
One Time Key In	Main			SPACER, RR FLOOR	1	130.60	130.60	25.00	97.95	Replace	0	0.00	Check	* X SVC
One Time Key In	Main			BOARD ASSY, RR RH	1	379.20	379.20	25.00	284.40	Replace	0	0.00	Check	* X SVC
One Time Key In	Main			PANEL ASSY, DECK LH	1	307.00	307.00	25.00	230.25	Replace	0	0.00	Check	* X SVC
One Time Key In	Main			PANEL ASSY, DECK RH	1	307.00	307.00	25.00	230.25	Replace	0	0.00	Check	* X SVC
One Time Key In	Main			SPARE TYRE PANEL	1	667.70	667.70	25.00	500.78	Replace	0	0.00	Check	* X SVC
One Time Key In	Main			CUSHION, SPARE WHEEL	1	230.80	230.80	25.00	173.10	Replace	0	0.00	Check	* X SVC
One Time Key In	Main			CARRIER, SPARE	1	18.70	18.70	25.00	14.77	Replace	0	0.00	Check	* X SVC
One Time Key In	Main			PROTECTOR, SPARE	1	143.70	143.70	25.00	107.77	Replace	0	0.00	Check	* X SVC
One Time Key In	Main			MEMBER SUB-ASSY, RR LH	1	174.10	174.10	25.00	130.57	Replace	0	0.00	Check	* X SVC
One Time Key In	Main			MEMBER SUB-ASSY, RR RH	1	174.10	174.10	25.00	130.57	Replace	0	0.00	Check	* X SVC
One Time Key In	Main			REINFORCEMENT, RR	2	34.60	69.20	25.00	51.90	Replace	0	0.00	Check	* X SVC

5470.30

Total Spare Part Cost 19,877.16

Surveyor Total 6,150.20

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 15,901.73

Final Sur Total 4,920.16

SMRT Recommendation

Surveyor Approval

BOM Type	Coating Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BATTERY	1	278.00	278.00	10.00	250.20	Replace	0	0.00	Check	• X SUC
One Time Key In	Main			TAILGATE DOOR GLASS MOULDING, RH	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace	• / Nec
One Time Key In	Main			TAILGATE DOOR GLASS MOULDING, LH	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace	• / Nec
One Time Key In	Main			MOULDING BACK WINDOW, LOWER NO.1	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace	• / NEC
One Time Key In	Main			TAILGATE LOWER WINDOW GLASS	1	721.30	721.30	25.00	540.978	Replace	1	540.9	Replace	• / CR4
One Time Key In	Main			SEALANT W/SCREEN	3	37.00	111.00	0.00	111.00	Replace	3	111.0	Replace	• / Nec
One Time Key In	Main			WIRE, BACK DOOR, NO.1	1	582.40	582.40	10.00	524.16	Replace	0	0.00	Not Give	• X SUC
One Time Key In	Main			TAILGATE DOOR STAY LH	1	241.50	241.50	25.00	181.13	Replace	0	0.00	Not Give	• X SUC
One Time Key In	Main			TAILGATE DOOR STAY RH	1	241.50	241.50	25.00	181.13	Replace	0	0.00	Not Give	• X SUC
One Time Key In	Main			TAILGATE LOCK COVER	1	15.70	15.70	25.00	11.778	Replace	1	11.77	Replace	• / Nec
One Time Key In	Main			STRIKER, BACK DOOR	1	48.90	48.90	25.00	36.67	Replace	0	0.00	Check	• X SUC
One Time Key In	Main			TAILGATE, BAORD ASSY	1	246.90	246.90	25.00	185.18	Replace	1	185.1	Replace	• / DP
One Time Key In	Main			LICENSE PLATE LAMP	2	35.70	71.40	10.00	64.26	Replace	0	0.00	Not Give	• X SUC
One Time Key In	Main			CAMERA ASSY, TELEVISION, RR	1	1,436.60	1,436.60	10.00	1,292.94	Replace	0	0.00	Not Give	• X SUC
One Time Key In	Main			NUMBER PLATE	1	15.00	15.00	0.00	15.00	Replace	0	0.00	Not Give	• X SUC
One Time Key In	Main			NUMBER PLATE FRAME	1	12.00	12.00	0.00	12.00	Replace	0	0.00	Not Give	• X SUC
One Time Key In	Main			STICKER DECAL SMRT	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	• / NA
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	• / Nec
One Time Key In	Main			FENDER RR/RH	1	766.80	766.80	25.00	575.10	Replace	0	0.00	Not Give	• X SUC
One Time Key In	Main			STICKER DECAL SMRT	1	7.80	7.80	0.00	7.80	Replace	0	0.00	Not Give	• X SUC

4914.40

Total Spare Part Cost	19,877.16	Surveyor Total	6,150.20
Lump Sum Discount (%)	20.00	Lump Sum Dis (%)	20
Final Spare Part Cost	15,901.73	Final Sur Total	4,920.16

SMRT Recommendation

Surveyor Approval

BOM Type	Coating Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	0	0.00	Not Giv	* X SVC
One Time Key In	Main			SEALANT W/SCREEN	1	37.00	37.00	0.00	37.00	Replace	0	0.00	Not Giv	* X SVC
One Time Key In	Main			TROUGH, BACK DOOR	1	110.90	110.90	25.00	83.18	Replace	0	0.00	Not Giv	* X SVC
One Time Key In	Main			TAIL LAMP BRACKET, RH	1	30.70	30.70	25.00	23.02	Replace	0	0.00	Check	* X SVC
One Time Key In	Main			DUCT ASSY, QUARTER	1	70.40	70.40	25.00	52.80	Replace	0	0.00	Check	* X SVC
One Time Key In	Main			FLOOR PANEL RR/RH	1	209.90	209.90	25.00	157.43	Replace	0	0.00	Not Giv	* X SVC
One Time Key In	Main			FENDER RR/LH	1	766.80	766.80	25.00	575.10	Replace	0	0.00	Not Giv	* X SVC
One Time Key In	Main			STICKER DECAL SMRT	1	7.80	7.80	25.00	5.85	Replace	0	0.00	Not Giv	* X SVC
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	0	0.00	Not Giv	* X SVC
One Time Key In	Main			QUARTER GLASS RR/LH	1	168.10	168.10	25.00	126.07	Replace	0	0.00	Not Giv	* X SVC
One Time Key In	Main			SEALANT W/SCREEN	1	37.00	37.00	0.00	37.00	Replace	0	0.00	Not Giv	* X SVC
One Time Key In	Main			TAIL LAMP LH	1	548.40	548.40	10.00	493.56	Replace	1	493.5	Replace	* / CR4
One Time Key In	Main			TAIL LAMP BRACKET, LH	1	30.70	30.70	25.00	23.02	Replace	0	0.00	Check	* X SVC
One Time Key In	Main			TROUGH, BACK DOOR LH	1	110.90	110.90	10.00	99.81	Replace	0	0.00	Check	* X SVC
One Time Key In	Main			FLOOR PANEL RR/LH	1	102.00	102.00	25.00	76.50	Replace	0	0.00	Not Giv	* X SVC
One Time Key In	Main			DUCT ASSY, QUARTER	1	70.40	70.40	25.00	52.80	Replace	0	0.00	Check	* X SVC
Standard	Main		6505517	BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	1	361.5	Replace	* / CR4
Standard	Main		6505518	BUMPER ENERGY ABSORBER FRT	1	78.80	78.80	25.00	59.10	Replace	0	0	Check	* X SVC
Standard	Main		6505539	BUMPER REINFORCEMENT FRT	1	498.40	498.40	25.00	373.80	Replace	0	0	Check	* X SVC
Standard	Main		6505544	ARM SUB-ASSY, FR BUMPER LH	1	250.40	250.40	25.00	187.80	Replace	0	0	Not Giv	* X SVC
Standard	Main		6505543	ARM SUB-ASSY,FR BUMPER RH	1	250.40	250.40	25.00	187.80	Replace	0	0	Not Giv	* X SVC

3404.70

Total Spare Part Cost	19,877.16	Surveyor Total	6,150.20
Lump Sum Discount (%)	20.00	Lump Sum Dis (%)	20
Final Spare Part Cost	15,901.73	Final Sur Total	4,920.16

SMRT Recommendation

Surveyor Approval

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main		6505541	BUMPER GRILLE SUB-ASSY,LOWER	1	311.10	311.10	25.00	233.33	Replace	0	0	Check	* X SVC
Standard	Main		6505616	BUMPER LIP FRT	1	139.60	139.60	25.00	104.70	Replace	0	0	Check	* X SVC
Standard	Main		6505540	BUMPER FRT ABSORBER LOWER	1	127.70	127.70	25.00	95.78	Replace	0	0	Check	* X SVC
Standard	Main		6505555	HOOD PANEL	1	748.10	748.10	25.00	561.08	Replace	0	0	Not Giv	* X SVC
Standard	Main		6505571	HOOD LOCK	1	128.90	128.90	25.00	96.68	Replace	0	0	Not Giv	* X SVC
Standard	Main		6505548	BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.9	Replace	* / bh
Standard	Main		6505547	BUMPER REINFORCEMENT REAR	1	205.70	205.70	25.00	154.27	Replace	0	0	Check	* X SVC
Standard	Main		6505546	ARM SUB-ASSY, RR BUMPER LH	1	139.60	139.60	25.00	104.70	Replace	0	0	Check	* X SVC
Standard	Main		6505545	ARM SUB-ASSY, RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	0	0	Check	* X SVC
Standard	Main		6505551	BUMPER SEAL, RR RH	1	65.70	65.70	25.00	49.28	Replace	1	49.28	Replace	* / Nec
Standard	Main		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	1	71.10	Replace	* / BR
Standard	Main		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	94.80	25.00	71.10	Replace	1	71.10	Replace	* / BR
Standard	Main		6505617	BUMPER LIP COVER RR/LH	1	72.20	72.20	25.00	54.15	Replace	0	0	Not Giv	* X SVC
Standard	Main		6505618	BUMPER LIP COVER RR/RH	1	118.10	118.10	25.00	88.57	Replace	0	0	Not Giv	* X SVC
Standard	Main		6505619	BUMPER LIP REAR	1	228.90	228.90	25.00	171.68	Replace	1	171.6	Replace	* / BR
Standard	Main		6505522	END PANEL	1	602.10	602.10	25.00	451.58	Replace	1	451.5	Replace	* / BR
Standard	Main		6505636	TAILGATE ASY	1	1,007.90	1,007.90	25.00	755.92	Replace	1	755.9	Replace	* / BR
Standard	Main		6505497	TAILGATE DOOR HINGE LH/RH	2	58.30	116.60	25.00	87.45	Replace	0	0	Not Giv	* X SVC
Standard	Main		6505906	TAILGATE DOOR LOCK	1	444.10	444.10	25.00	333.08	Replace	1	333.0	Replace	* / Jund
Standard	Main		6505937	TAILGATE DOOR WEATHER STRIP	1	353.40	353.40	25.00	265.05	Replace	1	265.0	Replace	* / NEC
Standard	Main		6505623	TAILGATE OUTSIDE GARNISH	1	504.90	504.90	25.00	378.67	Replace	1	378.6	Replace	* / BR
Standard	Main		6505639	EMBLEM REAR	1	60.30	60.30	25.00	45.22	Replace	1	45.22	Replace	* / NEC
Standard	Main		6505640	NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace	* / NEC
Standard	Main		6505642	NAME PLATE (PRIUS)	1	60.80	60.80	25.00	45.60	Replace	1	45.60	Replace	* / NEC
Standard	Main		6505643	NAME PLATE (TOYOTA)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace	* / NEC

Total Spare Part Cost 19,877.16

Surveyor Total 6,150.20

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 15,901.73

Final Sur Total 4,920.16

6773.70

SMRT Recommendation

Surveyor Approval

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks	
Standard	Main		6505464	3RD BRAKE LAMP	1	231.30	231.30	10.00	209.17	Replace	0	0	Not Give	X SVC	
Standard	Main		6505620	SPOILER REAR	1	953.70	953.70	25.00	715.28	Replace	0	0	Not Give	X SVC	
Standard	Main		6505526	QUARTER GLASS RRRH	1	846.50	846.50	25.00	634.88	Replace	0	0	Not Give	X SVC	
Standard	Main		6505462	TAIL LAMP RH	1	557.80	557.80	10.00	502.02	Replace	1	502.0	Replace	CRA	
Total Spare Part Cost									19,877.16	Surveyor Total		6,190.20			
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20			
Final Spare Part Cost									15,901.73	Final Sur Total		4,920.16			

2489.30

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT PORTION	338.00	200	/
2	Main	TO REPAIR REAR PORTION	1,690.00	800	/
Total:			2,028.00 2498	1,000.00 1270	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	300	/
2	Main	TO RESPRAY FRONT BUMPER LOWER GRILLE	180.00	0	
3	Main	TO REPSRAY FRONT HOOD	378.00	0	
4	Main	TO RESPRAY FRONT SUPPORT PANEL	180.00	0	
5	Main	TO RESPRAY REAR BUMPER	378.00	300	/
6	Main	TO RESPRAY BUMPER BEAM	180.00	0	
7	Main	TO RESPRAY REAR PANEL	180.00	60	/
8	Main	TO RESPRAY REAR SPARE TYRE PANEL	180.00	0	
9	Main	TO RESPRAY REAR MEMBER,LH	180.00	0	
10	Main	TO RESPRAY REAR MEMBER,RH	180.00	0	
Total:			4,806.00 5746	720.00 1040	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
11	Main	TO RESPRAY TAIL GATE	378.00	200	/
12	Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	80	/
13	Main	TO RESPRAY REAR SPOILER	180.00	0	
14	Main	TO RESPRAY REAR FENDER LH	378.00	0	
15	Main	TO RESPRAY REAR FENDER RH	378.00	0	
16	Main	TO RESPRAY TROUGH BACK DOOR LH	180.00	0	
17	Main	TO RESPRAY TROUGH BACK DOOR RH	180.00	0	
18	Main	TO RESPRAY REAR FLOOR SIDE PANEL LH	180.00	0	
19	Main	TO RESPRAY REAR FLOOR SIDE PANEL RH	180.00	0	
Total:			4,608.00	720.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TOWING CHARGE	55.00	0	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	/
3	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	20	/
4	Main	TO TRANSFER REAR TAILGATE MECHANISM	120.00	20	/
5	Main	TO REMOVE AND REFIX REAR WINDSCREEN	240.00	120	/
6	Main	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	725.00	125	/
7	Main	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	20	/
8	Main	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0	
9	Main	TO ALIGN CHASSIS	350.00	0	
10	Main	TO REPLACE SUNDRY PARTS	100.00	20	/
11	Main	TO WASH AND VACUUM	60.00	0	
Total:			2,091.00	345.00	

37244 010

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	15,901.73	4,920.16
Total Labour Cost	2,028.00	1,006.00
Total Spray Painting	4,608.00	720.00
Other	2,091.00	345.00
Overall Total	24,628.73	6,995.16
Lump Sum Repair Option	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Lump Sum Total	24,650.00	7,000.00
Surveyor Approved Amount		7,000.00
No of Repair Days*	14	10
Remarks		Lump sum Repair, Take after spray photo.
Surveyor Name		Sun Pin (LKK)
Signature		
Survey Date	08/11/2019	<input type="button" value="Save"/> <input type="button" value="Clear"/>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REQUEST FOR SUPPLYMENT PARTS

Contractor:		WEGA ENGINEERING PTE LTD		
Accident Case Number	7AX / 11 / 19 / 2019	Date of Collection	11 / 11 / 19	
Vehicle No	SHB 1246X	Date of Request	13 / 11 / 19	
Vehicle Model	TOYOTA PRIUS	Number of Days to Extend (If any)		
S/N	Part Number	Part Description	Quantity	Unit Price
	5571, 727, 74, 75 3576	To Repair Fender RR LH	/	\$ 200.00
		To Respray Spare Tyre Panel	/	\$ 180.00
		To Respray Member Sub Assy RR RH	/	\$ 180.00
		To Respray Fender RR LH	/	\$ 378.00
		Sticker Decal SMART	- Nec	\$ 7.50
		Sticker Decal 6555 8888	- Nec	\$ 21.60
		Sticker Petrol only	+ sup	\$ 7.50
		Pixel sticker	+ RPT	\$ 60.00


150 /
60 /
60 /
200 /
-
-
-
-

<<<Please submit photographs for damaged parts>>>

I, (Name) CHIA

(Position) _____

Do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

..... 

Signature of person making this declaration
[To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission

REQUEST FOR SUPPLYMENT PARTS

Contractor:		WEGA ENGINEERING PTE LTD	
Accident Case Number	7AX / 11 / 19 / 2019	Date of Collection	11 / 11 / 19
Vehicle No	SHB 1246 X	Date of Request	13 / 11 / 19
Vehicle Model	TOYOTA PRIUS	Number of Days to Extend (If any)	3 DAYS - 1 days

S/N	Part Number	Part Description	Quantity	Unit Price
	3555,56,57	Bracket Frt Bumper	✓ CRA	\$ 110.40
	3565,66,67	Panel Assy Deck LH	✓ CR4	\$ 379.20
	3568,69,70	Panel Assy Deck RH	✓ CR4	\$ 307.00
	3560,61,62,63,64	Bumper Grille Sub Assy Lower	✓ CRU	\$ 311.10
	3558,59	Bumper Lip Pnt	✓ CRU	\$ 139.60
	3577,78,79	Tail Lamp LH	X RPT	\$ 557.80
	3560,81,82,83	To Repair Spare Type Panel	✓	\$ 150.00
	3584,85,86	To Repair Member Sub Assy RR RH	✓	\$ 120.00

<<<Please submit photographs for damaged parts>>>

I, (Name) CHIA
 (Position) _____

Do solemnly and sincerely declare that - Supplementary Parts are raised for replacement for the aforesaid vehicle.


 Signature of person making this declaration
 [To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff	
Acknowledge By	ARC Executive / Supervisor / SA
Approval By	Surveyor / In-house Staff
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC
Photo Submitted	YES / NO
	Form22 / PO / WOC / Reservation / Number
	Date of submission

Section A - Accident Details	
Registration Number	SHB1246X
Case Reference Number	TAX/11/19/2019
Registration Date	6/4/2016
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	IDRIS BIN SUKI
Type of Accident	Head to Rear
Accident Date and Time	7/11/2019 7:45 AM
Accident Reported Date and Time	7/11/2019 10:09 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	7/11/2019 8:38 AM
Replacement Vehicle issued?	No
Job Card Number	24104213
Special Instruction to ARC, if any	TOWED \$40
Prepared Date and Time	8/11/2019 6:53 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,498.00	\$1,270.00
Total Spray Cost	\$5,346.00	\$1,040.00
Total Spare Part Cost	\$17,079.40	\$7,061.01
Total Other Cost	\$2,091.00	(\$1,621.01)
TOTAL COST	\$27,014.40	\$7,750.00 (LJS)
Lump Sum Total	\$27,000.00	\$0.00
Number of Repair Days	14.0	11.0
Prepared / Adjusted By	Tuck Foo Kok	Sun Pin (LKK) / NTUC
ARC / Surveyor Sign Off Date	18/11/2019 11:06 AM	15/11/2019 9:58 AM
Signature		
Remarks	Total number of repair days = 11 days. SUP = +1 day.	Lump sum Repair, Take after spray photo.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1912-0237	Invoice Number	
Quotation Date	18.12.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR SPARE TYRE PANEL	\$150.00	\$60.00 /
TO REPAIR REAR CHASSIS	\$120.00	\$60.00 /
TO REPAIR REAR FENDER LH	\$200.00	\$150.00 /
TO REPAIR FRONT PORTION	\$338.00	\$200.00 /
TO REPAIR REAR PORTION	\$1,690.00	\$800.00 /
Total Labour	\$2,498.00	\$1,270.00

Supp
Supp
Supp

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR SPARE TYRE PANEL	\$180.00	\$60.00 /
TO RESPRAY REAR MEMBER,RH	\$180.00	\$60.00 /
TO RESPRAY REAR FENDER LH	\$378.00	\$200.00 /
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00 /
TO RESPRAY FRONT BUMPER LOWER GRILLE	\$180.00	\$0.00
TO REPSRAY FRONT HOOD	\$378.00	\$0.00
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$0.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00 /
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$60.00 /
TO RESPRAY REAR SPARE TYRE PANEL	\$180.00	\$0.00
TO RESPRAY REAR MEMBER,LH	\$180.00	\$0.00
TO RESPRAY REAR MEMBER,RH	\$180.00	\$0.00
TO RESPRAY TAIL GATE	\$378.00	\$200.00 /
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$60.00 /
TO RESPRAY REAR SPOILER	\$180.00	\$0.00
TO RESPRAY REAR FENDER LH	\$378.00	\$0.00
TO RESPRAY REAR FENDER RH	\$378.00	\$0.00
TO RESPRAY TROUGH BACK DOOR LH	\$180.00	\$0.00
TO RESPRAY TROUGH BACK DOOR RH	\$180.00	\$0.00
TO RESPRAY REAR FLOOR SIDE PANEL LH	\$180.00	\$0.00
TO RESPRAY REAR FLOOR SIDE PANEL RH	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$5,346.00	\$1,040.00

Supp
Supp
Supp

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Lump Sum Adjustment by Surveyor	\$0.00	(\$1,956.01)
TOWING CHARGE	\$56.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00 /
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$20.00 /
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$20.00 /
TO REMOVE AND REFIX REAR WINDSCREEN	\$240.00	\$120.00 /
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$725.00	\$125.00 /
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	\$120.00	\$20.00 /
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	\$120.00	\$0.00
TO ALIGN CHASSIS	\$350.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00 /
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$2,091.00	(\$1,621.01)

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52114-47140	BRACKET, FR BUMPER	0.00	\$110.40	0.00	\$0.00	Replace	Not Given X
			NUMBER PLATE FRAME	1.00	\$15.00	0.00	\$15.00	Replace	Replace /
			NUMBER PLATE	1.00	\$12.00	0.00	\$12.00	Replace	Replace /
		52128-47903	COVER, FR BUMPER HOLE LH	1.00	\$18.50	25.00	\$13.88	Replace	Replace /
		52127-47903	COVER, FR BUMPER HOLE RH	0.00	\$18.50	0.00	\$0.00	Replace	Not Given X
		75310-47010	EMBLEM FRONT	1.00	\$86.50	25.00	\$64.88	Replace	Replace /
		53201-47902	SUPPORT SUB-ASSY	0.00	\$1,460.40	0.00	\$0.00	Replace	Not Given X
		52181-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace /
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace /
		89997-30070	ANTENNA, ELECTRICAL LOWER REAR	1.00	\$157.40	10.00	\$141.66	Replace	Replace /
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace /
		52592-47021	BUMPER SEAL, RR LH	1.00	\$66.90	25.00	\$50.18	Replace	Replace /
		58308-47011	UNDER COVER CENTER REAR	0.00	\$514.50	0.00	\$0.00	Replace	Check X
		64718-47031B0	END PANEL COVER, DECK TRIM HOLE	1.00	\$46.10	25.00	\$34.58	Replace	Replace /
		64718-47031B0	END PANEL COVER, DECK TRIM, RR	1.00	\$121.10	25.00	\$90.83	Replace	Replace /
			SEALANT SIKAFLEX	1.00	\$37.00	0.00	\$37.00	Replace	Replace /
		64993-47020	BOX, DECK FLOOR, RR	0.00	\$649.70	0.00	\$0.00	Replace	Check X
		58416-47030B3	BOX RR FLOOR, BOARD	0.00	\$679.60	0.00	\$0.00	Replace	Check X
		58415-47030	BOARD, RR FLOOR	0.00	\$392.30	0.00	\$0.00	Replace	Check X
		58418-47070B0	BOX, DECK FLOOR, COVER LH	0.00	\$230.10	0.00	\$0.00	Replace	Check X
		64997-47020	BOX, DECK FLOOR, LH	0.00	\$196.80	0.00	\$0.00	Replace	Check X
		58427-47040	SPACER, RR FLOOR	0.00	\$130.60	0.00	\$0.00	Replace	Check X
		58490-47140B0	BOARD ASSY, RR RH	0.00	\$379.20	0.00	\$0.00	Replace	Check X



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
85 Woodlands Industrial Park EA, Singapore 737708
FAX Number: 63665552
Estimate Telephone Number: 68623221
Accident Reporting Number: 8862672

Date Generated: 18/12/2018

User ID: PehJian

64740-47031B2	PANEL ASSY, DECK LH	0.00	\$307.00	0.00	\$0.00	Replace	Check	X
64730-47031B2	PANEL ASSY, DECK RH	0.00	\$307.00	0.00	\$0.00	Replace	Check	X
58311-47071	SPARE TYRE PANEL	0.00	\$667.70	0.00	\$0.00	Replace	Check	X
64777-47090	CUSHION, SPARE WHEEL	0.00	\$230.80	0.00	\$0.00	Replace	Check	X
51931-47020	CARRIER, SPARE	0.00	\$19.70	0.00	\$0.00	Replace	Check	X
64778-47050	PROTECTOR, SPARE	0.00	\$143.70	0.00	\$0.00	Replace	Check	X
57604-47030	MEMBER SUB-ASSY, RR LH	0.00	\$174.10	0.00	\$0.00	Replace	Check	X
57603-47030	MEMBER SUB-ASSY, RR RH	0.00	\$174.10	0.00	\$0.00	Replace	Check	X
58336-12090	REINFORCEMENT, RR	0.00	\$34.60	0.00	\$0.00	Replace	Check	X
	BATTERY	0.00	\$278.00	0.00	\$0.00	Replace	Check	X
75573-47080	TAILGATE DOOR GLASS MOULDING, RH	1.00	\$29.40	25.00	\$22.05	Replace	Replace	X
75574-47020	TAILGATE DOOR GLASS MOULDING, LH	1.00	\$29.40	25.00	\$22.05	Replace	Replace	X
75575-47030	MOULDING BACK WINDOW, LOWER NO.1	1.00	\$29.40	25.00	\$22.05	Replace	Replace	X
64821-47030	TAILGATE LOWER WINDOW GLASS	1.00	\$721.30	25.00	\$540.98	Replace	Replace	X
	SEALANT W/SCREEN	3.00	\$37.00	0.00	\$111.00	Replace	Replace	X
82184-47370	WIRE, BACK DOOR, NO.1	0.00	\$582.40	0.00	\$0.00	Replace	Not Given	X
68960-0W532	TAILGATE DOOR STAY LH	0.00	\$241.50	0.00	\$0.00	Replace	Not Given	X
68960-0W542	TAILGATE DOOR STAY RH	0.00	\$241.50	0.00	\$0.00	Replace	Not Given	X
69415-47020	TAILGATE LOCK, COVER	1.00	\$15.70	25.00	\$11.78	Replace	Replace	X
69431-47010	STRIKER, BACK DOOR	0.00	\$48.90	0.00	\$0.00	Replace	Check	X
67750-47071C9	TAILGATE, BAORD ASSY	1.00	\$246.90	25.00	\$185.18	Replace	Replace	X
81271-53011	LICENSE PLATE LAMP	0.00	\$35.70	0.00	\$0.00	Replace	Not Given	X
86790-47040	CAMERA ASSY, TELEVISION, RR	0.00	\$1,436.60	0.00	\$0.00	Replace	Not Given	X
	NUMBER PLATE	0.00	\$15.00	0.00	\$0.00	Replace	Not Given	X
	NUMBER PLATE FRAME	0.00	\$12.00	0.00	\$0.00	Replace	Not Given	X
	STICKER DECAL SMRT	1.00	\$7.80	0.00	\$7.80	Replace	Replace	X
	STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	X
61604-47090	FENDER RR/RH	0.00	\$766.80	0.00	\$0.00	Replace	Not Given	X
	STICKER DECAL SMRT	0.00	\$7.80	0.00	\$0.00	Replace	Not Given	X
	STICKER DECAL 6555 8888	0.00	\$21.60	0.00	\$0.00	Replace	Not Given	X
	SEALANT W/SCREEN	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X
61621-47030	TROUGH, BACK DOOR	0.00	\$110.90	0.00	\$0.00	Replace	Not Given	X
52562-47010	TAIL LAMP BRACKET, RH	0.00	\$30.70	0.00	\$0.00	Replace	Check	X
62940-16060	DUCT ASSY, QUARTER	0.00	\$70.40	0.00	\$0.00	Replace	Check	X
58302-47030	FLOOR PANEL RR/RH	0.00	\$209.90	0.00	\$0.00	Replace	Not Given	X
61602-47091	FENDER RR/LH	0.00	\$766.80	0.00	\$0.00	Replace	Not Given	X
	STICKER DECAL SMRT	0.00	\$7.80	0.00	\$0.00	Replace	Not Given	X
	STICKER DECAL 6555 8888	0.00	\$21.60	0.00	\$0.00	Replace	Not Given	X
62720-47031	QUARTER GLASS RR/LH	0.00	\$168.10	0.00	\$0.00	Replace	Not Given	X
	SEALANT W/SCREEN	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X
81561-47170	TAIL LAMP LH	1.00	\$548.40	10.00	\$493.56	Replace	Replace	X

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
 85 Woodlands Industrial Park East, Singapore 737708
 FAX Number: 63995662
 Estimate Telephone Number: 6882223
 Account Number: 6882872

Date Generated: 16/12/2018

User ID: PubliScan

	52583-47010	TAIL LAMP BRACKET, LH	0.00	\$30.70	0.00	\$0.00	Replace	Check	X
	81622-47030	TROUGH, BACK DOOR LH	0.00	\$110.90	0.00	\$0.00	Replace	Check	X
	58303-47301	FLOOR PANEL RR/LH	0.00	\$102.00	0.00	\$0.00	Replace	Not Given	X
	82940-16080	DUCT ASSY, QUARTER	0.00	\$70.40	0.00	\$0.00	Replace	Check	X
	52119-47930	BUMPER FRT	1.00	\$482.00	25.00	\$361.50	Replace	Replace	✓
	52611-47080	BUMPER ENERGY ABSORBER FRT	0.00	\$78.80	0.00	\$0.00	Replace	Check	X
	52021-47023	BUMPER REINFORCEMENT FRT	0.00	\$498.40	0.00	\$0.00	Replace	Check	X
	57014-47030	ARM SUB-ASSY, FR BUMPER LH	0.00	\$250.40	0.00	\$0.00	Replace	Not Given	✓
	57013-47030	ARM SUB-ASSY, FR BUMPER RH	0.00	\$250.40	0.00	\$0.00	Replace	Not Given	✓
	53102-47020	BUMPER GRILLE SUB-ASSY, LOWER	0.00	\$311.10	0.00	\$0.00	Replace	Check	X
	76851-47020	BUMPER LIP FRT	0.00	\$139.80	0.00	\$0.00	Replace	Check	X
	52618-47050	BUMPER FRT ABSORBER LOWER	0.00	\$127.70	0.00	\$0.00	Replace	Check	X
	53301-47080	HOOD PANEL	0.00	\$748.10	0.00	\$0.00	Replace	Not Given	X
	53510-47102	HOOD LOCK	0.00	\$128.90	0.00	\$0.00	Replace	Not Given	✓
	52159-47905	BUMPER REAR	1.00	\$458.80	25.00	\$343.95	Replace	Replace	✓
	52023-12240	BUMPER REINFORCEMENT REAR	0.00	\$205.70	0.00	\$0.00	Replace	Check	X
	52018-47030	ARM SUB-ASSY, RR BUMPER LH	0.00	\$139.80	0.00	\$0.00	Replace	Check	X
	52015-47050	ARM SUB-ASSY, RR BUMPER RH	0.00	\$139.80	0.00	\$0.00	Replace	Check	X
	52581-47021	BUMPER SEAL, RR RH	1.00	\$65.70	25.00	\$49.28	Replace	Replace	✓
	52575-47020	BUMPER SIDE RETAINER RR/RH	1.00	\$94.80	25.00	\$71.10	Replace	Replace	✓
	52576-47020	BUMPER SIDE RETAINER RR/LH	1.00	\$94.80	25.00	\$71.10	Replace	Replace	✓
	76088-47020	BUMPER LIP COVER RR/LH	0.00	\$72.20	0.00	\$0.00	Replace	Not Given	X
	76087-47020	BUMPER LIP COVER RR/RH	0.00	\$118.10	0.00	\$0.00	Replace	Not Given	X
	78891-47020	BUMPER LIP REAR	1.00	\$228.90	25.00	\$171.88	Replace	Replace	✓
	58307-47060	END PANEL	1.00	\$802.10	25.00	\$451.58	Replace	Replace	✓
	67005-47241	TAILGATE ASY	1.00	\$1,007.90	25.00	\$755.93	Replace	Replace	✓
	68810-47010	TAILGATE DOOR HINGE LH/RH	0.00	\$58.30	0.00	\$0.00	Replace	Not Given	X
	69350-47030	TAILGATE DOOR LOCK	1.00	\$444.10	25.00	\$333.08	Replace	Replace	✓
	67881-47022	TAILGATE DOOR WEATHER STRIP	1.00	\$353.40	25.00	\$265.05	Replace	Replace	✓
	76801-47070-B0	TAILGATE OUTSIDE GARNISH	1.00	\$504.90	25.00	\$378.68	Replace	Replace	✓
	75310-47020	EMBLEM REAR	1.00	\$60.30	25.00	\$45.23	Replace	Replace	✓
	75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace	✓
	75442-47030	NAME PLATE (PRIUS)	1.00	\$60.80	25.00	\$45.60	Replace	Replace	✓
	75443-47030	NAME PLATE (TOYOTA)	1.00	\$51.90	25.00	\$38.93	Replace	Replace	✓
	81006-47011	3RD BRAKE LAMP	0.00	\$231.30	0.00	\$0.00	Replace	Not Given	X
	76086-47910	SPOILER REAR	0.00	\$953.70	0.00	\$0.00	Replace	Not Given	✓
	62710-47130	QUARTER GLASS RR/RH	0.00	\$846.50	0.00	\$0.00	Replace	Not Given	X
	81551-47180	TAIL LAMP RH	1.00	\$557.80	10.00	\$502.02	Replace	Replace	✓
Total				\$25,212.11		\$6,180.28			

Added Spare Parts / Material Usage After Surveyor Signed off										
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	
		52114-47140	BRACKET, FR BUMPER	1.00	\$110.40	25.00	\$82.80	Replace	Replace	/ CRA
			PIXEL STICKER	0.00	\$60.00	0.00	\$0.00	Replace	Not Given	X X RPT
		84740-47031B2	PANEL ASSY, DECK LH	1.00	\$307.00	25.00	\$230.25	Replace	Replace	/ CRU -
		84730-47031B2	PANEL ASSY, DECK RH	1.00	\$307.00	25.00	\$230.25	Replace	Replace	/ CRU -
			STICKER PETROL ONLY	0.00	\$7.80	0.00	\$0.00	Replace	Not Given	X X Svc
			STICKER DECAL SMRT	1.00	\$7.80	0.00	\$7.80	Replace	Replace	/ NR -
			STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	/ NR -
		81561-47170	TAIL LAMP LH	0.00	\$548.40	0.00	\$0.00	Replace	Not Given	X X RPT
		83102-47020	BUMPER GRILLE SUB-ASSY, LOWER	1.00	\$311.10	25.00	\$233.33	Replace	Replace	/ CRU -
		76651-47020	BUMPER LIP FRT	1.00	\$139.80	25.00	\$104.70	Replace	Replace	/ CRU -
Total					1,820.70		910.73			

7061.01
 + 1270.00
 + 1385.00

 9716.01
 - 202

 7772.81
 L/S \$7750/-

11 days

327101.81

32744.90



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19020008/Qqf3e2	
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556	Date: 10-01-2020
Code: INC4	
1. Policy Particulars :- THIRD PARTY CLAIM	
Insured Veh. SJZ 4609M	Veh. Inspected SHB 1246X
Policy No. 5108727014	Coverage (\$) 0.00
Claim No. MT/1070321-003	Excess (\$) 0.00
Assign From	Assign Date 08/11/2019
2. Vehicle Particulars & Condition	
Make & Model TOYOTA PRIUS	c.c 1798
Engine No. HIDDEN	Year of Reg. 2016
Chassis No. JTDKN36U105767865	Colour MAROON
Odometer 602399	Steering IN ORDER
Brakes IN ORDER	Modification SPORTS RIM
General FAIR	
3. Conditions of Tyres	
	Size Make Balance
R/H Front Tyre	195/65 R15 FIRENZA 5 mm
L/H Front Tyre	195/65 R15 FIRENZA 5 mm
R/H Rear Tyre	195/65 R15 FIRENZA 5 mm
L/H Rear Tyre	195/65 R15 FIRENZA 5 mm
4. Description of Damages	
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.	
5. General Information	
Accident Date 07/11/2019	Inspection Date 08/11/2019
Survey held at SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705	
5a. Remarks	
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.	
5b. Estimate Days of Repair	
ESTIMATED NORMAL PERIOD FOR REPAIR:	11 Working Days



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 1246X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	COVER, FR BUMPER HOLE LH (DISC 25%)	SCRATCHED	18.50	13.88
1	EMBLEM FRONT (DISC 25%)	NECESSARY	86.50	64.88
10	BUMPER CLIPS @\$1.61 (DISC 25%)	NECESSARY	16.10	12.08
1	BUMPER SEAL, RR LH (DISC 25%)	NECESSARY	88.90	66.68
1	END PANEL COVER, DECK TRIM HOLE (DISC 25%)	MISSING	46.10	34.58
1	END PANEL COVER, DECK TRIM, RR (DISC 25%)	BROKEN	121.10	90.83
1	TAILGATE DOOR GLASS MOULDING, RH (DISC 25%)	NECESSARY	29.40	22.05
1	TAILGATE DOOR GLASS MOULDING, LH (DISC 25%)	NECESSARY	29.40	22.05
1	MOULDING BACK WINDOW, LOWER NO.1 (DISC 25%)	NECESSARY	29.40	22.05
1	TAILGATE LOWER WINDOW GLASS (DISC 25%)	CRUSHED	721.30	540.98
1	TAILGATE LOCK, COVER (DISC 25%)	NECESSARY	15.70	11.78
1	TAILGATE, BOARD ASSY (DISC 25%)	DENTED	246.90	185.18
1	BUMPER FRT (DISC 25%)	CRUSHED	482.00	361.50
1	BUMPER REAR (DISC 25%)	DENTED	458.60	343.95
1	BUMPER SEAL, RR RH (DISC 25%)	NECESSARY	65.70	49.28
1	BUMPER SIDE RETAINER RR/RH (DISC 25%)	BROKEN	94.80	71.10
1	BUMPER SIDE RETAINER RR/LH (DISC 25%)	BROKEN	94.80	71.10
1	BUMPER LIP REAR (DISC 25%)	CRUSHED	228.90	171.68
1	END PANEL (DISC 25%)	DENTED	602.10	451.58
1	TAILGATE ASY (DISC 25%)	DENTED	1,007.90	755.93
1	TAILGATE DOOR LOCK (DISC 25%)	JAMMED	444.10	333.08
1	TAILGATE DOOR WEATHER STRIP (DISC 25%)	NECESSARY	353.40	265.05
1	TAILGATE OUTSIDE GARNISH (DISC 25%)	BROKEN	504.90	378.68
1	EMBLEM REAR (DISC 25%)	NECESSARY	60.30	45.23
1	NAME PLATE (HYBRID) (DISC 25%)	NECESSARY	51.90	38.93
1	NAME PLATE (PRIUS) (DISC 25%)	NECESSARY	60.80	45.60
1	NAME PLATE (TOYOTA) (DISC 25%)	NECESSARY	51.90	38.93
1	BRACKET, FR BUMPER (DISC 25%)	CRACKED	110.40	82.80
1	PANEL ASSY, DECK LH (DISC 25%)	CRUSHED	307.00	230.25
1	PANEL ASSY, DECK RH (DISC 25%)	CRUSHED	307.00	230.25

Report Ref No. NS/INC19020008/Qqf3e2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No. 2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BUMPER GRILLE SUB-ASSY, LOWER (DISC 25%)	CRUSHED	311.10	233.33
1	BUMPER LIP FRT (DISC 25%)	CRUSHED	139.60	104.70
1	ANTENNA, ELECTRICAL LOWER REAR (DISC 10%)	BROKEN	157.40	141.66
1	TAIL LAMP LH (DISC 10%)	CRUSHED	548.40	493.56
1	TAIL LAMP RH (DISC 10%)	CRACKED	557.80	502.02
1	NUMBER PLATE FRAME (SN)	BENT	15.00	15.00
1	NUMBER PLATE (SN)	BENT	12.00	12.00
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	SENSOR REVERSE (SN)	SHORTED	180.00	180.00
1	SEALANT SIKAFLEX (SN)	NECESSARY	37.00	37.00
3	SEALANT W/SCREEN @\$37.00 (SN)	NECESSARY	111.00	111.00
1	STICKER DECAL SMRT (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 65555 8888 (SN)	NECESSARY	21.60	21.60
1	STICKER DECAL SMRT (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
1	BRACKET, FR BUMPER	SERVICEABLE	110.40	-
1	COVER, FR BUMPER HOLE RH	SERVICEABLE	18.50	-
1	SUPPORT SUB-ASSY	SERVICEABLE	1,460.40	-
1	UNDER COVER CENTER REAR	SERVICEABLE	514.50	-
1	BOX, DECK FLOOR, RR	SERVICEABLE	649.70	-
1	BOX RR FLOOR, BOARD	SERVICEABLE	679.60	-
1	BOARD, RR FLOOR	SERVICEABLE	392.30	-
1	BOX, DECK FLOOR, COVER LH	SERVICEABLE	230.10	-
1	BOX, DECK FLOOR, LH	SERVICEABLE	196.80	-
1	SPACER, RR FLOOR	SERVICEABLE	130.60	-
1	BOARD ASSY, RR RH	SERVICEABLE	379.20	-
1	PANEL ASSY, DECK LH	SERVICEABLE	307.00	-
1	PANEL ASSY, DECK RH	SERVICEABLE	307.00	-
1	SPARE TYRE PANEL	SERVICEABLE	667.70	-
1	CUSHION, SPARE WHEEL	SERVICEABLE	230.80	-
1	CARRIER, SPARE	SERVICEABLE	19.70	-
1	PROTECTOR, SPARE	SERVICEABLE	143.70	-
1	MEMBER SUB-ASSY, RR LH	SERVICEABLE	174.10	-

Report Ref No. NS/INC19020008/Qqf3e2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	MEMBER SUB-ASSY, RR RH	SERVICEABLE	174.10	-
2	REINFORCEMENT, RR @\$34.60	SERVICEABLE	69.20	-
1	BATTERY	SERVICEABLE	278.00	-
1	WIRE, BACK DOOR, NO.1	SERVICEABLE	582.40	-
1	TAILGATE DOOR STAY LH	SERVICEABLE	241.50	-
1	TAILGATE DOOR STAY RH	SERVICEABLE	241.50	-
1	STRIKER, BACK DOOR	SERVICEABLE	48.90	-
2	LICENSE PLATE LAMP @\$35.70	SERVICEABLE	71.40	-
1	CAMERA ASSY, TELEVISION, RR	SERVICEABLE	1,436.60	-
1	NUMBER PLATE	SERVICEABLE	15.00	-
1	NUMBER PLATE FRAME	SERVICEABLE	12.00	-
1	FENDER RR/RH	SERVICEABLE	766.80	-
1	STICKER DECAL SMRT	SERVICEABLE	7.80	-
1	STICKER DECAL 6555 8888	SERVICEABLE	21.60	-
1	SEALANT W/SCREEN	SERVICEABLE	37.00	-
1	TROUGH, BACK DOOR	SERVICEABLE	110.90	-
1	TAIL LAMP BRACKET, RH	SERVICEABLE	30.70	-
1	DUCT ASSY, QUARTER	SERVICEABLE	70.40	-
1	FLOOR PANEL RR/RH	SERVICEABLE	209.90	-
1	FENDER RR/LH	SERVICEABLE	766.80	-
1	STICKER DECAL SMRT	SERVICEABLE	7.80	-
1	STICKER DECAL 6555 8888	SERVICEABLE	21.60	-
1	QUARTER GLASS RR/LH	SERVICEABLE	168.10	-
1	SEALANT W/SCREEN	SERVICEABLE	37.00	-
1	TAIL LAMP BRACKET, LH	SERVICEABLE	30.70	-
1	TROUGH, BACK DOOR LH	SERVICEABLE	110.90	-
1	FLOOR PANEL RR/LH	SERVICEABLE	102.00	-
1	DUCT ASSY, QUARTER	SERVICEABLE	70.40	-
1	BUMPER ENERGY ABSORBER FRT	SERVICEABLE	78.80	-
1	BUMPER REINFORCEMENT FRT	SERVICEABLE	498.40	-
1	ARM SUB-ASSY, FR BUMPER LH	SERVICEABLE	250.40	-
1	ARM SUB-ASSY, FR BUMPER RH	SERVICEABLE	250.40	-
1	BUMPER GRILLE SUB-ASSY, LOWER	SERVICEABLE	311.10	-

Report Ref No. NS/INC19020008/Qqf3e2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BUMPER LIP FRT	SERVICEABLE	139.60	-
1	BUMPER FRT ABSORBER LOWER	SERVICEABLE	127.70	-
1	HOOD PANEL	SERVICEABLE	748.10	-
1	HOOD LOCK	SERVICEABLE	128.90	-
1	BUMPER REINFORCEMENT REAR	SERVICEABLE	205.70	-
1	ARM SUB-ASSY, RR BUMPER LH	SERVICEABLE	139.60	-
1	ARM SUB-ASSY, RR BUMPER RH	SERVICEABLE	139.60	-
1	BUMPER LIP COVER RR/LH	SERVICEABLE	72.20	-
1	BUMPER LIP COVER RR/RH	SERVICEABLE	118.10	-
2	TAILGATE DOOR HINGE LH / RH @\$58.30	SERVICEABLE	116.60	-
1	STICKER PETROL ONLY	SERVICEABLE	7.80	-
1	PIXEL STICKER	REPEATED	60.00	-
1	TAIL LAMP LH	REPEATED	548.40	-
1	3RD BRAKE LAMP	SERVICEABLE	231.30	-
1	SPOILER REAR	SERVICEABLE	953.70	-
1	QUARTER GLASS RR/RH	SERVICEABLE	846.50	-
			27,309.90	7,061.01
	LABOUR			
	PANEL BEATING & BODY WORK.		2,498.00	1,270.00
	SPRAY PAINT.		5,346.00	1,040.00
	TOWING CHARGE.		56.00	-
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	20.00
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.		120.00	20.00
	TO TRANSFER REAR TAILGATE MECHANISM.		120.00	20.00
	TO REMOVE AND REFIX REAR WINDSCREEN.		240.00	120.00
	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM.		725.00	125.00
	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.		120.00	20.00
	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE.	NOT NECESSARY	120.00	-
	TO ALIGN CHASSIS.	NOT NECESSARY	350.00	-
	TO REPLACE SUNDRY PARTS.		100.00	20.00

Report Ref No. NS/INC19020008/Qqf3e2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:5 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			9,935.00	2,655.00
GRAND TOTAL			37,244.90	9,716.01
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				7,750.00

Report Ref No. NS/INC19020008/Qqf3e2

OI SUN PIN

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.