

22/03/2012

ASS. REC. BY:

REF: CS/FC219020031 / Fsf3 02

Special Instruction:

Surveyor: Ram

ASSIGNMENT (Office)

From (Person): Sithara of FC1 Date/Time: 12.11.19 12.49 p.m.

Estimated Cost: Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHD 1435G Insured: SHB 36123

at Workshop m/s Premier Tel: 67148880

of 23 Changi South Ave 2 #01-02

Policy No: Claim No: D9007B6MPSH

Sum Insured: Excess:

Make of Veh: D.O.A. 10.11.19
(Client's Record)CA / REV / REP. / REV 24 HRS ^{up} H.O.D. Endorsement:

Date/Time: 12.11.19 1.15 p.m. Person Contacted: Hai Leong Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHB 36123 CS/FC219013423/KK1202 DCA: 11/07/2018
	SHD 1435G CC4/ASMVA005793/K2ph3 DCA: 3/03/2019
13/11/19 @ 14:01 pm	revised PA to Sithara via email.

Vol. No. SHD 1435G Yr. Expir. JUN 2017

The U/C / Chassis frame / Body Structure affected due to collision

part by part

[illegible]



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19007136MFSH

Date: 13 November 2019

Our Ref: CS/FCI19020031/Fsf3

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 1435G.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 12/11/2019 at the premises of M/s Premier Automotive Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ 4,250.30 .
Revised Estimate Amount	: S\$ 2,704.16 .
"Check" Items Amount	: S\$ - .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages
at the n/s front & front n/s portion.



Comments/ Present Status:

Damages Consistent.
Repair days: 3 days

Yours faithfully

Parasuram S/O Shanmugam
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	11-11-2019	Our Ref No. D19007136MFSH
Accident Date	10-11-2019	Claim Type. Third Party
Insured Vehicle	SHB3612J	Third Party Vehicle. SHD1435G
Survey Location	23 CHANGI SOUTH AVENUE 2 #01-02	
Contact Person.	LIEW HAI LEONG	
Contact No.	62148880/ 0	Fax No. 62141511
Survey Type	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PREMIER AUTOMOTIVE SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Wednesday, 13 November 2019 2:01 pm
To: 'Sithara'; 'CWS Motor Claims'
Cc: assignments; SUR; Admin-D (LKKAuto)
Subject: RE: SURVEY ASSESSMENT - D19007136MFSH/1
Attachments: PRELI ADVISE - SHD 1435G.pdf

Dear Sithara,

Enclosed preliminary revised of vehicle SHD 1435G.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Tuesday, 12 November 2019 1:33 pm
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19007136MFSH/1

Dear Sir/Madam,

Thank you for your assignment.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>
Sent: Tuesday, 12 November, 2019 12:49 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Sithara <Sithara@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19007136MFSH/1

Enquire Vehicle Registration Details

Owner Particulars

NRIC/Passport/Company Cert No.: 200304975H
 Owner ID Type: Company
 Owner Name: PREMIER TAXIS PTE. LTD.
 Registered Address: 23 CHANGI SOUTH AVENUE 2 #04-03 SINGAPORE 486443
 Mailing Address: -
 Birth Date: -

Vehicle Particulars

Vehicle No.: SHD1435G
 Previous Vehicle No.: -
 Effective Date of Ownership: 29 Jun 2017
 Original Regn Date: 29 Jun 2017
 Registration Date: 29 Jun 2017
 Year of Manufacture: 2016
 Vehicle Type: Public Transport Taxi (Motor Car)
 Vehicle Scheme: Taxi (Company)
 Vehicle Attachment 1: Air-Con (Taxi)
 Vehicle Attachment 2: -
 Vehicle Attachment 3: -
 Vehicle Make: HYUNDAI
 Vehicle Model: I30 GDH 1.6 TCI 5DR DCT
 Primary Colour: Silver
 Secondary Colour: -
 Passenger Capacity: 4
 Chassis No.: TMAD281UVHJ128018
 Engine No.: D4FBGZ122863
 Engine Capacity/Power Rating: 1582 cc / -
 Maximum Power Output: 100.0 kW (134 bhp)
 Propellant: Diesel
 Max Unladen Weight: 1496 kg
 Maximum Laden Weight: 1940 kg
 Open Market Value: \$20,545.00
 PARF Eligibility: Yes
 PARF Eligibility Expiry Date: 28 Jun 2025
 Minimum PARF Benefit: \$7,957.00
 No. of Transfers: 0
 IU Label No.: 1050706242
 COE No.: 2017062901003977G
 COE Expiry Date: 28 Jun 2025
 COE Category: A - Car up to 1600cc & 97kW (130bhp)
 COE Registration Category: A - Car up to 1600cc & 97kW (130bhp)
 Quota Premium (QP) / Prevailing Quota Premium: - / \$50,625.00
 PQP Paid: \$40,500.00
 QP (Regn Cat): -
 OPC Cash Rebate Eligibility: No

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

12-Nov-19

ESTIMATE REPAIR BILL FOR HYUNDAI I30 (A) REGN NO: SHD 1435 G

1 pc	Front bumper <i>crq</i>	\$	811.11	
1 pc	Front n/s fender <i>x</i> <i>(R)</i>	\$	514.02	
2 pcs	Front bumper n/s & o/s side bracket @ \$32.51 <i>rec</i>	\$	65.02	
1 pc	Front n/s fender inner shield <i>xun</i>	\$	181.94	
1 pc	Front n/s fog lamp cover <i>xun</i>	\$	25.00	
1 pc	Front n/s fender inner shield <i>xun</i>	\$	176.72	
1 pc	Front n/s head lamp <i>crq</i>	\$	1,531.57	
		\$	3,305.38	\$2407.7
	Less 20%	\$	661.08	
		\$	2,644.30	\$1926.16

S/NETT

1 set	Front bumper clips <i>rec</i>	\$	48.00	
1 pc	Front n/s fender sticker <i>rec</i>	\$	30.00	
1 set	Front n/s fender inner shield clips <i>xun</i>	\$	28.00	
	Sundry <i>rec</i>	\$	50.00	\$20
	To check front n/s wheel alignment	\$	80.00	<i>xun</i>
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc	\$	650.00	\$300
	To putty and spray painting on front bumper, front n/s fender, front o/s rim	\$	600.00	\$360
	To apply rustproofing on the repaired and replaced panels.	\$	120.00	\$20
		\$	4,250.30	\$778
				+1926.16
				\$20704.16

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

- Parts prices are subject to confirmation

Third party survey is on a "Without Prejudice" basis

No illegal modification(s) is allowed

- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

13/11/19
Ram (Lxx)
12/11/19 1620hrs
Ref Paint &
get repair
photo
ram.singh@lkk.com.sg
88622778
3 repair days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19020031/Fsf3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 26-11-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 3612J	Veh. Inspected	SHD 1435G	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19007136MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	12/11/2019	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I30	c.c	1582	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	TMAD281UVHJ128018	Colour	SILVER	
Odometer	134982	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	MAXXIS	6 mm	
L/H Front Tyre	195/65 R15	MAXXIS	6 mm	
R/H Rear Tyre	195/65 R15	MAXXIS	6 mm	
L/H Rear Tyre	195/65 R15	MAXXIS	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	10/11/2019	Inspection Date	12/11/2019	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 1435G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	CRACKED	811.11	811.11
1	FRONT N/S FENDER	TO REPAIR SEE LABOUR	514.02	-
2	FRONT BUMPER N/S & O/S SIDE BRACKET @\$32.51	NECESSARY	65.02	65.02
1	FRONT N/S FENDER INNER SHIELD	NOT NECESSARY	181.94	-
1	FRONT N/S FOG LAMP COVER	NOT NECESSARY	25.00	-
1	FRONT N/S FENDER INNER SHIELD	NOT NECESSARY	176.72	-
1	FRONT N/S HEAD LAMP	CRACKED	1,531.57	1,531.57
	LESS 20% DISCOUNT		-661.08	-481.54
			2,644.30	1,926.16
SPECIAL NETT ITEMS				
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	FRONT N/S FENDER STICKER (SN)	NECESSARY	30.00	30.00
1	SET FRONT N/S FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	28.00	-
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			156.00	98.00
LABOUR				
	TO CHECK FRONT N/S WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK-OUT,STRAIGHTEN,REPAIR,RESHAPE AND ADJUST OF THE SAME,ETC.INCLUSIVE OF THE REPAIR OF FRONT N/S FENDER.		650.00	300.00
	TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER,FRONT N/S FENDER,FRONT O/S RIM.		600.00	360.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		120.00	20.00
	-		-	-
	-		-	-
	-		-	-
			1,450.00	680.00
GRAND TOTAL			4,250.30	2,704.16



RECOMMENDED COST OF REPAIRS			2,704.16
-----------------------------	--	--	----------

Report Ref No. CS/FC119020031/Fsf3n2

PARASURAM S/O SHANMUGAM

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.