

# SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29  
 Kaki Bukit Autohub. Singapore 417921  
 Tel No. : 67461515 / 67471787 Fax No. : 67485015  
 Website : www.successunited.com.sg  
 Buss. Reg. No. : GST No. 200402570G

AIG Asia Pacific Insurance Pte Ltd  
 AIG Building  
 78 Shenton Way, #07-16  
 Singapore 079120

Attention : Motor Claim Department  
 Contact : 64191053 Fax No. : 68357416

*Khanchan*

Estimate : TP19-145

Date : 02/11/2019  
 Vehicle Num. : EQ1415G  
 Make/Model : Honda HRV-2015  
 Chassis/Eng# : MRHRU1830FP000473/L15Z7100088-  
 Accident Date : 01/11/2019  
 Claim No. :  
 Reference :  
 Policy No. :

S/N Quantity Particular Unit Price Amount S\$

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1 pc	Frt Door Weatherstrip RH <i>Ne n</i>		86.40 +
2.	1 pc	Frt Door RH <i>Dented</i>	966.20	1,355.90 -
3.	1 pc	Rear Door RH <i>Dented</i>	1,030.60	1,280.60 ✓
4.	1 pc	Rear Door Weatherstrip RH <i>new</i>		98.40 +
5.	1 pc	Rear Door Mechanism Lock RH <i>new</i>		283.00 +
6.	2 pcs	Rear Door Hinge, Top/Lower RH <i>new</i>	89.70	179.40 +
7.	1 pc	Rear Door Center Check RH <i>new</i>		62.80 +
8.	1 pc	Rear Door Glass Regulator Gear RH <i>new</i>		420.00 +
9.	1 pc	Side Rocker Skirt RH <i>cut</i>		477.50 -
10.	1 pc	Rear Fender Guard RH <i>cut</i>	195	281.00 -
11.	1 pc	Rear Shock Absorber RH <i>DM</i>		385.00 ✓
12.	1 pc	Rear Wheel Bearing RH <i>DM</i>		363.50 +
13.	1 pc	Rear Axle Beam Assy <i>new</i>	3387.81	1,513.50 +
14.	1 pc	Rear Door Sticker RH <i>new</i>		78.20 -
15.	1 pc	Rear Fender Inner Liner RH <i>new</i>	2710.24	268.70 +
16.	1 pc	Rear Bumper Splash Guard RH <i>cut</i>		255.31 ✓

List Total S\$ : 7,389.21  
 20.00% Discount S\$ : 1,477.84  
 -----  
 5,911.37

S/N	Quantity	Particular	Unit Price	Amount S\$
SPECIAL NETT ITEMS :				
1.	1 pc	Rear Sports Rim RH <i>new cut</i>		720.00 - 500
2.	1 pc	Rear Tyre RH <i>Att n</i>	500	380.00 +

Special Nett Total S\$ : 1,100.00

LABOUR :  
 To remove, rearrange electrical wirings, check lighting 80.00 30  
 To remove, replace & transfer door components. 200.00 160

CONTINUE / ...

# SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29  
 Kaki Bukit Autohub, Singapore 417921  
 Tel No. : 67461515 / 67471787 Fax No. : 67485015  
 Website : www.successunited.com.sg  
 Buss. Reg. No. : GST No. 200402570G

AIG Asia Pacific Insurance Pte Ltd  
 AIG Building  
 78 Shenton Way, #07-16  
 Singapore 079120  
 Attention : Motor Claim Department  
 Contact : 64191053 Fax No. : 68357416

Estimate : TP19-145

Date : 02/11/2019  
 Vehicle Num. : EQ1415G  
 Make/Model : Honda HRV-2015  
 Chassis/Eng# : MRHRU1830FP000473/L15Z7100088  
 Accident Date : 01/11/2019  
 Claim No. :  
 Reference :  
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		Transfer glass, gear & components.		320.00 ↑
		To remove, replace rear undercarriage parts.	1390	1,500.00 <del>600</del>
		To remove, repair and replaced damaged bodyparts, realign bodyworks & where consistent to the accident		1,200.00 <del>600</del>
		To putty and respray painting on affected area.		3,300.00
		Labour Total S\$ :		

PARTS: \$3,387.81  
 PARTS ( 20% DISCOUNT): \$ 2,710.24  
 S/N: \$500  
 LABOUR: \$ 1,390

total 4600.24  
 L/S: 3650

Admin G  
 2/s 11/11/19.  
 OS Pays.

Total S\$ : 10,311.37  
 =====

  
 SUCCESS UNITED PTE LTD

**LKK Auto Consultants** hence notify  
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: