

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29
 Kaki Bukit Autohub. Singapore 417921
 Tel No. : 67461515 / 67471787 Fax No. : 67485015
 Website : www.successunited.com.sg
 Buss. Reg. No. : GST No. 200402570G

AIG Asia Pacific Insurance Pte Ltd
 AIG Building
 78 Shenton Way, #07-16
 Singapore 079120

Attention : Motor Claim Department
 Contact : 64191053 Fax No. : 68357416

Khanchan

Estimate : TP19-145

Date : 02/11/2019
 Vehicle Num. : EQ1415G
 Make/Model : Honda HRV-2015
 Chassis/Eng# : MRHRU1830FP000473/L15Z7100088-
 Accident Date : 01/11/2019
 Claim No. :
 Reference :
 Policy No. :

S/N Quantity Particular Unit Price Amount S\$

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1 pc	Frt Door Weatherstrip RH <i>Ne n</i>		86.40 +
2.	1 pc	Frt Door RH <i>Dented</i>	966.20	1,355.90 -
3.	1 pc	Rear Door RH <i>Dented</i>	1,030.60	1,280.60 ✓
4.	1 pc	Rear Door Weatherstrip RH <i>new</i>		98.40 +
5.	1 pc	Rear Door Mechanism Lock RH <i>new</i>		283.00 +
6.	2 pcs	Rear Door Hinge, Top/Lower RH <i>new</i>	89.70	179.40 +
7.	1 pc	Rear Door Center Check RH <i>new</i>		62.80 +
8.	1 pc	Rear Door Glass Regulator Gear RH <i>new</i>		420.00 +
9.	1 pc	Side Rocker Skirt RH <i>cut</i>		477.50 -
10.	1 pc	Rear Fender Guard RH <i>cut</i>	195	281.00 -
11.	1 pc	Rear Shock Absorber RH <i>new</i>		385.00 ✓
12.	1 pc	Rear Wheel Bearing RH <i>Damaged</i>		363.50 +
13.	1 pc	Rear Axle Beam Assy <i>new</i>	3387.81	1,513.50 +
14.	1 pc	Rear Door Sticker RH <i>new</i>		78.20 -
15.	1 pc	Rear Fender Inner Liner RH <i>new</i>	2710.24	268.70 +
16.	1 pc	Rear Bumper Splash Guard RH <i>cut</i>		255.31 ✓

List Total S\$: 7,389.21
 20.00% Discount S\$: 1,477.84

 5,911.37

S/N	Quantity	Particular	Unit Price	Amount S\$
SPECIAL NETT ITEMS :				
1.	1 pc	Rear Sports Rim RH <i>new cut</i>		720.00 - 500
2.	1 pc	Rear Tyre RH <i>new</i>		380.00 +

Special Nett Total S\$: 1,100.00

LABOUR :
 To remove, rearrange electrical wirings, check lighting 80.00 30
 To remove, replace & transfer door components. 200.00 160

CONTINUE / ...

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29
 Kaki Bukit Autohub, Singapore 417921
 Tel No. : 67461515 / 67471787 Fax No. : 67485015
 Website : www.successunited.com.sg
 Buss. Reg. No. : GST No. 200402570G

AIG Asia Pacific Insurance Pte Ltd
 AIG Building
 78 Shenton Way, #07-16
 Singapore 079120
 Attention : Motor Claim Department
 Contact : 64191053 Fax No. : 68357416

Estimate : TP19-145

Date : 02/11/2019
 Vehicle Num. : EQ1415G
 Make/Model : Honda HRV-2015
 Chassis/Eng# : MRHRU1830FP000473/L15Z7100088
 Accident Date : 01/11/2019
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		Transfer glass, gear & components.		320.00
		To remove, replace rear undercarriage parts.		1,500.00
		To remove, repair and replaced damaged bodyparts, realign bodyworks & where consistent to the accident	1390	1,200.00 600
		To putty and respray painting on affected area.		1,200.00 600
		Labour Total S\$:		3,300.00

total 4600.24
 L/S: 3650
 Admin G
 L/S 11/11/19.
 OS Pays.

Total S\$: 10,311.37


 SUCCESS UNITED PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: