

KIAN TEONG AUTO CENTRE

Blk 176 Sin Ming Drive #01-08

Sin Ming AutoCare Singapore 575721

Tel No. : 64556268 Fax No. : 64555166

E-Mail : info@ktauto.com.sg

Website : www.ktauto.com.sg

Tax Reg. No. : 52991859E Buss. Reg. No. : 52991859E

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER, SINGAPORE 079909

Attention : Motor Claim Department

Contact : 6389 6111 Fax No. : 6222 1033 / 62253592

Estimate : ES000507

Date : 12/11/2019

Vehicle Num. : SJC 9208 A

Make/Model : MEC C180

Chassis/Eng# :

Accident Date : 12/11/2019

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	REAR BOOTH LID		2,150.00
2.	C180	REAR BOOTH LID EMBLEM		98.00
3.	C & C LOGO	REAR BOOTH LID EMBLEM		118.00
4.	LOGO	REAR BOOTH LID EMBLEM		150.00
5.	KCOMPRES	REAR BOOTH LID EMBLEM		98.00
6.	2	REAR BOOTH WEATHER STRIP	378.50	757.00
7.	2	REAR TAIL LAMP	1,350.00	2,700.00
8.	1	REAR BUMPER UNIT		1,930.00
9.	1	REAR BUMPER REINFORCEMENT		1,150.00
10.	CENTRE	REAR BUMPER CHROME MOULDING		385.00
11.	LH	REAR BUMPER CHROME MOULDING		178.00
12.	RH	REAR BUMPER CHROME MOULDING		178.00
13.	1	TOW HOOK COVER		115.00
14.	2	REAR BUMPER BRACKET	85.00	170.00
15.	2 PCS	REAR BUMPER REVERSE SENSOR	385.00	770.00
16.	1	FRONT RH HEADREST AIRBAG UNIT		860.00
List TotalS\$:				11,807.00
LABOUR :				
LABOUR FEES:				
TO PUTTY APPLY PRIMER & SPRAY PAINT THE AFFECTED AREAS				1,200.00
TO SPRAY PAINT ALL DAMAGED PARTS				
TO KNOCK AND REPAIR ALL DAMAGED PARTS				1,680.00
TO REMOVE AND CHANGE ALL DAMAGED PARTS				
TO REMOVE AND REFIT REAR ECHUAST UNIT TO FACIALTE				120.00
REPAIR				
TO CHECK ALL TAIL LAMP AND SENSOR WIRING				150.00
TO DIAGNOSE AND RESET AIRBAG CONTROL MODULE				380.00
Labour Total S\$:				3,530.00

E. & O.E.

Total S\$: 15,337.00

for KIAN TEONG AUTO CENTRE

Please do not hesitate to contact us at the above number if there is any other further quire.
We thank you for your kind attention. Your prompt reply is greatly appreciated.