



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO19020034/Byf3s2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 20-01-2020



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLL 9464E	Veh. Inspected	SKJ 8857J
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1905243/LJH	Excess (\$)	0.00
Assign From	MELVIN YE YONG KANG	Assign Date	12/11/2019

2. Vehicle Particulars & Condition

Make & Model	B.M.W. 316I	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	WBA3A12030J720431	Colour	BLACK
Odometer	105792	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/50 R17	MICHELIN	6 mm
L/H Front Tyre	225/50 R17	MICHELIN	6 mm
R/H Rear Tyre	225/50 R17	MICHELIN	6 mm
L/H Rear Tyre	225/50 R17	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	03/11/2019	Inspection Date	12/11/2019
Survey held at	160 SIN MING DRIVE # 01-14		
Repairer	TEAM AUTOPRO PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**