

ASS. REC. BY:

REF: CS | FWD19020038 | Kqf3

Special Instruction:

Survivor: Kenneth

ASSIGNMENT (Office)

From (Person): Vanessa Chan

of FWD

Date/Time: 12-11-19 10:30A.M

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SV 15966

Insured: SJN 15272

at Workshop m/s Hung yap song

Tel: 9183 3008

of BIK 160 Son ning Drive #08-13

Policy No: PNPUS019-00004234

Claim No: 12019000 34557

Sum Insured:

Excess:

Make of Veh: (Client's Record)

D.O.A. 8-11-2019

CA / REV / REP. / REV 24 HRS

mp

H.O.D. Endorsement:

Date/Time: 12-11-19 12:13p

Person Contacted: Mr Chong

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SJN 15272 : X
	SV 15966 : X
14/11/19 @ 11.00am	Informed Lionel Tan, we are pending estimate from repairer
21/11/19 @ 7.50pm	Mr Chong said the estimate just ready.
11/12/19 @ 11.50am	Mr Chong said the estimate not yet ready.
03/01/20 @ 11.45am	Mr Chong will check the estimate whether ready.

ASS. REC. BY:

REF: CTI / FWD

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop n/vs 1 Ken Yap Sng

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 811K

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SV1596G Yr Regn: 01, 10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toy Rush c.c. 1495

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 152817 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 5200E 0024579

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: Continental 215/65R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front R/Bal. 8 mm Rear R/Bal. 8 mm

L/Bal. 8 mm L/Bal. 8 mm

D.O.A. 8/11/19 D.O.I. 12/11/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or N/S Acc & U/C

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>1</u>	<u>File pass to EM not ready</u>
<u>16/01/20</u>	<u>@ 10.56am revised to Lionel Tan via Whatsapp.</u>
<u>15/1</u>	<u>U/Sng @ 250d email & confirmed (Ref @ 6606.85, 73/-)</u>

RECEIVED 16 JAN 2020

Date/Time, File Pass to? : Prell. Report : Final Report

Date/Time, File Return to?
 Report Format: MER-TP
 Lump Sum / I.B.A. (\$) 2500

Days Of Repair: 6
 Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech Invs (\$)
 : Weekend (\$)

Survey Fee:	<u>200</u>
Transportation:	<u>50</u>
S - RS. \$:	
Fees:	
Others:	
TOTAL:	<u>250</u>

Nivitha (LKK Auto)

From: venessa.chan@fwd.com
Sent: Tuesday, 12 November 2019 10:30 AM
To: admin-d@lkkauto.com; admin-a@lkkauto.com
Cc: motorclaims.sg@fwd.com; lionel.tan@fwd.com
Subject: Our Ref : BMC.3424.19.wh // ACCIDENT INVOLVING SJN1527Z & SJV1596G ON 08.11.2019 / OUR CLAIM REF: 1201900034557
Attachments: PRI - KURUP & BOO.PNG

Dear Nivitha/Summer,

Please refer to the email below and liaise with TP repairer for PRS.

Please create the case in Merimen.

Kindly upload all correspondence emails/documents sent to you into Merimen.

Thank you.

Best Regards,

Venessa Chan
Administrative Assistant, Claims




FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

E venessa.chan@fwd.com

W www.fwd.com.sg



From: Venessa Chan - SGUser
Sent: Tuesday, November 12, 2019 10:28 AM
To: Boo Moh Cheh
Cc: Motor Claims SG - SG Common; Lionel Tan Tian Pei - SGUser
Subject: Our Ref : BMC.3424.19.wh // ACCIDENT INVOLVING SJN1527Z & SJV1596G ON 08.11.2019 / OUR CLAIM REF: 1201900034557

Dear Sir/Madam,

Thank you for your selection of LKK Auto Consultants Pte Ltd.
We will proceed to assign survey.

Thank you.

*Veh In
est*

Best Regards,

Venessa Chan

Administrative Assistant, Claims




FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

E venessa.chan@fwd.com

W www.fwd.com.sg



From: Boo Moh Cheh [<mailto:boo@kurupnboo.com.sg>]

Sent: Tuesday, November 12, 2019 10:19 AM

To: Venessa Chan - SGUser

Cc: Motor Claims SG - SG Common; Lionel Tan Tian Pei - SGUser

Subject: RE: Our Ref : BMC.3424.19.wh // ACCIDENT INVOLVING SJN1527Z & SJV1596G ON 08.11.2019

Our Ref : BMC.3424.19.wh

Your Ref : Insured vehicle no. SJN 1527Z

12 November 2019

FWD Singapore Pte Ltd

Dear Sirs

**REQUEST FOR PRE REPAIR INSPECTION
ACCIDENT INVOLVING VEHICLES NO. SJV 1596G AND SJN 1527Z AT
JUNCTION OF MCNALLY STREEY AND PRINSEP STREET ON 8 NOVEMBER 2019**

We refer to you email dated 11 November 2019.

We are instructed to appoint LKK Auto Consultants Pte Ltd for the pre repair inspection.

Regards

Boo Moh Cheh
Kurup & Boo
111 North Bridge Road
#15-03 Peninsula Plaza
Singapore 179098
Tel : 6223 3343
Fax : 6225 7248

From: venessa.chan@fwd.com <venessa.chan@fwd.com>

Sent: Monday, 11 November, 2019 10:50 AM

To: boo@kurupnboo.com.sg

Cc: motorclaims.sg@fwd.com; lionel.tan@fwd.com

Subject: Our Ref : BMC.3424.19.wh // ACCIDENT INVOLVING SJN1527Z & SJV1596G ON 08.11.2019

WITHOUT PREJUDICE

Dear Sir/Madam,

Refer to your email dated on 11.11.2019 of the PRI Notice of your client's vehicle SJV1596G.

Please find our panel surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD
2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD
4. RT APPRAISAL PTE LTD

If you are not agreeable to any of the above, we reserve our rights to request for pre-repair inspection of your client's vehicle.

We look forward to receiving your reply.

Thank you.

*Please note that contents of this email should not be construed as any admission of liability on the part of our insured and/ or insurers. We hereby maintain full reservation of rights and all defences available to us.

***Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com.**

Thank you.

Best Regards,

Venessa Chan

Administrative Assistant, Claims




FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

E venessa.chan@fwd.com

W www.fwd.com.sg



From: Boo Moh Cheh [<mailto:boo@kurupnboo.com.sg>]

Sent: Monday, November 11, 2019 10:30 AM

To: Motor Claims SG - SG Common
Subject: Our Ref : BMC.3424.19.wh

Our Ref : BMC.3424.19.wh
Your Ref : Insured vehicle no. SJN 1527Z
11 November 2019

FWD Singapore Pte Ltd

Dear Sirs

**REQUEST FOR PRE REPAIR INSPECTION
ACCIDENT INVOLVING VEHICLES NO. SJV 1596G AND SJN 1527Z AT
JUNCTION OF MCNALLY STREEY AND PRINSEP STREET ON 8 NOVEMBER 2019**

We attach a copy of our letter today for your attention.

Regards

Boo Moh Cheh
Kurup & Boo
111 North Bridge Road
#15-03 Peninsula Plaza
Singapore 179098
Tel : 6223 3343
Fax : 6225 7248

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

KURUP & BOO
UEN 53130914B
ADVOCATE & SOLICITOR
COMMISSIONER FOR OATHS
NOTARY PUBLIC

111 North Bridge Road
#15-03 Peninsula Plaza
Singapore 179098
Tel. No. 6223 3343
6221 8623
Fax. No. 6225 7248
Writer's e-mail :
boo@kurupnboo.com.sg

Our Ref : BMC.3424.19.wh
Your Ref : Insured vehicle no. SJN 1527Z
11 November 2019

U R G E N T

FWD Singapore Pte Ltd
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

Email: motorclaims.sg.@fwd.com
and BY HAND

Dear Sirs

**ACCIDENT INVOLVING VEHICLES NO. SJV 1596G AND SJN 1527Z AT
JUNCTION OF MCNALLY STREEY AND PRINSEP STREET ON 8 NOVEMBER 2019**

We act for Trillium Leasing Pte Ltd , the owner of the vehicle no. SJV 1596G which was involved in the above accident.


For your immediate attention, we attach a copy of the Singapore Accident Statement lodged by or on behalf of our client.

By way of notice, we inform you that our client damaged vehicle is now in the workshop named below:

Heng Yap Seng Auto Services
Block 160, Sin Ming Drive
#08-13 Sin Ming AutoCity
Singapore 575722
Contact : Mr Chong Han Meng
HP No. : 9183 3008 Fax : 6873 2017

We hereby give you **two days'** notice for your representative to go the above workshop to inspect our client's damaged vehicle. Kindly contact Mr Chong Han Meng prior to going to the workshop for the survey.

Yours faithfully



BOO MOH CHEH

enc
cc Heng Yap Seng Auto Service

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Lionel Tan

Date: 16 Jan 2020

Preliminary Advice

Insured Vehicle No	: SJN1527Z	Accident Date	: 08/11/2019
TP Vehicle No	: SJV1596G	Assignment Date	: 14/11/2019
Make	: TOYOTA RUSH	Est. Duration of Repair	: 6.00
Date of Inspection	: 12/11/2019		
Inspection At	: HENG YAP SENG AUTO SERVICES 160 SIN MING AUTO CITY, #08-13 SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s rear portion & undercarriage and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,106.85
Revised Amount	:S\$	3,618.05
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,618.05
Lump Sum Repair	:S\$	2,500.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Shiau Chan (LKKAuto)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Thursday, 14 November 2019 11:00 AM
To: do-not-reply@merimen.com
Cc: SUR
Subject: TP VEHICLE SJV 1596G (YOUR REF: 1201900034557)

This mail is associated with :
***SJV1596G (1201900034557)**
[SJV1527Z]
TP
TRILLIUM LEASING PTE LTD
Nov 8 2019 12:00AM
[Tan Seok Keng]
Heng Yap Seng Auto Services

Dear Lionel,

Please be informed that we have inspected the vehicle SJV 1596G on 12/11/2019.

We are pending for estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms)
LKK Auto Consultants Pte Ltd

This is an auto-generated email. Do not reply to this email.

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/11/2019 18:16
Date Of Accident	08/11/2019 01:40
Exact Location Of Accident	JUNCTION OF MCNALLY ST & PRINSEP ST
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJV1596G
Insured/Policyholder	
Name Of Registered Owner	TRILLIUM LEASING PTE. LTD.
Co Reg No	201610925N
Email Address	ANDREW@COSMOAUTOMOBILES.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-83219090

Vehicle Particulars

Manufacturer	TOYOTA
Model	RUSH
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5112077358
Cover Note Number	

Driver


Name of Driver	ANDI RISFANDI BIN HAMZAH
NRIC No	S8112486H
Date Of Birth	03/05/1981
Occupation	OUTDOOR
Date Of Driving Pass	06/09/2010
Driving Experience	9 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-88927761
Fax Number	
Contact Number	
Email Address	ANDYSAMURAI13@GMAIL.COM

Vehicle Registration Number SJN1527Z
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver LIM WEI ZHI
NRIC/Passport Number S9337021Z
Contact Number 96966310
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name IZZ AKMAL SUPATI
Approximate Age
Injuries Sustain LEFT ARM INJURED
Injured person in which vehicle? SJV1596G
Were seat belts worn?
Was this injured conveyed to hospital by ambulance? YES
Address
Postcode

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer attached T/20191108/2017.
 police report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:



Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

20191108/2017

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	925N
Vehicle Details	
Vehicle No.:	SJV1596G
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Nov 2019
Vehicle Make:	TOYOTA
Vehicle Model:	RUSH 1.5X A
Primary Colour:	Red
Manufacturing Year:	2008
Engine No.:	3S22216603
Chassis No.:	J200E0024579
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$16,104.00
Original Registration Date:	13 Jan 2010
First Registration Date:	13 Jan 2010
Transfer Count:	3
Actual ARF Paid:	\$16,104.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Jan 2020
PARF Rebate Amount:	\$8,052.00
Intended COE Rebate Details	
COE Expiry Date:	12 Jan 2020
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$15,875.00
COE Rebate Amount:	\$309.00
Total Rebate Amount:	\$8,361.00

The information contained herein is correct as at 13 Nov 2019

OK

HENG YAP SENG AUTO SERVICES

Blk 160, Sin Ming Drive, #08-13 Sin Ming AutoCity, Singapore 575722
 Hp : 9183 3008 Fax : 6873 2017

*Not Notarised
 L1 Sur @ 2500k Max
 Resurvey After Paint*

Vehicle No : SJV1596G
 Vehicle Model : Toyota Rush

Estimate Repair Cost

No.	Qty	Parts List Items	
1	1	Rear fender LH	\$ <i>By</i> 1,062.10 ✓
2	1	Rear fender inner trim LH	\$ <i>Ln</i> 659.10 ✓
3	1	Rear door LH	\$ <i>By</i> 1,004.95 ✓
4	1	Rear door pillar LH	\$ <i>n</i> 606.10 ✓
5	1	Rear door lock LH	\$ <i>n</i> 509.10 ✓
6	1	Rear door weatherstrip LH	\$ <i>Ln</i> 212.45 ✓
7	1	Rear door inner trim LH	\$ <i>n</i> 666.40 ✓
8	1	Rear door outer handle LH	\$ <i>Ln</i> 210.10 ✓
9	1	Rear door regulator LH	\$ <i>By</i> 290.35 ✓
10	1	Rear door inner handle LH	\$ <i>Ln</i> 202.10 ✓
11	1	Rocker panel LH	\$ <i>n</i> 404.10 ✓
			<u>\$ 5,826.85</u>

25%

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: 1

Parts Special Nett Items

1 Rear wheel rim LH

rd \$ 300.00 *250Ln*
 \$ 300.00

Total Parts \$ 6,426.85

Labour

1	Labour charge to remove, cut out damage portion, jack out, straighten, panel beating, welding, align and renew replaced parts.	\$ 1,200.00 <i>800</i>
2	To putty and respray painting on affected areas.	\$ 800.00 <i>600</i>
3	To remove, replace rear door fittings to facilitate repair.	\$ 250.00 <i>60</i>
4	To remove, replace rear door windscreen glass.	\$ 100.00 <i>60</i>
5	To remove, replace rear wheel rims.	\$ 100.00 <i>20</i>
6	To remove, replace door upholstery, garnish and attachments.	\$ 150.00 <i>100</i>
7	To check wiring and lightings.	\$ 80.00 <i>20</i>

Total Labour \$ 2,680.00

Total Parts and Labour \$ 9,106.85

8806-85x

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Nov 2019 Edit Reg		12 Nov 2019 00:00 Edit Adj Rpt	S\$2,500.00 Edit Estimates	S\$2,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS				[Created by adjuster]					
Insured: Tan Seok Keng , ID: S1827307A									
Main Claimant: TRILLIUM LEASING PTE LTD , Co. Reg. No.: 201610925N									
Vehicle Reg. No.:	SJV1596G	Date of Loss:	08/11/2019 00:00 - :59 [117 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1201900034557	Policy/Cover Note No.:	PNPV2019-00004234 (Comprehensive) Coverage: 25/02/2019 - 24/02/2020						
Vehicle Reg. No. (Insured):	SJN1527Z	Policy No. (Claimant):							
		Excess:							
Repairer:	Heng Yap Seng Auto Services () 160 Sin Ming Auto City, #08-13, 575722 Sin Ming - Tel:								
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Lionel Tan]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 25/11/2019]								
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS				View All Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJV1596G (1201900034557)**
[SJN1527Z]

TP

TRILLIUM LEASING PTE LTD

Nov 8 2019 12:00AM

[Tan Seok Keng]

Heng Yap Seng Auto Services

Upload Documents			Upload Photos			Compose New Letter			View	View in Browser
Assessment Reports									1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	16/01/20 10:56	Adjuster Immediate Advice		Load HTM						
Photos/Images									3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	16/01/20 10:51	General View		Load JPG	<input checked="" type="checkbox"/>					
2	16/01/20 10:51	General View		Load JPG	<input checked="" type="checkbox"/>					
3	16/01/20 10:51	General View		Load JPG	<input checked="" type="checkbox"/>					
4	16/01/20 10:51	General View		Load JPG	<input checked="" type="checkbox"/>					
5	16/01/20 10:51	General View		Load JPG	<input checked="" type="checkbox"/>					
6	16/01/20 10:51	General View		Load JPG	<input checked="" type="checkbox"/>					
7	16/01/20 10:51	General View		Load JPG	<input checked="" type="checkbox"/>					
8	16/01/20 10:51	General View		Load JPG	<input checked="" type="checkbox"/>					
9	16/01/20 10:51	General View		Load JPG	<input checked="" type="checkbox"/>					
10	16/01/20 10:51	General View		Load JPG	<input checked="" type="checkbox"/>					
11	16/01/20 10:51	General View		Load JPG	<input checked="" type="checkbox"/>					
12	16/01/20 10:51	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>					
13	16/01/20 10:51	Chassis Number		Load JPG	<input checked="" type="checkbox"/>					
Documentation									1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	14/11/19 09:49	EMAIL FROM FWD ON 12/11/2019 TO CONDUCT SURVEY		Load PDF						
2	14/11/19 10:00	PRI - KURUP & BOO.PNG		Load JPG	<input checked="" type="checkbox"/>					
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)		Thumbnail	Print					
1	14/11/19 10:36	PRI - KURUP & BOO & TP GIA		Load PDF						
2	14/11/19 10:36	SJN1527Z OI GIA		Load PDF						

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/FWD19020038/KQF3S2

Date: 16/01/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2019-00004234
 Claimant Vehicle No: SJV1596G Insured Vehicle No: SJN1527Z
 Date of Loss: 08/11/2019 Nature of Claim: TP Claim No: 1201900034557

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJV1596G**
 Make & Model: TOYOTA RUSH, 1.5 X (A) Engine No: 3SZ2216603
 Reg. Date: 13/01/2010 (Man. Year: 2008) Chassis No: J200E0024579
 Colour: Red Odometer: 152817 km
 Engine Capacity: 1495 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/65 R16 Rear Tyre Size: 215/65 R16
 Front Left Side: Continental 4 mm Rear Left Side: Continental 8 mm
 Front Right Side: Continental 4 mm Rear Right Side: Continental 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,126.85	2,018.05	4,108.80	67.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,680.00	1,600.00	1,080.00	40.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,806.85	3,618.05	5,188.80	58.92
Approved Total (Overridden) (S\$)		2,500.00		
Nett Amount (S\$)	8,806.85	2,500.00	6,306.85	71.61

INSPECTION

Date of Assignment: 12/11/2019
 Date Inspected: 12/11/2019 Inspected At: BLK 160 Sin Ming Drive #08-13 Singapore 575722
 Repairer: Heng Yap Seng Auto Services
 Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 16 Jan 2020)
Parts: M1-SUV	TOYOTA RUSH 1.5 X (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJV1596G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER LH	Bent	1,062.10 F	*1,062.10 FL
2	1		*REAR FENDER INNER TRIM LH	Serviceable	659.10 F	*-FL
3	1		*REAR DOOR LH	Bent	1,004.95 F	*1,004.95 FL
4	1		*REAR DOOR PILLAR LH	Repair	606.10 F	*-FL
5	1		*REAR DOOR LOCK LH	Repair	509.10 F	*-FL
6	1		*REAR DOOR WEATHERSTRIP LH	Serviceable	212.45 F	*-FL
7	1		*REAR DOOR INNER TRIM LH	Serviceable	666.40 F	*-FL
8	1		*REAR DOOR OUTER HANDLE LH	Serviceable	210.10 F	*-FL
9	1		*REAR DOOR REGULATOR LH	Bent	290.35 F	*290.35 FL
10	1		*REAR DOOR INNER HANDLE LH	Serviceable	202.10 F	*-FL
11	1		*ROCKER PANEL LH	Repair	404.10 F	*-FL
12	1		*REAR WHEEL RIM LH	Dented	300.00 FS	*250.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	6,126.85	2,607.40
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	589.35
Total Parts (\$\$)	6,126.85	2,018.05

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGE TO REMOVE, CUT OUT DAMAGE PORTION, JACK OUT, STRAIGHTEN, PANEL BEATING, WELDING, ALIGN AND RENEW REPLACED PARTS.	New	1,200.00	800.00
2	TO PUTTY AND SPRAY PAINTING ON AFFECTED AREAS.	New	800.00	600.00
3	TO REMOVE, REPLACE REAR DOOR FITTINGS TO FACILITATE REPAIR.	New	250.00	60.00
4	TO REMOVE, REPLACE REAR DOOR WINDSCREEN GLASS.	New	100.00	0.00
5	TO REMOVE, REPLACE REAR WHEEL RIMS.	New	100.00	20.00
6	TO REMOVE, REPLACE DOOR UPHOLSTERY, GARNISH AND ATTACHMENTS.	New	150.00	100.00
7	TO CHECK WIRING AND LIGHTINGS.	New	80.00	20.00
Gross Labour Cost (S\$)			2,680.00	1,600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >