

15/5/2010

INS. CASE OWNER:

CC 4 / LPC19020045, P/E 1/12/19

LKK:

IDAC:

Surveyor:

Paul

DOI:

ASSIGNMENT

16/12/19

Date / Time:

14/11/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLG 6848C

Name of Insured:

BAHARAH BINTE MOHAMED Amin

Insured Tel No.:

HP:

Excess Sec II :\$

D.O.A:

7/11/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

MOHAMED BIN IBRAHIM

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

BEPK SOUTH RD SUP RD W/O
BEPK SOUTH RD 3.

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SLN 613R

INSRS:
WSP: HITACHI
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time	STAGE	DATE / PIC
21.11.19	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	☐
	After call ltr to OI:	☐
	Authorisation To Act: (NO NEED)	☐
	Release Voucher:	☒
	Final Repair Bill:	☒
	Car Rental Invoice:	☐
	Towing Invoice	☐
	LTA / GIA:	☒
	Medical Bill:	☐
	PIR:	☐
	Mandate/Reject Instruction:	☒
	LOD	☒
	Payment Breakdown Form:	☐
	Post-Repair Photos:	☒
	Others:	☐
PRELIMINARY ADVICE Date/Time: Sent By: Confirm with: Confirm by: MIB		
FINALIZATION Date/Time: Confirm with: Confirm by: MIB		
Repair Cost: P/P \$52,343.38 (4 days) Reduction: 53 % Email ☒ Call ☐		
FINAL SETTLEMENT Date/Time: 31.03.20 Confirm with: JAMILIA Email ☐ Call ☐		
Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 21 If NO or B 28, Ass. Lia:		
Repair Cost: 6/157 \$52,400.43 0.10 REAR ENDED TP		
Loss of Rental (LOR): \$5 - (days)		
Loss of Use (LOU): \$5 240.00 (\$ 60 x 4 days)		
Loss of Income (LOI): \$5 - (\$ x days)		
LOR only ☐ LOU only ☒ LOR + LOU ☐ LOR + LO ☐ [Tick only one]		
GIA/LTA Search \$5 2.00		
Medical: \$5 -		
Disbursement: \$5 - (e.g. Tow/ Independent)		
Legal Cost \$5 -		
Total: \$52,642.42 Global Sum \$5:		
FINAL PAYMENT Date/Time: 31.03.20 Confirm with: JAMILIA Email ☐ Call ☐		
Payee 1: \$52,642.42 Name 1: HITACHI CAPITAL ASIA PACIFIC PTE LTD.		
Payee 2: (Strike if N.A.) \$5 Name 2:		
Payee 3: (Strike if N.A.) \$5 Name 3:		

COPY SENT
6/11/2022

ASSIGNMENT

From: _____ Date: 16.12.2019
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SLN 613R
 at Workshop m/s HITACHI CAPITAL
 of 8 Fourth Lok Yang Road
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: After 2pm



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS mp
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLN 613R Yr Regn: 2017 APR
 Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: TOYOTA COROLLA ALTIS C.C. 1598
 Colour: BLACK A/C: Insured / Std / NI / NA
 Sp.Reading: 31832 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MR053REH104557483
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 215/45R17
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front
 R/Bal. 6 mm
 L/Bal. 6 mm
 D.O.A. 01/11/19
 Rear
 R/Bal. 6 mm
 L/Bal. 6 mm
 D.O.I. 16/12/19
 Survey held at HITACHI
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or •
Rear O/S
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	P/P: 72,243.38 (RBD: 72,531.37 52%)

Date/Time, File Pass to?

☐ : Preli. Report
 ☐ : Final Report

1) _____

Date/Time, File Return to?

2) _____

Rep. Format: _____

Lump Sum / F.B.I: _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$)
 ☐ : Interview (\$)
 ☐ : Tech. Invs (\$)
 ☐ : Weekend (\$)

Survey Fee: _____

Transportation: _____

S + RS. SI
 Photos
 Others

TOTAL



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC4/LPC19020045/R1cb3

Date: 17.12.2019

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.


SLN613R

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 16.12.2019 at the premises of M/s Hitachi Capital Asia Pacific Pte. Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	4,709.50
Revised Estimate Amount	: S\$	1,875.88
"Check" Items Amount	: S\$	296.25
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:
The vehicle sustained damages at the
Rear O/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4 days

Yours faithfully,

MOHD. RASUL
Licensed Appraiser

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	399N

Vehicle Details

Vehicle No.:	SLN613R
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Nov 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 CVT
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	1ZRY330889
Chassis No.:	MR053REH104557483
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$19,990.00
Original Registration Date:	21 Apr 2017
First Registration Date:	21 Apr 2017
Transfer Count:	0
Actual ARF Paid:	\$19,990.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Apr 2027
PARF Rebate Amount:	\$14,992.00

Intended COE Rebate Details

COE Expiry Date:	20 Apr 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$48,401.00
COE Rebate Amount:	\$35,801.00
Total Rebate Amount:	\$50,793.00

The information contained herein is correct as at 08 Nov 2019

OK

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
 Tel : 64663022 Fax : 68966591
 Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

VEHICLE ESTIMATE dated 11/11/2019

LONPAC

ATTN: MOTOR CLAIMS DEPT

ACCIDENT DATE : 07/11/2019 @ 11:30
 VRN : SLN613R
 MODEL : TOYOTA ALTIS 1.6
 TP VRN : SLG6848C

	<u>Qty</u>	<u>S\$ Unit</u>	<u>S\$ Amt</u>	<u>S\$ Labor</u>
<u>PARTS REPLACEMENT</u>				
<u>1. Body Repair</u>				
1 BOOT LID X	1	\$ 755.00	\$ 755.00	
2 BOOT LID LOGO X	1	\$ 60.00	\$ 60.00	
3 BOOT LID LOGO "COROLLA" X	1	\$ 48.00	\$ 48.00	
4 BOOT LID LOGO "ALTIS" X	1	\$ 45.00	\$ 45.00	
5 BOOT LOCK X	1	\$ 382.50	\$ 382.50	
6 BOOT HINGE R/L X	2	\$ 68.00	\$ 136.00	
7 BOOT INSULATOR CLIP X	10	\$ 5.00	\$ 50.00	
8 REAR BUMPER de	1	\$ 486.50	\$ 486.50	
9 REAR BUMPER CLIP ne	10	\$ 5.00	\$ 50.00	
10 REAR BUMPER RETAINER RH ne	1	\$ 120.00	\$ 120.00	
11 REAR BUMPER REFLECTOR RH ch	1	\$ 58.00	\$ 58.00	
12 REAR BUMPER REINFORCEMENT ?	1	\$ 395.00	\$ 395.00	
13 REVERSE SENSOR (SET) 4 X	1	\$ 360.00	\$ 360.00	
			\$ 2,946.00	
			\$ 736.50	
Discount -25%			\$ 2,209.50	
		PARTS TOTAL	\$ 2,209.50	

2. Labour Charges

Panel Beat, Cut, Weld, Re-align & Replace Damaged Parts Of REAR Affected Area
 Putty, Blend And Spray Paint on REAR Affected Area
 Check Wiring and Ensure Proper Functioning
 Dismantle and Transfer Boot Lid Fittings & Mechanisms to New Boot Lid
 Remove and Reinstall Reverse Sensors
 Remove and Reinstall Rear Reverse Camera

500
 \$ 1,000.00 ~~250~~
 \$ 1,000.00 750
 \$ 80.00 30
 \$ 180.00 X
 \$ 120.00 60
 \$ 120.00 X

Rosie
 He 90010068

LABOURS TOTAL

\$ 2,500.00

Grand Total : \$ 4,709.50
 Add 7% GST : \$ 329.67
Nett Total : \$ 5,039.17

No. of repair days: 4

16/12/19 @ 1410

Resy before paint

CUSTOMER SIGNATURE

HITACHI CAPITAL ASIA PACIFIC PTE LTD
 (MANAGER)



After

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
 Tel : 64663022 Fax : 68966591
 Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

VEHICLE ESTIMATE dated 11/11/2019

LONPAC

ATTN: MOTOR CLAIMS DEPT

ACCIDENT DATE : 07/11/2019 @ 11:30
 VRN : SLN613R
 MODEL : TOYOTA ALTIS 1.6
 TP VRN : SLG6848C

	<u>Qty</u>	<u>S\$ Unit</u>	<u>S\$ Amt</u>	<u>S\$ Labor</u>
<u>PARTS REPLACEMENT</u>				
<u>1. Body Repair</u>				
1 BOOT LID <i>Xⁿⁿ</i>	1	\$ 755.00	\$ 755.00	
2 BOOT LID LOGO <i>Xⁿⁿ</i>	1	\$ 60.00	\$ 60.00	
3 BOOT LID LOGO "COROLLA" <i>Xⁿⁿ</i>	1	\$ 48.00	\$ 48.00	
4 BOOT LID LOGO "ALTIS" <i>Xⁿⁿ</i>	1	\$ 45.00	\$ 45.00	
5 BOOT LOCK <i>Xⁿⁿ</i>	1	\$ 382.50	\$ 382.50	
6 BOOT HINGE R/L <i>Xⁿⁿ</i>	2	\$ 68.00	\$ 136.00	
7 BOOT INSULATOR CLIP <i>Xⁿⁿ</i>	10	\$ 5.00	\$ 50.00	
8 REAR BUMPER <i>de</i>	1	\$ 486.50	\$ 486.50	
9 REAR BUMPER CLIP <i>re</i>	10	\$ 5.00	\$ 50.00	
10 REAR BUMPER RETAINER RH <i>re</i>	1	\$ 120.00	\$ 120.00	
11 REAR BUMPER REFLECTOR RH <i>ch</i>	1	\$ 58.00	\$ 58.00	
12 REAR BUMPER REINFORCEMENT <i>ch</i>	1	\$ 395.00	\$ 395.00	
13 REVERSE SENSOR (SET) <i>9 X^{su}</i>	1	\$ 360.00	\$ 360.00	
			\$ 2,946.00	
Discount -25%			\$ 736.50	
			\$ 2,209.50	
		PARTS TOTAL	\$ 2,209.50	

2. Labour Charges

Panel Beat, Cut, Weld, Re-align & Replace Damaged Parts Of REAR Affected Area	\$ 1,000.00 <i>500</i>
Putty, Blend And Spray Paint on REAR Affected Area	\$ 1,000.00 <i>750</i>
Check Wiring and Ensure Proper Functioning	\$ 80.00 <i>30</i>
Dismantle and Transfer Boot Lid Fittings & Mechanisms to New Boot Lid	\$ 180.00 <i>X</i>
Remove and Reinstall Reverse Sensors	\$ 120.00 <i>60</i>
Remove and Reinstall Rear Reverse Camera	\$ 120.00 <i>X</i>
LABOURS TOTAL	\$ 2,500.00

Grand Total : \$ 4,709.50
 Add 7% GST : \$ 329.67
Nett Total : \$ 5,039.17

No. of repair days: 4

CUSTOMER SIGNATURE

Rasul
Hp 90010068
P/P
16/12/19 @ 1410
Resy before print


 HITACHI CAPITAL ASIA PACIFIC PTE LTD
 (MANAGER)

**Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre**

No. 8 Fourth Lok Yang Road Singapore 629705
Tel : 64663022 Fax : 68966591
Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

SUPPLEMENTARY VEHICLE ESTIMATE dated 18/11/2019

LONPAC

ATTN: MOTOR CLAIMS DEPT

ACCIDENT DATE : 07/11/2019 @ 11:30
VRN : SLN613R
MODEL : TOYOTA ALTIS 1.6
TP VRN : SLG6848C

	<u>Qty</u>	<u>S\$ Unit</u>	<u>S\$ Amt</u>	<u>S\$ Labor</u>
<u>PARTS REPLACEMENT</u>				
<u>1. Body Repair</u>				
1 REAR REINFORCEMENT BRACKET RH	1	\$ 95.00	\$ 95.00	
			\$ 95.00	
Discount -25%			\$ 23.75	
			\$ 71.25	
		PARTS TOTAL	\$ 71.25	

P = 1109.50
supp = 95.00

1204.50
- 25%

903.38
L = 1340.00
T = 2243.38

Grand Total : \$ 71.25
Add 7% GST : \$ 4.99
Nett Total : \$ 76.24

No. of repair days: 8

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- Damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____



HITACHI CAPITAL ASIA PACIFIC PTE LTD
(MANAGER)

Nivitha (LKK Auto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Tuesday, 12 November 2019 10:44 AM
To: assignments@lkkauto.com
Cc: MT_Claim_SG; Vonn, LM Siow
Subject: FW: SLN613R / SLG6848C DOA: 7/11/2019 TP SURVEY & LIABILITY [External Confidential]

Lonpac External - Confidential

Our Ref: 19/19/19/VP05/022615

Dear Nivitha,

Kindly proceed accordingly.


Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

From: GERALD POH WEE BIN
Sent: Tuesday, 12 November, 2019 10:35 AM
To: 'Vonn, LM Siow'
Cc: MT_Claim_SG
Subject: RE: SLN613R / SLG6848C DOA: 7/11/2019 TP SURVEY & LIABILITY [External General]

Lonpac External - General

WITHOUT PREJUDICE

Our Ref : 19/19/19/VP05/022615

Dear Vonn,

Our appointed surveyors will look into Direct Settlement cases and assess liability clearance on our behalf.

Please contact LKK Auto Consultants Pte Ltd if a survey is required.


*Veh Out
Check liability first*

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: Vonn, LM Siow [mailto:vonnlm.siow@hcspl.com.sg]
Sent: Tuesday, 12 November, 2019 9:11 AM
To: CHEW BENG KEE; GERALD POH WEE BIN
Cc: Jamilah, Binte MohdKassim; JiongHow, Ng
Subject: SLN613R / SLG6848C DOA: 7/11/2019 TP SURVEY & LIABILITY

Dear sirs,

We refer to the subject above and the attachment is for your reference.

Vehicle is NOT IN workshop.

Kindly advise on the liability and we will arrange survey with you again.

Thanks & Regards

Vonn Siow
Motor Claims Advisor
Auto Servicing
Total Vehicle Solutions Department

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre (Automobile Leasing & Workshop)
8 Fourth Lok Yang Road Singapore 629705
DID: 6833 6274 Mobile: 96435107
e: vonnlm.siow@hcspl.com.sg
w: www.hitachi-capital.com.sg

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Thursday, 21 November 2019 2:38 PM
To: vonnlm.siew@hcspl.com.sg
Cc: Jamilah, Binte MohdKassim; JiongHow, Ng
Subject: RE: SLN613R / SLG6848C DOA: 7/11/2019 TP SURVEY & LIABILITY [External Confidential]

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Hi Sir/Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents to us (LKK) to proceed on negotiate settlement.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



From: Vonn, LM Siow <vonnlm.siow@hcspl.com.sg>
Sent: Wednesday, 13 November 2019 1:25 pm
To: assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: Jamilah, Binte MohdKassim <jamilahbegum@hcspl.com.sg>; JiongHow, Ng <jionghow.ng@hcspl.com.sg>
Subject: RE: SLN613R / SLG6848C DOA: 7/11/2019 TP SURVEY & LIABILITY [External Confidential]

Dear LKK,

We refer to the subject above.

Kindly advise on the liability.

Thanks & Regards

Vonn Siow
Motor Claims Advisor
Auto Servicing
Total Vehicle Solutions Department

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre (Automobile Leasing & Workshop)
8 Fourth Lok Yang Road Singapore 629705
DID: 6833 6274 Mobile: 96435107
e: vonnlm.siow@hcspl.com.sg
w: www.hitachi-capital.com.sg

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Tuesday, November 12, 2019 10:44 AM
To: assignments@lkkauto.com
Cc: MT_Claim_SG <mt_claim@lonpac.com>; Vonn, LM Siow <vonnlm.siow@hcspl.com.sg>
Subject: FW: SLN613R / SLG6848C DOA: 7/11/2019 TP SURVEY & LIABILITY [External Confidential]

Lonpac External - Confidential
Our Ref: 19/19/19/VP05/022615

Dear Nivitha,

Kindly proceed accordingly.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

From: GERALD POH WEE BIN
Sent: Tuesday, 12 November, 2019 10:35 AM
To: 'Vonn, LM Siow'
Cc: MT_Claim_SG
Subject: RE: SLN613R / SLG6848C DOA: 7/11/2019 TP SURVEY & LIABILITY [External General]

Lonpac External - General
WITHOUT PREJUDICE


Our Ref : 19/19/19/VP05/022615

Dear Vonn,

Our appointed surveyors will look into Direct Settlement cases and assess liability clearance on our behalf.

Please contact LKK Auto Consultants Pte Ltd if a survey is required.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: Vonn, LM Siow [<mailto:vonnlm.siow@hcspl.com.sg>]
Sent: Tuesday, 12 November, 2019 9:11 AM
To: CHEW BENG KEE; GERALD POH WEE BIN
Cc: Jamilah, Binte MohdKassim; JiongHow, Ng
Subject: SLN613R / SLG6848C DOA: 7/11/2019 TP SURVEY & LIABILITY

Dear sirs,

We refer to the subject above and the attachment is for your reference.

Vehicle is NOT IN workshop.

Kindly advise on the liability and we will arrange survey with you again.

Thanks & Regards

Vonn Siow
Motor Claims Advisor
Auto Servicing
Total Vehicle Solutions Department

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre (Automobile Leasing & Workshop)
8 Fourth Lok Yang Road Singapore 629705
DID: 6833 6274 Mobile: 96435107
e: vonnlm.slow@hcspl.com.sg
w: www.hitachi-capital.com.sg



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref : CC4/LPC19020045/R1ea3n2	
300 BEACH ROAD		Date : 06-04-2020	
#17-04/07 THE CONCOURSESINGAPORE 199555		Code : LPC2	
Policy Particulars :- THIRD PARTY CLAIM			
1.			
Insured Veh.	SLG 6848C	Veh. Inspected	SLN 613R
Policy No.	Z19VP05024459	Coverage (\$)	0.00
Claim No.	19/19/19/VP05/022615	Excess (\$)	0.00
Assign From	GERALD	Assign Date	12/11/2019
Vehicle Particulars & Condition			
2.			
Make & Model	TOYOTA COROLLA ALTIS	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	MR053REH104557483	Colour	BLACK
Odometer	31832	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
Conditions of Tyres			
3.			
	Size	Make	Balance
R/H Front Tyre	215/45 R17	MICHELIN	6 mm
L/H Front Tyre	215/45 R17	MICHELIN	6 mm
R/H Rear Tyre	215/45 R17	MICHELIN	6 mm
L/H Rear Tyre	215/45 R17	MICHELIN	6 mm
Description of Damages			
4.			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.			
DAMAGES SEE DETAILS.			
General Information			
5.			
Accident Date	07/11/2019	Inspection Date	16/12/2019
Survey held at	HITACHI CAPITAL (S) PTE LTD JUN TAIYO SERVICE CENTRE NO. 8 FOURTH LOK YANG ROAD SINGAPORE 629705		
Remarks			
5a.			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.			
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
Estimate Days of Repair			
5b.			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 613R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BOOT LID	NOT NECESSARY	755.00	-
1	BOOT LID LOGO	NOT NECESSARY	60.00	-
1	BOOT LID LOGO "COROLLA"	NOT NECESSARY	48.00	-
1	BOOT LID LOGO "ALTIS"	NOT NECESSARY	45.00	-
1	BOOT LOCK	NOT NECESSARY	382.50	-
2	BOOT HINGE R/L @\$68.00	NOT NECESSARY	136.00	-
10	BOOT INSULATOR CLIP @\$5.00	NOT NECESSARY	50.00	-
1	REAR BUMPER	DEFORMED	486.50	486.50
10	REAR BUMPER CLIP @\$5.00	NECESSARY	50.00	50.00
1	REAR BUMPER RETAINER RH	NECESSARY	120.00	120.00
1	REAR BUMPER REFLECTOR RH	CRACKED	58.00	58.00
1	REAR BUMPER REINFORCEMENT	BENT	395.00	395.00
1	SET REVERSE SENSOR	SERVICEABLE	360.00	-
1	REAR REINFORCEMENT BRACKET RH (ADDITIONAL)	BENT	95.00	95.00
	LESS 25% DISCOUNT		-760.25	-301.12
			2,280.75	903.38
LABOUR				
	PANEL BEAT,CUT,WELD,RE-ALIGN & REPLACE DAMAGED PARTS OF REAR AFFECTED AREA.		1,000.00	500.00
	PUTTY,BLEND AND SPRAY PAINT ON REAR AFFECTED AREA.		1,000.00	750.00
	CHECK WIRING AND ENSURE PROPER FUNCTIONING.		80.00	30.00
	DISMANTLE AND TRANSFER BOOT LID FITTINGS & MECHANISMS TO NEW BOOT LID.	NOT NECESSARY	180.00	-
	REMOVE AND REINSTALL REVERSE SENSORS.		120.00	60.00
	REMOVE AND REINSTALL REAR REVERSE CAMERA.	NOT NECESSARY	120.00	-
	-		-	-
	-		-	-
	-		-	-
			2,500.00	1,340.00
GRAND TOTAL			4,780.75	2,243.38

Report Ref No. CC4/LPC19020045/R1ea3n2



RECOMMENDED COST OF REPAIRS			2,243.38
-----------------------------	--	--	----------

Report Ref No. CC4/LPC19020045/R1ea3n2

MOHAMMED RASUL BIN MOHD YUNUS
Automotive Assessor

HO LEONG CHUAN
Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.