

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
Tel : 64663022 Fax : 68966591
Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

VEHICLE ESTIMATE dated 11/11/2019

LONPAC

ACCIDENT DATE : 07/11/2019 @ 11:30

ATTN: MOTOR CLAIMS DEPT

VRN : SLN613R

MODEL : TOYOTA ALTIS 1.6

TP VRN : SLG6848C

	<u>Qty</u>	<u>S\$ Unit</u>	<u>S\$ Amt</u>	<u>S\$ Labor</u>
<u>PARTS REPLACEMENT</u>				
<u>1. Body Repair</u>				
1 BOOT LID X	1	\$ 755.00	\$ 755.00	
2 BOOT LID LOGO X	1	\$ 60.00	\$ 60.00	
3 BOOT LID LOGO "COROLLA" X	1	\$ 48.00	\$ 48.00	
4 BOOT LID LOGO "ALTIS" X	1	\$ 45.00	\$ 45.00	
5 BOOT LOCK X	1	\$ 382.50	\$ 382.50	
6 BOOT HINGE R/L X	2	\$ 68.00	\$ 136.00	
7 BOOT INSULATOR CLIP X	10	\$ 5.00	\$ 50.00	
8 REAR BUMPER de	1	\$ 486.50	\$ 486.50	
9 REAR BUMPER CLIP ne	10	\$ 5.00	\$ 50.00	
10 REAR BUMPER RETAINER RH ne	1	\$ 120.00	\$ 120.00	
11 REAR BUMPER REFLECTOR RH ch	1	\$ 58.00	\$ 58.00	
12 REAR BUMPER REINFORCEMENT ?	1	\$ 395.00	\$ 395.00	
13 REVERSE SENSOR (SET) 3 X	1	\$ 360.00	\$ 360.00	
			\$ 2,946.00	
Discount -25%			\$ 736.50	
			\$ 2,209.50	
		PARTS TOTAL	\$ 2,209.50	

2. Labour Charges

Panel Beat, Cut, Weld, Re-align & Replace Damaged Parts Of REAR Affected Area	\$ 1,000.00
Putty, Blend And Spray Paint on REAR Affected Area	\$ 1,000.00
Check Wiring and Ensure Proper Functioning	\$ 80.00
Dismantle and Transfer Boot Lid Fittings & Mechanisms to New Boot Lid	\$ 180.00
Remove and Reinstall Reverse Sensors	\$ 120.00
Remove and Reinstall Rear Reverse Camera	\$ 120.00

Rasul
Hp 90010068

LABOURS TOTAL

\$ 2,500.00

Grand Total : \$ 4,709.50

Add 7% GST : \$ 329.67

Nett Total : \$ 5,039.17

No. of repair days: 4

P/P
16/12/19 @ 1410

Resy before print

CUSTOMER SIGNATURE


HITACHI CAPITAL ASIA PACIFIC PTE LTD
(MANAGER)