



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :

www.toyota.com.sg

Toyota Bodycare Centre

No. 2 Pandan Crescent

Singapore 128462

Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	Mr Ang Choon Hin 286 Bishan Street 24 #13-90 Singapore 570286 Mobile: 96182259
	Document No 0	
	Document Date 12/11/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	ANTMT	E1	29/07/2019	SMN9668L	0	50408	650D/SMN9668L
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTEZB3GH10J004711	8ARZ161448	60	Francis Cher T S	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:DMPCSN1930651900 ACC DATE:09.11.19 TOW/DRIVE IN: EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				50. 100.00
2	Z	BP-SLANT SUPPLY SEALANT (NETT)				✓ 100.00
3	B	BP-LAB2 REPLACE AND REFOCUS HEADLAMP.				✓ 180.00
4	B	BP-MECH2 RESET AND REPROGRAMME ECU.				✓ 180.00
5	B	BP-MECH2 REMOVE AIR CON COMPONENTS TO REGAS AND ASSIST REPAIR.				7 360.00
6	B	BP-LAB2 REMOVE ALL NECESSARY DAMAGED PARTS TO REPLACE, REPAIR, STRAIGHTEN FRT BUMPER, BONNET, FRT SUPPORT PANEL, L/F FENDER AND AFFECTED PORTION OF CAR. 720.				2880 3600.00
7	B	BP-RES2 SPRAY PAINT ON DAMAGED AFFECTED 590. PORTION OF CAR.				2360. 2950.00
8	1	T53301-48170 HOOD SUB-ASSY	1.00	1983.90		61- 1983.90
9	2	T75770-48060 MOULDING ASSY, HOOD,	1.00	567.50		mis 567.50

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge the repairer's signature and notify the Repairer of the following: • To resurvey before/after painting • To display damaged parts (if damaged) • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final repair and performance company		Tan Jiah 97495749 Not Authorise 12/11/19 410pm Resurvey before paint 07 days Amount Due sure I know to do Ex: to be advise 4135467

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO SMN9668L

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :

www.toyota.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 120462
Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	Mr Ang Choon Hin 286 Bishan Street 24 #13-90 Singapore 570286 Mobile: 96182259
	Document No 0	
	Document Date 12/11/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	ANTMT	E1	ASU60R	29/07/2019	SMN9668L	0	50408 650D/SMN9668L
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTEZB3GH10J004711	8ARZ161448	60	Francis Cher T S	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
10	3	T53101-48920	GRILLE SUB-ASSY,	1.00	1351.40	1351.40
11	4	T52119-4D946	COVER, FR BUMPER	1.00	811.30	811.30
12	5	S52161-OK040	PIECE, RR BUMPER	4.00	4.10	16.40
13	6	T52535-48040	RETAINER, FR BUMPER	1.00	115.20	115.20
14	7	T52536-48030	RETAINER, FR BUMPER	1.00	115.20	115.20
15	8	T53812-48190	PANEL, FR FENDER, LH	1.00	1446.30	1446.30
16	9	T53102-48081	GRILLE SUB-ASSY,	1.00	417.70	417.70
17	0	T52701-48010	MOULDING SUB-ASSY,	1.00	465.60	465.60
18	1	T52411-48050	GUARD, FR BUMPER	1.00	340.20	340.20
19	2	T89341-48040 C3	SENSOR, ULTRASONIC,	1.00	481.90	481.90
20	3	T81145-48E40	UNIT, HEADLAMP RH	1.00	6714.50	6714.50
21	4	T81185-48E40	UNIT, HEADLAMP LH	1.00	6714.50	6714.50
22	5	T52614-48050	ABSORBER, FR BUMPER	1.00	112.20	112.20
23	6	T52021-48090	REINFORCEMENT	1.00	521.70	521.70
24	7	T52029-48010	REINFORCEMENT	1.00	301.10	301.10
25	8	T52612-48050	ABSORBER, FR BUMPER	1.00	49.80	49.80
26	9	T53208-48091	SUPPORT SUB-ASSY,	1.00	407.30	407.30
27	0	T88460-48160	CONDENSER ASSY	1.00	2044.10	2044.10
28	1	T53289-48021	COVER, RADIATOR	1.00	400.70	400.70
29	2	T90467-07217	CLIP	6.00	2.50	15.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 25,393.50	32,863.50
		Labour 7,470.00	GST 7.00%
		Materials 0.00	2,300.45
		Lubrication/Fluid 0.00	Less 0.00
		Others 0.00	Amount Due 35,163.95

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO SMN9668L

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape

4135468

4135468

DATE: 12/11/2019
TIME: 08:30