

BENZ BODYWORK

53 UBI AVENUE 1. PAYA UBI INDUSTRIAL PARK.
 #05-15. SINGAPORE 408934. TEL: 6844 4617 FAX: 6844 4619
 Email : benzbodykit@gmail.com

AIG ASIA PACIFIC INSURANCE PTE LTD

DATE : 14/11/2019

Car Made/Model: TOYOTA ESQUIRE HYBRID 1.8GI CVT
 Vehicle No. : SMF3201G
 Chassis No. : ZWR800299891
 Policy No. : 2ZROA83271
 Date of Accident : 31/10/2019

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Estimate repair cost to vehicle Regn No. SMF3201G

<u>PARTS LIST :</u>	<u>Remarks</u>	<u>Quantity</u>	<u>Price \$</u>
Front rh door	To repair		0
Rear rh door	To repair		0
Rear rh fender	To Repair		0
Rear bumper	To Repair		0

Rocker Panel RH } X Repair -

Labour:

1) Panel beating charges to damaged areas.	800.00	<i>200</i>
2) Spray painting of all affected parts and areas.	1,200.00	<i>1000</i>
TOTAL LABOUR COST	2,000.00	

TOTAL COST OF REPAIRS **2,000.00**

Total: \$1200
2 Days.
Guo Qiang
LKK

Vic



Tan Joo Meng (DIRECTOR)
 BENZ BODYKIT PTE LTD