

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMK 8940 Y

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$	480.00 ✓	✓
2	To dismantle lhs front door and panel trim. To remove and reinstall lhs wing mirror assy.	S/N \$	300.00 300 ✓	✓
3	To dislodge lhs front wheel suspension. To inspect for further damages and renew accordingly.	S/N \$	1,800.00 ? ✓	✓
4	To dismantle and renew front bumper, lhs front fender, bonnet and lhs headlight. To repair lhs front door. Re-organise crash management components. Reinstall all parts removed.	\$	3,500.00 1750 ✓	✓
5	To respray front bumper, lhs front fender, bonnet and lhs front door.	\$	3,700.00 2000 2200 ✓	✓
6	To renew lhs front rim and carry out wheel alignment.	S/N \$	280.00 ✓	✓
7	To tow vehicle from accident scene	S/N \$	280.00 X 11 ✓	✓
8	To carry out diagnostic checks.	S/N \$	192.00 ✓	✓
TOTAL LABOUR CHARGES		:	\$ 10,532.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMK 8940 Y

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>de-</i>	\$ 1,999.00	1,599.20
2	FRONT BUMPER FIXING PARTS <i>? X8V</i>	\$ 531.00	
3	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>X8V</i>	\$ 191.00	
4	FRONT BUMPER AIR GUIDE - LH <i>? X8V</i>	\$ 56.00	
5	FRONT BUMPER AIR GUIDE GRILLE - LH <i>? X8V</i>	\$ 123.00	
6	FRONT BUMPER CARRIER <i>? X8V</i>	\$ 733.00	
7	FRONT BUMPER FOAM FILLER PIECE <i>? X8V</i>	\$ 113.00	
8	FRONT BUMPER GUIDE SECTION - LH <i>? N8V</i>	\$ 33.00	26.08
9	FRONT PARKING AID SENSOR - INNER / OUTER <i>? X8V</i>	\$ 231.00	
10	FRONT PARKING AID SEAL RING <i>u-</i> <i>4</i>	\$ 12.00	10.24
11	HORN - LH HIGH TONE <i>X8V</i>	\$ 37.00	
12	SPRING SHACKLE - LH <i>X8V</i>	\$ 26.00	
13	FRONT FENDER - LH <i>bf</i>	\$ 700.00	559.60
14	FRONT FENDER ATTACHMENT PARTS <i>X8V</i>	\$ 183.00	
15	FRONT FENDER CLOSING ELEMENT - LH <i>? C8V</i>	\$ 45.00	36.00
16	FRONT FENDER BRACKET - LH <i>? bf</i>	\$ 32.00	25.20
17	FRONT FENDER BRACE - LH FRONT <i>? bf</i>	\$ 107.00	85.60
18	FRONT FENDER DEFORMATION ELEMENT BRACKET - LH <i>? H8V</i>	\$ 45.00	35.60
19	FRONT FENDER BRACKET - LH <i>? X8V</i>	\$ 29.00	
20	FRONT WHEEL HOUSING LINER - LH <i>de-</i>	\$ 223.00	178.40
SUB TOTAL SPARE PARTS CHARGES		\$ 5,449.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMK 8940 Y

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
21	WHEEL HOUSING LINER ATTACHMENT PARTS <i>? Xsuc</i>	\$ 211.00	
22	WHEEL SPOILER - LH <i>de /</i>	\$ 66.00	<i>52.30</i>
23	WHEEL SPOILER TRIM - LH <i>? Xsuc</i>	\$ 32.00	
24	STONE CHIP GUARD - LH <i>X suc</i>	\$ 46.00	
25	BONNET <i>bt /</i>	\$ 2,554.00	<i>2013.20</i>
26	BONNET ATTACHMENT PARTS <i>? Xsuc</i>	\$ 373.00	
27	BONNET IMPACT PROTECTION - CENTRE / LH / RH <i>nee /</i>	3 \$ 75.00	<i>59.44</i>
28	FENDER LEDGE COVER - LH <i>X suc</i>	\$ 28.00	
29	FENDER TOP LEDGE COVER - LH <i>X suc</i>	\$ 21.00	
30	LED HEADLIGHT - LH <i>ca /</i>	\$ 7,087.00	<i>5669.60</i>
31	LIFT CYLINDER - LH <i>? Xsuc</i>	\$ 192.00	
32	FRONT ALUMINIUM RIM - LH <i>cut /</i>	\$ 651.00	<i>520.80</i>
33	ALUMINIUM RIM RUBBER VALVE <i>ne /</i>	<i>4 /</i> \$ 13.00	<i>9.92</i>
34	FRONT WISHBONE LINK - LH <i>? bt /</i>	\$ 491.00	<i>392.40</i>
35	FRONT SUSPENSION GUIDE - LH <i>? bt /</i>	\$ 861.00	<i>688.40</i>
36	UPPER CONTROL ARM - LH FRONT / REAR <i>? bt /</i>	2 \$ 932.00	<i>745.60</i>
37	WHEEL BEARING HOUSING - LH <i>? bt /</i>	\$ 884.00	<i>707.20</i>
38	SWIVEL JOINT <i>? bt /</i>	\$ 175.00	<i>140.00</i>
39	WHEEL HUB <i>? bt /</i>	\$ 451.00	<i>360.40</i>
40	DOUBLE ANGLED BALL BEARING <i>? ne /</i>	\$ 232.00	<i>185.60</i>
SUB TOTAL SPARE PARTS CHARGES		: \$ 15,375.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMK 8940 Y

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
41	SUSPENSION FORKS - LH ? bt ✓	\$ 239.00	190.80
42	COUPLING ROD ? bt ✓	\$ 123.00	98.00
43	GAS SHOCK ABSORBER ? xs ✓	\$ 276.00	
44	DRIVE SHAFT ? xs ✓	\$ 2,422.00	
45	TRACK ROD ? bt ✓	\$ 90.00	71.68
46	TIE ROD END ? bt ✓	\$ 180.00	144.00
47	SUNDRIES ? new ✓	\$ 400.00	295.20
TOTAL SPARE PARTS CHARGES		\$ 24,554.00	
TOTAL LABOUR CHARGES		\$ 10,532.00	
GRAND TOTAL		\$ 35,086.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

: RASUL - Hp 90010068

Surveyed Date

: 11/11/19 @ 1520

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

:

7 days / p/p + 3 = 10 days
Repairing before paint

Please Note

- : This estimate is based on visual inspection of the affected
Should we require further labour charges and spare parts
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/TP/1333/2019/NS 6-Jan-20 Glory Tan 1 of 1 SMK 8940 Y A4 Sedan 2.0 TFSI 8W
Quantity	Description	Unit Price	Amount
<u>Labour</u> 1	Renew air cond pipe. Vacuum and regas.	S/N \$ 480.00	\$ 480.00
TOTAL		\$ 480.00	\$ 480.00

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/TP/1333/2019/NS 14-Nov-19 Glory Tan 1 of 1 SMK 8940 Y A4 Sedan 2.0 TFSI 8W
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Assembly carrier	\$ 1,726.00	\$ 1,380.80 X su
2	Aircon refrigerant pipe	\$ 476.00	\$ 380.40 bt ✓
TOTAL		\$ 2,202.00	\$ 1,761.20

For Premium Automobiles Pte Ltd

Authorised Signature