COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO: SHC 1868X

MAKE

DATE 11/11/2019 10:25

CHINA

Qty	Parts Description/ Labour				AIIIIIII	
	/ ~	Type	Unit Price	\$	2,256.40	1
	Front Door (LH) × (R) Front Door Mirror Assy (LH)			\$	670.00	
	Front Door Mirror Assy (LH)			Ψ	070.00	
	SUB TOTAL			\$	2,926.40	1
	LESS 20%			\$	585.28	
	DISCOUNTED TOTAL			\$	2,341.12	1
	DISCOUNTED TOTAL			Φ	2,571.12	1
	Front Door Comfort Logo (LH)			\$	75.00	
	Front Door Advertisement Logo (LH)			\$	100.00	Nett
				\$	175.00	-
						1
	Labour Charge					
	Panel Beating			\$	350.00	329
	Spray Painting Charge				350.00	\$2
				\$		1.
	Wiring Charge			\$	50.00	XIII
	Tuff Kote			\$	50.00	1
	Towing Charge			\$	60.00	
	Transfer of Door			\$	80.00	\$ 2
	TOTAL LABOUR			\$	940.00	
	ESTIMATE TOTAL		Pared Lice 2017 Pared Lice 2017 Pared Lice 2017 Roughly Pared Red 20	\$	3,456.12	1
	LKK Auto Consultants hence notify					
	the Repairer of the following:		MILEC)	Ju.		1
	To resurvey before/after spray painting		count 20		a conte	
	To display damaged part(s) during resurvey Parts prices are subject to confirmation		1110	20	Fle	der
	Third party survey is on a "Without Prejudice" basis		Illi, worn	208	ave Por	
	No illegal modification(s) is allowed		127°	100	2	
	Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company		for Les	*		
	A Louis de de Consiste	7-5	IN ROY		Ofon	
	Acknowledged by Repairer		Bankon	1	X	
	Signature: Date:		200	1		
			& en			
	This is an initial estimate based on a visual inspection of the	e above v	ehicle. The final repa	ir qua	intum will	

COMFORTDELGRO ENGINEERING

A member of COMFORTDELGRO

Name of Attending Staff/Guard

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline +65 6383 6280 Facsimile +65 6280 9755

Service Centres
205 Braddel Road Singapore 57970
45 Pandarn Road Singapore 509288
383 Sin Ming Drive Singapore 57877
5 Sungel Kadut Way Singapore 728791
320 Ubl Road 3 Singapore 408649
24 Senoko Loop Singapore 758156

@6553 1111 SPARKO Assist

Signature of Attending Staff/Guard

CUSTOMER'S COPY



JOB REQUISITION FOR BREAKDOWN / TOWING SERVICE

3. Vehicle Type: Private Taxi (CTPL/CCPL Fleet STK (Boon Lay)	4. Type of Towing: Normal Tow King Dolly Flat Bed Crane-up				
5. Nature of Service: Jumpstart Recovery Change Tyre / Bat	6. Parts Replaced/Remarks:				
Pandan Ubi Cycle & Carriage (PD)	8. Vehicle Tow - In Workshop: Smoky Exhaust Wheel Jammed Overheating Steering Faulty Brake Faulty Alternator Faulty Starting Problem Loss Power Accident Engine Stalled Return Taxi				
Fuel Level : F 1/4 1/2 3/4 E OK Not tested					
TZ YISHUN [TOWING	#: Cracked X: Dented /: Scatched O: Missing Signature of Customer				
Global Positioning System (Car Care™ will not be held lial ow nor proceed with the reparation	(GPS), audio compact disk, thumbdrive, carpark coupons, able for such losses. Pairs in SPARK Car Care™. Signature of Customer				
	Private				

Date & Time of Arrival