

HO BENG TRADING

Block 3020A Ubi Road 1 # 01-33 Singapore 408714

PRITAM MISRA
BLOCK 3020A UBI ROAD 1
01-33
Singapore 408714

12nd Nov 2019

TP FWD.

Xiao Tony

Accident date: 31st OCT 2019

Estimated repair cost for vehicle no: SLL6636X Hyundai TL Tucson 2.0 (2017)

S/n	Qty	Items	U/price	Amount
1	1	Front L/H fender <i>Dented</i>		\$695.20 ✓
2	1	Front L/H fender cowling <i>2 new</i>		\$275.30 ✓
3	8	Front L/H fender cowling clips	\$6.50	\$52.00 ✓
4	1	Front fender mud -shiled -LH <i>new</i>		\$112.10 ✓
5	1	fender mud shiled clips <i>new</i>	\$12.90	\$12.90 ✓
6	1	Front L/H headlamp <i>2 new</i>		\$885.00 ✓
7	1	Front tyre -LH <i>2 new</i>		\$350.00 ✓
8	1	Front rim-LH		\$550.00 ✓
9	1	Front L/H shock absorber <i>2 new</i>		\$425.10 ✓
10	1	Front L/H lower arm		\$380.20 ✓
11	1	Front L/H Knuckle arm		\$360.80 ✓
12	1	Front L/H Knuckle arm bearing <i>new</i>		\$102.80 ✓
13	1	Front bumper <i>Dented</i>		\$882.30 ✓
14	8	Front bumper clips <i>new</i>	\$7.50	\$60.00 30
15	2	Front Bumper Side Bracket <i>LH new</i>	\$115.00	\$230.00 65
16	1	Front bumper fog lamp -LH <i>new</i>		\$255.00 ✓
17	1	Front bumper fog lamp cover -LH <i>new</i>		\$155.00 ✓
18	1	Front bumper lower cover <i>new</i>		\$288.50 ✓

Subtotal :- \$6,072.20

Labour charges

To Remove & Refix undercarriage

\$280.00 ✓

To check wheel alignment computer

\$120.00 ✓

To Check Wiring System

\$80.00 30

\$120.00 ✓

\$600.00 400

\$600.00 400

Subtotal :- \$1,800.00

Total :- \$7,872.20

LKK Auto Consultants hence notify the Repairer of the following:

- To Panel Beating
- To resurvey before/after Spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total: 23880

L/S: 1.9K

Adrian Lij

W/S 12/11/19

04 Days.