

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 18795

## Telefax

Estimate : Accident Repairs  
Workshop : Ubi Road 1  
Contact No : 6366 2323  
Fax No : 6841 1183  
Reference : PA/OD/1344/2019/NS  
Date : 11-Nov-19

**Vehicle NOT IN workshop. Kindly arrange for survey.**

### AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Yeow Tee Leng  
Address : 30 Lorong 107 Changi  
#05-04  
Singapore 426446  
Telephone : HP +65 96398787  
Type of Claim : Own Damage Claims  
Policy No. :  
Vehicle No : **SMQ 392 A**  
Model Code : A4 Sedan 2.0 TFSI 8W  
Model / Year : Oct-19  
Engine No : CVK 086195  
Chassis No : WAUZZZF41KA104681  
Mileage :  
Date In :  
Estimated By : Johnny Boo / Allan Wu  
Accident Date : 9-Nov-19  
Place of Accident : Sheares Avenue Towards ECP

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle. SMQ 392 A

<u>S/n</u>	<u>Nature of Jobs</u>		<u>Estimated Charges</u>	<u>Surveyor's Recommendations</u>
1	To remove and transfer rear parking aid and rear lid kick sensor.	S/N \$	360.00	✓
2	To renew rear windscreen and rhs 1/4 glass to facilitate fender renewal.	S/N \$	600.00	✓
3	To install rear windscreen solar film.	S/N \$	400.00	✓
4	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N \$	1,400.00	✓
<b>SUB TOTAL LABOUR CHARGES</b>		<b>:</b>	<b>\$ 2,760.00</b>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle. SMQ 392 A

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
5	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Doslodge roof liner and disengage curtain airbag etc.	S/N \$ 1,400.00 ✓	
6	To dismantle rear bumper and rear lid. To renew rear bumper. Cut out and weld rhs rear fender. Re-organise crash management components. Reinstall all parts removed.	\$ <del>5,600.00</del> 3000 ✓	
7	To respray rear bumper, rhs rear fender, rhs sill panel, door entrances, roof channel, drain panel and end panelling. To carry out stone chip treatment and joint sealer works.	\$ <del>4,800.00</del> 2200 ✓	
8	To carry out diagnostic check.	S/N \$ 192.00 ✓	
<b>TOTAL LABOUR CHARGES</b>		<b>: <u>\$ 14,752.00</u></b>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

Telefax

## Material List for Accident Vehicle Reqn No. SMQ 392 A

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	REAR BUMPER GUIDE SECTION - RH <i>new</i>	\$ 41.00	✓
2	REAR FENDER - RH <i>dented</i>	\$ 2,443.00	✓ 1954.40
3	REAR WINDSCREEN <i>new</i>	\$ 1,049.00	✓ 839.20
4	SIDE WINDOW - RH <i>new</i>	\$ 561.00	✓ 448.40
5	PRIMER <i>new</i>	\$ 19.00	✓ 14.88
6	LED TAIL LIGHT - RH OUTER <i>cracked</i>	\$ 931.00	✓ 744.80
7	TAIL LIGHT TRIM - RH OUTER <i>ut</i>	\$ 27.00	✓ 21.52
8	LED TAIL LIGHT - RH INNER <i>ut</i>	\$ 931.00	✓ 744.80
9	TAIL LIGHT TRIM - RH INNER <i>ut</i>	\$ 27.00	✓ 21.52
10	REAR WHEEL HOUSING LINER - RH <i>new</i>	\$ 223.00	+
11	WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	\$ 211.00	+
12	REAR BUMPER <i>Repis</i>	\$ 2,491.00	✓ 1992.80
13	REAR BUMPER FIXING PARTS <i>new</i>	\$ 416.00	+
14	REAR BUMPER SECURING STRIP <i>new</i>	\$ 203.00	+
15	ACRYLIC SEALANT	S/N \$ 180.00	✓✓
16	CAVITY WAX	S/N \$ 140.00	✓✓
17	STONE CHIP	S/N \$ 180.00	✓✓
18	METAL FILLER POWDER	S/N \$ 280.00	✓✓
19	REAR WINDSCREEN SEALANT	S/N \$ 200.00	✓✓
20	1/4 GLASS SEALANT	S/N \$ 100.00	✓✓
21	SUNDRIES <i>new</i>	\$ 400.00	? 6.64 ✓

**TOTAL SPARE PARTS CHARGES**

: \$ 11,053.00

**TOTAL LABOUR CHARGES**

: \$ 14,752.00

**GRAND TOTAL**

: \$ 25,805.00

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

**Name** : Adrian   
**Surveyed Date** : 12/11/19.  
**Authorised Date** :  
**Excess Cost** :  
**Liability** :  
**Remarks** : not Authorised, 12 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

**Please Note** : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant

# Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

## Supplementary Estimate 1

GST Reg No. 19-9902271-W

**AIG Asia Pacific Insurance Pte Ltd**  
78 Shenton Way  
#07-16 AIG Building  
Singapore 079120  
Attn: Mr. Adrian Ling - Motor Claims Dept  
Tel: 6841 0055 - Fax: 6256 4315

Estimate No. PA/OD/1344/2019/NS  
Date 25-Nov-19  
Service Advisor Glory Tan  
Pages 1 of 1  
Regn No SMQ 392 A  
Model No A4 Sedan 2.0 TFSI 8W

Quantity	Description	Unit Price	Amount
<b>Parts</b>			
1	Audi emblem	\$ 113.00	✓ 90.
2	A4 emblem	\$ 87.00	✓ 69.28
		<u>\$ 200.00</u>	
<b>Labours</b>			
1	To respray rear lid.	\$ 1,050.00	550 /
2	To respray lhs rear fender.	\$ 1,050.00	550 /
		<u>\$ 2,100.00</u>	
		<u>\$ 200.00</u>	
	<b>GRAND TOTAL</b>	<u>\$ 2,300.00</u>	

For Premium Automobiles Pte Ltd

Adrian L  
26/11/19.  
H.S.

\_\_\_\_\_  
Authorised Signature