

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 18795

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1344/2019/NS
Date : 11-Nov-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

*Hi Adrian
12 days exclude 2 Sundays - jb
10-Feb-20*

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Yeow Tee Leng
Address : 30 Lorong 107 Changi
#05-04
Singapore 426446
Telephone : HP +65 96398787
Type of Claim : Own Damage Claims
Policy No. :
Vehicle No : **SMQ 392 A**
Model Code : A4 Sedan 2.0 TFSI 8W
Model / Year : Oct-19
Engine No : CVK 086195
Chassis No : WAUZZZF41KA104681
Mileage :
Date In :
Estimated By : Johnny Boo / Allan Wu
Accident Date : 9-Nov-19
Place of Accident : Sheares Avenue Towards ECP

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMQ 392 A

<u>S/n</u>	<u>Nature of Jobs</u>		<u>Estimated Charges</u>	<u>Surveyor's Recommendations</u>
1	To remove and transfer rear parking aid and rear lid kick sensor.	S/N \$	360.00	\$ 360.00
2	To renew rear windscreen and rhs 1/4 glass to facilitate fender renewal.	S/N \$	600.00	\$ 600.00
3	To install rear windscreen solar film.	S/N \$	400.00	\$ 400.00
4	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N \$	1,400.00	\$ 1,400.00
SUB TOTAL LABOUR CHARGES			\$ 2,760.00	\$ 2,760.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMQ 392 A

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
			\$ 2,760.00
5	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Doslodge roof liner and disengage curtain airbag etc.	<i>c/f</i> S/N \$ 1,400.00	\$ 1,400.00
6	To dismantle rear bumper and rear lid. To renew rear bumper. Cut out and weld rhs rear fender. Re-organise crash management components. Reinstall all parts removed.	\$ 5,600.00	\$ 3,000.00
7	To respray rear bumper, rhs rear fender, rhs sill panel, door entrances, roof channel, drain panel and end panelling. To carry out stone chip treatment and joint sealer works.	\$ 4,800.00	\$ 2,200.00
8	<i>Added labour charges - see attached</i>	\$ 2,100.00	\$ 1,100.00
9	To carry out diagnostic check.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 16,852.00	\$ 10,652.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMQ 392 A

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	REAR BUMPER GUIDE SECTION - RH	\$ 41.00	
2	REAR FENDER - RH	\$ 2,443.00	\$ 1,954.40
3	REAR WINDSCREEN	\$ 1,049.00	\$ 839.20
4	SIDE WINDOW - RH	\$ 561.00	\$ 448.40
5	PRIMER	\$ 19.00	\$ 14.88
6	LED TAIL LIGHT - RH OUTER	\$ 931.00	\$ 744.80
7	TAIL LIGHT TRIM - RH OUTER	\$ 27.00	\$ 21.52
8	LED TAIL LIGHT - RH INNER	\$ 931.00	\$ 744.80
9	TAIL LIGHT TRIM - RH INNER	\$ 27.00	\$ 21.52
10	REAR WHEEL HOUSING LINER - RH	\$ 223.00	
11	WHEEL HOUSING LINER ATTACHMENT PARTS	\$ 211.00	
12	REAR BUMPER	\$ 2,491.00	\$ 1,992.80
13	REAR BUMPER FIXING PARTS	\$ 416.00	
14	REAR BUMPER SECURING STRIP	\$ 203.00	
15	ACRYLIC SEALANT	S/N \$ 180.00	\$ 180.00
16	CAVITY WAX	S/N \$ 140.00	\$ 140.00
17	STONE CHIP	S/N \$ 180.00	\$ 180.00
18	METAL FILLER POWDER	S/N \$ 280.00	\$ 280.00
19	REAR WINDSCREEN SEALANT	S/N \$ 200.00	\$ 200.00
20	1/4 GLASS SEALANT	S/N \$ 100.00	\$ 100.00
21	<i>Added parts - see attached</i>	\$ 200.00	\$ 159.28
22	SUNDRIES	\$ 400.00	\$ 6.64
TOTAL SPARE PARTS CHARGES		\$ 11,253.00	\$ 8,028.24
TOTAL LABOUR CHARGES		\$ 16,852.00	\$ 10,652.00
GRAND TOTAL		\$ 28,105.00	\$ 18,680.24

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/1344/2019/NS 25-Nov-19 Glory Tan 1 of 1 SMQ 392 A A4 Sedan 2.0 TFSI 8W
Quantity	Description	Unit Price	Amount
Parts			
1	Audi emblem	\$ 113.00	\$ 90.00
2	A4 emblem	\$ 87.00	\$ 69.28
		\$ 200.00	\$ 159.28
Labours			
1	To respray rear lid.	\$ 1,050.00	\$ 550.00
2	To respray lhs rear fender.	\$ 1,050.00	\$ 550.00
			\$ 1,100.00
	Labours total	\$ 2,100.00	\$ 1,100.00
	Parts total	\$ 200.00	\$ 159.28
	GRAND TOTAL	\$ 2,300.00	\$ 1,259.28

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant