

Not Notch in  
 04/11/19  
 Presumy After Paint  
 4-5 day,



File No: SH/2019/091/11/004/TP  
 Date: 11-November-2019

Wong Peng Mun  
 Blk 293 Bishan St 22 #23-87  
 Singapore 570293

8 3631.61

Estimated cost of repair for vehicle no: **SGC8278P** Honda Vezel  
 Accident involving vehicle no: **SGC8278P** & **SKW7279R** on **09.11.2019**

| Description                                                                                                                                                                                                                                                              | Quantity | Cost Price                     |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|--------------------------------|
| Tail gate                                                                                                                                                                                                                                                                | 1        | \$ Bu 953.30 ✓                 |
| Tail gate inner handle cover                                                                                                                                                                                                                                             | 1        | \$ Bu 85.60 ✓                  |
| Tail gate inner trim board                                                                                                                                                                                                                                               | 1        | \$ Bu 265.30 ✓                 |
| Tail gate badge "VEZEL"                                                                                                                                                                                                                                                  | 1        | \$ Bu 68.20 ✓                  |
| Tail gate weatherstrip                                                                                                                                                                                                                                                   | 1        | \$ 82.65 sn 165.30 50/100 ✓    |
| Tail gate inner lock                                                                                                                                                                                                                                                     | 1        | \$ Bu 195.20 ✓                 |
| Rear windscreen moulding                                                                                                                                                                                                                                                 | 1        | \$ Bu 128.00 ✓                 |
| LH outer tail lamp                                                                                                                                                                                                                                                       | 1        | \$ Bu 652.00 X                 |
| LH inner tail lamp                                                                                                                                                                                                                                                       | 1        | \$ Bu 265.40 X                 |
| Rear end panel                                                                                                                                                                                                                                                           | 1        | \$ R 485.60 X Repair           |
| Rear end panel inner trim garnish                                                                                                                                                                                                                                        | 1        | \$ Bu 115.00 X                 |
| Rear bumper                                                                                                                                                                                                                                                              | 1        | \$ Bu 780.70 X                 |
| Rear bumper clips (1 set)                                                                                                                                                                                                                                                | 1        | \$ Bu 4.00 ✓                   |
| LH rear bumper top garnish                                                                                                                                                                                                                                               | 1        | \$ Bu 295.00 ✓                 |
| Rear bumper reinforcement                                                                                                                                                                                                                                                | 1        | \$ NIP 685.50 X                |
| LH rear bumper reflector                                                                                                                                                                                                                                                 | 1        | \$ Bu 161.50 X                 |
|                                                                                                                                                                                                                                                                          |          | \$ 5,305.60                    |
|                                                                                                                                                                                                                                                                          | less 20% | \$ 1,061.12                    |
|                                                                                                                                                                                                                                                                          |          | \$ 4,244.48                    |
| Rear windscreen sealant                                                                                                                                                                                                                                                  | 1        | \$ S. Nett Bu 60.00 40/50 ✓    |
| Rear windscreen inner seal                                                                                                                                                                                                                                               | 1        | \$ S. Nett Bu 28.00 ✓          |
| Rear parking sensors (1 set)                                                                                                                                                                                                                                             | 1        | \$ S. Nett Bu 260.00 200/200 ✓ |
| Rear number plate                                                                                                                                                                                                                                                        | 1        | \$ S. Nett Bu 45.00 X          |
| To remove and reinstall rear windscreen and conduct water leak test                                                                                                                                                                                                      |          | \$ 120.00 ✓                    |
| To remove rear damaged parts, to jack out rear end panel and rear floor panel and cut out body panel, to reweld, reshape and repair rear end panel, rear floor panel, rear body panel, to straighten out rear chassis member and adjust rear body and tailgate alignment |          | \$ 800.00 500 ✓                |
| To spray paint affected rear and inner damaged portion inclusive of preparatory works and material                                                                                                                                                                       |          | \$ 850.00 500 ✓                |
| To perform computer diagnostic on drivetrain, ABS systems, parking system, and clear fault codes                                                                                                                                                                         |          | \$ 120.00 50 ✓                 |
|                                                                                                                                                                                                                                                                          |          | \$ 6,527.48                    |

T/Party: FWD Singapore Pte Ltd

Wong Peng Mun  
Blk 293 Bishan St 22 #23-87  
Singapore 570293

File No.: SH/2019/091/11/004/TP  
Date: 13-November-2019

Supplementary estimated cost of repair for vehicle no: SGC8278P Honda Vezel  
Accident involving vehicle no: SGC8278P & SKW7279R on 09.11.2019

| Description              | Quantity | Cost Price                                                         |
|--------------------------|----------|--------------------------------------------------------------------|
| Rear panel buzzer sensor | Less 20% | <div>\$ CM 185.60 ✓</div> <div>\$ 37.12</div> <div>\$ 148.48</div> |

T/Party: FWD Singapore Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: