

Our Ref : SH/2019/091/11/004/TP

Date : 23 April 2020

The Motor Claims Department
FWD INSURANCE - SINGAPORE
TEMASEK BOULEVARD
SUNTEC TOWER FOUR
SINGAPORE 038986

Dear Sir / Madam,

RE : Accident Involving SGC8278P & SKW7279R on 11.11.2019

I forward herewith copies of the following documents for claiming against your insured for my loss of use :-

Cost Of Repair - Invoice No: AR202004-0083	:	S\$ 3,902.94
Loss Of Use (\$ 80.00 x 7 days)	:	S\$ 560.00
LTA Search Fee	:	S\$ 2.00
		<u>S\$ 4,464.94</u>


Your co-operation and prompt settlement towards this matter are much appreciated.

Kindly acknowledge the receipt of this letter.

Thank you very much for your kind attention.

Yours faithfully,

encl.



LETTER OF AUTHORITY

To: FWD Insurance-
Singapore

ACCIDENT INVOLVING SGC8278P & SKW 7279R ON
11.11.2019 (Date) ALONG Causeway from Singapore
to Johor Bahru (Location)

I, Wong Peng Mun NRIC no. S13680026
of BLK 293 #23-87 Biehan Street 22, S(570293) (Address),
owner of Motor Vehicle Registration No. SGC8278P do hereby
authorise M/s S & H Motor Pte Ltd to be my agent and representative to correspond,
negotiate and settle, on my behalf, my claim against the parties involved in the above
mentioned accident.



Signature of Owner & Date

Tax Invoice No.:

AR202004-0083



WONG PENG MUN

File No: SH/2019/091/11/004/TP

BLK 293 #23-87

Date: 22-April-2020

BISHAN STREET 22

SINGAPORE 570293

Cost of repair for vehicle no: SGC8278P

Model: HONDA VEZEL 1.5XA

Accident involving vehicle no: SGC8278P & SKW7279R on 11-November-2019

Description

Tail gate	\$	953.30
Tail gate inner handle cover	\$	85.60
Tail gate inner trim board	\$	265.30
Tail gate badge 'VEZEL'	\$	68.20
Tail gate inner lock	\$	195.20
Rear windscreen moulding	\$	128.00
Rear bumper	\$	508.50
Rear bumper clips @ set	\$	24.00
LH rear bumper	\$	245.00
Rear panel buzzer sensor	\$	185.60
	\$	2,658.70
Less 20%	\$	-531.74
	\$	2,126.96
Rear windscreen sealant	\$	40.00
Rear windscreen inner seal	\$	28.00
Rear parking sensors @ set	\$	200.00
Tail gate weatherstrip	\$	82.65
To remove and reinstall rear windscreen and conduct water leak test.	\$	120.00
To remove rear damaged parts, to jack out rear end panel and rear floor panel and cut out body panel, to reweld, reshape and repair rear end panel, rear floor panel, rear body panel, to straighten out rear chassis member and adjust rear body and tailgate alignment.	\$	500.00
To spray paint affected rear and inner damaged portion inclusive of preparatory works and material.	\$	500.00
To perform computer diagnostic on drivetrain, ABS system, parking system and clear fault codes.	\$	50.00
Cost of Repair	\$	3,647.61
7% GST	\$	255.33
	\$	3,902.94

T/Party: FWD INSURANCE - SINGAPORE

Tax Invoice No.:

AR202004-0083



WONG PENG MUN

BLK 293 #23-87
BISHAN STREET 22
SINGAPORE 570293

File No: SH/2019/091/11/004/TP

Date 22-April-2020

Cost of repair for vehicle no: SGC8278P

Model: HONDA VEZEL 1.5XA


Accident involving vehicle no: SGC8278P & SKW7279R on 11-November-2019

Description

Received By

No signature is required as this is a computer generated invoice

Page 2 of 2



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-19-184981
Date of Request: 09/11/2019

Your Ref No: Online Purchase

S & H Motor Pte Ltd
160 Sin Ming Drive #07-02
Sin Ming AutoCity
Singapore 575722

Dear Sir/Madam,

Enquiry Date: 09/11/2019
Enquiry By: Doris Ang Hui Leng
TP Vehicle No: SKW7279R
Accident Date: 09/11/2019

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SKW7279R	FWD Singapore Pte. Ltd.	13/11/2018-12/11/2019	6727 5700

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-19-184981
Date of Request: 09/11/2019

Your Ref No: Online Purchase

S & H Motor Pte Ltd
160 Sin Ming Drive #07-02
Sin Ming AutoCity
Singapore 575722

Dear Sir/Madam,

Enquiry Date: 09/11/2019
Enquiry By: Doris Ang Hui Leng
TP Vehicle No: SKW7279R
Accident Date: 09/11/2019

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

TP Insurer Enquiry

ENQUIRY DETAILS

Accident Date	09/11/2019	  
NRIC/FIN or Co. Reg. No.		
Vehicle No.	SKW7279R	

Policy Details

Doris Ang Hui Leng [S & H Motor Pte Ltd]	09/11/2019 12:33 SKW7279R	09/11/2019	FWD Singapore Pte. Ltd. 6727 5700 13/11/2018-12/11/2019	Refresh
---	---------------------------	------------	---	-------------------------

Note:

- All submitted enquiry will be recorded and you can refer back from the History.