

ASSIGNMENT

Surveyor:

KENNETH

DOI: 18/11/2019

Date / Time: 12.11.2019

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No: GBG 8730M

Claim No.: 19/19/19/VC05/022619

Name of Insured: ACE INTEGRATED PTE LTD

Policy No.: Z19VC05002418

Insured Tel No: HP:

Make / Model: NISSAN CABSTAR

Excess Sec II :S\$ D.O.A: 09/11/2019 09:40

Place of Accident: CTE > ORCHARD ROAD

Is driver the owner? (YES / ☒ NO) Nature of Accident:

If NO: Driver Name / Age: TAN POH LEE

OI GIA REPORT: ☒ YES / NO : TP GIA REPORT: ☒ YES / NODriver Tel No.: 90043341 (V/L: ☒ YES / NO)

Insured Liability: % Final ? Yes / No

SLV 7552U

INSRS:
WSP: TROPICAL
Tel: SUCCESS
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time	SLV 7552U - X	GBG8730M - X	STAGE	DATE / PIC
			Non-Reporting ltr (1st):	
			Non-Reporting ltr (2nd):	
			Non-Reporting ltr (Final):	
			Notification ltr (if non-pickup):	
			Call OI:	
			After call ltr to OI:	
			Documentation Check List: Handler	Typist
			Notification ltr (if non-pickup)	☐
			After call ltr to OI:	☒
			Authorisation To Act:	☒
			Release Voucher:	☒
			Final Repair Bill:	☒
			Car Rental Invoice:	☒
			Towing Invoice:	☐
			LTA / GIA:	☒
			Medical Bill:	☐
			PIR:	☐
			Mandate/Reject Instruction:	☒
			LOD	☐
			Payment Breakdown Form:	☐
			Post-Repair Photos:	☐
			Others:	☐
20/11/19	- FILE REVIEWED. OLD RATE-ENDED TP.			
	- EMAIL LIABILITY CLERK			
	- FINALISED			
	- ORIGINAL TP LOD IN			
18/01/2020	- SEND PA TO LPC			
	- TYPE REPORT FOR MANDATE APPROVAL			
	- REPORT DONE			
05/03/2020	- BOOK MANDATE APPROVAL TO LPC			
13/03/2020	- LPC APPROVED MANDATE			
14/03/2020	- SEND 1st OFFER TO TP			
27/03/2020	- RECEIVED ORIG. DV. TP ACCEPTED OFFER.			
	- ALL DOCS IN ORDER.			
	- TO CLOSE			
PRELIMINARY ADVICE	Date/Time: 18/01/2020	Sent By: VIC		
FINALIZATION	Date/Time:	Confirm with:	Confirm by:	
Repair Cost: P/P	S\$ 2,300.56 (4 days) Reduction: 72 %		Email ☐ Call ☐	
FINAL SETTLEMENT	Date/Time: 20/03/20	Confirm with: MIC SIM	Email ☒ Call ☐	
Final Liability:	% 100 (A Free / Assessed) BOLA S/N No.:	27		
Repair Cost: (w/gst)	S\$ 2,300.56			(OLD RATE-ENDED TP)
Loss of Rental (LOR):	S\$ 400.00 (4 days) X \$100.00			
Loss of Use (LOU):	S\$ - (5 x days)			
Loss of Income (LOI):	S\$ - (5 x days)			
LOR only ☒ LOU only ☐	LOR + LOU ☐ LOR + LOI ☐ (Tick only one)			
GIA/LTA Search	S\$ 7.19			
Medical:	S\$ -			
Disbursement:	S\$ - (e.g. Tow/ Independent)			
Legal Cost	S\$ -			
Total:	S\$ 2,708.05	Global Sum S\$: 2,700.00		
FINAL PAYMENT	Date/Time:	Confirm with:	Email ☐ Call ☐	
Payee 1:	S\$ 2,700.00	Name 1: TROPICAL TECH AUTOMOBILE SERVICES		
Payee 2: (Strike if N.A.)	S\$ -	Name 2: -		
Payee 3: (Strike if N.A.)	S\$ -	Name 3: -		

AM amount different
to affixed amount.
- LOR done



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: 19/19/19/VC05/022619
Our ref: CC4/LPC19020074/Kha3

Date: 18.02.2020

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SLV 7552U

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 09.11.2019 at the premises of M/s TROPICAL TECH AUTOMOBILES SERVICES and have the following to report:-

Workshop Estimate Amount	: S\$	8,305.60
Revised Estimate Amount	: S\$	2,300.56
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

Kh

Tropical Tech Automobile Services

Blk 5030, Ang Mo Kio Avenue 3, #01-201, Industrial Park 2, Singapore 569535

Tel : 6481 7773 / 6481 1403 Fax : 6484 4978

E-mail : tasc303@singnet.com.sg

M/s : **Lompac Insurance Bhd**
101 Thomson Road,
#18-01 United Square,
S'pore 307591

Not Authored
Pruning B4pain

Estimate bill : TT 77 / 19 / TP / WT

Registration No : SLV7552U

Attn : Attention : Motor Claims Third Party Department
Tel : Tel : 62507388
Fax : Fax : 62532058

4 days

Make model : Nissan Note

8 2300.56

Mileage : Date : 18 / 11 / 2019

TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : GBG8730M AND SLV7552U CTE TOWARDS CITY ON 09 NOVEMBER 2019 AT ABOUT 0945 HRS.

1pc	Rear windscreen		\$	Sm	3,655.00	X
1pc	Rear boot	976.40	\$	R	1,754.00	✓
1pc	Rear boot license plate garnish		\$	Sm	473.00	X
1pc	Rear bumper	414	\$	Ber	594.00	✓
2pcs	Rear bumper side bracket	(Each \$68.00)	\$	Sm	136.00	X
	Sub A total :		\$		6,612.00	
	Less 20% discount : 10%		\$		1,322.40	
	A total :		\$		5,289.60	

Special net items :

1pc	Rear boot emblem	\$	<i>Sm</i> 122.00	—
1pc	Rear boot 'Note' designation	\$	<i>Sm</i> 149.00	—
1set	Rear bumper parktronic sensor	\$	<i>Sm</i> 280.00	X
1pc	Rear license smart plate	\$	<i>Sm</i> 55.00	X
1pc	Rear license smart plate casing	\$	606.00	
	B total :	\$	5,895.60	

Total amount of Page 1 :

\$ 5,895.60

Tropical Tech Automobile Services

(Authorised Signature)
William Tan



LOR Auto Consultants hence notify the Repairer of the following:

- To survey & repair after spray painting
- To display damaged parts during repairing
- Parts prices are subject to market rate
- Third party survey was a "Without Prejudice" basis
- No legal responsibility is allowed
- Supplementary to work to be completed and is subject to final approval from Insurance Company

Authorised by Repairer

Signature:

Date:

Tropical Tech Automobile Services

Blk 5030, Ang Mo Kio Avenue 3, #01-201, Industrial Park 2, Singapore 569535

Tel : 6481 7773 / 6481 1403 Fax : 6484 4978

E-mail : tasc303@singnet.com.sg

M / s : **Lonpac Insurance Bhd**
101 Thomson Road,
#18-01 United Square,
S'pore 307591

Estimate billl : TT 77 / 19 / TP / WT

Registration No : SLV7552U

Attn : Attention : Motor Claims Third Party Department
Tel : Tel : 62507388
Fax : Fax : 62532058

Make model : Nissan Note

Mileage : Date : 18 / 11 / 2019

**TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : GBG8730M AND SLV7552U CTF
TOWARDS CITY ON 09 NOVEMBER 2019 AT ABOUT 0945 HRS.**

Remove and refit rear windscreen.	S	220.00	120/
Remove and transfer rear boot necessary attachment spare part items.			
Remove and transfer rear bumper necessary attachment spare part items.			400/
Remove and refit rear boot, rear boot license plate garnish, rear bumper, rear bumper parktronic sensor, rear bumper side bracket.	S	1,000.00	
Heat /weld / beating / pull / straighten / align rear chassis frame by Chassis Alignment jack.			30/
Tuff kote rear damaged portion.	S	150.00	
Diagnostic rear bumper parktronic sensor by HHT	S	40.00	X
Putty / primer application, spray painting on rear boot, rear bumper, rear bumper parktronic sensor	S	1,000.00	400/
Balance amount brought from Page 1 :	S	5,895.60	
Grand final amount :	S	8,305.60	8966.80

Tropical Tech Automobile Services

(Authorised Signature)
William Tan



Tropical Tech Automobile Services

Blk 5030 Ang Mo Kio Avenue 3 #01-201 Industrial Park 2 Singapore 569535
Tel : 6481 7773 / 6481 1403 Fax : 6484 4978
E-mail : tsac303@singnet.com.sg

Claim No : TT 77 / 19 / TP / WT

SATISFACTION VOUCHER

I / We, Sim Chor Hang, holding of NRIC / Company Registration No : S10378322, hereby agree to accept the sum of Singapore Dollars Two thousand eight hundred twenty eight dollars & cents five only (\$ 2,828.05), from **Lompac Insurance Bhd** in full and final settlement of all my / our claims arising from a **TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : GBG8730M AND SLV7552U CTE TOWARDS CITY ON 09 NOVEMBER 2019 AT ABOUT 0945 HRS.**

In consideration of the above payment made to me / us by **Lompac Insurance Bhd**, I / We the undersigned hereby declare that I / We have no further claim or claims of whatsoever nature present or future against either owner / driver of vehicle no. : **GBG8730M** and their said Insurance Company for compensation, demands, damages, or costs incurred in connection with this accident.

It is further understood and agreed that this settlement is made without admission of liability on the part of the said Insurance Company and / or their Insured / driver of the said motor vehicle **GBG8730M**.

* I / We request all correspondence to be forwarded to "TROPICAL TECH AUTOMOBILE SERVICES".

* I / We authorise you to issue the above amount to "TROPICAL TECH AUTOMOBILE SERVICES".

Witnessed by Repairers

Name : William Tan Boon Leng

Tropical Tech Automobile Services

Address : Blk 5030 Ang Mo Kio Ave 3
#01-303 Industrial Park 2

Singapore 569535

Tel: 6481 7773 / 6481 1403 Fax: 6484 4978

Email: tsac303@singnet.com.sg

Date : 18/11/2019



(Company chop if applicable)

Signature of Claimant

Name : Sim Chor Hang

Tropical Tech Automobile Services

Address : Blk 5030 Ang Mo Kio Ave 3
#01-303 Industrial Park 2

Singapore 569535

Tel: 6481 7773 / 6481 1403 Fax: 6484 4978

Email: tsac303@singnet.com.sg

Date : 18/11/2019

(Company chop if applicable)

Tropical Tech Automobile Services

BLK 5030 ANG MO KIO AVENUE 3 #01-201 INDUSTRIAL PARK 2 SINGAPORE 569535

TEL : 6481 7773 / 6481 1403 FAX : 6484 4978

E-mail : tsac303@singnet.com.sg

M / s : **LKK Auto Consultants Pte Ltd**

51, Ubi Avenue 1, #01-25,

Paya Ubi Industrial Park,

Singapore 408933

Attn : Surveyor : Mr Kenneth (Lonpac Insurance)

Tel : 62563561

Fax : 62564315

Mileage :

Vic



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC4/LPC19020074/Kha3n2		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 31-03-2020		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBG 8730M	Veh. Inspected	SLV 7552U
	Policy No.	Z19VC05002418	Coverage (\$)	0.00
	Claim No.	19/19/19/VC05/022619	Excess (\$)	0.00
	Assign From	GERALD	Assign Date	12/11/2019
2. Vehicle Particulars & Condition				
	Make & Model	NISSAN NOTE (A)	c.c	1198
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	JN1TAAE12Z0980165	Colour	METALLIC SILVER
	Odometer	41212	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/65 R15	CONTINENTAL	9 mm
	L/H Front Tyre	185/65 R15	CONTINENTAL	9 mm
	R/H Rear Tyre	185/65 R15	YOKOHAMA	7 mm
	L/H Rear Tyre	185/65 R15	YOKOHAMA	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	09/11/2019	Inspection Date	18/11/2019
	Survey held at	TROPICAL TECH AUTOMOBILE SERVICES BLK 5032, ANG MO KIO AVENUE 3 #01-303 IND. PARK 2 SINGAPORE 569535		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 7552U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR WINDSCREEN	SERVICEABLE	3,655.00	-
1	REAR BOOT	BENT	1,754.00	976.40
1	REAR BOOT LICENSE PLATE GARNISH	SERVICEABLE	473.00	-
1	REAR BUMPER	BUCKLED	594.00	414.00
2	REAR BUMPER SIDE BRACKET @\$68.00	SERVICEABLE	136.00	-
	LESS 10% DISCOUNT		-661.20	-139.04
			5,950.80	1,251.36
SPECIAL NETT ITEMS				
1	REAR BOOT EMBLEM (SN)	NECESSARY	122.00	55.30
1	REAR BOOT "NOTE" DESIGNATION (SN)	NECESSARY	149.00	43.90
1	SET REAR BUMPER PARKTRONIC SENSOR (SN)	SERVICEABLE	280.00	-
1	REAR LICENSE SMART PLATE CASING (SN) }	SERVICEABLE	55.00	-
1	REAR LICENSE SMART PLATE (SN) }		-	-
			606.00	99.20
LABOUR				
	REMOVE AND REFIT REAR WINDSCREEN.		220.00	120.00
	REMOVE AND REFIT REAR BOOT,REAR BOOT LICENSE PLATE GARNISH,REAR BUMPER,REAR BUMPER PARKTRONIC SENSOR,REAR BUMPER SIDE BRACKET.)		1,000.00	400.00
	REMOVE AND TRANSFER REAR BOOT NECESSARY ATTACHMENT SPARE PART ITEMS.)		-	-
	REMOVE AND TRANSFER REAR BUMPER NECESSARY ATTACHMENT SPARE PART ITEMS.)		-	-
	HEAT/WELD/BEATING/PULL/ STRAIGHTEN/ALIGN REAR CHASSIS FRAME BY CHASSIS ALIGNMENT JACK.)		-	-
	TUFF KOTE REAR DAMAGED PORTION.		150.00	30.00
	DIAGNOSTIC REAR BUMPER PARKTRONIC SENSOR BY HHT.	NOT NECESSARY	40.00	-
	PUTTY/PRIMER APPLICATION,SPRAY PAINTING ON REAR BOOT,REAR BUMPER,REAR BUMPER PARKTRONIC SENSOR.		1,000.00	400.00
			2,410.00	950.00

Report Ref No. CC4/LPC19020074/Kha3n2



GRAND TOTAL		8,966.80	2,300.56
RECOMMENDED COST OF REPAIRS			2,300.56

Report Ref No. CC4/LPC19020074/Kha3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.