

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

11-Nov-19

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6099 R

1 pc	Front bumper <i>x repair</i>	\$	531.00
1 pc	Front bumper emblem <i>x</i>	\$	44.00
1 pc	Front bumper o/s side retainer <i>x</i>	\$	16.00
1 pc	Front o/s fender <i>x repair</i>	\$	384.00
1 pc	Front o/s fender inner shield <i>x</i>	\$	120.00
1 pc	Front o/s door <i>x repair</i>	\$	761.00
2 pcs	Front o/s door hinges @ \$34.00 <i>x</i>	\$	68.00
1 pc	Rear o/s door <i>x repair</i>	\$	791.00
2 pcs	Rear o/s door hinges @ \$34.00 <i>x</i>	\$	68.00
1 pc	o/s rocker panel garnish <i>x</i>	\$	286.00
2 pcs	Front & rear o/s wheel cover <i>x repair</i>	\$	232.00
	<i>Per o/s fender x repair</i>	\$	3,301.00
	<i>o/s wing mirror</i>	\$	330.10
	<i>\$ 590 Less 10%</i>	\$	2,970.90

### S/NETT

1 set	Front bumper clips <i>x</i>	\$	48.00
1 pc	Front o/s fender sticker <i>x</i>	\$	30.00
1 set	Front o/s fender inner shield clips <i>x</i>	\$	28.00
1 set	o/s rocker panel garnish clips <i>x</i>	\$	38.00
1 set	o/s door stickers <i>-</i>	\$	100.00
1 pc	Rear o/s fender sticker <i>-</i>	\$	60.00
	<i>Kahin 1000</i>		
	<i>11/11/19 150sh.</i>		
	<i>4 B Pr</i>	\$	50.00 <i>20</i>
	<i>US</i>	\$	160.00 <i>x</i>
Sundry			
	To check wheel alignment - Front & Rear		
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		
	To dismantle / refit inner components of the front o/s door & rear o/s door into new shell door	\$	300.00 <i>x</i>
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the rear o/s fender, etc.	\$	850.00 <i>400</i>
	To putty and spray painting on front bumper, front o/s fender, front o/s door, front o/s windscreen pillar, rear o/s door, o/s rocker panel garnish, rear o/s fender	\$	1,400.00 <i>1050</i>
	To apply rustproofing on the repaired and replaced panels.	\$	200.00 <i>x</i>
		\$	6,414.90

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )  
THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE  
ANY UNFORESEEN DAMAGES.

*Final*