

JSS: Ref: BY Sun Pin

REF:

NTUC

NS/INC19020085/QyF352

## ASSIGNMENT

From:

Date:

11/11/19

Estimated Cost:

OE / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SHC 4377B

at Workshop m/s

SMRT

of

Woodlands Depot

Insured:

SLG 86335

Policy No.

5094542734-02 (17/10/2019-16/10/2020)

Claims No.

MT/1070647-002

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS up

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SHC 4377B

Yr Regn:

19/03/2014

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Prius.

C.C.

1798

Colour

Maroon.

A/C:

Insured / Std / NI / NA

Sp. Reading

719118

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDKN36UXG5738381

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65 R15

R:

195/65 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

D.O.I.

11/11/2019

Survey held at

SMRT.

Des. of Damages: Frt / Rear / O/S / (N/S) / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

SLG 86335: X

SHC 4377B NS/INC19020085/QyF352 REP: 20/08/2017

TR

TAX/11/19/2024

SLG 86335

Confirm finalize \$2050 @ 3 days. (Red \$3750/monthly 64%)  
(Lump Sum).

26/11/2019

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2)

29/11/19 Typist

Days Of Repair:

3

Resurvey No. of Trip:

2

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Insp (\$)



Weekend (\$)

Survey Fee:

Transportation:

S + RS: \$

Photo

Other

TOTAL

Report Format:

Lump Sum (L.S.):

\$2050/-

TP Claims against NTUC Income: Follow-Through Survey

Date : 27/11/2019

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate
1	MT/1070647-002	SMRT-BUSES-LTD SMRT TAXIS PTE LTD	SHC4377B	SLG8633S	08/11/2019	15:45	\$ 5,800.00
2	MT/1073574 001	SMRT-BUSES-LTD SMRT TAXIS PTE LTD	SHC4654B	SLS9142Y	11/11/2019	20:15	\$ 3,150.00

eBaoTech

General Claim

Hello, NAC\_PAYA\_UBI\_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

## Policy Query

Policy No.  Date of Accident   
Vehicle No.(For Motor)  Certificate Number

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="radio"/>	5094542734-02		GOH BEE GEOK	S2555478G	GPC	drive CLASSIC	SLG8633S	SLG8633S	17/10/2019	16/10/2020

## Yvonne Wong (LKK Auto)

---

**From:** Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis) <YeoPohsuan@smrt.com.sg>  
**Sent:** Friday, November 22, 2019 2:40 PM  
**To:** Oi Sun Pin (LKK Auto)  
**Cc:** Yvonne Wong (LKK Auto)  
**Subject:** RE: Finalize SHC4377B

**Follow Up Flag:** Follow up  
**Flag Status:** Completed

Hi,

Amount confirmed as per your recommendation, thanks.

Regards  
Poh Suan

-----Original Message-----

**From:** Oi Sun Pin (LKK Auto) [mailto:sunpin@lkkauto.com]  
**Sent:** Friday, 22 November 2019 2:11 PM  
**To:** Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)  
**Cc:** Yvonne Wong (LKK Auto)  
**Subject:** Finalize SHC4377B

Dear Poh Suan,

Confirm the finalize amount \$2,050. Day of repair 3 working days under L/S repair.

Thank you.

Best Regards,  
Oi Sun Pin | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: Sunpin@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25  
| S(408933)

-----Original Message-----

**From:** Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis) [mailto:YeoPohsuan@smrt.com.sg]  
**Sent:** Wednesday, 20 November, 2019 5:54 PM  
**To:** Oi Sun Pin (LKK Auto)  
**Cc:** SUR; CS A Team  
**Subject:** SHC4377B

Hi Sun Pin,

Attached herewith the repair estimate of SHC 4377B having Case No: TAX/11/19/2024.

There is no change to the approved amount of \$2,050 @ 3 working days under lump sum repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards

Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)

Sent: Wednesday, 20 November 2019 5:51 PM

To: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)

Subject: Scan Data from FX-D421D6

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	08/11/2019 16:54
Date Of Accident	08/11/2019 15:45
Exact Location Of Accident	BUKIT TIMAH PLAZA TAXI STAND
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC4377B
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000
<b>Vehicle Particulars</b>	
Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
<b>Insurance Company</b>	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-19093197MFSH
Cover Note Number	
<b>Driver</b>	
Name of Driver	TAN KAH POH
NRIC No	S1662138B
Date Of Birth	21/10/1964
Occupation	OUTDOOR
Date Of Driving Pass	28/01/1985
Driving Experience	34 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	25
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

I WAS DRIVING STRAIGHT ALONG THE DRIVE WAY OF BUKIT TIMAH ROAD NEAR THE TAXI STAND. SUDDENLY THE VEHICLE SLG8633S WHICH WAS QUEUING TO THE TAXI STAND CUT OUT ABRUPTLY INTO MY TRAVEL PATH AND COLLIDED ONTO THE LEFT FRONT PORTION OF MY TAXI. NO PAX

#### Attachment(s)



Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLG8633S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## Sketch Plan Pg. 1

### SKETCH PLAN



A-SHC 4377B  
B-SLG 8632S


B-52686325

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There is no handwriting or other markings on the paper.

## DECLARATION

I/We declare that foregoing particulars are true in every respect.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



## Sketch Plan Pg. 2

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


#### 8. Consent under the Personal Data Protection Act (PDPA)


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:

Owner ID:

### Vehicle Details

Vehicle No.:

Vehicle to be Exported:

Intended Deregistration Date:

Vehicle Make:

Vehicle Model:

Primary Colour:

Manufacturing Year:

Engine No.:

Chassis No.:

Maximum Power Output:

Open Market Value:

Original Registration Date:

First Registration Date:

Transfer Count:

Actual ARF Paid:

### Intended PARF Rebate Details

PARF Eligibility:

PARF Eligibility Expiry Date:

PARF Rebate Amount:

### Intended COE Rebate Details

COE Expiry Date:

COE Category:

COE Period(Years):

PQP Paid:

COE Rebate Amount:

Total Rebate Amount:

### Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 12 Nov 2019

Company

369K

SHC4377B

No

12 Nov 2019

TOYOTA

PRIUS TAXI (SMRT)

Maroon

2014

22R1342743

JTDKN36UX05738381

100.0 kW (134 bhp)

\$33,120.00

19 Mar 2014

19 Mar 2014

0

\$8,368.00

Yes

18 Mar 2022

\$5,857.00

18 Mar 2022

A - Car up to 1600cc & 97kW (130bhp)

8

\$58,745.00

\$17,252.00

\$23,109.00



OK

## Section A - Accident Details

Registration Number	SHC4377B
Case Reference Number	TAX/11/19/2024
Registration Date	19/3/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	TAN KAH POH
Type of Accident	Side Swipe
Accident Date and Time	8/11/2019 3:45 PM
Accident Reported Date and Time	8/11/2019 4:58 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24104251
Special Instruction to ARC, if any	TP
Prepared Date and Time	9/11/2019 9:56 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

## Section B - Summary of Repair Estimates

## Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$338.00	\$200.00
Total Spray Cost	\$936.00	\$450.00
Total Spare Part Cost	\$8,174.91	\$1,853.04
Total Other Cost	\$360.00	(\$463.04)
<b>TOTAL COST</b>	<b>\$7,808.91</b>	<b>\$2,050.00 (L/S)</b>
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	4.0	3.0
Prepared / Adjusted By	Ang Bang Kien	Sun Pin (LKK) / NTUC
ARC / Surveyor Sign Off Date	15/11/2019 12:37 PM	15/11/2019 10:00 AM
Signature		
Remarks	Total number of repair days = 3 days. SUP = +0 day.	Lump Sum repairs, Take after spray photo. send to sunpin@lkkauto.com

## Case Details

Case Reference Number :

TAX/11/19/2024

Type of Repair : Accident Repair

Vehicle Registration Number : SHC4377B

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-9251-ID

Assigned By : Taxi Claims Manager Team

Insurance Company Name : NTUC Income Insurance Co-operative Ltd

Accident Date and Time : 08/11/2019 07:45 AM

Vehicle Age(In Months) : 68

## Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

## Estimation Details

### Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace Remarks
One Time Key In	Main			BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	1	361.50	Replace ✓ PD.
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace ✓ NEC
One Time Key In	Main			BUMPER SUPPORT F/RH	1	76.40	76.40	25.00	57.30	Replace	0	0	Check ✓ SVC
One Time Key In	Main			BUMPER SUPPORT F/LH	1	76.40	76.40	25.00	57.30	Replace	0	0	Check ✓ SVC
One Time Key In	Main			FOG LAMP LH	1	280.10	280.10	10.00	252.09	Replace	0	0	Not Give ✓ SVC
One Time Key In	Main			BUMPER LIP FRT	1	139.60	139.60	25.00	104.70	Replace	0	0	Not Give ✓ SVC
One Time Key In	Main			UNDER COVER CENTER	1	448.30	448.30	25.00	336.23	Replace	0	0	Not Give ✓ SVC
One Time Key In	Main			UNDER COVER SIDE/LH	1	46.10	46.10	25.00	34.58	Replace	0	0	Not Give ✓ SVC
One Time Key In	Main			UNDER COVER SIDE/RH	1	46.10	46.10	25.00	34.58	Replace	0	0	Not Give ✓ SVC
One Time Key In	Main			HEAD LAMP LH	1	945.20	945.20	10.00	850.68	Replace	0	0	Not Give ✓ SVC

Total Spare Part Cost 5,207.83

Lump Sum Discount (%) 20.00

Final Spare Part Cost 4,166.26

Surveyor Total 955.05

Lump Sum Dis (%) 20

Final Sur Total 764.04

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			MIRROR ASSY,LH	1	1,224.90	1,224.90	25.00	918.68	Replace	0	0	Not Give	✖ X Svc
One Time Key In	Main			COVER, OUTER MIRROR, LH	1	107.40	107.40	25.00	80.55	Replace	0	0	Not Give	✖ X Svc
One Time Key In	Main			FENDER FRT/LH	1	723.40	723.40	25.00	542.55	Replace	1	542.55	Replace	✖ / DP.
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace	✖ / NEC
One Time Key In	Main			FENDER PROTECTOR FRT/LH UPPER	1	46.10	46.10	25.00	34.58	Replace	0	0	Check	✖ X Svc
One Time Key In	Main			PROTECTOR, FRONT FENDER SIDE PANEL LH	1	114.50	114.50	25.00	85.88	Replace	0	0	Check	✖ X Svc
One Time Key In	Main			FENDER LINER FRT/LH	1	171.70	171.70	25.00	128.77	Replace	0	0	Not Give	✖ X Svc
One Time Key In	Main			FENDER LINER PAD, FR WHEEL. LH	1	49.30	49.30	25.00	36.97	Replace	0	0	Not Give	✖ X Svc
One Time Key In	Main			WHEEL DISC. FRONT	1	1,484.20	1,484.20	25.00	1,113.15	Replace	1	0	Repair	✖ X Repair.
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give	✖ X Svc

Total Spare Part Cost 5,207.83

Surveyor Total 955.05

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 4,166.26

Final Sur Total 764.04

#### Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT LH PORTION	338.00	200	✓
Total:			338.00	200.00	

#### Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200	✓
Total:			936.00	450.00	



S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
2	Main	TO RESPRAY FRONT FENDER LH	378.00	200	/
3	Main	TO RESPRAY RIM	180.00	50	/
Total:			936.00	450.00	

#### Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPLACE SUNDRY PARTS	100.00	20	/
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0	
3	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60	/
4	Main	TO WASH AND VACUUM	60.00	0	
Total:			360.00	80.00	

9390.84

## Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	4,166.26	764.04
Total Labour Cost	338.00	200.00
Total Spray Painting	936.00	450.00
Other	360.00	80.00
Overall Total	5,800.26	1,494.04
Lump Sum Repair Option	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Lump Sum Total	5,800.00	1,500.00
Surveyor Approved Amount		1,500.00
No of Repair Days*	4	3
Remarks		Lump Sum repairs, Take after spray photo. send to sunpin@lkkauto.com
Surveyor Name		Sun Pin (LKK)
Signature		

Save

Clear

Estimator Assessment(\$)

Surveyor Assessment(\$)

Survey Date

11/11/2019

**LKK Auto Concurs - hence notify**

**the Repairer of the following:**

- To resurvey before spray painting
- To display damage (if) during resurvey
- Parts prices are to confirmation
- Third party survey on "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by (Name):

Signature:

Date:

## Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1911-0309	Invoice Number	
Quotation Date	20.11.2019	Invoice Date	
Invoice Amount		Prepared Date	

## Section D - Details of Repair Estimates

## Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT LH PORTION	\$338.00	\$200.00
Total Labour	\$338.00	\$200.00

## Part 2 - Spray Painting &amp; Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$50.00
Total Spray Painting & Panel Beating	\$936.00	\$450.00

## Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00
TO WASH AND VACUUM	\$60.00	\$0.00
Lump Sum Adjustment by Surveyor	\$0.00	(\$543.03)
Total Other Costs	\$360.00	(\$463.03)

## Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119-47930	BUMPER FRT	1.00	\$482.00	25.00	\$361.50	Replace	Replace
		52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace
		52115-47040	BUMPER SUPPORT F/RH	0.00	\$76.40	0.00	\$0.00	Replace	Check
		52116-47040	BUMPER SUPPORT F/LH	0.00	\$76.40	0.00	\$0.00	Replace	Check
		81220-12230	FOG LAMP LH	0.00	\$280.10	0.00	\$0.00	Replace	Not Given
		76851-47020	BUMPER LIP FRT	0.00	\$139.60	0.00	\$0.00	Replace	Not Given
		51410-12105	UNDER COVER CENTER	0.00	\$448.30	0.00	\$0.00	Replace	Not Given
		51444-12050	UNDER COVER SIDE/LH	0.00	\$46.10	0.00	\$0.00	Replace	Not Given
		51443-12080	UNDER COVER SIDE/RH	0.00	\$46.10	0.00	\$0.00	Replace	Not Given
		81170-47500	HEAD LAMP LH	0.00	\$945.20	0.00	\$0.00	Replace	Not Given
		87940-47310	MIRROR ASSY, LH	0.00	\$1,224.90	0.00	\$0.00	Replace	Not Given
		87945-74010	COVER, OUTER MIRROR, LH	0.00	\$107.40	0.00	\$0.00	Replace	Not Given
		53802-47050	FENDER FRT/LH	1.00	\$723.40	25.00	\$542.55	Replace	Replace
		75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace



# SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd  
 63 Woodlands Industrial Park E4, Singapore 757705  
 FAX Number: 63655592  
 Estimate Telephone Number: 65652623  
 Accident Reporting Number: 6562672

Date Generated: 20/11/2019  
 User ID: PehSuen

	53826-47010	FENDER PROTECTOR FRT/LH UPPER	0.00	\$46.10	0.00	\$0.00	Replace	Check	X
	53828-47060	PROTECTOR, FRONT FENDER SIDE PANEL LH	0.00	\$114.50	0.00	\$0.00	Replace	Check	X
	53876-47030	FENDER LINER FRT/LH	0.00	\$171.70	0.00	\$0.00	Replace	Not Given	X
	53852-47020	FENDER LINER PAD, FR WHEEL, LH	0.00	\$49.30	0.00	\$0.00	Replace	Not Given	X
	42611-47140	WHEEL DISC. FRONT	1.00	\$1,484.20	100.00	\$0.00	Replace	Repair	R
		TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X
Total				\$6,641.95		\$955.06			

## Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		52116-47040	BUMPER SUPPORT F/LH	1.00	\$76.40	25.00	\$57.30	Replace	Replace
		81170-47500	HEAD LAMP LH	1.00	\$945.20	10.00	\$850.68	Replace	Replace
		52611-47080	BUMPER ENERGY ABSORBER FRT	0.00	\$78.80	0.00	\$0.00	Replace	Not Given
Total					1,100.40		907.98		

1863.04  
 + 200.00  
 + 530.00  
 -----  
 2593.04  
 - 207  
 -----  
 2074.43  
 45 \$2050/-

# REQUEST FOR SUPPLYMENT PARTS

Contractor:			
Accident Case Number	TAX/11/19/2014	Date of Collection	1 / 1
Vehicle No	SHC 4377 B	Date of Request	13/4/2019
Vehicle Model	TOYOTA PRIUS	Number of Days to Extend (If any)	10

S/N	Part Number	Part Description	Quantity	Unit Price
		BOMPER SUPPORT FRONT LH	1pc	
		HEAD LAMP LH	1pc	
		FRONT BOMPER FORM	1pc	MISSING

/CRA  
/CRA  
X old damage

<<<Please submit photographs for damaged parts>>>

I, (Name) \_\_\_\_\_  
(Position) \_\_\_\_\_

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

.....  
Signature of person making this declaration  
[to be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission



## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19020085/Qyf3s2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE  
189556

Date: 02-12-2019



Code: INC4

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLG 8633S	Veh. Inspected	SHC 4377B
Policy No.	5094542734-02	Coverage (\$)	0.00
Claim No.	MT/1070647-002	Excess (\$)	0.00
Assign From		Assign Date	11/11/2019

### 2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JTDKN36UX05738381	Colour	MAROON
Odometer	719118	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	WEST LAKE	5 mm
L/H Front Tyre	195/65 R15	WEST LAKE	5 mm
R/H Rear Tyre	195/65 R15	WEST LAKE	5 mm
L/H Rear Tyre	195/65 R15	WEST LAKE	5 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.
DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	08/11/2019	Inspection Date	11/11/2019
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 4377B**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	BUMPER FRT (DISC 25%)	DENTED	482.00	361.50
10	BUMPER CLIPS @ \$1.61 (DISC 25%)	NECESSARY	16.10	12.08
1	FENDER FRT/LH (DISC 25%)	DENTED	723.40	542.55
1	NAME PLATE (HYBRID) (DISC 25%)	NECESSARY	51.90	38.93
1	BUMPER SUPPORT F/RH	SERVICEABLE	76.40	-
1	BUMPER SUPPORT F/LH	SERVICEABLE	76.40	-
1	FOG LAMP LH	SERVICEABLE	280.10	-
1	BUMPER LIP FRT	SERVICEABLE	139.60	-
1	UNDER COVER CENTER	SERVICEABLE	448.30	-
1	UNDER COVER SIDE/LH	SERVICEABLE	46.10	-
1	UNDER COVER SIDE/RH	SERVICEABLE	46.10	-
1	HEAD LAMP LH	SERVICEABLE	945.20	-
1	MIRROR ASSY, LH	SERVICEABLE	1,224.90	-
1	COVER, OUTER MIRROR, LH	SERVICEABLE	107.40	-
1	FENDER PROTECTOR FRT/LH UPPER	SERVICEABLE	46.10	-
1	PROTECTOR, FRONT FENDER SIDE PANEL LH	SERVICEABLE	114.50	-
1	FENDER LINER FRT/LH	SERVICEABLE	171.70	-
1	FENDER LINER PAD, FR WHEEL LH	SERVICEABLE	49.30	-
1	TYRE	SERVICEABLE	126.74	-
1	WHEEL DISC, FRONT	TO REPAIR SEE LABOUR	1,484.20	-
1	BUMPER SUPPORT FRONT LH (DISC 25%)	CRACKED	76.40	57.30
1	HEAD LAMP LH (DISC 10%)	CRACKED	945.20	850.68
1	FRONT BUMPER FOAM (MISSING)	OLD DAMAGE	78.80	-
			<b>7,756.84</b>	<b>1,863.04</b>
<b><u>LABOUR</u></b>				
PANEL BEATING & BODYWORK. INCLUSIVE OF THE REPAIR OF WHEEL DISC, FRONT.			338.00	200.00
SPRAY PAINT.			936.00	450.00
TO REPLACE SUNDRY PARTS.			100.00	20.00

Report Ref No. NS/INC19020085/Qyf3s2



## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK WIRING AND SYSTEM FUNCTION.	NOT NECESSARY	80.00	-
	TO DO WHEEL ALIGNMENT / TYRE BALANCING.		120.00	60.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			1,634.00	730.00
GRAND TOTAL			9,390.84	2,593.04
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS RE-ACCIDENT CONDITION) (CONFIRMED)				2,050.00

Report Ref No. NS/INC19020085/Qyf3s2

OI SUN PIN

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,  
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part does so at his or her own risk.