

ASS. REC. BY:

REF: CS/CTI 1902089 / Uyf3k2

Special Instruction:

Surveyor: MARCUS

ASSIGNMENT (Office)

From (Person):

Tan Kah Long

of CTI

Date/Time:

12.11.19 17.50PM

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No:

SLA 39A76

Insured:

SMG 1464Y

at Workshop m/s

RICO 60

Tel:

9187 8064

of

8 Kaki Bukit Ave 4 #02-24

Policy No:

DTP PSN 30799418000

Claim No:

SMN 190205334 COR

Sum Insured:

Excess:

Make of Veh:

D.O.A.

9.11.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

13.11.19 9.44am

Person Contacted:

Shanella

Vehicle:

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLA 39A76 - NA / UYF3K2

DOB - 09/11/2019

SMG 1464Y - CS/CTI 1902089 / Uyf3

DOB - 09/11/2019

ASS. REC. BY:

MCI (W)

RICH:

C711

ASSIGNMENT

Front

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SLA 3997G

at Workshop m/s

R110 60

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

50k.

IDAC Accident Rpt:

Consistent? Yes or No

GIA / PR Seen:

Consistent? Yes or No

Est. Repairs:

7 days

Res.: Yes or No

Lum Sum:

2 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

not 10481

Veh No:

SLA 3997G

Yr Regn:

216

Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

Honda city

C.C. 1497

Colour

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

57197

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MR HGM 66606 P 000477

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size:

F:

185/55 216

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

9/11/19

D.O.I.

13/11/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S R/L, O/S L/R

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

27/12/19

SLA 39519 6ys 3m Rep 7500

1/5 6000 continue work John (Red \$6150.00, 50%)

RECEIVED 07 JAN 2020

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

3/1/20 Typist

Report Form:

Camp 2000 / 1.1.1.1

\$6000

Days Of Repair:

7

Resurvey No. of Trip:

3

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (2

☐

: Wheel And +2

Survey Fee:

270

Transportation:

S + RS \$1

Pins

Others

TOTAL

270

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Nov 2019		12 Nov 2019 17:50 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:									
Main Claimant: LEE VINCENT , ID: S7135767H									
Vehicle Reg. No.:		SLA3997G	Date of Loss:	09/11/2019 17:00 - :59					
Claim Type:		TP / SNM19D205334C02	Policy/Cover Note No.:	DMPCSN30799418000					
Vehicle Reg. No. (Insured):		SMG1464Y	Policy No. (Claimant):	S119V02150/VPC/R03					
		Excess:	S\$1,000.00						
Repairer: RICO 60 AUTO SERVICES PTE LTD (HQ) 8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel:									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]									
Claimant's Insurer: Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 21/11/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Sent: Tuesday, 12 November 2019 5:46 PM
To: Rico 60; assignments
Subject: RE: OUR REF: SNM19D205334/SMG1464Y/TKL & YOUR REF: SLA3997G - TOCONDUCT PRS - PRI Arrangement for SLA 3997 G

WITHOUT PREJUDICE

Dear Elfphaine,

We refer to your email dated 12.11.2019.

We will be assigning M/s LKK Auto Consultants to survey your client's vehicle on a without prejudice basis.

Aside to LKK,

Please refer to the email below & proceed to survey the third party vehicle.

Thank you.

Regards

Tan Kah Leong

Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Rico 60 [mailto:claims@rico60.com]
Sent: Tuesday, November 12, 2019 5:00 PM
To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Subject: RE: OUR REF: SNM19D205334/SMG1464Y/TKL & YOUR REF: SLA3997G - TOCONDUCT PRS - PRI Arrangement for SLA 3997 G

Dear Mr Tan,

Please have Marcus Chua to survey the said vehicle.

Thank you.

Best Regards,

Elfphaine Tan



RICO 60 AUTO SERVICES PTE. LTD.

Co. & GST Reg. No.: 201807623M

8 Kaki Bukit Avenue 4, Premier @ Kaki Bukit

#02-24, Singapore 415875

Tel: +65 6286 6060 | Fax: +65 6286 7060

Email: enquiry@rico60.com

From: Tan Kah Leong

Sent: Tuesday, 12 November 2019 1:49 PM

To: claims@rico60.com

Subject: RE: OUR REF: SNM19D205334/SMG1464Y/TKL & YOUR REF: SLA3997G - TOCONDUCT PRS - PRI Arrangement for SLA 3997 G

Without Prejudice

Dear Shanelle,

We refer to your email below.

Please see attached and let us know if you agree with SJE.

Thank you.

Regards

Tan Kah Leong

Assistant Executive

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI

Sent: Tuesday, November 12, 2019 1:43 PM

To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; claims@rico60.com

Subject: OUR REF: SNM19D205334/SMG1464Y/TKL & YOUR REF: SLA3997G - TO CONDUCT PRS - PRI Arrangement for SLA 3997 G

Dear Kah Leong,

Please conduct PRS –SLA3997G soonest possible

File with officer in charge- Tan Kah Leong –DID: 6389 6193

Regards

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

TEL: (65) 63896116 - F: (65) 6224 7478

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Enquiry [<mailto:claims@rico60.com>]

Sent: Tuesday, November 12, 2019 11:15 AM

To: Claims Dept of CTI

Subject: PRI Arrangement for SLA 3997 G

Dear All,

Kindly arrange PRI to survey the said vehicle as follows:

Our Client – SLA 3997 G

Your Insured – SMG 1464 Y

DOA – 09/11/2019

Thank you.

Best Regards,
Shanelle Lim



RICO 60 AUTO SERVICES PTE. LTD.

Co. & GST Reg. No.: 201807623M

8 Kaki Bukit Avenue 4, Premier @ Kaki Bukit

#02-24, Singapore 415875

Mobile: +65 9187 8064 | Tel: +65 6286 6060 | Fax: +65 6286 7060

Email: enquiry@rico60.com

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/11/2019 17:30
Date Of Accident	09/11/2019 17:00
Exact Location Of Accident	63 SIMS PLACE GREENTOPS CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLA3997G
Insured/Policyholder	
Name Of Registered Owner	LEE VINCENT
NRIC No	S7135767H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91195955
Alternative Phone No	OTHERS-91195955

Vehicle Particulars

Manufacturer	HONDA
Model	CITY
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SI19V02150/VPC/R03
Cover Note Number	

Driver

Name of Driver	CHAN FONG SIN
NRIC No	S7102627B
Date Of Birth	22/01/1971
Occupation	INDOOR
Date Of Driving Pass	28/07/2003
Driving Experience	16 YEARS AND 3 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91195855
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	162 CANBERRA DRIVE #07-52
Postcode	768000
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	4
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJT6593S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SMA6897E
-----------------------------	----------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

SMG1464Y

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to assist us the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, collectively the "Purposes";
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/ID No.:

Individual Statement

A: 87407776
B: 87407735C: 87407736
D: 87407737

SKETCH PLAN

63 SWS NERVE
GREENFORD CARPARK

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date & time, I, vehicle A was parked stationary on the stated venue. When I return to my vehicle I realise my vehicle had been being by other car. After that there's a witness approach to me & tell me, he saw this accident happens.

Witness: Marshall Thean (8611 5941)

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name:
NIC/FIN No:

scene photo



> Back to OneMotoring

Jimmy

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	767H
Vehicle Details	
Vehicle No.:	SLA3997G
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Nov 2019
Vehicle Make:	HONDA
Vehicle Model:	CITY 1.5 SV CVT
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	L15Z12720059
Chassis No.:	MRHGM6660GP000477
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$18,503.00
Original Registration Date:	29 Feb 2016
First Registration Date:	29 Feb 2016
Transfer Count:	0
Actual ARF Paid:	\$13,503.00 <i>6257</i>
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Feb 2026
PARF Rebate Amount:	\$10,127.00
Intended COE Rebate Details	
COE Expiry Date:	28 Feb 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,651.00
COE Rebate Amount:	\$29,392.00
Total Rebate Amount:	\$39,519.00

The information contained herein is correct as at 11 Nov 2019

OK

Google Pixel 4 XL

Get a free Google Nest Hub with every Pixel 4 XL purchase. Deal ends

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

New 5 Year/60,000 Km Toyota 2016 5.0L



2016 Toyota 5.0L V8
Automatic 4WD 100000
Kilometers, 100000
Kilometers, 100000
Kilometers



Sort by Date Posted 20 results/page

5 vehicles

HONDA CITY

Reset Search

Price Any price **Depre** Any depre **Reg Date** 2016 to 2016 **Eng Cap** Any **Veh Type** All types
Fuel Any fuel **Mileage** Any **OMV** Any **Gear** Any Gear **Past Owners** Any
Category All categories **Scheme** All schemes **Dealer** Any Dealer **Location** Any **Status** Available

Make & Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
 Honda City 1.5A SV 1.98% Limited-Time Special Interest Rate For This Week End Only, 5 Year Warranty By Kah Motor, Free Ceramic Coating Worth \$888 Come With 5 Years Warranty, Servicing Record Provided, Can Arrange For STA Evaluation, High Trade In Up To \$2K More And Flexible. Accendone Autolution Pte Ltd Posted: 30-Nov-2019 Tags: 2016 Honda City, 2016 Honda city, Honda City, honda city, Honda, City, city, Used Honda	\$60,800	\$7,850 /yr	21-Oct-2016	1,497 cc	75,548 km	Sedan	Available
 Honda City 1.5A SV 1st Owner Unit! Honda Classy Black On Black Interior. Honda City 1.5 SV CVT, Low Mileage Done, Flexible Loan Available. Beautiful Car And Engine Condition, Decent Honda Ride. Low In Petrol, Road Tax And Insurance. Come View And We Discuss Further, Thanks. Posted: 06-Nov-2019 Tags: 2016 Honda City, 2016 honda city, Honda City, honda city, Honda, City, city, Used Honda	\$60,500	\$7,990 /yr	24-Aug-2016	1,497 cc	68,155 km	Sedan	Available
 Honda City 1.5A SV 1 Owner, Best Condition, Facelift Model, Very Well Maintained, Low Mileage, 100% Accident Free. Don't Miss It! View Now, 100% Flexible Loan, 100% Loan Available. We Provide Lowest Interest Rate. Flexible Loan And High Trade In Are Available. Package With Unrivalled W.. Classic Credit Pte Ltd Posted: 08-Nov-2019 Tags: 2016 Honda City, 2016 honda city, Honda City, honda city, Honda, City, city, Used Honda	\$59,800	\$7,650 /yr	07-Dec-2016	1,497 cc	34,663 km	Sedan	Available
 Honda City 1.5A SV Full Loan Available At \$900 Plus, In House Loan Or Bank Loan Available! Fast, Easy And Flexible Loan Approval! We Are sgCarMart Premium Dealer! Buy With Confidence! Viewing And Test Drive Available Daily Including Weekend From 10.30 A.M. To 6.30 P.M.! All Ou.. BB Motor Trading Posted: 05-Nov-2019 Tags: 2016 Honda City, 2016 honda city, Honda City, honda city, Honda, City, city, Used Honda	\$55,800	\$7,400 /yr	22-Jul-2016	1,497 cc	-	Sedan	Available
 In a Nutshell: Uber's unhired fleet cars Hundreds of Uber's unhired cars have hit the used car market since the app shut down. Here's what you need to know in a nutshell and why you should care. Read this article							
 Honda City 1.5A SV STA Inspection Done And New Road Tax Till Next Year! Well Taken Care By 1 Owner, Well Maintained And Low Fuel Efficient, Beautiful Elegant Grey Well Kept Interior And Exterior. Drive With Passion. Trade-In And Loan Available Together With Private Hirer Loan. Contact.. Posted: 15-Oct-2019 Tags: 2016 Honda City, 2016 honda city, Honda City, honda city, Honda, City, city, Used Honda	\$60,800	\$7,910 /yr	04-Oct-2016	1,497 cc	52,000 km	Sedan	Available

Make & Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page



Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com
Tel: 6286 6060 , FAX: 6286 7060

VEHICLE NUM:
MAKE & MODEL:
MILEAGE:
TYRE:
CHASSIS NUM:

SLA 3997 G
HONDA CITY

Not Allocated
13/11/19
1/5/20
707.

Take care of the car.

ATTN:			
NO.	DESCRIPTION - PARTS	QTY	PRICE
1	HEADLAMP (L+R) 11 X	2	
2	HEADLAMP BRACKET (L+R) 11 X	2	
3	FRONT BUMPER cut ✓	1	
4	FRONT BUMPER RETAINER (L+R) 0.5 set 4c	2	
5	FRONT BUMPER REINFORCEMENT BAR 11 X	1	
6	FRONT BUMPER BRACKET (L+R) 11 X	2	
7	FRONT BUMPER BEAM 11 X	1	
8	FRONT BUMPER SPONGE 11 X	1	
9	FRONT BUMPER GRILLE 11 X	1	
10	FRONT BUMPER FOG LAMP (L+R) 11 X	2	
11	FRONT BUMPER FOG LAMP GARNISH (L+R) 11 X	2	
12	FRONT BUMPER UNDERCOVER 11 X	1	
13	FRONT FENDER (RH) 20/24 ✓	1	
14	FRONT FENDER QUARTER GARNISH (RH) 11 X	1	
15	FRONT FENDER INNER PANEL (RH) 2 X	1	
16	FRONT FENDER COWLING (RH) ?	1	
17	FRONT DOOR (RH) 20/24 ✓	1	
18	FRONT DOOR SIDE MIRROR ASSY (RH) cut ✓	1	
19	FRONT DOOR SIDE MIRROR COVER (RH) 2 X	1	
20	FRONT DOOR SIDE MIRROR SIGNAL LAMP (RH) 11 X	1	
21	FRONT DOOR HANDLE (RH) 11 X	1	
22	FRONT DOOR HANDLE END CAP (RH) 11 X	1	
23	FRONT DOOR LOCK CYLINDER (RH) 11 X	1	
24	FRONT DOOR LOCK SWITCH (RH) 11 X	1	
25	FRONT DOOR WINDOW MOULDING (RH) 11 X	1	
26	FRONT DOOR INNER LOCK (RH) 11 X	1	
27	FRONT DOOR INNER LOCK CATCH (RH) 11 X	1	
28	FRONT DOOR INNER BOARD (RH) ?	1	
29	FRONT DOOR INNER BOARD SWITCH (RH) 11 X	1	
30	FRONT DOOR POWER WINDOW MOTOR (RH) 7	1	
31	FRONT DOOR WINDOW REGULATOR (RH) 7	1	
32	FRONT DOOR HINGE (UPPER & LOWER) (RH) 11 X	2	
33	FRONT DOOR CHECKER (RH) 11 X	1	
34	FRONT DOOR WEATHERSTRIP (RH) 2m ✓	1	
35	FRONT DOOR INNER WEATHERSTRIP (RH) 2m ✓	1	
36	REAR DOOR (RH) 20/24 ✓	1	
37	REAR DOOR HANDLE (RH) 11 X	1	
38	REAR DOOR HANDLE END CAP (RH) 11 X	1	
39	REAR DOOR WINDOW MOULDING (RH) 11 X	1	
40	REAR DOOR INNER LOCK (RH) 11 X	1	

41	REAR DOOR INNER LOCK CATCH (RH)	11X	1
42	REAR DOOR INNER BOARD (RH)	?	1
43	REAR DOOR INNER BOARD SWITCH (RH)	11X	1
44	REAR DOOR POWER WINDOW MOTOR (RH)	?	1
45	REAR DOOR REGULATOR (RH)	?	1
46	REAR DOOR HINGE (UPPER & LOWER) (RH)	11X	2
47	REAR DOOR CHECKER (RH)	11X	1
48	REAR DOOR WEATHERSTRIP (RH)	mm -	1
49	REAR DOOR INNER WEATHERSTRIP (RH)	mm -	1
50	ROCKER PANEL (RH)	2x50 -	1
51	ROCKER PANEL GARNISH (RH)	WSX	1
52	REAR WINDSCREEN MOULDING	11X	1
53	REAR FENDER (RH)	RX	1
54	REAR FENDER INNER TRIM (RH)	11X	1
55	REAR FENDER QUARTER GARNISH (RH)	11X	1
56	REAR FENDER COWLING (RH)	11X	1
57	TAIL LAMP (RH)	11X	1
58	TAIL LAMP PANEL (RH)	11X	1
59	REAR BUMPER	RX	1
60	REAR BUMPER RETAINER (L+R)	11X	2
61	REAR BUMPER REINFORCEMENT BAR	11X	1
62	REAR BUMPER BRACKET (L+R)	11X	2
63	REAR BUMPER BEAM	11X	1
64	REAR BUMPER SPONGE	11X	1
65	REAR BUMPER REVERSE SENSOR SET	11X	4
66	REAR BUMPER REFLECTOR (RH)	11X	1
67	REAR BUMPER UNDERCOVER	11X	1
68	FRONT ABSORBER (RH)	11X	1
69	FRONT LOWER ARM (RH)	11X	1
70	FRONT KNUCKLE (RH)	11X	1
71	FRONT KNUCKLE BEARING (RH)	11X	1
72	FRONT BEARING HUB (RH)	11X	1
73	FRONT CROSSMEMBER	11X	1
74	FRONT STEERING RACK AND PINION ASSY	11X	1
75	FRONT DRIVE SHAFT (RH)	11X	1
76	FRONT TIE ROD (RH)	11X	1
77	FRONT TIE ROD END (RH)	11X	1
78	FRONT STABILIZER BAR	11X	1
79	FRONT STABILIZER LINK (RH)	11X	1
80	REAR ABSORBER (RH)	11X	1
81	REAR LOWER ARM (RH)	11X	1
82	REAR KNUCKLE (RH)	11X	1
83	REAR KNUCKLE BEARING (RH)	11X	1
84	REAR BEARING HUB (RH)	11X	1
85	REAR AXLE	11X	1
		SUBTOTAL	\$ -
		LESS 20%	\$ -

		PARTS TOTAL	\$ -	
SPECIAL NETT		QTY	PRICE	
1	FRONT BUMPER CLIPS <i>mel 40</i>	10	\$ 100.00	
2	FRONT CARPLATE <i>11X</i>	1	\$ 120.00	
3	FRONT CARPLATE FRAME <i>11X</i>	1	\$ 120.00	
4	FRONT FENDER INNER PANEL SEALANT <i>11X</i>	1	\$ 120.00	
5	FRONT FENDER COWLING CLIPS <i>122 40</i>	10	\$ 100.00	
6	FRONT DOOR INNER BOARD CLIPS <i>11X</i>	10	\$ 100.00	
7	REAR DOOR INNER BOARD CLIPS <i>11X</i>	10	\$ 100.00	
8	ROCKER PANEL SEALANT <i>11X</i>	1	\$ 120.00	
9	ROCKER PANEL GARNISH CLIPS <i>11X</i>	10	\$ 100.00	
10	REAR WINDSCREEN MOULDING SEALANT <i>11X</i>	1	\$ 120.00	
11	TAIL LAMP CLIPS (L+R) <i>11X</i>	4	\$ 80.00	
12	REAR BUMPER CLIPS <i>11X</i>	10	\$ 100.00	
13	REAR FENDER SEALANT <i>11X</i>	1	\$ 120.00	
14	REAR FENDER INNER TRIM CLIPS <i>11X</i>	20	\$ 200.00	
15	REAR FENDER COWLING CLIPS <i>11X</i>	20	\$ 200.00	
16	FRONT TYRE SET <i>11X</i>	2	\$ 1,600.00	
17	FRONT RIM SET <i>cut 4005.2</i>	2	\$ 3,000.00	
18	REAR TYRE SET <i>11X</i>	2	\$ 1,600.00	
19	REAR RIM SET <i>11X</i>	2	\$ 3,000.00	
SPECIAL NETT TOTAL			\$ 1,800.00	
LABOUR		QTY	PRICE	
1	TO RNR ACCIDENT DAMAGE PARTS, CUT/WELD, KNOCK&REALIGN <i>800</i>	1	\$ 3,600.00	
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA <i>1400</i>	1	\$ 3,000.00	
3	TO RUST PROOF ACCIDENT AFFECTED AREA <i>100</i>	1	\$ 250.00	
4	TO RNR REAR WINDSCREEN <i>11X</i>	1	\$ 400.00	
5	TO RNR UPHOLSTERY, GARNISH AND ATTACHMENT PARTS <i>80</i>	1	\$ 400.00	
6	TO RNR DOOR MECHANISM FRONT & BACK <i>120</i>	1	\$ 800.00	
7	TO RNR REVERSE SENSOR & CHECK FUNCTION. <i>11X</i>	1	\$ 120.00	
8	TO RNR UNDERCARRIAGE SYSTEM <i>11X</i>	1	\$ 250.00	
9	TO CHECK WHEEL ALIGNMENT <i>60</i>	1	\$ 250.00	
10	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS <i>20</i>	1	\$ 150.00	
11	TO CHECK WIRING LAYOUT AND TAIL LAMP FUNCTION <i>20</i>	1	\$ 150.00	
12	TO RNR TYRE AND WHEEL BALANCING <i>11X</i>	1	\$ 250.00	
13	TO DO DIAGNOSIS AND RESET, REPROGRAM OR CODING FAULT CODE. <i>11X</i>	1	\$ 400.00	
14	TO DO WATER LEAK TEST. <i>11X</i>	1	\$ 80.00	
15	TO RNR FUEL TANK TO ASSIST WORK LOAD <i>11X</i>	1	\$ 250.00	
TOTAL			\$ 10,350.00	
GRAND TOTAL COST			\$ 12,150.00	



Rico 60 Auto Services Pte Ltd. Blk 8, Kaki Bukit Avenue 4, #02-24
Premier @ Kaki Bukit Singapore 415875. Email: claims@rico60.com
Tel: 6286 6060, FAX: 6286 7060

VEHICLE NUM:
MAKE & MODEL:
MILEAGE:
TYRE:
CHASSIS NUM:

SLA 3997 G
HONDA CITY

Not Almt
13/11/19
1/5 6000
705

Take the Airbag

ATTN	DESCRIPTION - PARTS	QTY	PRICE	
1	HEADLAMP (L+R) 11 X	2	41248.80	X
2	HEADLAMP BRACKET (L+R) 11 X	2	4240.80	X
3	FRONT BUMPER cut ✓ 459.80	1	4599.70	✓
4	FRONT BUMPER RETAINER (L+R) 8/5 steel 11c 25.20 659.00	21	4118.00	IPC
5	FRONT BUMPER REINFORCEMENT BAR 11 X	1	4264.30	X
6	FRONT BUMPER BRACKET (L+R) 11 X	2	NIL	X
7	FRONT BUMPER BEAM 11 X	1	NIL	X
8	FRONT BUMPER SPONGE 11 X	1	4246.60	X
9	FRONT BUMPER GRILLE 11 X	1	4194.40	X
10	FRONT BUMPER FOG LAMP (L+R) 11 X	2	4703.20	X
11	FRONT BUMPER FOG LAMP GARNISH (L+R) 11 X	2	4104.80	X
12	FRONT BUMPER UNDERCOVER 11 X	1	4293.10	X
13	FRONT FENDER (RH) 11/21 — 343.80	1	4443.50	✓
14	FRONT FENDER QUARTER GARNISH (RH) 11 X	1	482.00	X
15	FRONT FENDER INNER PANEL (RH) 11 X	1	4470.90	X
16	FRONT FENDER COWLING (RH) 2 De/Torn	1	475.70	✓
17	FRONT DOOR (RH) 11/21 — 738.40	1	41259.50	✓
18	FRONT DOOR SIDE MIRROR ASSY (RH) cut ✓ 227.00	1	4644.30	✓
19	FRONT DOOR SIDE MIRROR COVER (RH) 11 X	1	4201.50	X
20	FRONT DOOR SIDE MIRROR SIGNAL LAMP (RH) 11 X	1	4140.00	X
21	FRONT DOOR HANDLE (RH) 11 X	1	4201.40	X
22	FRONT DOOR HANDLE END CAP (RH) 11 X	1	487.00	X
23	FRONT DOOR LOCK CYLINDER (RH) 11 X	1	4281.50	X
24	FRONT DOOR LOCK SWITCH (RH) 11 X	1	491.00	X
25	FRONT DOOR WINDOW MOULDING (RH) 11 X	1	4163.80	X
26	FRONT DOOR INNER LOCK (RH) 11 X	1	4439.20	X
27	FRONT DOOR INNER LOCK CATCH (RH) 11 X	1	480.00	X
28	FRONT DOOR INNER BOARD (RH) De/Torn 435.50	1	4839.00	✓
29	FRONT DOOR INNER BOARD SWITCH (RH) 11 X	1	4703.20	X
30	FRONT DOOR POWER WINDOW MOTOR (RH) Best 309.20	1	4314.80	✓
31	FRONT DOOR WINDOW REGULATOR (RH) Best 309.20	1	4242.20	X
32	FRONT DOOR HINGE (UPPER & LOWER) (RH) 11 X	2	4136.60	
33	FRONT DOOR CHECKER (RH) 11 X	1	445.70	X
34	FRONT DOOR WEATHERSTRIP (RH) 11 — 64.90	1	4164.40	✓
35	FRONT DOOR INNER WEATHERSTRIP (RH) 11 — 60.60	1	4170.10	✓
36	REAR DOOR (RH) 11/21 — 712.50	1	41028.20	✓
37	REAR DOOR HANDLE (RH) 11 X	1	4188.90	X
38	REAR DOOR HANDLE END CAP (RH) 11 X	1	487.00	X
39	REAR DOOR WINDOW MOULDING (RH) 11 X	1	4163.80	X
40	REAR DOOR INNER LOCK (RH) 11 X	1	4430.90	X

12443.50

[illegible]

		PARTS TOTAL		\$	
SPECIAL NETT		QTY	PRICE		
1	FRONT BUMPER CLIPS <i>me 40</i>	10	\$	100.00	40
2	FRONT CARPLATE <i>11X</i>	1	\$	120.00	X
3	FRONT CARPLATE FRAME <i>11X</i>	1	\$	120.00	X
4	FRONT FENDER INNER PANEL SEALANT <i>11X</i>	1	\$	120.00	X
5	FRONT FENDER COWLING CLIPS <i>122 40</i>	10	\$	100.00	40
6	FRONT DOOR INNER BOARD CLIPS <i>11X</i>	10	\$	100.00	X
7	REAR DOOR INNER BOARD CLIPS <i>11X</i>	10	\$	100.00	X
8	ROCKER PANEL SEALANT <i>11X</i>	1	\$	120.00	X
9	ROCKER PANEL GARNISH CLIPS <i>11X</i>	10	\$	100.00	X
10	REAR WINDSCREEN MOULDING SEALANT <i>11X</i>	1	\$	120.00	X
11	TAIL LAMP CLIPS (L+R) <i>11X</i>	4	\$	80.00	X
12	REAR BUMPER CLIPS <i>11X</i>	10	\$	100.00	X
13	REAR FENDER SEALANT <i>11X</i>	1	\$	120.00	X
14	REAR FENDER INNER TRIM CLIPS <i>11X</i>	20	\$	200.00	X
15	REAR FENDER COWLING CLIPS <i>11X</i>	20	\$	200.00	X
16	FRONT TYRE SET <i>11X</i>	2	\$	1,600.00	X
17	FRONT RIM SET <i>11X 400'S.N</i>	2	\$	3,000.00	400
18	REAR TYRE SET <i>11X</i>	2	\$	1,600.00	X
19	REAR RIM SET <i>11X</i>	2	\$	3,000.00	X
<i>S/N: P480</i>					
SPECIAL NETT TOTAL			\$	1,800.00	
LABOUR		QTY	PRICE		
1	TO RNR ACCIDENT DAMAGE PARTS, CUT/WELD, KNOCK&REALIGN <i>800</i>	1	\$	3,600.00	
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA <i>1400</i>	1	\$	3,000.00	
3	TO RUST PROOF ACCIDENT AFFECTED AREA <i>100</i>	1	\$	250.00	
4	TO RNR REAR WINDSCREEN <i>11X</i>	1	\$	400.00	
5	TO RNR UPHOLSTERY, GARNISH AND ATTACHMENT PARTS <i>80</i>	1	\$	400.00	
6	TO RNR DOOR MECHANISM FRONT & BACK <i>120</i>	1	\$	800.00	
7	TO RNR REVERSE SENSOR & CHECK FUNCTION. <i>11X</i>	1	\$	120.00	
8	TO RNR UNDERCARRIAGE SYSTEM <i>11X</i>	1	\$	250.00	
9	TO CHECK WHEEL ALIGNMENT <i>60</i>	1	\$	250.00	
10	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS <i>20</i>	1	\$	150.00	
11	TO CHECK WIRING LAYOUT AND TAIL LAMP FUNCTION	1	\$	150.00	
12	TO RNR TYRE AND WHEEL BALANCING <i>11X</i>	1	\$	250.00	
13	TO DO DIAGNOSIS AND RESET, REPROGRAM OR CODING FAULT CODE. <i>11X</i>	1	\$	400.00	
14	TO DO WATER LEAK TEST. <i>11X</i>	1	\$	80.00	
15	TO RNR FUEL TANK TO ASSIST WORK LOAD <i>11X</i>	1	\$	250.00	
<i>P- 4488.80 L: P2580</i>					
<i>S.N- 480.00 Total: P10,562.40</i>					
<i>L- 2580.00 -20% = P8450</i>					
<i>TOTAL- 7548.80</i>					
<i>6039.04</i>					
TOTAL			\$	10,350.00	
GRAND TOTAL COST			\$	12,150.00	

02708 24

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Nov 2019		12 Nov 2019 17:50 Edit Adj Rpt	S\$6,000.00 Edit Estimates	S\$6,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	Co. Reg. No.: -								
Main Claimant:	LEE VINCENT, ID: S7135767H								
Vehicle Reg. No.:	SLA3997G	Date of Loss:	09/11/2019 17:00 - :59 [44 Months and 11 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D205334C02	Policy/Cover Note No.:	DMPCSN30799418000						
Vehicle Reg. No. (Insured):	SMG1464Y	Policy No. (Claimant):	SI19V02150/VPC/R03						
		Excess:	S\$1,000.00						
Repairer:	RICO 60 AUTO SERVICES PTE LTD (HQ) 8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]								
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 21/11/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLA3997G (SNM19D205334C02)**
[SMG1464Y]
TP
LEE VINCENT
Nov 9 2019 5:00PM
[-]
RICO 60 AUTO SERVICES PTE LTD

[Upload Documents](#) [Upload Photos](#) [Compose New Letter](#)

View [View in Browser](#)

No documents found.

Linked Accident Report Documents

View [View in Browser](#)

Assessment Reports				1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print	
1	06/12/19 19:00	Accident Statement	Load HTM		
2	06/12/19 19:00	Accident Statement	Load HTM		
3	06/12/19 19:01	Accident Statement	Load HTM		
4	06/12/19 19:01	Accident Statement	Load HTM		
Photos/Images				3 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print	
1	11/11/19 17:41	Accident Photo	Load JPG	☒	
2	11/11/19 17:41	Accident Photo	Load JPG	☒	
3	11/11/19 17:41	Accident Photo	Load JPG	☒	
4	11/11/19 17:41	Accident Photo	Load JPG	☒	
5	11/11/19 17:41	Accident Photo	Load JPG	☒	
6	11/11/19 17:41	Accident Photo	Load JPG	☒	
7	11/11/19 17:41	Accident Photo	Load JPG	☒	
8	11/11/19 17:41	Accident Photo	Load JPG	☒	
9	11/11/19 17:41	Accident Photo	Load JPG	☒	
10	11/11/19 17:41	Accident Photo	Load JPG	☒	
11	11/11/19 17:41	Accident Photo	Load JPG	☒	
12	11/11/19 17:41	Accident Photo	Load JPG	☒	
Documentation				1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print	
1	11/11/19 17:42	Accident Sketch Plan	Load JPG	☒	
2	11/11/19 17:42	Individual Statement	Load JPG	☒	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119020089/UYF3E2

Date: 22/01/2020

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN30799418000

Claimant Vehicle
No: SLA3997GInsured Vehicle
No: SMG1464Y

Date of Loss: 09/11/2019

Nature of Claim: TP

Claim
No: SNM19D205334C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLA3997G

Make & Model: HONDA CITY, 1.5 SV CVT (A)

Engine No: L15Z12720059

Reg. Date: 29/02/2016 (Man. Year: 2016)

Chassis No: MRHGM6660GP000477

Colour: Grey

Odometer: 57197 km

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55 R16

Rear Tyre Size: 185/55 R16

Front Left Side: Yokohama 7 mm

Rear Left Side: Yokohama 7 mm

Front Right Side: Yokohama 7 mm

Rear Right Side: Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	36,858.24	4,968.80	31,889.44	86.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,350.00	2,580.00	7,770.00	75.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	47,208.24	7,548.80	39,659.44	84.01
Approved Total (Overridden) (S\$)		6,000.00		
(S\$)	47,208.24	6,000.00	41,208.24	87.29
+ GST 7.00/7.00% (S\$)	3,304.58	420.00	2,884.58	87.29
Nett Amount (S\$)	50,512.82	6,420.00	44,092.82	87.29

INSPECTION

Date of Assignment: 12/11/2019

Date Inspected: 13/11/2019 Inspected At:

RICO 60 AUTO SERVICES PTE LTD (HQ)
8, KAKI BUKIT AVENUE 4, #02-24,
PREMIER @ KAKI BUKIT
Singapore 415875

Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA**Manager:** YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Jan 2020)
Parts:	143	HONDA CITY 1.5 SV CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLA3997G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	2	*HEADLAMP (L+R)	Not Necessary	1,248.80 FL	*- FL
2	2	*HEADLAMP BRACKET (L+R)	Not Necessary	240.80 FL	*- FL
3	1	*FRONT BUMPER	Cut	599.70 FL	*459.80 FL
4	1	*FRONT BUMPER RETAINER (L+R)	O/S Bent	118.00 FL	*25.20 FL
5	1	*FRONT BUMPER REINFORCEMENT BAR	Not Necessary	264.30 FL	*- FL
6	2	*FRONT BUMPER BRACKET (L+R) (NPA)	Not Necessary	0.00 FL	*- FL
7	1	*FRONT BUMPER BEAM (NPA)	Not Necessary	0.00 FL	*- FL
8	1	*FRONT BUMPER SPONGE	Not Necessary	246.60 FL	*- FL
9	1	*FRONT BUMPER GRILLE	Not Necessary	194.40 FL	*- FL
10	2	*FRONT BUMPER FOG LAMP (L+R)	Not Necessary	703.20 FL	*- FL
11	2	*FRONT BUMPER FOG LAMP GARNISH (L+R)	Not Necessary	104.80 FL	*- FL
12	1	*FRONT BUMPER UNDERCOVER	Not Necessary	293.10 FL	*- FL
13	1	*FRONT FENDER (RH)	Dented / Bent	443.50 FL	*343.80 FL
14	1	*FRONT FENDER QUARTER GARNISH (RH)	Not Necessary	82.00 FL	*- FL
15	1	*FRONT FENDER INNER PANEL (RH)	Repair	470.90 FL	*- FL
16	1	*FRONT FENDER COWLING (RH)	Deformed / Torn	95.70 FL	*95.70 FL
17	1	*FRONT DOOR (RH)	Dented / Bent	1,258.50 FL	*738.40 FL
18	1	*FRONT DOOR SIDE MIRROR ASSY (RH)	Cut	644.30 FL	*227.00 FL
19	1	*FRONT DOOR SIDE MIRROR COVER (RH)	Repair	201.50 FL	*- FL
20	1	*FRONT DOOR SIDE MIRROR SIGNAL LAMP (RH)	Not Necessary	140.00 FL	*- FL
21	1	*FRONT DOOR HANDLE (RH)	Not Necessary	201.40 FL	*- FL
22	1	*FRONT DOOR HANDLE END CAP (RH)	Not Necessary	87.00 FL	*- FL
23	1	*FRONT DOOR LOCK CYLINDER (RH)	Not Necessary	281.50 FL	*- FL
24	1	*FRONT DOOR LOCK SWITCH (RH)	Not Necessary	91.00 FL	*- FL
25	1	*FRONT DOOR WINDOW MOULDING (RH)	Not Necessary	163.80 FL	*- FL
26	1	*FRONT DOOR INNER LOCK (RH)	Not Necessary	439.20 FL	*- FL
27	1	*FRONT DOOR INNER LOCK CATCH (RH)	Not Necessary	80.00 FL	*- FL
28	1	*FRONT DOOR INNER BOARD (RH)	Deformed / Torn	829.50 FL	*435.50 FL
29	1	*FRONT DOOR INNER BOARD SWITCH (RH)	Not Necessary	707.30 FL	*- FL
30	1	*FRONT DOOR POWER WINDOW MOTOR (RH)	Bent / Jammed	314.80 FL	*309.20 FL
31	1	*FRONT DOOR WINDOW REGULATOR (RH)	Bent	482.20 FL	*- FL
32	2	*FRONT DOOR HINGE (UPPER & LOWER) (RH)	Not Necessary	136.60 FL	*- FL
33	1	*FRONT DOOR CHECKER (RH)	Not Necessary	45.70 FL	*- FL
34	1	*FRONT DOOR WEATHERSTRIP (RH)	Necessary	164.40 FL	*64.90 FL
35	1	*FRONT DOOR INNER WEATHERSTRIP (RH)	Necessary	170.10 FL	*60.80 FL
36	1	*REAR DOOR (RH)	Dented / Bent	1,028.30 FL	*712.50 FL
37	1	*REAR DOOR HANDLE (RH)	Not Necessary	188.90 FL	*- FL
38	1	*REAR DOOR HANDLE END CAP (RH)	Not Necessary	87.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	1		*REAR DOOR WINDOW MOULDING (RH)	Not Necessary	163.80 FL	*- FL
40	1		*REAR DOOR INNER LOCK (RH)	Not Necessary	430.90 FL	*- FL
41	1		*REAR DOOR INNER LOCK CATCH (RH)	Not Necessary	80.00 FL	*- FL
42	1		*REAR DOOR INNER BOARD (RH)	Deformed / Torn	803.90 FL	*435.50 FL
43	1		*REAR DOOR INNER BOARD SWITCH (RH)	Not Necessary	697.60 FL	*- FL
44	1		*REAR DOOR POWER WINDOW MOTOR (RH)	Bent / Jammed	304.80 FL	*302.20 FL
45	1		*REAR DOOR REGULATOR (RH)	Bent	482.20 FL	*- FL
46	2		*REAR DOOR HINGE (UPPER & LOWER) (RH)	Not Necessary	136.60 FL	*- FL
47	1		*REAR DOOR CHECKER (RH)	Not Necessary	45.60 FL	*- FL
48	1		*REAR DOOR WEATHERSTRIP (RH)	Necessary	168.90 FL	*64.90 FL
49	1		*REAR DOOR INNER WEATHERSTRIP (RH)	Necessary	170.10 FL	*60.80 FL
50	1		*ROCKER PANEL (RH)	Badly Dented	1,345.60 FL	*1,274.80 FL
51	1		*ROCKER PANEL GARNISH (RH)	Not Necessary	690.90 FL	*- FL
52	1		*REAR WINDSCREEN MOULDING	Not Necessary	142.30 FL	*- FL
53	1		*REAR FENDER (RH)	Repair	845.30 FL	*- FL
54	1		*REAR FENDER INNER TRIM (RH)	Not Necessary	490.40 FL	*- FL
55	1		*REAR FENDER QUARTER GARNISH (RH)	Not Necessary	79.00 FL	*- FL
56	1		*REAR FENDER COWLING (RH)	Not Necessary	110.40 FL	*- FL
57	1		*TAIL LAMP (RH)	Not Necessary	490.80 FL	*- FL
58	1		*TAIL LAMP PANEL (RH)	Not Necessary	240.20 FL	*- FL
59	1		*REAR BUMPER	Repair	872.30 FL	*- FL
60	2		*REAR BUMPER RETAINER (L+R)	Not Necessary	116.80 FL	*- FL
61	1		*REAR BUMPER REINFORCEMENT BAR (NPA)	Not Necessary	0.00 FL	*- FL
62	2		*REAR BUMPER BRACKET (L+R)	Not Necessary	164.20 FL	*- FL
63	1		*REAR BUMPER BEAM (NPA)	Not Necessary	0.00 FL	*- FL
64	1		*REAR BUMPER SPONGE (NPA)	Not Necessary	0.00 FL	*- FL
65	4		*SET REAR BUMPER REVERSE SENSOR	Not Necessary	1,080.40 FL	*- FL
66	1		*REAR BUMPER REFLECTOR (RH)	Not Necessary	73.40 FL	*- FL
67	1		*REAR BUMPER UNDERCOVER	Not Necessary	263.90 FL	*- FL
68	1		*FRONT ABSORBER (RH)	Not Necessary	496.70 FL	*- FL
69	1		*FRONT LOWER ARM (RH)	Not Necessary	342.60 FL	*- FL
70	1		*FRONT KNUCKLE (RH)	Not Necessary	398.60 FL	*- FL
71	1		*FRONT KNUCKLE BEARING (RH)	Not Necessary	199.70 FL	*- FL
72	1		*FRONT BEARING HUB (RH)	Not Necessary	241.90 FL	*- FL
73	1		*FRONT CROSSMEMBER	Not Necessary	1,246.10 FL	*- FL
74	1		*FRONT STEERING RACK AND PINION ASSY	Not Necessary	1,898.80 FL	*- FL
75	1		*FRONT DRIVE SHAFT (RH)	Not Necessary	1,078.70 FL	*- FL
76	1		*FRONT TIE ROD (RH)	Not Necessary	284.00 FL	*- FL
77	1		*FRONT TIE ROD END (RH)	Not Necessary	103.20 FL	*- FL
78	1		*FRONT STABILIZER BAR	Not Necessary	689.50 FL	*- FL
79	1		*FRONT STABILIZER LINK (RH)	Not Necessary	120.00 FL	*- FL
80	1		*REAR ABSORBER (RH)	Not Necessary	289.50 FL	*- FL
81	1		*REAR LOWER ARM (RH) (NPA)	Not Necessary	0.00 FL	*- FL
82	1		*REAR KNUCKLE (RH) (NPA)	Not Necessary	0.00 FL	*- FL
83	1		*REAR KNUCKLE BEARING (RH)	Not Necessary	290.30 FL	*- FL
84	1		*REAR BEARING HUB (RH)	Not Necessary	203.20 FL	*- FL
85	1		*REAR AXLE	Not Necessary	1,100.90 FL	*- FL
86	10		*FRONT BUMPER CLIPS	Necessary	100.00 FS	*40.00 FS
87	1		*FRONT CARPLATE	Not Necessary	120.00 FS	*- FS
88	1		*FRONT CARPLATE FRAME	Not Necessary	120.00 FS	*- FS
89	1		*FRONT FENDER INNER PANEL SEALANT	Not Necessary	120.00 FS	*- FS
90	10		*FRONT FENDER COWLING CLIPS	Necessary	100.00 FS	*40.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
91	10		*FRONT DOOR INNER BOARD CLIPS	Not Necessary	100.00 FS	*- FS
92	10		*REAR DOOR INNER BOARD CLIPS	Not Necessary	100.00 FS	*- FS
93	1		*ROCKER PANEL SEALANT	Not Necessary	120.00 FS	*- FS
94	10		*ROCKER PANEL GARNISH CLIPS	Not Necessary	100.00 FS	*- FS
95	1		*REAR WINDSCREEN MOULDING SEALANT	Not Necessary	120.00 FS	*- FS
96	4		*TAIL LAMP CLIPS (L+R)	Not Necessary	80.00 FS	*- FS
97	10		*REAR BUMPER CLIPS	Not Necessary	100.00 FS	*- FS
98	1		*REAR FENDER SEALANT	Not Necessary	120.00 FS	*- FS
99	20		*REAR FENDER INNER TRIM CLIPS	Not Necessary	200.00 FS	*- FS
100	20		*REAR FENDER COWLING CLIPS	Not Necessary	200.00 FS	*- FS
101	2		*SET FRONT TYRE	Not Necessary	1,600.00 FS	*- FS
102	2		*SET FRONT RIM	Cut	3,000.00 FS	*400.00 FS
103	2		*SET REAR TYRE	Not Necessary	1,600.00 FS	*- FS
104	2		*SET REAR RIM	Not Necessary	3,000.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	43,322.80	6,091.00
- List Item Discount on L Items 20.00/20.00% (S\$)	6,464.56	1,122.20
Total Parts (S\$)	36,858.24	4,968.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RNR ACCIDENT DAMAGE PARTS, CUT/WELD, KNOCK&REALIGN	New	3,600.00	800.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	New	3,000.00	1,400.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA	New	250.00	100.00
4	TO RNR REAR WINDSCREEN	New	400.00	0.00
5	TO RNR UPHOLSTERY, GARNISH AND ATTACHMENT PARTS	New	400.00	80.00
6	TO RNR DOOR MECHANISM FRONT & BACK	New	800.00	120.00
7	TO RNR REVERSE SENSOR & CHECK FUNCTION	New	120.00	0.00
8	TO RNR UNDERCARRIAGE SYSTEM	New	250.00	0.00
9	TO CHECK WHEEL ALIGNMENT	New	250.00	60.00
10	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS	New	150.00	20.00
11	TO CHECK WIRING LAYOUT AND TAIL LAMP FUNCTION	New	150.00	0.00
12	TO RNR TYRE AND WHEEL BALANCING	New	250.00	0.00
13	TO DO DIAGNOSIS AND RESET, REPROGRAM OR CODING FAULT CODE	New	400.00	0.00
14	TO DO WATER LEAK TEST	New	80.00	0.00
15	TO RNR FUEL TANK TO ASSIST WORK LOAD	New	250.00	0.00
Gross Labour Cost (S\$)			10,350.00	2,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >