

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 18793

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1349/2019/NS
Date : 12-Nov-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Lim Lay Cheng Jesslyn
(Lin Liqing)
Address : Blk 1E Cantonment Road
#32-49
Singapore 085501
Telephone : HP +65 97486511
Type of Claim : Own Damage Claims
Policy No. : 1800127905-01
Vehicle No : **SGJ 4009 P**
Model Code : Audi A4 SEDAN 2.0 TFSI 8W
Model / Year : 26-10-18
Engine No : CVK 068777
Chassis No : WAUZZZF40JA231825
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 07-Nov-19
Place of Accident : Traffic Junction Of Ang Mo Kio Ave 5

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SGJ 4009 P

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓	
2	To dismantle and renew front bumper, bonnet and both headlights. Re-organise crash management components. Reinstall all parts removed.	570 \$ 2,800.00 1000	
3	To respray front bumper and bonnet. 550	\$ 2,000.00 1100	
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: <u>\$ 5,472.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGJ 4009 P

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER / <i>OD</i>	\$	1,999.00
2	FRONT BUMPER FIXING PARTS <i>X</i>	\$	258.00
3	FRONT BUMPER SECURING STRIP ?	2 \$	64.00
4	FRONT BUMPER GRILLE - CENTRE / <i>OR</i>	\$	178.00
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE ?	\$	191.00
6	FRONT BUMPER AIR GUIDE - LH / RH ?	2 \$	112.00
7	RADIATOR GRILLE / <i>OR</i>	\$	1,227.00
8	AIR GUIDE GRILLE - LH / RH <i>X</i>	2 \$	246.00
9	FRONT BUMPER CARRIER / <i>OD (Photo)</i>	\$	733.00
10	FRONT BUMPER FOAM FILLER PIECE / <i>OR (Photo)</i>	\$	113.00
11	FRONT BUMPER COVER ?	\$	116.00
12	FRONT BUMPER GUIDE SECTION - LH ?	\$	33.00
13	FRONT BUMPER GUIDE SECTION - RH ?	\$	34.00
14	CAUTION SIGN STICKER ?	NEC \$	13.00
15	AIRCON STICKER ?	NEC \$	7.00
16	LOCK CARRIER BRACKET ?	\$	125.00
17	FRONT BUMPER SUPPORT - LH / RH ?	2 \$	52.00
18	FRONT PARKING AID SENSOR - LH / RH <i>RH ?</i>	2 \$	462.00
19	FRONT PARKING AID SEAL RING / <i>MC</i>	4 \$	12.00
20	HORN - LH HIGH TONE ?	\$	37.00
SUB TOTAL SPARE PARTS		\$	<u>6,012.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGJ 4009 P

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
21	HORN - RH LOW TONE ?	\$	262.00
22	SPRING SHACKLE - LH / RH ?	2 \$	52.00
23	BONNET / 00	\$	2,554.00
24	BONNET ATTACHMENT PARTS ?	\$	111.00
25	BONNET LID HINGE - LH / RH X	2 \$	554.00
26	BONNET IMPACT PROTECTION - CENTRE / LH / RH / MC	3 \$	75.00
27	BONNET STRIKER - LH / RH ?	2 \$	92.00
28	BONNET LID LOCK ?	2 \$	391.00
29	FLAT CONNECTOR HOUSING ?	2 \$	24.00
30	BONNET BOWDEN CABLE - CENTRE ?	\$	53.00
31	BONNET BOWDEN CABLE ?	\$	53.00
32	BONNET RELEASE LEVER ?	\$	12.00
33	LED HEADLIGHT - LH / RH X	2 \$	14,174.00
34	LIFT CYLINDER - LH / RH X	2 \$	384.00
35	HEADLIGHT CORRUGATED PIPE X	\$	83.00
36	RADIATOR AIR GUIDE - LH / RH ?	2 \$	50.00
37	RADIATOR UPPER AIR GUIDE - LH / RH ?	2 \$	22.00
38	RADIATOR AIR GUIDE - UPPER ?	2 \$	15.00
39	RADIATOR AIR GUIDE - LOWER ?	\$	19.00
40	AIR INTAKE AIR DUCT X	\$	19.00
41	AIR INTAKE AIR GUIDE X	\$	48.00
42	AIR INTAKE FILTER X	\$	339.00
43	AIR INTAKE HOSE X	\$	85.00
44	AIR MASS METRE X	\$	533.00
45	FRONT NO PLATE / BT	S/N \$	40.00
46	SUNDRIES ?	\$	400.00

TOTAL SPARE PARTS

\$ 26,456.00

TOTAL LABOUR CHARGES

\$ 5,472.00

GRAND TOTAL

\$ 31,928.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Steve (LKK)
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :
13/11/19, 10:30 am
OO - Not Author (Rev'd)
EXCER - ?
5 days
P/P
Ry Ref sm

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant