

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/1349/2019/NS

5-Dec-19

Glory Tan

1 of 1

SGJ 4009 P

Audi A4 SEDAN 2.0 TFSI 8W

Quantity	Description	Unit Price	Amount
Parts			
1	Front bumper reinforcement bracket LHS	\$ 207.00	BT
2	Front bumper reinforcement bracket RHS	\$ 207.00	BT
3	External temperature bracket	\$ 17.00	MC
4	Aircond condenser	\$ 568.00	DD
		\$ 999.00	
Labours			
1	To remove and renew aircond condenser. Pressurise cooling system. To carry out vacuum and regas.	s/n \$ 960.00	
2	To dislodge and reinstall front lock carrier to facilitate front bumper reinforcement brackets renewal.	\$ 2,100.00	1040 (photo to renew)
3	To repair rhs front fender. 1/2	\$ 700.00	250
4	To respray rhs front fender.	\$ 900.00	550
Labours total		\$ 4,660.00	
Parts total		\$ 999.00	
TOTAL		\$ 5,659.00	

Steve 6/12/19

For Premium Automobiles Pte Ltd

additional 4 repair days, total 9 days

Authorised Signature