

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 433T**AAD1911-090***Not Authored**Pursuing B4 going***12 NOV 2019**

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

11 NOV 2019**SHD 433T**

VF1ABL15AUC283406

RENAULT

LATITUDE

9.11.19

AIG

27/4/2017

PART

1	1	BUMPER COVER REAR
2	1	BUMPER LOWER REAR
3	1	BUMPER BRACKET CTR REAR
4	1	BUMPER BRACKET SIDE RH REAR
5	1	BUMPER RETAINER RH REAR
6	1	BUMPER REFLECTOR RH
7	1	BUMPER BRACKET SIDE LH REAR
8	1	BUMPER RETAINER LH REAR
9	1	BUMPER REFLECTOR LH
10	1	BUMPER BEAM REAR
11	1	BUMPER BEAM BRACKET LH REAR
12	1	BUMPER BEAM BRACKET RH REAR
13	1	BUMPER BLOCK LH REAR
14	1	BUMPER BLOCK RH REAR
15	1	BUMPER HARNESS REAR
16	1	OUTER PANEL REAR (End Panel)
17	1	OUTER PANEL REAR (End Panel) TRIM
18	1	SPARE WHEEL PANEL (Luggage Floor Panel)
19	1	SPARE WHEEL PANEL TRIM
20	1	SPARE TYRE BOARD
21	1	TAILLAMP RH
22	1	TAILLAMP PANEL RH
23	1	TAILLAMP LH
24	1	TAILLAMP PANEL LH
25	1	BOOT REAR
26	1	BOOT FINISHER

LIST

\$	<i>Bul Lum</i>	561.70	✓
\$	<i>Dis Lum</i>	411.90	✓
\$	<i>SL</i>	98.10	X
\$	<i>SL</i>	82.10	X
\$	<i>SL</i>	59.80	X
\$	<i>SL</i>	16.60	X
\$	<i>SL</i>	80.80	X
\$	<i>SL</i>	54.20	X
\$	<i>CM</i>	16.60	✓
\$	<i>Bz</i>	547.80	✓
\$	<i>Dis</i>	114.50	✓
\$	<i>Dis</i>	100.90	✓
\$	<i>SL</i>	75.70	X
\$	<i>SL</i>	76.50	X
\$	<i>SL</i>	301.10	X
\$	<i>Bz</i>	745.80	✓
\$	<i>nd</i>	404.56	✓
\$	<i>Bz/Bu</i>	1,229.40	✓
\$	<i>SL</i>	612.21	X
\$	<i>SL</i>	680.90	X
\$	<i>ngcm</i>	313.10	✓
\$	<i>KL</i>	401.40	X
\$	<i>ngcm</i>	401.40	✓
\$	<i>KL</i>	401.40	X
\$	<i>Bz</i>	1,677.20	✓
\$	<i>SL</i>	344.70	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD1911-090**SHD 433T**

27	1	BOOT WHEATERSTRIP	\$	Sn	178.20	X
28	1	BOOT REFLECTOR LAMP LH	\$	Sn	277.70	X
29	1	BOOT REFLECTOR LAMP RH	\$	Sn	277.70	X
30	1	BOOT INNER BOARD	\$	Sn	611.00	X
31	1	BOOT BADGE 'RENAULT'	\$	na	82.40	✓
32	1	BOOT BADGE	\$	na	95.80	✓
33	1	BOOT STRUT LH	\$	Sn	145.10	} X
34	1	BOOT STRUT RH	\$	Sn	145.10	
35	1	BOOT HINGE LH	\$	na	254.20	
36	1	BOOT HINGE RH	\$	na	253.80	
37	2	BOOT RUBBER PLUG	\$	Sn	139.90	
38	2	BOOT BUFFER	\$	Sn	26.80	
39	1	BOOT LOCK LINKAGE	\$	Sn	20.60	
40	1	BOOT LOCK LINKAGE HOLDER	\$	Sn	99.50	
41	1	BOOT TRIM BOARD	\$	Sn	611.00	
42	1	BOOT SWITCH	\$	Sn	113.00	} X
43	1	BOOT LOCK	\$	na	246.60	
44	1	BOOT LOCK CATCH	\$	na	41.70	
45	1	EXHAUST REAR	\$	By	5,263.60	✓
46	1	EXHAUST CAP REAR	\$	na	125.40	✓
TOTAL			\$		18,819.47	
10%			\$		1,881.95	
			\$		16,937.52	

Special Nett

1	1SET	PARKING AID	\$	Shot	700.00	400.00
2	1SET	REAR BUMPER CLIP	\$	na	66.00	✓
3	1SET	BUMPER BRACKET CTR CLIP	\$	na	33.00	✓
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X
5	1SET	BUMPER RETAINER RH CLIP RR	\$	na	20.00	X
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00	X
7	1SET	BUMPER RETAINER CLIP LH RR	\$	na	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	na	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	na	66.00	✓
10	1	BOOT STICKER "Trans-cab"	\$	na	30.00	✓

Trans-cab Auto Services Pte Ltd**AAD1911-090**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 433T

11	1	BOOT STICKER "6555-3333"	\$	na	30.00	✓
12	2	REAR WINDSCREEN SEALANT	\$	na	80.00	X
13	1	WINDSCREEN MOULDING	\$	na	100.00	X
14	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	X
15	1	BOOT INNER TRIM CLIP	\$	na	45.00	X
16	1SET	BOOT FINISHER CLIP	\$	na	24.20	X
17	1	EXHAUST MOUNTING REAR	\$	na	16.00	X
18	1	Rear Bumper Protector	\$	na	100.00	4050
19	1	TAILLAMP CLIP LH	\$	na	5.00	✓
20	1	TAILLAMP CLIP RH	\$	na	5.00	✓
21	1	Rear licence plate with holder	\$	na	80.00	X
TOTAL			\$		1,562.20	
TOTAL PARTS			\$		18,499.72	

LABOUR

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	na	380.00 X
To Rust-Proofing Of The Affected Areas.	\$	170.00	901
To Check Electrical Lighting Concerned.	\$	170.00	201
To transfer of tire, rim and on wheel balancing.	\$	na	170.00 X
To reinstall rear bumper parking sensor.	\$	170.00	601
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	7,500.00	12001
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	na	170.00 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 433T**AAD1911-090**

To transfer of rear windscreen glass to facilitate bodywork repair.	\$	<i>na</i>	170.00	<i>X</i>
To repair and realign rear exhaust pipe.	\$		170.00	<i>801</i>
To check steering geometry and computer wheel alignment	\$	<i>na</i>	220.00	<i>X</i>
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$		170.00	<i>801</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>na</i>	380.00	<i>X</i>
Putty and spray painting of the affected portion.	\$		7,500.00	<i>8801</i>
To supply and re-do rear luggage floor panel insulation padding.	\$		380.00	<i>801</i>
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	<i>na</i>	170.00	<i>X</i>
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	<i>na</i>	380.00	<i>X</i>
Towing Fees	\$	<i>na</i>	170.00	<i>X</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>na</i>	170.00	<i>X</i>
TOTAL	\$		18,780.00	
Over All Total	\$		37,279.72	

LKK Auto Consultancy Pte Ltd
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PART BY PART (REPAIR DAY)**25 DAYS***8 days*