

Your Ref : MT/1070771-002

Date: 22nd November 2019

Our Ref : CS/INC19020129/Gsd3s2

M/s NTUC Income Insurance Co-Operative Ltd

73 Bras Basah Road
#05-01 NTUC Trade Union House
Singapore 189556
(The Motor Claims Department)

Attn; Helena Tan

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE EM 1175U
ACCIDENT ON 10/11/2019 INSURED VEHICLE SHD 1108B**

Instruction was received to inspect the vehicle Reg. No. EM 1175U. The inspection was conducted on 22/11/2019 at the premises of M/s Kinsmen Auto Pte Ltd, 1 Kaki Bukit Avenue 6 #02-19 Autobay Building Singapore 417883.

The following vehicle information was recorded:

Registration Number	: EM 1175U
Make/Model	: Mercedes Benz C180
Year of Registration	: 2005
Body Colour	: Silver
Chassis Number	: WDC2030462R181366
Engine Capacity	: 1796 cc

The vehicle sustained damages at the front portion and undercarriage. The chassis frame affected due to collision. (Details see photographs enclosed).

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **"Total Loss"**.

Market Value	SS	43,000.00
Less: LTA Reimbursement Value (RV)	(SS	40,004.00)
Nett Liability	SS	<u>2,996.00</u>

Vehicle Inspected By:



XING GUO QIANG
M.MATAI, AMSAE-A
Automotive Assessor



K.K.LAU
MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.