

PRECISE AUTO SERVICE

NO. 1 KAKI BUKIT AVE 6 #02-33/34/36 SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO. : 35766600C

GST REG. NO. : 35766600C

16-03-2020

Date Of Accident : 11-11-2019

OUR REF : SLC 2823X/T/19

Lee Fu Sin

Blk 678B Jurong West Street 64

#07-319

Singapore 642678

Lkk Adrian TPAIG
Aster

Date In/out: 14/12/19 to 19/12/19

Tax 68416315
on 17/03/20

ESTIMATE BILL ON VEH. NO. : SLC 2823X

MODEL : TOYOTA WISH

CHASSIS NO : JTDGG20W40J004136

LIST ITEM

Rear Bumper Fascia	del	609	579	1,678.90
Rear Bumper Side Retainer LH	new	456.75	*	121.25
Rear Bumper Clips	new	8pcs @ 12.90	30	103.20
				1,903.35
Less Discount 25%:				475.84
				1,427.51

LABOUR CHARGE

To remove & refix reverse sensor	50	120.00
To respray affected areas	400	780.00
To check computer wheel alignment	730	80
To renew damaged parts, straighten & repair rear LH fender, rear LH sport rim & aligned all parts	200	750.00
		3,197.51
GST 7%:		223.83
AMOUNT DUE :		3,421.34

total: 1186.75
h/s: 950 ✓
03 Dimp ✓

Consultants hence notify
order of the following:
* before/after spray painting
* damaged part(s) during resurvey
* all works are subject to confirmation
* resurvey is on a "Without Prejudice" basis
* modification(s) is allowed
* any item(s) must be resurveyed and
subject to final approval from Insurance Company.

Accepted by Repairer