

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19020139/T1DA3Q2

Date: 10/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant

Vehicle No : FBN5379C

Insured Vehicle No : SCX414C

Date of Loss: 10/11/2019

Nature of Claim: TP

Claim No: 6070747764SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBN5379C**

Make & Model: YAMAHA JUPITER 115 Z1, 114cc

Engine No: E3R5E0210924

Reg. Date: 25/10/2018 (Man. Year: 2018)

Chassis No: MH3UE1120JJ199911

Colour: Blue

Odometer: 26023 km

Engine Capacity: 114 cc

Market Value/New Car

Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 70/90 R17

Rear Tyre Size:

80/90 R17

Front Left Side: Michelin 6 mm

Rear Left Side:

Michelin 6 mm

Front Right Side: 0 mm

Rear Right Side:

0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,651.00	2,832.50	4,818.50	62.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,980.00	750.00	1,230.00	62.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	9,631.00	3,582.50	6,048.50	62.80
Approved Total (Overridden) (\$\$)		2,850.00		
Nett Amount (\$\$)	9,631.00	2,850.00	6,781.00	70.41
+ Car Rental (7.0 x S\$40.00/day) (\$\$)		280.00		
+ Doc/Search Fee (\$\$)		36.49		
Nett Liability (\$\$)		3,166.49		

INSPECTION

Date of Assignment: 13/11/2019

Date Inspected: 14/11/2019 Inspected At:

KARZ WORKS PTE LTD

53 Ubi Avenue 1 #01-23 Paya Ubi Ind. Park

Singapore 408934

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SET FRONT FAIRING (FULL SET)	Cracked	500.00 FL	*350.00 FL
2	1		*SET WING MIRROR	Cut	250.00 FL	*150.00 FL
3	1		*SET BALANCER	Cut	180.00 FL	*120.00 FL
4	1		*FRONT HEADLAMP	Cracked	450.00 FL	*195.00 FL
5	1		*FRONT HEADLAMP FAIRING	Cut	280.00 FL	*105.00 FL
6	1		*SPEEDO METER	Not Necessary	600.00 FL	*- FL
7	1		*IU UNIT	Cracked	300.00 FL	*200.00 FL
8	1		*SET FRONT FORK	Bent	550.00 FL	*400.00 FL
9	1		*SET FRONT FORK BRACKET	Bent	290.00 FL	*185.00 FL
10	1		*BRAKE PADEL	Not Necessary	150.00 FL	*- FL
11	1		*CLUTCH PADEL	Not Necessary	150.00 FL	*- FL
12	1		*FRONT FOOTREST	Bent	210.00 FL	*100.00 FL
13	1		*PILLION FOOTREST	Dented	210.00 FL	*100.00 FL
14	1		*SEAT	Not Necessary	850.00 FL	*- FL
15	1		*PILLION HANDREST	Repair	280.00 FL	*- FL
16	1		*LH SIGNAL LAMP	Cracked	220.00 FL	*158.00 FL
17	1		*FRONT FENDER	Cracked	250.00 FL	*122.00 FL
18	1		*REAR LAMP	Cracked	210.00 FL	*210.00 FL
19	1		*REAR FENDER	Cut	250.00 FL	*250.00 FL
20	1		*KEY	Bent	300.00 FS	*180.00 FS
21	1		*REAR BOX	Not Necessary	350.00 FS	*- FS
22	1		*GEAR SHIT SHAFT OIL SEAL	Not Necessary	12.00 FS	*- FS
23	1		*FORK OIL SEAL	Necessary	45.00 FS	*30.00 FS
24	1		*FORK OIL	Necessary	12.00 FS	*12.00 FS
25	1		*REAR CARPLATE	Bent	60.00 FS	*15.00 FS
26	1		*FRONT CARPLATE	Bent	60.00 FS	*15.00 FS
27	1		*RIM	Bent	350.00 FS	*200.00 FS
28	2		*TYRE	Not Necessary	900.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,269.00	3,097.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	618.00	264.50
Total Parts (\$\$)	7,651.00	2,832.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REPLACE ,REALIGN AND ADJUST ABOVE DAMAGE PARTS AND CHECK WIRING AND LIGHTING SYSTEM	New	600.00	250.00
2	TO REMOVE/REFIT ,REPLACE FRONT FORK	New	380.00	100.00
3	SPRAY PAINTING	New	700.00	300.00
4	REMOVE AND RESTICK STICKER	New	300.00	100.00
Gross Labour Cost (\$\$)			1,980.00	750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >