

CHOO MOTOR SPRAY PAINTER  
 BLK1 KAKI BUKIT AVE 6  
 #01-39 AUTOBAY  
 SINGAPORE 417883

Not Authorized on  
 work  
 PIP # 1296.38  
 2/17 - 13/1/19

VEHICLE NO: SJP 5599D

QTY	PARTICULAR		
1 PCS	REAR BUMPER		
1 PCS	REAR BUMPER LOWER GARNISH		
1 PCS	REAR BUMPER LOWER CHROME	743.32	
1 PCS	REAR BUMPER LICENCE PLATE GARNISH	75.50	
1 PCS	REAR BUMPER PDC SENSOR		
1 PCS	REAR LICENCE PLATE W/HOLDER		
<b>LABOUR CHARGES</b>			
	TO CHECK WIRING		\$30.00 20
	TO DISMANTLE & REFIX PDC SENSOR		\$80.00 50
	TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTREY		\$120.00 X
	LABOUR FOR PANEL BEATING & REPLACING PARTS		\$380.00 250
	TO PUTTY & SPRAY PAINTING		\$450.00 200
<b>TOTAL</b>			<b>\$4,693.90</b>

n \$1,615.45 X  
 su \$788.50 X  
 sca/cm \$815.45 /  
 belt/m \$99.50 /  
 sc \$265.00 X  
 seat \$50.00 40 s.v

10%

P- 818.82  
 102  
 736.93  
 1296.93

LICK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: