

e

Not Allowed
1600
13/11/19
3/27

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50

AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6886 9095 Email: claims@focusauto.com.sg

GST:200712509E RCB NO:201004495R

e

M/S : LONPAC INSURANCE

Estimate No: EST0001048

Date: 12 Nov 2019

Policy No:

Veh Reg No: **GBA863Y**

Make/Model: TOYOTA DYNA

Chassis No: 1KD1575487

Engine No: JTFAT35Y703000353

Reg. Date: 02/02/2007

ATTN: Motor Claim Department
Your Ref No: GBA863Y
Claim Type: Third Party
Accident Date: 21/10/2019

Estimate Repair Cost to Vehicle No :GBA863Y

PAGE:1/1

Description	U/Price	Quantity	List Price	Amount	
				SS	SS
List Price					
1 Rear Tail Gate	1,237.20	1 PC	1,237.20		X
2 Rear Tail Gate Side Lock - RH	78.20	1 PC	78.20		X
3 Rear Tail Gate Emblem (Toyota)	120.20	1 PCS	120.20		X
4 Rear Side Gate - RH	2,346.20	1 PC	2,346.20		X
			3,781.80		
	Less 25%		945.45	2,836.35	
Special Net					
5 Rear Tail Gate Sticker 70 KM/H	20.00	1 PC	20.00		X
6 Rear Tail Gate Sticker - 13 Pax	20.00	1 PC	20.00		X
7 Rear Tail Gate Aluminium Plate	650.00	1 PCS	650.00		X
			690.00	690.00	
Labour					
8 Panel Beating	800.00	1 PC	800.00		400
9 Spray Painting	800.00	1 PC	800.00		400
			1,600.00	1,600.00	
			Total	SS 5,126.35	

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND ONE HUNDRED TWENTY SIX AND CENTS THIRTY FIVE ONLY

...ence notify
the Receiver of the following:
... damaged part(s) during resurvey
... prices are subject to confirmation

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature

For FOCUS AUTO PTE LTD

AUTHORISED SIGNATURE

2063.82