

ASS. REC. BY:

REF:

es/INC19020152/R19d3⁵²

Special Instruction:

Surveyor: Rasul

ASSIGNMENT (Office)

From (Person): Huzalya Bt Ibrahim of INC Date/Time: 13/11/19 9:47am

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLL 3226R Insured: GBJ9737Y

at Workshop m/s Pegasus Tel: 65137748

of 74 Kiah Teck Road

Policy No: Claim No: MT/1071048-001

Sum Insured: Excess:

Make of Veh: D.O.A. 11/11/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10:01am @ 13/11/19 Person Contacted: cheun Vehicle IN/OUT

Date/Time	Action/Instruction Estimate
	SIR 3226R-X
22/01/20 @ 10:40am	Ramir finalised with UNAN US \$2000, 4 days (Paid \$5995.60, 79%)

ASS. REC. BY:

REF:

2004

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SLL 3226Rat Workshop m/s PEGASUSof 74, KIAN TUCK RDInsured: NTUC

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLL 3226R Yr Regn: 2017 / PGRType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MAZDA 3 SEDAN 1.8L c.c. 1496Colour: GREEN A/C: Insured / Std / NI / NASp. Reading: 173145 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM6BN22A8H0141459Gen. Cond: Good / ☒ Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/60R16R: 1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or TRIANGLE

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 11/11/19 D.O.I. 13/11/19 1.39pmSurvey held at PEGASUS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 05 FEB 2020

Date/Time, File Pass to?

1) 04/2 11/19

Date/Time, File Return to?

2) _____

Report Formed: TPLump Sum / A.P. / G. 2000Days Of Repair: 4Resurvey No. of Trip: 1

Add Fee:

☐ Site Insp (\$ _____)☐ Interview (\$ _____)☐ Tech. Inve (\$ _____)☐ Weekend (\$ _____)

Survey Fee:

Transportation:

3 + RS \$ _____

Photos

Others

TOTAL

Nivitha (LKK Auto)

From: Hazalysa Binte Ibrahim <hazalysa.ibrahim@income.com.sg>
Sent: Thursday, 14 November 2019 8:49 AM
To: Admin-D (LKKAuto); assignments
Cc: SUR; Hazalysa Binte Ibrahim
Subject: RE: TP CASES FARMED OUT TO LKK ON 13/11/2019

Dear LKK,

Re-send with complete details.

Warmest Regards

Hazalysa Bte Ibrahim
Admin Assistant
Operations, Motor & Personal Lines (PL)
www.income.com.sg

income
made different



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Thursday, 14 November 2019 7:41 AM
To: Hazalysa Binte Ibrahim <hazalysa.ibrahim@income.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: TP CASES FARMED OUT TO LKK ON 13/11/2019

Dear Hazalysa,

Kindly assist to provide us the complete details of the below assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hazalya Binte Ibrahim [mailto:hazalya.ibrahim@income.com.sg]

Sent: Wednesday, 13 November 2019 9:47 AM

To: Admin-D (LKKAuto) <admin-d@lkkauto.com>; assignments <assignments@lkkauto.com>

Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Hazalya Binte Ibrahim <hazalya.ibrahim@income.com.sg>

Subject: TP CASES FARMED OUT TO LKK ON 13/11/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	Azhari	MT/1071002-001	FBH4158L	HKL LIM TEAM MOTORSPORT	BLK 1008 #01-24 BUKIT MERAH LANE 3 SINGAPORE 159722	James Lim (Keong) / 6275-6656		SGG1021M	23/06/19	6275-6566
2	Chryllis Quah	MT/1070958-001	SCR233P	MAXIMUS RACING PTE LTD	MR PERFORMANCE CENTRE 7 SOON LEE STREET #05-05 ISPACE SINGAPORE 627608	Arry Seah / 8858 3131	12:00-16:00	SKT7763A	11/11/19	9638 2477
3	Jared Liu	MT/1071048-001	SLL3226R	PEGASUS ENGINEERING & TRADING PTE LTD	74 KIAN TECK ROAD SINGAPORE 628800	Chern / 65137748	14:00-16:00	GBJ9737Y	11/11/19	Driver waiting
4	Eric Tang	MT/1070984-001	SLR4815C	PEGASUS ENGINEERING & TRADING PTE LTD	74 KIAN TECK ROAD SINGAPORE 628800	Chern / 65137748	10:30-16:00	XD3747D	12/11/19	

5	Muhammad Airwan	MT/1070829-002	SMD4745H	TRANS EUROKARS PTE LTD	27A TANJONG PERJURU SINGAPORE 609042	Samuel Ng /	15:00-16:00	SJA3340A	11/11/19	
6	Jeff Lin	MT/1071063-001	SMH5296J	XINYA AUTO SERVICES PTE LTD	BLK 1002 #01-75 BUKIT MERAH LANE 3 SINGAPORE 159719	/ 62703481		SKJ1748L	08/11/19	
7	Muhammad Airwan	MT/1068445-002	SMH4477K	AUTO INSURE PTE LTD	6 MARSILING LANE	Mr Sam Goh / 31572628		SLJ4787S	21/10/19	9743 6363
8	Charlotte Chew	MT/1067845-002	SML3246X	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD	209 PANDAN GARDENS SINGAPORE 609339	Kevin Leong / 81680997	10:00-12:00	SKW4924G	19/10/19	6568 4501
9	Fiona Shen	MT/1055123-002	SLR758K	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD	209 PANDAN GARDENS SINGAPORE 609339	Edwin Calna / 91819978	10:00-12:00	FBH1536Z	25/07/19	6568 4501
10	Helena Tan	MT/1070771-002	EM1175U	CYCLE & CARRIAGE INDUSTRIES PTE LTD	188 PANDAN LOOP SINGAPORE 128378	GO CHEE HAN / 9181 7717		SHD1108B	10/11/19	6771 4336
11	Jared Liu	MT/1065746-002	SLX4511Y	ETHOZ AUTOMOTIVE SOLUTIONS LTD	30 BUKIT BATOK CRESCENT SINGAPORE 658075	Lee Chen Sin / 8822 8339		GBJ5365M	07/10/19	6654 7520
12	Jeff Lin	MT/1071022-001	SGG5504K	WOON MENG MOTOR PTE LTD	50 BUKIT BATOK STREET 23 #01-06 MIDVIEW BUILDING SINGAPORE 659578	/ 63161131		XE1549S	08/11/19	63161151

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

Warmest Regards

Hazalya Bte Ibrahim
Admin Assistant
Motor Department
T +65 6430 7902
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.

Find out more at Income.com.sg/careers

in with you

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

Shiau Chan (LKKAUTO)

From: Vivian Tan <vivian.pegasusengrg@gmail.com>
Sent: Wednesday, 22 January 2020 10:40 AM
To: Rasul (LKKAUTO)
Subject: Re: Finalise For SLL3226R (DOA 11/11/2019)-TP (NTUC)

Without Prejudice,

We confirm COR @ L/S S\$2,000.00 and 04 repair days.

Regards,
Vivian Tan
Pegasus Engineering & Trading Pte Ltd

Tel : 6513 7748 | Fax : 6251 3161
Add : 74 Kian Teck Road Singapore 628800

Make Life a Beautiful Ride

On Wed, 15 Jan 2020 at 11:26, Rasul (LKKAUTO) <Rasul@lkkauto.com> wrote:

Hi Vivian,

-

Kindly confirm the finalised amount below that is \$ 2000

-

-

-

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/11/2019 11:42
Date Of Accident	11/11/2019 16:25
Exact Location Of Accident	JUNCTION OF BENDEMEER RD & KALLANG BAHRU
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLL3226R
Insured/Policyholder	
Name Of Registered Owner	GRAB RENTALS PTE LTD
Co Reg No	201617200G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96395109
Alternative Phone No	OFFICE-66550005

Vehicle Particulars

Manufacturer	MAZDA
Model	3
Exact Purpose for which vehicle was being used at time of accident	PRIVATE HIRE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	A29114756MKF
Cover Note Number	

Driver

Name of Driver	THIANG CHEONG PIN
NRIC No	S1442181E
Date Of Birth	30/05/1960
Occupation	OUTDOOR
Date Of Driving Pass	03/12/1981
Driving Experience	37 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96395109
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 170 LORONG 1 TOA PAYOH #05-1088
Postcode	310170
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : ADERYL GENDER: : FEMALE
Passenger 2	NAME: : UNKNOWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 11 NOV 2019 AT ABOUT 1625HRS, I WAS DRIVING MY VEHICLE SLL3226R AT LAVENDER ST TOWARDS KALLANG BAHRU. AT THE TRAFFIC LIGHT JUNCTION, I INTENDED TO MAKE A RIGHT TURN TO TURN INTO KALLANG BAHRU. I WAS IN FIRST LANE. SUDDENLY VEHICLE GBJ9737Y FROM SECOND LANE OVERTOOK MY VEHICLE AND CUT INTO MY LANE. WHILE OVERTAKING VEHICLE GBJ9737Y COLLIDED ONTO MY LEFT SIDE FRONT PORTION. NOBODY WAS INJURED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	SD CARD WITH WORKSHOP
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBJ9737Y
Vehicle Make/Model/Colour	TOYOTA DYNA
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	

Contact Number +6586610311

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

3

Passenger 1

NAME: :

GENDER: :

Passenger 2

NAME: :

GENDER: :

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time: 12/11/14-10301


Reporting Centre Personnel's Signature
Name: Khimly
NRIC/FIN No.:

Sketch Plan #2



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 11 NOV 2014 at about 1625 hrs, I was driving my vehicle SLG 3226R at Lavender St Towards Kallang Bharu. At the traffic light junction I intended to make a right turn to turned into Kallang Bharu. I was in first lane. Suddenly vehicle GBJ 9737Y from second lane overtook my vehicle and cut into my lane. While overtook vehicle GBJ 9737Y collided onto my left side front portion. No body was injured.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 10/11/14 - 1020H

Reporting Centre Personnel's Signature
Name: Khamay
NRIC/FIN No.:

PEGASUS

ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : CHIN XIAN CHERN Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No. :
---	---

Quotation No. : QO19/11-1121	Quotation Date : 12/11/2019	Terms : 30 DAYS
Vehicle No. : SLL3226R	Chassis No. : JM6BN22A8H0141459	Third Party Insurer : NTUC
Model : MAZDA 3	Date of Accident : 11/11/2019	
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
1	FRONT BUMPER <i>sea -</i>	1	1,130.0000	1,130.00
2	FRONT BUMPER SIDE RETAINER LHS <i>? X SUC</i>	1	75.0000	75.00
3	FRONT BUMPER FOGLAMP LHS <i>* SUC -</i>	1	218.0000	218.00
4	FRONT BUMPER FOGLAMP COVER LHS <i>sea -</i>	1	85.0000	85.00
5	FRONT BUMPER FOGLAMP COVER EXTENSION <i>X SUC</i>	1	35.0000	35.00
6	FRONT HEADLAMP LHS <i>7X SUC X</i>	1	1,075.0000	1,075.00
7	FRONT FENDER LHS <i>bt -</i>	1	428.0000	428.00
8	FRONT FENDER SPLASH SHIELD <i>de -</i>	1	148.0000	148.00
9	FRONT FENDER SPLASH SHIELD CLIPS <i>sea -</i>	10	4.0000	40.00
10	FRONT FENDER LOWER AIR DEFLECTOR LHS <i>X SUC</i>	1	95.0000	95.00
11	FRONT FENDER WHEEL HOUSE PANEL <i>X SUC</i>	1	550.0000	550.00
12	FRONT FENDER INNER SIDE BRACKET LHS <i>? X X SUC</i>	1	85.0000	85.00
13	FRONT RADIATOR GRILLE CHROME MOULDING BASE LHS <i>X SUC</i>	1	55.0000	55.00
14	FRONT RADIATOR GRILLE CHROME MOULDING LHS <i>X SUC</i>	1	198.0000	198.00
15	FRONT BUMPER INNER BRACKET LHS <i>? X SUC</i>	1	45.0000	45.00
16	FRONT DOOR LHS <i>X AN</i>	1	1,345.0000	1,345.00
17	LESS 20%	1	-1,121.4000	-1,121.40
18	FRONT WHEEL HUP CAP LHS <i>X SUC</i>	1	120.0000	120.00
19	FRONT TYRE LHS <i>X AN</i>	1	400.0000	400.00
20	FRONT RIM LHS <i>X AN</i>	1	500.0000	500.00
21	TO REMOVE&REFOCUS FRONT HEADLAMP	1	100.0000	100.00 <i>30</i>
22	TO REMOVE&REPLACED TYRE&RIM& CONDUCT WHEEL BALANCING <i>AN</i>	1	120.0000	120.00 <i>AN X</i>

C/F 0.00



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :	Customer :
PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : CHIN XIAN CHERN Tel : Email :	GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No. :

Quotation No. : QO19/11-1121	Quotation Date : 12/11/2019	Terms : 30 DAYS
Vehicle No. : SLL3226R	Chassis No. : JM6BN22A8H0141459	Third Party Insurer : NTUC
Model : MAZDA 3	Date of Accident : 11/11/2019	
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
				B/F 0.00
23	TO CONDUCT WHEEL ALIGNMENT	1	150.0000	150.00
24	TO APPLY RUSTPROOFING& TUFFCOATING TREATMENT FOR FACILITATE REPAIR	1	120.0000	120.00
25	TO KNOCKING& PANEL BEATING	1	1,000.0000	1,000.00
26	TO PUTTY&SPRAY PAINT ON THE AFFECTED AREAS	1	1,000.0000	1,000.00

[Handwritten signature]

Hp 90010068

4 days

4/5

13/11/19 @1330

Review after repair

1. All the Participants hence notify
the following:
a. The time to be taken after spray painting
b. The time to be taken for the part(s) during resurvey
c. The time to be taken for the part(s) during confirmation
d. The time to be taken for the part(s) during a "Without Prejudice" basis
e. The time to be taken for the part(s) is allowed
f. The time to be taken for the part(s) must be resurveyed and
g. The time to be taken for the part(s) must be approved from Insurance Company
h. The time to be taken for the part(s) must be confirmed by Repairer

Sub Total 7,995.60
GST(7.00%) 559.69
Total (SGD) 8,555.29

Please conduct the survey at
Pegasus Engineering @ 74 Kian Teck Road Singapore 628800



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : CHIN XIAN CHERN Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No. :
---	---

Quotation No. : QO19/11-1121	Quotation Date : 12/11/2019	Terms : 30 DAYS
Vehicle No. : SLL3226R	Chassis No. : JM6BN22A8H0141459	Third Party Insurer : NTUC
Model : MAZDA 3	Date of Accident : 11/11/2019	
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
1	FRONT BUMPER <i>sea</i>	1	1,130.0000	1,130.00
2	FRONT BUMPER SIDE RETAINER LHS ? <i>X</i>	1	75.0000	75.00 <i>X</i>
3	FRONT BUMPER FOGLAMP LHS <i>* sea</i>	1	218.0000	218.00
4	FRONT BUMPER FOGLAMP COVER LHS <i>sea</i>	1	85.0000	85.00
5	FRONT BUMPER FOGLAMP COVER EXTENSION <i>X</i>	1	35.0000	35.00 <i>X</i>
6	FRONT HEADLAMP LHS ? <i>X</i>	1	1,075.0000	1,075.00 <i>X</i>
7	FRONT FENDER LHS <i>lt</i>	1	428.0000	428.00
8	FRONT FENDER SPLASH SHIELD <i>ole</i>	1	148.0000	148.00
9	FRONT FENDER SPLASH SHIELD CLIPS <i>sea</i>	10	4.0000	40.00
10	FRONT FENDER LOWER AIR DEFLECTOR LHS <i>X</i>	1	95.0000	95.00 <i>X</i>
11	FRONT FENDER WHEEL HOUSE PANEL <i>X</i>	1	550.0000	550.00 <i>X</i>
12	FRONT FENDER INNER SIDE BRACKET LHS ? <i>X</i>	1	85.0000	85.00 <i>X</i>
13	FRONT RADIATOR GRILLE CHROME MOULDING BASE LHS <i>X</i>	1	55.0000	55.00 <i>X</i>
14	FRONT RADIATOR GRILLE CHROME MOULDING LHS <i>X</i>	1	198.0000	198.00 <i>X</i>
15	FRONT BUMPER INNER BRACKET LHS ? <i>X</i>	1	45.0000	45.00 <i>X</i>
16	FRONT DOOR LHS <i>X</i>	1	1,345.0000	1,345.00 <i>X</i>
17	LESS 20%	1	-1,121.4000	-1,121.40
18	FRONT WHEEL HUP CAP LHS <i>X</i>	1	120.0000	120.00 <i>X</i>
19	FRONT TYRE LHS <i>X</i>	1	400.0000	400.00 <i>X</i>
20	FRONT RIM LHS <i>X</i>	1	500.0000	500.00 <i>X</i>
21	TO REMOVE&REFOCUS FRONT HEADLAMP	1	100.0000	100.00 <i>30</i>
22	TO REMOVE&REPLACED TYRE&RIM& CONDUCT WHEEL BALANCING	1	120.0000	120.00 <i>X</i>

PEGASUS
ENGINEERING & TRADING PTE LTD
 GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : CHIN XIAN CHERN Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No. :
---	---

Quotation No. : QO19/11-1121	Quotation Date : 12/11/2019	Terms : 30 DAYS
Vehicle No. : SLL3226R	Chassis No. : JM6BN22A8H0141459	Third Party Insurer : NTUC
Model : MAZDA 3		Date of Accident : 11/11/2019
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
				B/F 0.00
23	TO CONDUCT WHEEL ALIGNMENT	1	150.0000	150.00 X
24	TO APPLY RUSTPROOFING& TUFFCOATING TREATMENT FOR FACILITATE REPAIR	1	120.0000	120.00 40
25	TO KNOCKING& PANEL BEATING	1	1,000.0000	1,000.00 400
26	TO PUTTY&SPRAY PAINT ON THE AFFECTED AREAS	1	1,000.0000	1,000.00 400

870

Repair

Hp 90010068

4 days

4/5

13/11/19 @1330

Repair after repair

P - \$ 2499.20
 L - \$ 870.00
 \$ 3369.20
 4/5 = 2700.00

1639.20
 870.00
 2509.20
 20%
 2007.36
 4/5 - 2000

Sub Total	7,995.60
GST(7.00%)	559.69
Total (SGD)	8,555.29

Please conduct the survey at
 Pegasus Engineering @ 74 Kian Teck Road Singapore 628800



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19020152/R1qd3ds2

73 BRAS BASAH ROAD

Date: 05-02-2020

#05-01 NTUC TRADE UNION HOUSESINGAPORE

189556



ATTN: JARED LIU

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBJ 9737Y	Veh. Inspected	SLL 3226R
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1071048-001	Excess (\$)	0.00
Assign From	HAZALYSA BINTI IBRAHIM	Assign Date	13/11/2019

2. Vehicle Particulars & Condition

Make & Model	MAZDA 3 SEDAN 1.5L	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JM6BN22A8H0141459	Colour	GREY
Odometer	173145 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	TRIANGLE	6 mm
L/H Front Tyre	205/60 R16	TRIANGLE	6 mm
R/H Rear Tyre	205/60 R16	TRIANGLE	6 mm
L/H Rear Tyre	205/60 R16	TRIANGLE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/11/2019	Inspect Date / Time	13/11/2019 (01:39 PM)
Survey held at	74 KIAN TECK ROAD		
Repairer	PEGASUS ENGINEERING & TRADING PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 3226R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	SCRATCHED	1,130.00	1,130.00
1	FRONT BUMPER SIDE RETAINER LHS	SERVICEABLE	75.00	-
1	FRONT BUMPER FOGLAMP LHS	SCRATCHED	218.00	218.00
1	FRONT BUMPER FOGLAMP COVER LHS	SCRATCHED	85.00	85.00
1	FRONT BUMPER FOGLAMP COVER EXTENSION	SERVICEABLE	35.00	-
1	FRONT HEADLAMP LHS	SERVICEABLE	1,075.00	-
1	FRONT FENDER LHS	BENT	428.00	428.00
1	FRONT FENDER SPLASH SHIELD	DEFORMED	148.00	148.00
10	FRONT FENDER SPLASH SHIELD CLIPS @ \$4.00	NECESSARY	40.00	40.00
1	FRONT FENDER LOWER AIR DEFLECTOR LHS	SERVICEABLE	95.00	-
1	FRONT FENDER WHEEL HOUSE PANEL	SERVICEABLE	550.00	-
1	FRONT FENDER INNER SIDE BRACKET LHS	SERVICEABLE	85.00	-
1	FRONT RADIATOR GRILLE CHROME MOULDING BASE LHS	SERVICEABLE	55.00	-
1	FRONT RADIATOR GRILLE CHROME MOULDING LHS	SERVICEABLE	198.00	-
1	FRONT BUMPER INNER BRACKET LHS	SERVICEABLE	45.00	-
1	FRONT DOOR LHS	NOT NECESSARY	1,345.00	-
	LESS 20% DISCOUNT		-1,121.40	-409.80
			4,485.60	1,639.20
<u>SPECIAL NETT ITEMS</u>				
1	FRONT WHEEL HUB CAP LHS (SN)	SERVICEABLE	120.00	-
1	FRONT TYRE LHS (SN)	NOT NECESSARY	400.00	-
1	FRONT RIM LHS (SN)	NOT NECESSARY	500.00	-
			1,020.00	-
<u>LABOUR</u>				
	TO REMOVE & REFOCUS FRONT HEADLAMP.		100.00	30.00
	TO REMOVE & REPLACED TYRE & RIM & CONDUCT WHEEL BALANCING.	NOT NECESSARY	120.00	-
	TO CONDUCT WHEEL ALIGNMENT.	NOT NECESSARY	150.00	-
	TO APPLY RUSTPROOFING & TIFF COATING TREATMENT FOR FACILITATE REPAIR.		120.00	40.00

Report Ref No. CS/INC19020152/R1qd3ds2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO KNOCKING & PANEL BEATING.		1,000.00	400.00
	TO PUTTY & SPRAY PAINT ON THE AFFECTED AREAS.		1,000.00	400.00
			2,490.00	870.00
GRAND TOTAL			7,995.60	2,509.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				2,000.00

Report Ref No. CS/INC19020152/R1qd3ds2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.