

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 355B

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER (CONSISTENT)	BROKEN	7,306.59	7,306.59
2	GASKET @\$5.32 (CONSISTENT)	NECESSARY	10.64	10.64
1	FRONT LEFT HAND SIDE LAMP (CONSISTENT)	BROKEN	925.21	925.21
1	FRONT LEFT HAND SIDE LATERAL GRAVEL GUARD (CONSISTENT)	BENT	498.50	498.50
1	LEFT HAND SIDE LOWER GUARD FOR UNDERBODY (CONSISTENT)	BROKEN	137.71	137.71
1	RIGHT HAND SIDE LOWER GUARD FOR UNDERBODY (CONSISTENT)	BENT	137.71	137.71
1	FRONT LEFT HAND SIDE LOWER GRAVEL GUARD (CONSISTENT)	BROKEN	107.94	107.94
14	SCREW @\$1.66 (CONSISTENT)	NECESSARY	23.24	23.24
14	WASHER @\$1.66 (CONSISTENT)	NECESSARY	23.24	23.24
10	SCREW @\$1.66 (CONSISTENT)	NECESSARY	16.60	16.60
10	WASHER @\$1.66 (CONSISTENT)	NECESSARY	16.60	16.60
4	BLOCK @\$1.66 (CONSISTENT)	NECESSARY	6.64	6.64
6	CLIP @\$2.50 (CONSISTENT)	NECESSARY	15.00	15.00
			9,225.62	9,225.62
	LABOUR			
	PAINTING AND REPAIR-REPAIR AND RESPRAY FRONT SIDE COVERING,RESPRAY FRONT BUMPER ,RESPRAY FRONT BONNET.		3,300.00	2,600.00
	LABOUR-REMOVE AND REPLACE FRONT BUMPER AND GASKET, REMOVE AND REPLACE FRONT LEFT HAND SIDE LAMP, REMOVE AND REPLACE FRONT LEFT HAND SIDE LATERAL GRAVEL GUARD, REMOVE AND REPLACE BOTH LEFT AND RIGHT FRONT LOWER GUARD FOR UNDERBODY, REMOVE AND REPLACE FRONT LEFT HAND SIDE GRAVEL GUARD, REMOVE AND REPLACE SCREW, WASHER, BLOCK AND CLIP.		960.00	960.00
			4,260.00	3,560.00
	GRAND TOTAL		13,485.62	12,785.62

RECOMMENDED COST OF REPAIRS			12,785.62
-----------------------------	--	--	-----------

Report Ref No. CC4/ASM19020156/Eps3q2





Report Ref No. CC4/ASM19020156/Eps3q2



CHEN TSUE YEE

Automotive Assessor



HO LEONG CHUAN

Automotive Assessor