




SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 12/11/2019

User ID : TuckFoo

Section A - Accident Details	
Registration Number	SHC4165X
Case Reference Number	TAX/11/19/2022
Registration Date	11/29/2013
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	LIM KOK SING
Type of Accident	Side Swipe
Accident Date and Time	11/8/2019 11:11 AM
Accident Reported Date and Time	11/8/2019 1:41 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24104248
Special Instruction to ARC, if any	TP
Prepared Date and Time	11/9/2019 10:49 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$800.00
Total Spray Cost	\$3,168.00	\$1,290.00
Total Spare Part Cost	\$9,089.25	\$3,277.52
Total Other Cost	\$1,725.00	\$535.00
TOTAL COST	\$14,996.25	\$5,902.52
Lump Sum Total	\$15,000.00	\$5,900.00
Number of Repair Days	7.0	6.0
Prepared / Adjusted By	Tuck Foo Kok	Sun Pin (LKK)
ARC / Surveyor Sign Off Date	11/11/2019 5:03 PM	11/11/2019 4:39 PM
Signature		
Remarks		Lump sum repair, take after spray photo, send to sunpin@lkkauto.com

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

6011, 6136



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd	
60 Woodlands Industrial Park E4, Singapore 757705	
FAX Number : 63685592	
Estimator Telephone Number : 68662623	
Accident Reporting Number : 68662672	

Date Generated : 12/11/2019

User ID : TuckFoo

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	\$1,014.00	\$800.00
Total Labour	\$1,014.00	\$800.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00 ✓
TO RESPRAY FRONT BUMPER LOWER GRILLE	\$180.00	\$0.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00 ✓
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$0.00
TO RESPRAY RIM	\$180.00	\$50.00 ✓
TO RESPRAY FRONT DOOR LH	\$378.00	\$200.00 ✓
TO RESPRAY VIEW MIRROR	\$180.00	\$40.00 ✓
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$0.00
TO RESRAY REAR DOOR LH	\$378.00	\$200.00 ✓
TO RESPRAY REAR FENDER LH	\$378.00	\$200.00 ✓
TO RESPRAY REAR BUMPER	\$378.00	\$200.00 ✓
Total Spray Painting & Panel Beating	\$3,168.00	\$1,290.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00 ✓
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	\$20.00 ✓
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00 ✓
TO TRANSFER DOOR MECHANISM	\$240.00	\$80.00 ✓
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$125.00	\$125.00 ✓
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	\$120.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$50.00 ✓
TO REMOVE & REFIT REAR QUARTER GLASS LH	\$120.00	\$80.00 ✓
TO REMOVE AND REFIT WIRE HARDESS	\$200.00	\$0.00
TO REMOVE / REFIT SEAT	\$120.00	\$0.00
TO REMOVE & REFIT FUEL TANK	\$120.00	\$80.00 ✓
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00 ✓
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$1,725.00	\$535.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		67002-47070	DOOR FRT/LH	1.00	\$894.40	100.00	\$0.00	Replace	Repair X R
			STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace / NEC
		68720-15151	HINGE UPPER LHF, DOOR	0.00	\$80.50	0.00	\$0.00	Replace	Not Given X SVC
		68740-12120	HINGE LOWER LHF, DOOR	0.00	\$90.10	0.00	\$0.00	Replace	Not Given X SVC
		68610-47021	CHECK ASSY, FR DOOR,	0.00	\$150.30	0.00	\$0.00	Replace	Not Given X SVC
		87940-47310	MIRROR ASSY, LH	1.00	\$1,224.90	25.00	\$918.68	Replace	Replace / J4med.
		81740-52040	MIRROR LAMP LH	1.00	\$65.30	10.00	\$58.77	Replace	Replace / SCR
		87945-74010	COVER, OUTER MIRROR, LH	1.00	\$107.40	25.00	\$80.55	Replace	Replace / SCR.



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd	
60 Woodlands Industrial Park E4, Singapore 757705	
FAX Number : 63685592	
Estimator Telephone Number : 68662623	
Accident Reporting Number : 68662672	

Date Generated : 12/11/2019

User ID : TuckFoo

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		75852-47900	MOULDING BODY, LH	0.00	\$673.60	0.00	\$0.00	Replace	Not Given X SVC
		67004-47080	DOOR RR/LH	1.00	\$954.50	100.00	\$0.00	Replace	Repair X R
			PIXEL STICKER	1.00	\$60.00	0.00	\$60.00	Replace	Replace / NEC
		61602-47091	FENDER RR/LH	1.00	\$766.80	25.00	\$575.10	Replace	Replace / DD
			SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace / NEC
			STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace / NEC
		65638-47021	FENDER LINER RR/LH	1.00	\$141.30	25.00	\$105.98	Replace	Replace
		62720-47031	QUARTER GLASS RR/LH	1.00	\$168.10	25.00	\$126.07	Replace	Replace / NEC
			SEALANT W/SCREEN	1.00	\$37.00	0.00	\$37.00	Replace	Replace / NEC
		52592-47021	BUMPER SEAL, RR LH	0.00	\$88.90	0.00	\$0.00	Replace	Not Given X SVC
		52159-47905	BUMPER REAR	1.00	\$458.60	100.00	\$0.00	Replace	Repair X R
		52576-47020	BUMPER SIDE RETAINER RR/LH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given X SVC
			PIXEL STICKER	1.00	\$60.00	0.00	\$60.00	Replace	Replace / NEC
		52119-47930	BUMPER FRT	1.00	\$482.00	25.00	\$361.50	Replace	Replace / CRM
		52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace / NEC
		52611-47080	BUMPER ENERGY ABSORBER FRT	0.00	\$78.80	0.00	\$0.00	Replace	Check X SVC
		52021-47023	BUMPER REINFORCEMENT FRT	0.00	\$498.40	0.00	\$0.00	Replace	Check X SVC
		57014-47030	ARM SUB-ASSY, FR BUMPER LH	0.00	\$250.40	0.00	\$0.00	Replace	Not Given X SVC
		52128-47903	COVER, FR BUMPER HOLE LH	1.00	\$18.50	25.00	\$13.88	Replace	Replace / SCR
		52116-47040	BUMPER SUPPORT FLH	0.00	\$76.40	0.00	\$0.00	Replace	Check X SVC
		53102-47020	BUMPER GRILLE SUB-ASSY, LOWER	0.00	\$311.10	0.00	\$0.00	Replace	Check X SVC
		81220-12230	FOG LAMP LH	0.00	\$280.10	0.00	\$0.00	Replace	Check X SVC
		76851-47020	BUMPER LIP FRT	0.00	\$139.60	0.00	\$0.00	Replace	Not Given X SVC
		52618-47050	BUMPER FRT ABSORBER LOWER	0.00	\$127.70	0.00	\$0.00	Replace	Check X SVC
		53113-47040	GRILLE RADIATOR LOWER NO.2	0.00	\$94.60	0.00	\$0.00	Replace	Not Given X SVC
		82113-47180	WIRE, ENGINE ROOM, NO.3	0.00	\$242.00	0.00	\$0.00	Replace	Not Given X SVC
		81529-47060	BRACKET, FR TURN CENTER LH	0.00	\$58.20	0.00	\$0.00	Replace	Not Given X SVC
		81529-47050	BRACKET, FR TURN LOWER LH	0.00	\$26.00	0.00	\$0.00	Replace	Not Given X SVC
		81529-47040	BRACKET, FR TURN UPPER LH	0.00	\$24.40	0.00	\$0.00	Replace	Not Given X SVC
		81521-47050	LENS & BODY, FR TURN LH	0.00	\$511.80	0.00	\$0.00	Replace	Check X SVC
		53201-47902	SUPPORT SUB-ASSY	0.00	\$1,460.40	0.00	\$0.00	Replace	Not Given X SVC
		81170-47500	HEAD LAMP LH	1.00	\$945.20	10.00	\$850.68	Replace	Replace / SCR
		53876-47030	FENDER LINER FRT/LH	1.00	\$171.70	25.00	\$128.77	Replace	Replace /
		53852-47020	FENDER LINER PAD, FR WHEEL LH	1.00	\$49.30	25.00	\$36.97	Replace	Replace
		53826-47010	FENDER PROTECTOR FRT/LH UPPER	0.00	\$46.10	0.00	\$0.00	Replace	Check X SVC
		53828-47060	PROTECTOR, FRONT FENDER SIDE PANEL LH	0.00	\$114.50	0.00	\$0.00	Replace	Check X SVC
		53802-47050	FENDER FRT/LH	1.00	\$723.40	25.00	\$542.55	Replace	Replace / DD
		75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.92	Replace	Replace / NA
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given X SVC

? photo

? photo



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 12/11/2019

User ID : TuckFoo

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		42611- 47140 (Frt)	WHEEL DISC. FRONT	1.00	\$1,484.20	100.00	\$0.00	Replace	Repair X R
Total					\$14,600.95		\$4,096.90		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: