

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19020165/T1PA3Q2

Date: 22/09/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SJU4658Y	Insured Vehicle No :	SHA6791K
Date of Loss: 10/11/2019	Nature of Claim: TP	Claim No: MCT19110241

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJU4658Y		
Make & Model:	MITSUBISHI LANCER, 1.5 MIVEC SPORTS AT ABS D/AB (A)	Engine No:	4A910126022
Reg. Date:	11/12/2009 (Man. Year: 2009)	Chassis No:	JMYSRCY2AAU000344
Colour:	Silver	Odometer:	159397 km
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	0.00	0.00	0.00	
Approved Total (Overridden) (S\$)		3,055.00		
Nett Amount (S\$)	0.00	3,055.00	-3,055.00	
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
+ Other Costs (S\$)		90.00		
Nett Liability (S\$)		3,385.00		
Global Sum Settlement (S\$)		3,000.00		

INSPECTION

Date of Assignment:	12/11/2019	
Date Inspected:	12/11/2019 Inspected At:	Wah Hong Motors & Credit Pte Ltd (HQ) 38 Toh Guan Road East, #01-57, Enterprise Hub Singapore 608581
Estimated Period of Repair:	0.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

SPECIAL REMARKS

PLEASE BE INFORMED THAT THE VEHICLE IS NOT ECONOMICAL FOR REPAIR.

MARKET VALUE : \$12,500.00(est)

LTA REIMBURSEMENT VALUE (RV) : \$9,445.00(est)

NETT VALUE : \$3,055.00(est)

IN VIEW OF THE ABOVE, THE VEHICLE IS UNECONOMICAL TO BE REPAIRED.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Nov 2019)
Parts:	143	MITSUBISHI LANCER 1.5 MIVEC SPORTS AT ABS D/AB (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJU4658Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >