

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5560B**AAD1911-080***Not Authored**Resurvey B4 pain*

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :
 Date of Registration:

12 NOV 2019

12 NOV 2019

SHD 5560B

JTDKB3FU503076908

TOYOTA

PRIUS

8.11.19

III

22/11/2018

PART		LIST	
1	1 REAR BUMPER	\$	<i>Tn</i> 442.60 ✓
2	1 REAR BUMPER RE-INFORCEMENT	\$	<i>Bn</i> 332.70 ✓
3	1 REAR BUMPER TOWING COVER	\$	<i>Sn</i> 15.40 X
4	1 REAR BUMPER UNDER COVER (BLACK)	\$	<i>Bn</i> 576.30 ✓
5	1 REAR BUMPER SIDE RETAINER LH	\$	<i>Dil</i> 116.50 ✓
6	1 REAR BUMPER SIDE RETAINER RH	\$	<i>Sn</i> 117.70 X
7	1 REAR BUMPER SIDE SEAL LH	\$	<i>Sn</i> 88.50 ✓
8	1 ANTENNA, ELECTRICAL KEY	\$	<i>Sn</i> 72.00 X
9	1 REAR TAILGATE	\$	<i>Bn</i> 1,147.80 ✓
10	1 REAR TAILGATE OUTER GARNISH	\$	<i>CM</i> 925.60 ✓
11	1 REAR SPOILER SUB ASSY	\$	<i>Sn</i> 1,575.40 X
12	1 GLASS, BACK WINDOW FIX	\$	<i>Sn</i> 746.50 X
13	1 COVER, REAR COMBINATION LAMP, RH	\$	<i>Sn</i> 64.50 X
14	1 COVER, REAR COMBINATION LAMP, LH	\$	<i>Sn</i> 64.50 X
15	1 GARNISH, BACK DOOR SIDE, LH	\$	<i>Sn</i> 95.60 X
16	1 GARNISH, BACK DOOR SIDE, RH	\$	<i>Sn</i> 95.60 X
17	1 MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER RH	\$	<i>Sn</i> 56.50 X
18	1 MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER LH	\$	<i>Sn</i> 56.50 X
19	1 BOARD ASSY, BACK DOOR TRIM	\$	<i>Dil/Wn</i> 259.20 ✓
20	1 PANEL ASSY, BACK DOOR TRIM, UPPER	\$	<i>Sn</i> 52.10 X
21	1 REAR TAILGATE WEATHERSTRIP	\$	<i>Sn</i> 372.30 X
22	1 PANEL SUB-ASSY, BODY LOWER BACK	\$	<i>W</i> 650.30 X
23	1 TAILLAMP LOWER RH	\$	<i>Sn</i> 502.00 X
24	1 TAILLAMP UPPER RH	\$	<i>Sn</i> 451.80 X
25	1 REAR BUMPER SIDE RH	\$	<i>Sn</i> 123.70 X
26	1 REAR BUMPER SIDE LH	\$	<i>CM</i> 123.70 ✓
27	1 TAILLAMP LOWER LH	\$	<i>CM</i> 502.00 ✓

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5560B**AAD1911-080**

28	1	TAILLAMP UPPER LH	\$	MJC M	443.30	✓
29	1	REAR LH FENDER PANEL	\$	R	854.80	✓
30	1	LINER, REAR WHEEL HOUSE, LH	\$	n	139.80	} X
31	1	PANEL, QUARTER WHEEL HOUSE, OUTER LH	\$	S _L	296.20	
32	1	BOARD, BACK DOOR TRIM	\$	S _L	225.20	
33	1	PANEL ASSY, DECK TRIM SIDE, RH	\$	S _L	355.90	
34	1	PANEL ASSY, DECK TRIM SIDE, LH	\$	S _L	355.90	
35	1	COVER, FLOOR UNDER, NO.1	\$	S _L	175.10	
36	1	COVER, FLOOR UNDER, NO.2	\$	S _L	241.90	
37	1	COVER, REAR FLOOR	\$	S _L	229.90	
38	1	COVER, DECK TRIM, REAR	\$	S _L	126.70	
39	1	DUCT ASSY, QUARTER VENT, LH	\$	DC	67.00	
40	1	HUB & BEARING ASSY, REAR AXLE, LH	\$	S _L	725.60	} X
41	1	DISC REAR	\$	S _L	450.70	
42	1	CARRIER SUB ASSY, REAR AXLE, LH	\$	S _L	953.60	
43	1	CYLINDER ASSY, DISC BRAKE, REAR LH	\$	S _L	1,001.90	
44	1	PAD KIT, DISC BRAKE, REAR	\$	S _L	188.40	
45	1	COVER, DISC BRAKE DUST, REAR LH	\$	S _L	58.20	
46	1	BAR, STABILIZER, REAR	\$	S _L	295.70	
47	1	LINK ASSY, REAR STABILIZER, LH	\$	S _L	179.10	
48	1	BUSH, STABILIZER, REAR	\$	S _L	71.20	
49	1	BRACKET, REAR STABILIZER BAR, NO.1	\$	S _L	11.50	
50	1	BRACKET, REAR SUSPENSION ARM, LH	\$	S _L	107.20	
51	1	COVER, REAR SUSPENSION ARM, LH	\$	S _L	49.70	
52	1	ARM ASSY, REAR SUSPENSION, NO.1 LH	\$	S _L	239.20	
53	1	ARM ASSY, TRAILING, REAR LH	\$	S _L	370.40	
54	1	ABSORBER ASSY, SHOCK, REAR LH	\$	S _L	127.00	
55	1	SUPPORT ASSY, REAR SUSPENSION, LH	\$	S _L	149.30	
56	1	SPRING, COIL, REAR LH	\$	S _L	199.00	
57	1	INSULATOR, REAR COIL SPRING, LOWER LH	\$	S _L	13.90	
58	1	INSULATOR, REAR COIL SPRING, UPPER LH	\$	S _L	19.80	
59	1	ARM ASSY, REAR SUSPENSION, NO.2 LH	\$	S _L	497.50	
60	1	ARM ASSY, UPPER CONTROL, REAR LH	\$	S _L	420.80	
61	1	MEMBER SUB ASSY, REAR SUSPENSION	\$	S _L	2,245.20	
62	1	WIRE, SKID CONTROL SENSOR, LH	\$	S _L	94.70	
63	1	TROUGH, BACK DOOR OPENING, LH	\$	S _L	103.40	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5560B

AAD1911-080

TOTAL	\$	21,712.00
25%	\$	5,428.00
	\$	16,284.00

Special Nett

1	1SET	PARKING AID	\$	<i>nn</i>	700.00	<i>250sn</i>
2	1SET	REAR BUMPER CLIP	\$	<i>nn</i>	66.00	<i>—</i>
3	2	REAR WINDSCREEN SEALANT	\$	<i>nn</i>	80.00	<i>40sn</i>
4	1	WINDSCREEN MOULDING	\$	<i>nn</i>	100.00	<i>—</i>
5	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i>	100.00	<i>30sn</i>
6	1	REAR TAILGATE TOYOTA LOGO	\$	<i>nc</i>	47.00	<i>—</i>
7	1	REAR TAILGATE WORDING 'PRIUS'	\$	<i>nc</i>	52.90	<i>—</i>
8	1	REAR TAILGATE WORDING 'HYBRID'	\$	<i>nn</i>	53.50	<i>—</i>
9	1	REAR TAILGATE STICKER 'TRANS-CAB'	\$	<i>nn</i>	80.00	<i>30sn</i>
10	1	REAR TAILGATE STICKER '6555-3333'	\$	<i>nn</i>	80.00	<i>30sn</i>
11	1	REAR BUMPER PROTECTOR	\$	<i>sn</i>	100.00	} <i>X</i>
12	1	REAR WHEEL RIM	\$	<i>sn</i>	1,570.55	
13	1	REAR TYRE 195/65/15	\$	<i>sn</i>	350.00	
14	1	REAR WHEEL RIM COVER	\$	<i>sn</i>	175.80	
15	1SET	REAR LH FENDER LINER CLIP	\$	<i>nn</i>	35.00	
16	1SET	BUMPER RETAINER LH CLIP	\$	<i>nn</i>	20.00	
TOTAL			\$		3,610.75	

TOTAL PARTS	\$	19,894.75
--------------------	-----------	------------------

LABOUR

To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	170.00	<i>60</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	7,500.00	<i>1200</i>
Putty And Spray Painting Of The Affected Portion.	\$	7,500.00	<i>1100</i>
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	170.00	<i>X</i>

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5560B**AAD1911-080**

To Rust-Proofing Of The Affected Areas.	\$	170.00	901
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	170.00	1201
To reinstall rear bumper parking sensor.	\$	170.00	501
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>na</i> 170.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00	} 1001
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>na</i> 380.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
Towing Fees	\$	<i>na</i> 170.00	X
To dismantle and refit rear undercarriage parts, final checking and testing.	\$	<i>na</i> 380.00	X
To dismantle and refit rear axle housing assy, remove and renewal of parts, final checking and testing.	\$	<i>na</i> 380.00	X
To check ABS and brake efficiency, final checking and testing.	\$	<i>na</i> 380.00	X

Trans-cab Auto Services Pte Ltd

AAD1911-080

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5560B

To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.

	\$	<i>nn</i> 380.00	X
TOTAL	\$	19,410.00	
Over All Total	\$	39,304.75	

(PART-BY-PART) Repair Days

25 Days

7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: