

Singer: AdnanASSIGNMENT (Office)From (Person): Yong Kong Melvin of SMODate/Time: 13/11/19 4:10pm

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKE G802BInsured: GBJ 7121 Dat Workshop m/s: 8M AutomotivTel: 6747 9241of 1 Kakki Bukit Ave 6 # 01-43

Policy No: \_\_\_\_\_

Claim No: CMTD1905275/HHE

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

Make of Veh:  
(Client's Record)D.O.A. 13/11/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 4:51pm @ 13/11/19Person Contacted: SelugiVehicle IN OUT

| Date/Time                | Action/Instruction                                                                                                           |
|--------------------------|------------------------------------------------------------------------------------------------------------------------------|
|                          | <u>SKE G802B - CC3/11/14/2015410/plm</u>                                                                                     |
|                          | <u>GBJ 7121 D - X</u>                                                                                                        |
| <u>14/11/19 @ 5:26pm</u> | <u>Informed Melvin Ye, we are pending estimate from repairer.</u>                                                            |
| <u>18/11/19 @ 1:29M</u>  | <u>revised to Melvin by email. (TP owner find a repair his vehicle &amp; repairer request to repair the vehicle at 68k).</u> |

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 12 days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SKF6802B Yr Regn: 2012, June  
 Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Nissan Almera cc 1498  
 Colour: Blue AC: Insured / Std / NI / NA  
 Sp. Reading: 168573 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: MNTBBAN1720000005  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Mod: Nil / S/Rim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: 205/55R16  
 R: 205/55R16  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Continental  
 Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. 06 mm R/Bal. 06 mm  
 L/Bal. 06 mm L/Bal. 06 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 14/11/19  
 Survey held at SM  
 Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or \_\_\_\_\_  
 The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time        | Action / Instruction                                                                  |
|--------------------|---------------------------------------------------------------------------------------|
| 17/11/19 @ 10.52am | TP Sampo. not revised to Melvin by email. & informed him that the rental is on going. |
|                    | MV : 32K Depreciation @ 8.5 x 26yr = 22 + 10K (Min Perf) = 32K                        |
|                    | PV : 273K                                                                             |
|                    | Nett. 4.7K.                                                                           |
|                    | RECEIVED 14 JAN 2020                                                                  |
|                    | US \$4800, 12 days (Red \$ 21911-40, 82%)                                             |

Date/Time, File Pass to? ☐ : Preli. Report  
☐ : Final Report  
 1/14/19 hmsr  
 Date/Time, File Return to?

Days Of Repair: 12  
 Resurvey No. of Trip: 1

Report Format: TP  
 Lump Sum / LSR: 4800

Add Fee: ☐ : Site Insp (\$) ☐ : Interview (\$) ☐ : Tech. Insp (\$) ☐ : Weekend (\$)

|                 |     |
|-----------------|-----|
| Survey Fee:     |     |
| Transportation: |     |
| S + PS          |     |
| Photos          |     |
| Other           |     |
| TOTAL           | 450 |

## Nivitha (LKK Auto)

---

**From:** Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>  
**Sent:** Wednesday, 13 November 2019 4:10 PM  
**To:** SUR; assignments  
**Cc:** Henry, Irene James; Choo, Thelma; sm automotive  
**Subject:** RE: SKF6802B CLAIMING AGAINST GBB7121D DOA:13.11.19 Our ref : CMTD1905275/THE

Without Prejudice

Dear LKK Auto,

Please make arrangement to conduct the survey for SKF6802B on a without prejudice basis.

Best Regards

Melvin Ye

Claims Division

D: 6322 4667 | T: 6461 6555 | F: 6221 3302



**SOMPO**  
INSURANCE

**A Century of Trust**

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

Quick & Easy Claims Submission<sup>1</sup> & Product Purchase<sup>2</sup> via Sompo SG



Download now @

or

<sup>1</sup> For Travel, Personal Accident & Home Insurance | <sup>2</sup> For Travel, Personal Accident, Home & Private Motor Insurance

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

---

**From:** sm automotive <sm\_automotive@hotmail.com>  
**Sent:** Wednesday, 13 November, 2019 2:54 PM  
**To:** Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>  
**Cc:** Henry, Irene James <irene.henry@sompo.com.sg>; Choo, Thelma <thelma.choo@sompo.com.sg>  
**Subject:** Re: SKF6802B CLAIMING AGAINST GBB7121D DOA:13.11.19 Our ref : CMTD1905275/THE

Without Prejudice

Hi Melvin

There was typo error of workshop name, our workshop name is SM Automotive instead of Hua Meng Spray Painting Workshop.

Please kindly arrange for LKK Auto Consultants @ Marcus Chua (East area)

Regards,

Sukyi Chong  
**SM AUTOMOTIVE**

1 Kaki Bukit Ave 6  
Blk C #01-43  
Singapore 417883  
Tel: 6747 9241 Fax: 6741 7276

---

**From:** Ye, Yong Kang Melvin <[melvin.ye@sompo.com.sg](mailto:melvin.ye@sompo.com.sg)>  
**Sent:** Wednesday, November 13, 2019 2:48 PM  
**To:** sm automotive <[sm\\_automotive@hotmail.com](mailto:sm_automotive@hotmail.com)>  
**Cc:** Henry, Irene James <[irene.henry@sompo.com.sg](mailto:irene.henry@sompo.com.sg)>; Choo, Thelma <[thelma.choo@sompo.com.sg](mailto:thelma.choo@sompo.com.sg)>  
**Subject:** RE: SKF6802B CLAIMING AGAINST GBB7121D DOA:13.11.19 Our ref : CMTD1905275/THE

Our Reference : CMTD1905275/THE

Your Reference: SKF6802B

**Without Prejudice**

Date: 13/11/2019

**Attention:**  
**HUA MENG SPRAY PAINTING WORKSHOP**

Dear Jing Yee,

**ACCIDENT INVOLVING SKF6802B & GBB7121D ON 13.11.2019**

We refer to your Notice of Accident dated 13/11/2019.

Please be informed that Ms Thelma Choo is the handler of this case.

We regret to inform that we are unable to revert on liability for direct settlement as we have yet to receive our insured's accident report.

Kindly advise should you still require us to conduct survey on a "Without Prejudice" basis.

If you are agreeable to conduct survey on a "Without Prejudice" basis, we propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

**Pre-Repair Survey**

|  | Motor Surveyor | Surveyor | Selection (Indicate as tick) |
|--|----------------|----------|------------------------------|
|--|----------------|----------|------------------------------|

|   |                      |                           |  |
|---|----------------------|---------------------------|--|
| 1 | Raleigh Services     | Andrew Ow Yong            |  |
|   |                      | Vincent Ng                |  |
| 2 | LKK Auto Consultants | Kenneth Kong (North area) |  |
|   |                      | Marcus Chua (East area)   |  |
|   |                      | Mohd Rasul (West area)    |  |
|   |                      | Mohd Taufikh (West area)  |  |
| 3 | Priority Services    | Jimmy Lee                 |  |
|   |                      | Lawrence Ng               |  |
|   |                      | Jeffery Ong               |  |
| 4 | In House surveyor    | Teo See Ling              |  |

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Melvin Ye

Claims Division

D: 6322 4667 | T: 6461 6555 | F: 6221 3302



Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: [www.sompo.com.sg](http://www.sompo.com.sg) | Facebook: [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

Quick & Easy Claims Submission<sup>1</sup> & Product Purchase<sup>2</sup> via Sompo SG



<sup>1</sup> For Travel, Personal Accident & Home Insurance | <sup>2</sup> For Travel, Personal Accident, Home & Private Motor Insurance

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

**From:** sm automotive <[sm\\_automotive@hotmail.com](mailto:sm_automotive@hotmail.com)>  
**Sent:** Wednesday, 13 November, 2019 11:44 AM  
**To:** Claims - Motor Survey <[MotorSurvey@sompo.com.sg](mailto:MotorSurvey@sompo.com.sg)>  
**Subject:** SKF6802B CLAIMING AGAINST GBB7121D DOA:13.11.19

Without Prejudice

Hi Motor Claim Dept

Please send us your surveyor list,thanks.

Regards,

**Sukyi Chong**  
**SM AUTOMOTIVE**

1 Kaki Bukit Ave 6  
Blk C #01-43  
Singapore 417883  
Tel: 6747 9241 Fax: 6741 7276

## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Tuesday, 19 November 2019 10:52 AM  
**To:** 'Ye, Yong Kang Melvin'; SUR; assignments  
**Cc:** 'Henry, Irene James'; 'Choo, Thelma'  
**Subject:** RE: SKF6802B CLAIMING AGAINST GBB7121D DOA:13.11.19 Our ref : CMTD1905275/THE  
**Attachments:** CSSMO19020173Aqd3(2).pdf

Dear Melvin,

Enclosed herewith 2<sup>nd</sup> preliminary advice of SKF 6802B. (with adjusted estimate repair cost)

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Shiau Chan (LKKAUTO) <[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com)>  
**Sent:** Monday, 18 November 2019 1:29 PM  
**To:** 'Ye, Yong Kang Melvin' <[melvin.ye@sompo.com.sg](mailto:melvin.ye@sompo.com.sg)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** 'Henry, Irene James' <[irene.henry@sompo.com.sg](mailto:irene.henry@sompo.com.sg)>; 'Choo, Thelma' <[thelma.choo@sompo.com.sg](mailto:thelma.choo@sompo.com.sg)>  
**Subject:** RE: SKF6802B CLAIMING AGAINST GBB7121D DOA:13.11.19 Our ref : CMTD1905275/THE

Dear Melvin,

Enclosed herewith preliminary advice of SKF 6802B.

According to the repairer, the TP owner insist to repair his vehicle and they request to repair the vehicle at \$8,000.00.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Shiau Chan (LKKAUTO) <[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com)>  
**Sent:** Thursday, 14 November 2019 5:26 PM  
**To:** 'Ye, Yong Kang Melvin' <[melvin.ye@sompo.com.sg](mailto:melvin.ye@sompo.com.sg)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** 'Henry, Irene James' <[irene.henry@sompo.com.sg](mailto:irene.henry@sompo.com.sg)>; 'Choo, Thelma' <[thelma.choo@sompo.com.sg](mailto:thelma.choo@sompo.com.sg)>  
**Subject:** RE: SKF6802B CLAIMING AGAINST GBB7121D DOA:13.11.19 Our ref : CMTD1905275/THE

Dear Melvin,

Please be informed that we have inspected the vehicle SKF 6802B on 14/11/2019.

We are pending for estimate from repairer.



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563501 FAX : (065) 62564315

Your Ref: CMTD1905275/THE

Date: 19<sup>th</sup> November 2019

Our Ref: CS/SMO19020173/Aqd3

Without Prejudice

The Motor Claims Department  
Sompo Insurance

Attn: Melvin

Dear Sirs/Mdm


**PRELIMINARY ADVICE OF VEHICLE NO. SKF 6802B**

We thank you for the instruction on 13/11/2019.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 14/11/2019 at the premises of M/s SM AUTOMOTIVE and have the following to report:-

|                            |                        |
|----------------------------|------------------------|
| Workshop Estimate Amount   | : S\$ <u>26,711.40</u> |
| Revised Estimate Amount    | : S\$ <u>10,447.71</u> |
| "Check" Items Amount       | : S\$ <u>-</u>         |
| Lump Sum Amount (Estimate) | : S\$ <u>8,350.00</u>  |
| Market Value               | : S\$ <u>32,000.00</u> |
| LTA Reimbursement Value    | : S\$ <u>27,265.00</u> |
| Nett Value                 | : S\$ <u>4,735.00</u>  |

Description of Damage:  
The vehicle sustained damages at the front and rear portion.



Comments/ Present Status:  
Damages consistent.  
Days of repair: 12 day.  
Repairer request to repair the vehicle at \$8,000.00.  
The TP owner insist to repair his vehicle.  
We have not authorized repair.

Yours faithfully

ADRIAN LING WAI PING  
B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI  
Licensed Appraiser



## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Monday, 18 November 2019 1:29 PM  
**To:** 'Ye, Yong Kang Melvin'; SUR; assignments  
**Cc:** 'Henry, Irene James'; 'Choo, Thelma'  
**Subject:** RE: SKF6802B CLAIMING AGAINST GBB7121D DOA:13.11.19 Our ref : CMTD1905275/THE  
**Attachments:** CSSMO19020173Aqd3.pdf

Dear Melvin,

Enclosed herewith preliminary advice of SKF 6802B.

According to the repairer, the TP owner insist to repair his vehicle and they request to repair the vehicle at \$8,000.00.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Shiau Chan (LKKAUTO) <[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com)>  
**Sent:** Thursday, 14 November 2019 5:26 PM  
**To:** 'Ye, Yong Kang Melvin' <[melvin.ye@sompo.com.sg](mailto:melvin.ye@sompo.com.sg)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** 'Henry, Irene James' <[irene.henry@sompo.com.sg](mailto:irene.henry@sompo.com.sg)>; 'Choo, Thelma' <[thelma.choo@sompo.com.sg](mailto:thelma.choo@sompo.com.sg)>  
**Subject:** RE: SKF6802B CLAIMING AGAINST GBB7121D DOA:13.11.19 Our ref : CMTD1905275/THE

Dear Melvin,

Please be informed that we have inspected the vehicle SKF 6802B on 14/11/2019.

We are pending for estimate from repairer.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO) <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>  
**Sent:** Wednesday, 13 November 2019 4:50 PM  
**To:** 'Ye, Yong Kang Melvin' <[melvin.ye@sompo.com.sg](mailto:melvin.ye@sompo.com.sg)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** 'Henry, Irene James' <[irene.henry@sompo.com.sg](mailto:irene.henry@sompo.com.sg)>; 'Choo, Thelma' <[thelma.choo@sompo.com.sg](mailto:thelma.choo@sompo.com.sg)>  
**Subject:** RE: SKF6802B CLAIMING AGAINST GBB7121D DOA:13.11.19 Our ref : CMTD1905275/THE

Dear Sir/Mdm,

Thank you for the assignment.



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CMTD1905275/THE

Date: 18<sup>th</sup> November 2019

Our Ref: CS/SMO19020173/Aqd3

Without Prejudice

The Motor Claims Department  
Sompo Insurance

Attn: Melvin

Dear Sirs/Mdm


**PRELIMINARY ADVICE OF VEHICLE NO. SKF 6802B**

We thank you for the instruction on 13/11/2019.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 14/11/2019 at the premises of M/s SM AUTOMOTIVE and have the following to report:-

|                          |                        |
|--------------------------|------------------------|
| Workshop Estimate Amount | : S\$ <u>NOT READY</u> |
| Revised Estimate Amount  | : S\$ <u>-</u>         |
| "Check" Items Amount     | : S\$ <u>-</u>         |
| Market Value             | : S\$ <u>32,000.00</u> |
| LTA Reimbursement Value  | : S\$ <u>27,265.00</u> |
| Nett Value               | : S\$ <u>4,735.00</u>  |

Description of Damage:  
The vehicle sustained damages at the front and rear portion.



Comments/ Present Status:  
Damages consistent.  
Days of repair: 12 day.  
We have not authorized repair.

Yours faithfully

ADRIAN LING WAI PING  
B.Eng. AMSOE, AMIRTE, AMSAE-A, M.MATAI  
Licensed Appraiser

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Thursday, 14 November 2019 5:26 PM  
**To:** 'Ye, Yong Kang Melvin'; SUR; assignments  
**Cc:** 'Henry, Irene James'; 'Choo, Thelma'  
**Subject:** RE: SKF6802B CLAIMING AGAINST GBB7121D DOA:13.11.19 Our ref : CMTD1905275/THE

Dear Melvin,

Please be informed that we have inspected the vehicle SKF 6802B on 14/11/2019.

We are pending for estimate from repairer.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto) <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>  
**Sent:** Wednesday, 13 November 2019 4:50 PM  
**To:** 'Ye, Yong Kang Melvin' <[melvin.ye@sompo.com.sg](mailto:melvin.ye@sompo.com.sg)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** 'Henry, Irene James' <[irene.henry@sompo.com.sg](mailto:irene.henry@sompo.com.sg)>; 'Choo, Thelma' <[thelma.choo@sompo.com.sg](mailto:thelma.choo@sompo.com.sg)>  
**Subject:** RE: SKF6802B CLAIMING AGAINST GBB7121D DOA:13.11.19 Our ref : CMTD1905275/THE

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

**G.NIVITHA**

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Ye, Yong Kang Melvin [<mailto:melvin.ye@sompo.com.sg>]  
**Sent:** Wednesday, 13 November 2019 4:10 PM  
**To:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** Henry, Irene James <[irene.henry@sompo.com.sg](mailto:irene.henry@sompo.com.sg)>; Choo, Thelma <[thelma.choo@sompo.com.sg](mailto:thelma.choo@sompo.com.sg)>; sm automotive <[sm\\_automotive@hotmail.com](mailto:sm_automotive@hotmail.com)>  
**Subject:** RE: SKF6802B CLAIMING AGAINST GBB7121D DOA:13.11.19 Our ref : CMTD1905275/THE

Without Prejudice

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC  
Owner ID: 863E

**Vehicle Details**

Vehicle No.: SKF6802B  
Vehicle to be Exported: No  
Intended Deregistration Date: 13 Nov 2019  
Vehicle Make: NISSAN  
Vehicle Model: ALMERA1.5 4AT ABS AIRBAG  
2WD 4DR

Primary Colour: Blue  
Manufacturing Year: 2011  
Engine No.: HR15992974A  
Chassis No.: MNTBBAN17Z0000005  
Maximum Power Output: 73.0 kW (97 bhp)  
Open Market Value: \$19,711.00  
Original Registration Date: 26 Jun 2012  
First Registration Date: 26 Jun 2012  
Transfer Count: 1  
Actual ARF Paid: \$19,711.00

**Intended PARF Rebate Details**

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 25 Jun 2022  
PARF Rebate Amount: \$11,826.00

**Intended COE Rebate Details**

COE Expiry Date: 25 Jun 2022  
COE Category: A - Car (1600cc & below)  
COE Period(Years): 10  
QP Paid: \$59,004.00  
COE Rebate Amount: \$15,439.00  
**Total Rebate Amount: \$27,265.00**

The information contained herein is correct as at 13 Nov 2019

OK

# SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM\_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

SIM BENG HUAT

13/11/2019

Blk 1 Kaki Bukit Ave 6

# 01-43

Singapore 417883

Accident date: 13/11/2019

Estimated repair cost for vehicle no: SKF6802B NISSAN ALMERA 1.5 A '12

CHASSIS: MNTBBA17Z00J0005

| S/n | Qty | Items / Nett                                   | U/price  | Amount                              |
|-----|-----|------------------------------------------------|----------|-------------------------------------|
| 1   | 2   | Front Headlamp <i>2 set</i>                    | \$494.50 | \$989.00 <i>X</i>                   |
| 2   | 2   | Front Headlamp Lower Bracket <i>2 set</i>      | \$35.10  | \$70.20 <i>X</i>                    |
| 3   | 1   | Front Grille <i>wt</i>                         |          | \$384.30 <i>-</i>                   |
| 4   | 8   | Front Grille Clip <i>nee</i>                   | \$6.50   | <del>\$52.00</del> <i>20</i>        |
| 5   | 1   | Front Grille Emblem Logo <i>nee</i>            |          | \$79.30 <i>✓</i>                    |
| 7   | 1   | Front Bumper <i>Delc</i>                       |          | \$482.60 <i>✓</i>                   |
| 8   | 10  | Front Bumper Clip <i>nee</i>                   | \$6.50   | <del>\$65.00</del> <i>30</i>        |
| 9   | 2   | Front Bumper Side Retainer <i>nee</i>          | \$28.40  | \$56.80 <i>✓</i>                    |
| 10  | 2   | Front Bumper Fog Lamp Cover <i>nee</i>         | \$130.10 | \$260.20 <i>X</i>                   |
| 11  | 1   | Front Bumper Number Plate <i>Best</i>          |          | \$50.00 <i>-</i>                    |
| 13  | 1   | Front Bumper Inner Foam <i>2 set</i>           |          | \$214.40 <i>X</i>                   |
| 14  | 1   | Front Bumper Reinforcement <i>1 set</i>        |          | \$1,495.20 <i>+</i>                 |
| 15  | 1   | Rear Boot Lid <i>Distorted</i>                 |          | \$872.10 <i>✓</i>                   |
| 16  | 2   | Rear Boot Lid Hinge <i>Best</i>                | \$94.90  | \$189.80 <i>-</i>                   |
| 17  | 1   | Rear Boot Lid Emblem Logo <i>2 set</i>         |          | \$64.50 <i>✓</i>                    |
| 18  | 1   | Rear Boot Lid Almera Logo                      |          | \$98.90 <i>✓</i>                    |
| 19  | 1   | Rear Boot Lid Center Moulding <i>nee</i>       |          | \$243.80 <i>X</i>                   |
| 20  | 1   | Rear Boot Lid Inner Lock <i>Distorted</i>      |          | \$102.50 <i>✓</i>                   |
| 21  | 1   | Rear Boot Lid Inner Rubber <i>wt</i>           |          | \$108.20 <i>✓</i>                   |
| 22  | 1   | Rear Boot Lid Inner Trim Board <i>nee</i>      |          | \$143.30 <i>X</i>                   |
| 23  | 1   | Rear Boot Lid Windscreen <i>shattered</i>      |          | <del>\$2,274.80</del> <i>1080</i>   |
| 24  | 2   | Rear Taillamp <i>lt smashed</i>                | \$292.40 | <del>\$584.80</del> <i>292.40</i>   |
| 25  | 4   | Rear Taillamp Clip <i>nee</i>                  | \$8.00   | <del>\$32.00</del> <i>10</i>        |
| 26  | 1   | Rear L/H Taillamp Panel <i>Distorted</i>       |          | \$185.50 <i>✓</i>                   |
| 27  | 1   | Rear L/H Taillamp Inner Panel <i>nee</i>       |          | \$252.70 <i>X</i>                   |
| 28  | 2   | Rear Fender L/H <i>Distorted</i>               | \$818.80 | <del>\$1,637.60</del> <i>818.80</i> |
| 29  | 2   | Rear Fender Inner Trim Board <i>lt cramped</i> | \$328.30 | <del>\$656.60</del> <i>328.30</i>   |
| 30  | 16  | Rear Fender Inner Trim Board Clip <i>nee</i>   | \$6.50   | <del>\$104.00</del> <i>30</i>       |

|    |    |                                  |            |          |          |        |
|----|----|----------------------------------|------------|----------|----------|--------|
| 31 | 2  | Rear Fender Top Trim Board       | Lt wt      | \$238.30 | \$476.60 | 238.30 |
| 32 | 12 | Rear Fender Top Trim Board Clip  | Neu        | \$6.50   | \$78.00  | 20     |
| 33 | 1  | Rear L/H Fender Inner Panel      | Repair     |          | \$548.00 | X      |
| 34 | 1  | Rear L/H Fender Air Duct         | Distorted  |          | \$97.10  | ✓      |
| 35 | 1  | Rear L/H Fender Cowling          | ton        |          | \$51.20  | ✓      |
| 36 | 6  | Rear L/H Fender Cowling Clip     | neu        | \$6.50   | \$39.00  | 20     |
| 37 | 1  | Rear L/H Fuel Tank               | neu        |          | \$488.40 | X      |
| 38 | 1  | Rear L/H Fuel Tank Cover         | neu        |          | \$80.80  | X      |
| 39 | 1  | Rear L/H Fuel Tank Cover Lock    | neu        |          | \$168.40 | X      |
| 40 | 1  | Rear L/H Door                    | Repair     |          | \$872.80 | X      |
| 41 | 1  | Rear Bumper                      | Distorted  |          | \$563.00 | ✓      |
| 42 | 10 | Rear Bumper Clip                 | neu        | \$6.50   | \$65.00  | 30     |
| 43 | 2  | Rear Bumper Side Retainer        | Lt Damaged | \$35.20  | \$70.40  | 35.20  |
| 45 | 1  | Rear Bumper Inner Foam           | neu        |          | \$133.80 | X      |
| 47 | 1  | Rear End Panel                   | Distorted  |          | \$422.30 | ✓      |
| 48 | 1  | Rear End Panel Top Garnish       | Distorted  |          | \$105.00 | ✓      |
| 49 | 1  | Rear Spare Tyre Panel            | Repair     |          | \$788.70 | X      |
| 50 | 1  | Rear Spare Tyre Panel Top Cover  | Distorted  |          | \$275.80 | ✓      |
| 51 | 1  | Rear Spare Tyre Panel Inner Foam | neu        |          | \$177.40 | X      |

7141 90

692771

Subtotal :- \$17,251.80

| S/n | Qty | Items / Special Next                  | U/price | Amount   |
|-----|-----|---------------------------------------|---------|----------|
| 52  | 2   | Front Bumper Fog Lamp                 | neu     | \$654.60 |
| 53  | 1   | Rear Boot Lid Windscreen Seal         | neu     | \$85.00  |
| 54  | 1   | Rear Boot Lid Reverse Camera          | neu     | \$880.00 |
| 55  | 1   | Rear Boot Lid Windscreen Video Camera | neu     | \$850.00 |
| 56  | 1   | Rear Bumper Reverse Sensor            | Damaged | \$450.00 |
| 57  | 1   | Rear Spare Tyre Panel Sealant         | neu     | \$450.00 |

Subtotal :- \$3,269.60

260

### Labour charges

To remove & refit cushion, trim board & send for interior cleaning

~~\$380.00~~ 120

To remove & refit rear windscreen

~~\$120.00~~ ✓

Gum

~~\$50.00~~ ✓

To remove & refit reverse sensor

~~\$100.00~~ 50

To remove & refit reverse camera

~~\$180.00~~ 50

To remove & refit rear video camera

~~\$180.00~~ 50

To remove & refit fuel tank

~~\$280.00~~ 80

To check wiring

~~\$150.00~~ 60

Tuff kote

~~\$200.00~~ 120

Towing fee

3760 ~~\$150.00~~ 60

Panel beating

~~\$2,400.00~~ 1600

Spray painting

~~\$2,000.00~~ 1400

Subtotal :- \$6,190.00

Total :- \$26,711.40

total 10447.71

c/s. 2.3K

12 Days

# SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM\_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

SIM BENG HUAT

13/11/2019

Blk 1 Kaki Bukit Ave 6

# 01-43

Singapore 417883

TP Sampo  
Kino Chen.

Accident date: 13/11/2019

Estimated repair cost for vehicle no: SKF6802B NISSAN ALMERA 1.5 A '12

CHASSIS: MNTBBAN17Z00J0005

| S/n | Qty | Items / Nett                                   | U/price  | Amount                              |
|-----|-----|------------------------------------------------|----------|-------------------------------------|
| 1   | 2   | Front Headlamp <i>2 x NP</i>                   | \$494.50 | \$989.00 <i>x</i>                   |
| 2   | 2   | Front Headlamp Lower Bracket <i>2 x NP</i>     | \$35.10  | \$70.20 <i>x</i>                    |
| 3   | 1   | Front Grille <i>wt</i>                         |          | \$384.30 <i>-</i>                   |
| 4   | 8   | Front Grille Clip <i>new</i>                   | \$6.50   | \$52.00 <i>20</i>                   |
| 5   | 1   | Front Grille Emblem Logo <i>new</i>            |          | \$79.30 <i>✓</i>                    |
| 7   | 1   | Front Bumper <i>Delco</i>                      |          | \$482.60 <i>✓</i>                   |
| 8   | 10  | Front Bumper Clip <i>new</i>                   | \$6.50   | \$65.00 <i>30</i>                   |
| 9   | 2   | Front Bumper Side Retainer <i>new</i>          | \$28.40  | \$56.80 <i>✓</i>                    |
| 10  | 2   | Front Bumper Fog Lamp Cover <i>new</i>         | \$130.10 | \$260.20 <i>x</i>                   |
| 11  | 1   | Front Bumper Number Plate <i>Bent</i>          |          | \$50.00 <i>-</i>                    |
| 13  | 1   | Front Bumper Inner Foam <i>2 x NP</i>          |          | \$214.40 <i>x</i>                   |
| 14  | 1   | Front Bumper Reinforcement <i>2 x NP</i>       |          | \$1,495.20 <i>x</i>                 |
| 15  | 1   | Rear Boot Lid <i>Distorted</i>                 |          | \$872.10 <i>✓</i>                   |
| 16  | 2   | Rear Boot Lid Hinge <i>Bent</i>                | \$94.90  | \$189.80 <i>-</i>                   |
| 17  | 1   | Rear Boot Lid Emblem Logo <i>2 x NP</i>        |          | \$64.50 <i>✓</i>                    |
| 18  | 1   | Rear Boot Lid Almera Logo <i>2 x NP</i>        |          | \$98.90 <i>✓</i>                    |
| 19  | 1   | Rear Boot Lid Center Moulding <i>new</i>       |          | \$243.80 <i>x</i>                   |
| 20  | 1   | Rear Boot Lid Inner Lock <i>new</i>            |          | \$102.50 <i>✓</i>                   |
| 21  | 1   | Rear Boot Lid Inner Rubber <i>wt</i>           |          | \$108.20 <i>✓</i>                   |
| 22  | 1   | Rear Boot Lid Inner Trim Board <i>new</i>      |          | \$143.30 <i>x</i>                   |
| 23  | 1   | Rear Boot Lid Windscreen <i>shattered</i>      |          | <del>\$2,274.80</del> <i>1080</i>   |
| 24  | 2   | Rear Taillamp <i>LH smashed</i>                | \$292.40 | <del>\$584.80</del> <i>292.40</i>   |
| 25  | 4   | Rear Taillamp Clip <i>new</i>                  | \$8.00   | <del>\$32.00</del> <i>10</i>        |
| 26  | 1   | Rear L/H Taillamp Panel <i>Distorted</i>       |          | \$185.50 <i>✓</i>                   |
| 27  | 1   | Rear L/H Taillamp Inner Panel <i>new</i>       |          | \$252.70 <i>x</i>                   |
| 28  | 2   | Rear Fender LH <i>Distorted</i>                | \$818.80 | <del>\$1,637.60</del> <i>818.80</i> |
| 29  | 2   | Rear Fender Inner Trim Board <i>LH crushed</i> | \$328.30 | <del>\$656.60</del> <i>328.30</i>   |
| 30  | 16  | Rear Fender Inner Trim Board Clip <i>new</i>   | \$6.50   | <del>\$104.00</del> <i>30</i>       |



|    |    |                                  |             |          |          |        |
|----|----|----------------------------------|-------------|----------|----------|--------|
| 31 | 2  | Rear Fender Top Trim Board       | Hit ut      | \$238.30 | \$476.60 | 238.30 |
| 32 | 12 | Rear Fender Top Trim Board Clip  | Neu         | \$6.50   | \$78.00  | 2.2    |
| 33 | 1  | Rear L/H Fender Inner Panel      | Repair      |          | \$548.00 | x      |
| 34 | 1  | Rear L/H Fender Air Duct         | Distorted   |          | \$97.10  | ✓      |
| 35 | 1  | Rear L/H Fender Cowling          | ton         |          | \$51.20  | ✓      |
| 36 | 6  | Rear L/H Fender Cowling Clip     | neu         | \$6.50   | \$39.00  | 2.0    |
| 37 | 1  | Rear L/H Fuel Tank               | neu         |          | \$488.40 | x      |
| 38 | 1  | Rear L/H Fuel Tank Cover         | neu         |          | \$80.80  | x      |
| 39 | 1  | Rear L/H Fuel Tank Cover Lock    | neu         |          | \$168.40 | x      |
| 40 | 1  | Rear L/H Door                    | Repair      |          | \$872.80 | x      |
| 41 | 1  | Rear Bumper                      | Distorted   |          | \$563.00 | ✓      |
| 42 | 10 | Rear Bumper Clip                 | neu         | \$6.50   | \$65.00  | 3.0    |
| 43 | 2  | Rear Bumper Side Retainer        | Hit Damaged | \$35.20  | \$70.40  | 3.5    |
| 45 | 1  | Rear Bumper Inner Foam           | neu         |          | \$133.80 | x      |
| 47 | 1  | Rear End Panel                   | Distorted   |          | \$422.30 | ✓      |
| 48 | 1  | Rear End Panel Top Garnish       | Distorted   |          | \$105.00 | ✓      |
| 49 | 1  | Rear Spare Tyre Panel            | Repair      |          | \$788.70 | x      |
| 50 | 1  | Rear Spare Tyre Panel Top Cover  | Distorted   |          | \$275.80 | ✓      |
| 51 | 1  | Rear Spare Tyre Panel Inner Foam | neu         |          | \$177.40 | x      |

7141 90  
6427-71

Subtotal :- \$17,251.80

| S/n | Qty | Items / Special Net                   | U/price | Amount   |
|-----|-----|---------------------------------------|---------|----------|
| 52  | 2   | Front Bumper Fog Lamp                 | neu     | \$654.60 |
| 53  | 1   | Rear Boot Lid Windscreen Seal         | neu     | \$85.00  |
| 54  | 1   | Rear Boot Lid Reverse Camera          | neu     | \$880.00 |
| 55  | 1   | Rear Boot Lid Windscreen Video Camera | neu     | \$850.00 |
| 56  | 1   | Rear Bumper Reverse Sensor            | Damaged | \$350.00 |
| 57  | 1   | Rear Spare Tyre Panel Sealant         | neu     | \$450.00 |

Subtotal :- \$3,269.60

260

### Labour charges

To remove & refit cushion, trim board & send for interior cleaning

~~\$380.00~~ 120.

To remove & refit rear windscreen

\$120.00 ✓

Gum *hec*

~~\$50.00~~ ✓

To remove & refit reverse sensor

~~\$100.00~~ 50

To remove & refit reverse camera

~~\$180.00~~ 50

To remove & refit rear video camera

~~\$180.00~~ 50

To remove & refit fuel tank

~~\$280.00~~ 80

To check wiring

~~\$150.00~~ 60.

Tuff kote

~~\$200.00~~ 120.

Towing fee

3760

~~\$150.00~~ 60.

Panel beating

~~\$2,400.00~~ 1600

Spray painting

~~\$2,000.00~~ 1400.

Subtotal :- \$6,190.00

Total :- \$26,711.40

total: 10447.71

c/s. 4.8K. ✓

12 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                       |                             |            |                                                                                     |
|----------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------|-----------------------------|------------|-------------------------------------------------------------------------------------|
| SOMPO INSURANCE SINGAPORE PL                                                                                                           |                                                                       | Ref : CS/SMO19020173/Aqd3n2 |            |                                                                                     |
| 50 RAFFLES PLACE<br>#05-01/06<br>SINGAPORE LAND TOWERSINGAPORE 048623                                                                  |                                                                       | Date : 16-01-2020           |            |  |
|                                                                                                                                        |                                                                       | Code : SMO                  |            |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                       |                             |            |                                                                                     |
| Insured Veh.                                                                                                                           | GBB 7121D                                                             | Veh. Inspected              | SKF 6802B  |                                                                                     |
| Policy No.                                                                                                                             |                                                                       | Coverage (\$)               | 0.00       |                                                                                     |
| Claim No.                                                                                                                              | CMTD1905275/THE                                                       | Excess (\$)                 | 0.00       |                                                                                     |
| Assign From                                                                                                                            | YONG KANG MELVIN                                                      | Assign Date                 | 13/11/2019 |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                       |                             |            |                                                                                     |
| Make & Model                                                                                                                           | NISSAN ALMERA                                                         | c.c                         | 1498       |                                                                                     |
| Engine No.                                                                                                                             | HIDDEN                                                                | Year of Reg.                | 2012       |                                                                                     |
| Chassis No.                                                                                                                            | MNTBBAN17Z0000005                                                     | Colour                      | BLUE       |                                                                                     |
| Odometer                                                                                                                               | 168573                                                                | Steering                    | IN ORDER   |                                                                                     |
| Brakes                                                                                                                                 | IN ORDER                                                              | Modification                | SPORTS RIM |                                                                                     |
| General                                                                                                                                | GOOD                                                                  |                             |            |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                       |                             |            |                                                                                     |
|                                                                                                                                        | Size                                                                  | Make                        | Balance    |                                                                                     |
| R/H Front Tyre                                                                                                                         | 205/55 R16                                                            | CONTINENTAL                 | 6 mm       |                                                                                     |
| L/H Front Tyre                                                                                                                         | 205/55 R16                                                            | CONTINENTAL                 | 6 mm       |                                                                                     |
| R/H Rear Tyre                                                                                                                          | 205/55 R16                                                            | CONTINENTAL                 | 6 mm       |                                                                                     |
| L/H Rear Tyre                                                                                                                          | 205/55 R16                                                            | CONTINENTAL                 | 6 mm       |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                       |                                                                       |                             |            |                                                                                     |
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.<br>DAMAGES SEE DETAILS.                                                   |                                                                       |                             |            |                                                                                     |
| <b>5. General Information</b>                                                                                                          |                                                                       |                             |            |                                                                                     |
| Accident Date                                                                                                                          | 13/11/2019                                                            | Inspection Date             | 14/11/2019 |                                                                                     |
| Survey held at                                                                                                                         | SM AUTOMOTIVE<br>BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883 |                             |            |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                     |                                                                       |                             |            |                                                                                     |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                       |                             |            |                                                                                     |
| <b>5b. Estimate Days of Repair</b>                                                                                                     |                                                                       |                             |            |                                                                                     |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                       | 12 Working Days             |            |                                                                                     |



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKF 6802B

| Qty | Description of Parts                      | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|-------------------------------------------|---------------|---------------------------|-------------------|
|     | <b>REPLACEMENT OF PARTS</b>               |               |                           |                   |
| 2   | FRONT HEADLAMP @\$494.50                  | NOT NECESSARY | 989.00                    | -                 |
| 2   | FRONT HEADLAMP LOWER BRACKET @\$35.10     | NOT NECESSARY | 70.20                     | -                 |
| 1   | FRONT GRILLE                              | CUT           | 384.30                    | 384.30            |
| 8   | FRONT GRILLE CLIP @\$6.50                 | NECESSARY     | 52.00                     | 20.00             |
| 1   | FRONT GRILLE EMBLEM LOGO                  | NECESSARY     | 79.30                     | 79.30             |
| 1   | FRONT BUMPER                              | DEFORMED      | 482.60                    | 482.60            |
| 10  | FRONT BUMPER CLIP @\$6.50                 | NECESSARY     | 65.00                     | 30.00             |
| 2   | FRONT BUMPER SIDE RETAINER @\$28.40       | NECESSARY     | 56.80                     | 56.80             |
| 2   | FRONT BUMPER FOG LAMP COVER @\$130.10     | NOT NECESSARY | 260.20                    | -                 |
| 1   | FRONT BUMPER NUMBER PLATE                 | BENT          | 50.00                     | 50.00             |
| 1   | FRONT BUMPER INNER FOAM                   | NOT NECESSARY | 214.40                    | -                 |
| 1   | FRONT BUMPER REINFORCEMENT                | NOT NECESSARY | 1,495.20                  | -                 |
| 1   | REAR BOOT LID                             | DISTORTED     | 872.10                    | 872.10            |
| 2   | REAR BOOT LID HINGE @\$94.90              | BENT          | 189.80                    | 189.80            |
| 1   | REAR BOOT LID EMBLEM LOGO                 | NECESSARY     | 64.50                     | 64.50             |
| 1   | REAR BOOT LID ALMERA LOGO                 | NECESSARY     | 98.90                     | 98.90             |
| 1   | REAR BOOT LID CENTER MOULDING             | NOT NECESSARY | 243.80                    | -                 |
| 1   | REAR BOOT LID INNER LOCK                  | DAMAGED       | 102.50                    | 102.50            |
| 1   | REAR BOOT LID INNER RUBBER                | CUT           | 108.20                    | 108.20            |
| 1   | REAR BOOT LID INNER TRIM BOARD            | NOT NECESSARY | 143.30                    | -                 |
| 1   | REAR BOOT LID WINDSCREEN                  | SHATTERED     | 2,274.80                  | 1,080.00          |
| 2   | REAR TAILLAMP @\$292.40                   | N/S SMASHED   | 584.80                    | 292.40            |
| 4   | REAR TAILLAMP CLIP @\$8.00                | NECESSARY     | 32.00                     | 10.00             |
| 1   | REAR L/H TAILLAMP PANEL                   | DISTORTED     | 185.50                    | 185.50            |
| 1   | REAR L/H TAILLAMP INNER PANEL             | NOT NECESSARY | 252.70                    | -                 |
| 2   | REAR FENDER @\$818.80                     | N/S DISTORTED | 1,637.60                  | 818.80            |
| 2   | REAR FENDER INNER TRIM BOARD @\$328.30    | N/S CRUMPLED  | 656.60                    | 328.30            |
| 16  | REAR FENDER INNER TRIM BOARD CLIP @\$6.50 | NECESSARY     | 104.00                    | 30.00             |
| 2   | REAR FENDER TOP TRIM BOARD @\$238.30      | N/S CUT       | 476.60                    | 238.30            |
| 12  | REAR FENDER TOP TRIM BOARD CLIP @\$6.50   | NECESSARY     | 78.00                     | 20.00             |

Report Ref No. CS/SMO19020173/Aqd3n2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

| Qty | Description of Parts                                               | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--------------------------------------------------------------------|----------------------|---------------------------|-------------------|
| 1   | REAR L/H FENDER INNER PANEL                                        | TO REPAIR SEE LABOUR | 548.00                    | -                 |
| 1   | REAR L/H FENDER AIR DUCT                                           | DISTORTED            | 97.10                     | 97.10             |
| 1   | REAR L/H FENDER COWLING                                            | TORN                 | 51.20                     | 51.20             |
| 6   | REAR L/H FENDER COWLING CLIP @\$6.50                               | NECESSARY            | 39.00                     | 20.00             |
| 1   | REAR L/H FUEL TANK                                                 | NOT NECESSARY        | 488.40                    | -                 |
| 1   | REAR L/H FUEL TANK COVER                                           | NOT NECESSARY        | 80.80                     | -                 |
| 1   | REAR L/H FUEL TANK COVER LOCK                                      | NOT NECESSARY        | 168.40                    | -                 |
| 1   | REAR L/H DOOR                                                      | TO REPAIR SEE LABOUR | 872.80                    | -                 |
| 1   | REAR BUMPER                                                        | DISTORTED            | 563.00                    | 563.00            |
| 10  | REAR BUMPER CLIP @\$6.50                                           | NECESSARY            | 65.00                     | 30.00             |
| 2   | REAR BUMPER SIDE RETAINER @\$35.20                                 | N/S DAMAGED          | 70.40                     | 35.20             |
| 1   | REAR BUMPER INNER FOAM                                             | NOT NECESSARY        | 133.80                    | -                 |
| 1   | REAR END PANEL                                                     | DISTORTED            | 422.30                    | 422.30            |
| 1   | REAR END PANEL TOP GARNISH                                         | DEFORMED             | 105.00                    | 105.00            |
| 1   | REAR SPARE TYRE PANEL                                              | TO REPAIR SEE LABOUR | 788.70                    | -                 |
| 1   | REAR SPARE TYRE PANEL TOP COVER                                    | DEFORMED             | 275.80                    | 275.80            |
| 1   | REAR SPARE TYRE PANEL INNER FOAM                                   | NOT NECESSARY        | 177.40                    | -                 |
|     | LESS 10% DISCOUNT                                                  |                      | -                         | -714.19           |
|     |                                                                    |                      | 17,251.80                 | 6,427.71          |
|     | <b>SPECIAL NETT ITEMS</b>                                          |                      |                           |                   |
| 2   | FRONT BUMPER FOG LAMP @\$327.30 (SN)                               | NOT NECESSARY        | 654.60                    | -                 |
| 1   | REAR BOOT LID WINDSCREEN SEAL (SN)                                 | NECESSARY            | 85.00                     | 60.00             |
| 1   | REAR BOOT LID REVERSE CAMERA (SN)                                  | NOT NECESSARY        | 880.00                    | -                 |
| 1   | REAR BOOT LID WINDSCREEN VIDEO CAMERA (SN)                         | NOT NECESSARY        | 850.00                    | -                 |
| 1   | REAR BUMPER REVERSE SENSOR (SN)                                    | DAMAGED              | 350.00                    | 200.00            |
| 1   | REAR SPARE TYRE PANEL SEALANT (SN)                                 | NOT NECESSARY        | 450.00                    | -                 |
| 1   | GUM (SN)                                                           | NECESSARY            | 50.00                     | 50.00             |
|     |                                                                    |                      | 3,319.60                  | 310.00            |
|     | <b>LABOUR</b>                                                      |                      |                           |                   |
|     | TO REMOVE & REFIT CUSHION,TRIM BOARD & SEND FOR INTERIOR CLEANING. |                      | 380.00                    | 120.00            |

Report Ref No. CS/SMO19020173/Aqd3n2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

| Qty                                                                         | Description of Parts                                                                                            | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|-----------|---------------------------|-------------------|
|                                                                             | TO REMOVE & REFIT REAR WINDSCREEN.                                                                              |           | 120.00                    | 120.00            |
|                                                                             | TO REMOVE & REFIT REVERSE SENSOR.                                                                               |           | 100.00                    | 50.00             |
|                                                                             | TO REMOVE & REFIT REVERSE CAMERA.                                                                               |           | 180.00                    | 50.00             |
|                                                                             | TO REMOVE & REFIT REAR VIDEO CAMERA.                                                                            |           | 180.00                    | 50.00             |
|                                                                             | TO REMOVE & REFIT FUEL TANK.                                                                                    |           | 280.00                    | 80.00             |
|                                                                             | TO CHECK WIRING.                                                                                                |           | 150.00                    | 60.00             |
|                                                                             | TUFF KOTE.                                                                                                      |           | 200.00                    | 120.00            |
|                                                                             | TOWING FEE.                                                                                                     |           | 150.00                    | 60.00             |
|                                                                             | PANEL BEATING, INCLUSIVE OF THE REPAIR OF REAR L/H FENDER INNER PANEL, REAR L/H DOOR AND REAR SPARE TYRE PANEL. |           | 2,400.00                  | 1,600.00          |
|                                                                             | SPRAY PAINTING.                                                                                                 |           | 2,000.00                  | 1,400.00          |
|                                                                             |                                                                                                                 |           | 6,140.00                  | 3,710.00          |
| <b>GRAND TOTAL</b>                                                          |                                                                                                                 |           | <b>26,711.40</b>          | <b>10,447.71</b>  |
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b> |                                                                                                                 |           |                           | <b>4,800.00</b>   |

Report Ref No. CS/SMO19020173/Aqd3n2

**ADRIAN LING WAI PING****B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI****Licensed Appraiser**

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.