

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 48997
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : 53321974D

SAMSUNG - KOH BROTHERS JOINT VENTURE

NO 3 CHURCH STREET

11-01 SAMSUNG HUB

SINGAPORE 049483

TEL : 62140029 FAX :

PH : 93825690

ATTN :

LKK Auto Consultants hence notify

the Repairer of the following:

• To resurvey before after spray painting

• To display damaged part(s) during resurvey

• Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

• Supplementary items must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATE BILL

Number : EB00005334

Date : 12/11/2019

Case No : AD00010784

Vehicle No : SKZ4934L

Chassis : SJNFEAJ11U1561649

Year of Mfr 2015

Policy No

Model : NISSAN QASHQAI 1.2

DIG-T CVT ABS 2WD

Term:

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
1	REAR DOOR LH / <i>bmc</i> / <i>acc.</i>	1.0	1,104.80	10	994.32
2	REAR DOOR STICKER LH	1.0	35.90	10	32.31
3	REAR DOOR LOCK LH ?	1.0	166.70	10	150.03
4	REAR DOOR PROTECTOR LH / <i>ee</i>	1.0	264.80	10	238.32
5	REAR DOOR OUTER CHROME LH X	2.0	188.90	10	340.02
6	REAR DOOR OUTER HANDLER ASSEMBLY LH X <i>SNN</i>	1.0	165.80	10	149.22
7	REAR DOOR INNER BRACKET LH X	1.0	85.60	10	77.04
8	REAR DOOR REGULATOR GEAR WITH MOTOR LH ?	1.0	487.90	10	439.11
9	REAR DOOR TRIMBOARD LH ?	1.0	1,267.10	10	1,140.39
10	REAR FENDER PROTECTOR LH / <i>scr</i>	1.0	483.80	10	435.42
Nett Price - Parts Sub Total					3,996.18
11	REAR FENDER LH - REPAIR	1.0			
12	FRONT DOOR LH - REPAIR	1.0			
13	ROCKER PANEL LH - REPAIR	1.0			
Special Nett Price - Parts Sub Total					0.00
Parts Total					3,996.18
14	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	800.00	0 <i>500</i>	800.00
15	SPRAY PAINT ON THE AFFECTED AREAS	1.0	900.00	0 <i>500</i>	900.00
16	ANTI-RUST COATING	1.0	200.00	0 <i>NXX</i>	200.00
Labour 1 Sub Total					1,900.00
SINGAPORE DOLLARS : SIX THOUSAND THREE HUNDRED EIGHT AND CENTS NINETY-ONE ONLY					
Less Excess					0.00
SUBTOTAL					5,896.18
GST 7.00%					412.73
TOTAL					6,308.91

Date of accident : 07/07/2019 05:45 AM. Place : PARKING SPACE AT CHANGI EAST COMMAND CENTRE

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

*5 Days .
Unpssm repair
After repair photos.*

Guo Qiang @ lkk auto. com

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

* N = Item not subjected to GST

Page 1 of 1

Issued by : Anysia