

ASS. REC. BY:

REF: CS/FCI No 20199 / Fgf3n2 Special Instruction:

Surveyor: Ram

ASSIGNMENT (Office)

From (Person): Karen of FCI Date/Time: 13.11.19 5:51pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHC 6742 S Insured: SHA 2136 D

at Workshop m/s Premier Tel: 62148880

of 23 Changi South Ave 2 # 01-02

Policy No: Claim No: D19007105MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 7.11.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 14.11.19 9:19am

Person Contacted: Hai Leong

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHC 6742 S - CS / DAI 15001820/H196K3 DOA - 30/9/2014
	SHA 2136 D - CS / FCI 18022413/UVCL302 DOA - 11/12/2013
15/11/19 @	11.51am Varised to Karen Tan by email.

ASS. REC. BY:

REF: FCI

ASSIGNMENT

From:

Date:

14/11/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SHC 6742S

at Workshop m/s

Premier

of

23 chengji south Ave 2 #01-02

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

(DS)

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SHC 6742S

Yr Regn:

12/mar, 2014

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Kia Optima 1.7A

c.c. 1685

Colour:

silver

A/C: Insured / Std / NI / NA

Sp. Reading:

783320

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KNAGM414MESAS4485

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 205/65 R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

maxxis

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

07/11/19

D.O.I.

14/11/19

Survey held at

Premier

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

P/P = \$760/=

(Red \$ 1507.20, 66%)

NO. of repairs days: 3

Labour Only

Part by Part

confirm on 21/11/19 with vicat cheng

no lump sum.

21/11/2019

RECEIVED 21 NOV 2019

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

Prel. Report

Final Report

11/11/19

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Insp (\$)
☐ : Weekend (\$)
☐ : Other (\$)
☐ : Other (\$)

Site Insp (\$)

Interview (\$)

Tech. Insp (\$)

Weekend (\$)

Other (\$)

Other (\$)

Survey Fee:

Transportation:

S+PS, SI

Photos

Other:

TOTAL

110

50

50

32

242

Report Format:

TP

Lump Sum / P.P. (\$)

760



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19007105MFSH

Date: 15 November 2019

Our Ref: CS/FCI19020199/Fqf3

The Motor Claims Department
MS First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 6742S

Please be informed that we had conducted the inspection of the abovementioned vehicle on 14/11/2019 at the premises of M/s PREMIER AUTOMOTIVE, and have the following to report:-

Workshop Estimate Amount	: S\$ 2,267.30 .
Revised Estimate Amount	: S\$ 760.00 .
"Check" Items Amount	: S\$ - .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Pending for some parts prices.

Description of Damage:
The vehicle sustained damages
at the o/s front portion.



Yours faithfully

Parasuram
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	08-11-2019	Our Ref No. D19007105MFSH
Accident Date	07-11-2019	Claim Type. Third Party
Insured Vehicle	SHA2136D	Third Party Vehicle. SHC6742S
Survey Location	23 CHANGI SOUTH AVENUE 2 #01-02	
Contact Person.	LIEW HAI LEONG	
Contact No.	62148880/ 0	Fax No. 62141511
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PREMIER AUTOMOTIVE SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 15 November 2019 11:51 AM
To: 'CWS Motor Claims'; assignments; SUR
Cc: 'Karen Tan'
Subject: RE: SURVEY ASSESSMENT - D19007105MFSH/1
Attachments: CSFCI19020199Fqf3.pdf

Dear Karen,

Enclosed herewith preliminary advice of SHC 6742S.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Thursday, 14 November 2019 9:20 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19007105MFSH/1

Dear Sir/Madam,

Thank you for your assignment.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>
Sent: Wednesday, 13 November, 2019 5:51 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan <karentan@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19007105MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time:	12 Mar 2014 / 09:21:21	Receipt No.:	AACCK001-AX239-140312-000012
Asset Type:	Vehicle	Transaction Amount:	\$71,081.00
Asset ID:	SHC6742S	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20140312092121999227		

Vehicle No.:	SHC6742S
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Scheme:	Taxi (Company)

First Registration Date:	12 Mar 2014
--------------------------	-------------

Original Registration Date:	12 Mar 2014
Vehicle Make:	KIA
Vehicle Model:	OPTIMA 1.7(A) DIESEL
Chassis No.:	KNAGM414ME5454485
Engine No.:	D4FDDH308936
Motor No.:	-
Trailer Chassis No.:	-

Propellant:	Diesel
-------------	--------

Passenger Capacity:	4
---------------------	---

Engine Capacity:	1685
------------------	------

Power Rating:	-
---------------	---

Unladen Weight:	1584
-----------------	------

Maximum Laden Weight:	2050
-----------------------	------

Primary Color:	Silver
----------------	--------

Secondary Color:	-
------------------	---

Manufacturing Year:	2013
---------------------	------

Open Market Value:	\$19,696.00
--------------------	-------------

Minimum PARF Benefit:	\$7,317.00
-----------------------	------------

PARF Eligibility:	Y
-------------------	---

No. of Transfer:	0
------------------	---

Effective Ownership Date/Time:	12 Mar 2014 09:21:21
--------------------------------	----------------------

COE No.:	2014031201000885N
----------	-------------------

COE Expiry Date	11 Mar 2022
-----------------	-------------

COE Bid Category	-
------------------	---

Actual OP/POP Paid Amount:	\$58,745.00
----------------------------	-------------

Lifespan Expiry Date	11 Mar 2022
----------------------	-------------

Owner ID Type:	Company
----------------	---------

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG: 200707743D GST REG: 200707743D

7-Nov-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6742 S

1 pc	Front bumper X (R)	\$	531.00
1 pc	Front bumper emblem Xnn	\$	44.00
1 pc	Front o/s rim Xnn	\$	246.00
1 pc	Front bumper o/s side retainer Xnn	\$	16.00
1 pc	Front o/s fender inner shield Xnn	\$	120.00
		\$	957.00
Less 10%		\$	95.70
		\$	861.30

S/NETT

1 pc	Front bumper clips Xnn	\$	48.00
1 pc	Front o/s fender sticker Xnn	\$	30.00
1 set	Front o/s fender inner shield clips Xnn	\$	28.00
Sundry		\$	50.00 \$20
To check front o/s wheel alignment Xnn		\$	80.00
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc.		\$	650.00 \$360

To putty and spray painting on front bumper, front o/s fender

\$ 400.00 \$360

To apply rustproofing on the repaired and replaced panels.

\$ 120.00 \$20

\$ 2,267.30

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

(ALL THE REPAIR COSTS ARE SUBJECT TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES

Acknowledged by Repairer

Signature:

Date:

19/11/19

Ram (LKK)

14/11/19 1045hrs

Paraburam@LKKauto.com

88622778 hp

Part by Part

3 repair days

after repair photo



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI19020199/Fqf3n2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 22-11-2019



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 2136D	Veh. Inspected	SHC 6742S
Policy No.		Coverage (\$)	0.00
Claim No.	D19007105MFSH	Excess (\$)	0.00
Assign From	KARENT	Assign Date	13/11/2019

2. Vehicle Particulars & Condition

Make & Model	KIA OPTIMA 1.7A	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	KNAGM414ME5454485	Colour	SILVER
Odometer	783320	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/65 R16	MAXXIS	7 mm
L/H Front Tyre	205/65 R16	MAXXIS	7 mm
R/H Rear Tyre	205/65 R16	MAXXIS	7 mm
L/H Rear Tyre	205/65 R16	MAXXIS	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	07/11/2019	Inspection Date	14/11/2019
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 6742S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	TO REPAIR SEE LABOUR	531.00	-
1	FRONT BUMPER EMBLEM	NOT NECESSARY	44.00	-
1	FRONT O/S RIM	NOT NECESSARY	246.00	-
1	FRONT BUMPER O/S SIDE RETAINER	NOT NECESSARY	16.00	-
1	FRONT O/S FENDER INNER SHIELD	NOT NECESSARY	120.00	-
	LESS 10% DISCOUNT		-95.70	-
			861.30	-
	SPECIAL NETT ITEMS			
1	FRONT BUMPER CLIPS (SN)	NOT NECESSARY	48.00	-
1	FRONT O/S FENDER STICKER (SN)	NOT NECESSARY	30.00	-
1	SET FRONT O/S FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	28.00	-
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			156.00	20.00
	LABOUR			
	TO CHECK FRONT O/S WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK-OUT,STRAIGHTEN,REPAIR,RESHAPE AND ADJUST OF THE SAME,ETC.INCLUSIVE OF THE REPAIR OF FRONT BUMPER.		650.00	360.00
	TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER,FRONT O/S FENDER.		400.00	360.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		120.00	20.00
			1,250.00	740.00
	GRAND TOTAL		2,267.30	760.00
RECOMMENDED COST OF REPAIRS				760.00

Report Ref No. CS/FC19020199/Fqf3n2

PARASURAM S/O SHANMUGAM

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.