

SUPREME AUTO SERVICE PTE LTD

c/o 176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

AM CHEF CATERING PTE LTD

Not Authorized
Li Ling 840504
Review After Repair
5 days

14/11/19
1.30PM

Date: 14/11/2019

QUANTITY	PARTICULARS	AMOUNT (\$)
RE: NISSAN MG4E 25 / GY 6371 A		
1 pc	rear bumper <i>617</i>	<i>R1</i> 867.70 ✓
1 pc	read bumper reinforcement	<i>NIP</i> 327.60 X
1 pc	rear tailgate <i>1916-20</i>	<i>R1</i> 1998.30 ✓
1 pc	rear retainer	<i>CRM</i> 67.30 ✓
1 pc	rear tail lamp	<i>CRM</i> 357.30 ✓
1 set	rear exhaust silensor	<i>R1</i> 797.80 ?
1 pc	<i>Tailgate embler m</i> 59.70 <i>108</i>	<i>m</i> 89.80 ✓
Sub-total		<i>40m</i> 80.00
	windscreen sealant s.nett	<i>m</i> 30.00 <i>12h</i>
	sticker <i>70km</i> s.nett	<i>m</i> 250.00
	reverse sensor s.nett	<i>200h</i>
	To remove and replace all the parts mentioned above, knocking and straighten up the necessary affected areas.	<i>540h</i> 600.00
	To spray painting on affected areas.	600.00 ✓
	To install reverse sensors.	<i>501</i> 80.00
	To remove rear windscreen glass(es) to enable repair.	100.00 ✓
	To transfer door(s) accessories.	<i>601</i> 100.00
	To carry out exhaust system	60.00 ✓
Total		5,653.70
		6405.80

LKK Auto Consultants hence notify

repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: