

ASS. REC. BY:

REF: CS/CTI19020209/KtF3ⁿ²

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Irene Tay Hui Ping

of CTI

Date/Time: 14.11.19 11.42a.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMC 29705

Insured:

XD 7904R

at Workshop in/s

Yee Auto

Tel:

64572625

of

160 sin ming drive #02-17 sin ming

Policy No:

DMEVSN 142668/9000

Claim No:

SNM 190205370102

Sum Insured:

Excess:

Make of Veh:

D.O.A.

11.11.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

14.11.19 11.42a.m

Person Contacted:

Winnie

Vehicle

IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SMC 29705 - X
	XD 7904R - NA/EQ18021330/14 ROP -26/11/2019
8/1	11 Lp @ 13, 2nd email (Red: 30986.20, 70%)

ASS. REC. BY:

REF: C71

ASSIGNMENT

From: _____ Date: 14.11.19

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMC 2970C

at Workshop m/s Yee Auto

of 160 Sin ming Drive #02-17

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: B7Hc

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 11 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS mp

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SMC 29705 Yr Regn: 06.18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or Wagon

Make: Honda Shuttle C.C. 1496

Colour: M. Grey A/C: Insured / Std / NI / NA

Sp. Reading: 90560 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GP 7 - 1210632

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/60R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 11/11/19

Rear

R/Bal. 8 mm

L/Bal. 8 mm

D.O.I. 14/11/19

Survey held at ✓

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

clash & Acc

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 20 JAN 2020

Date/Time, File Pass to?

☐ : Preli. Report

17/11 Typist

☒ : Final Report

Date/Time, File Return to?

21

Days Of Repair: 11Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

20

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Wheel and (\$Rep. Format: TPLump Sum / L.R. / 13,200/-

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Nov 2019		14 Nov 2019 11:42 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:			
Main Claimant:	RK TRANSPORTATON SERVICES		
Vehicle Reg. No.:	SMC2970S	Date of Loss:	11/11/2019 17:00 - :59
Claim Type:	TP / SNM19D205370C02	Policy/Cover Note No.:	DMCVSN19266819000
Vehicle Reg. No. (Insured):	XD7904R	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Yee Auto Pte Ltd (HQ) 160 SIN MING DRIVE, #02-17 SIN MING AUTOCITY, 575722 Sin Ming - Tel: 6457 2625		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 25/11/2019]		
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Thursday, 14 November 2019 11:30 AM
To: bonnie kwok
Cc: assignments; Admin A
Subject: RE: OUR REF: SNM19D205370/XD7904R/IRENE & YOUR REF: SMC2970S -PRI - Acc Inv: SMC 2970 S & XD 7904 R ON 11 NOVEMBER 2019

Dear Sir (LKK),

We refer to the above matter.

Please get your surveyor to liaise with YEE AUTO PTE LTD @ 6457-5768 to conduct PRS.

Regards,

Irene Tay
Executive
Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 63896192 | F:(65) 62247478/62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅域 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: bonnie kwok [mailto:litigation@bonniekwok.com]
Sent: Thursday, November 14, 2019 10:34 AM
To: Irene Tay <irene.tay@sg.cntaiping.com>
Subject: Re: OUR REF: SNM19D205370/XD7904R/IRENE & YOUR REF: SMC2970S -PRI - Acc Inv: SMC 2970 S & XD 7904 R ON 11 NOVEMBER 2019

Dear Irene,

We refer to your email dated 13 November 2019.

Our client has no objection of appointing the motor surveyor LKK stated in your said list to conduct the joint pre-repair survey as a single joint expert.

Regards,

June

On Wed, 13 Nov 2019 at 11:14, Irene Tay <irene.tay@sg.cntaiping.com> wrote:

WITHOUT PREJUDICE

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

LKK / LBS / STA

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Irene Tay

Executive

Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896192 | F: (65) 62247478/62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI
Sent: Wednesday, November 13, 2019 9:25 AM
To: Irene Tay <irene.tay@sg.cntaiping.com>; litigation@bonniekwok.com
Subject: OUR REF: SNM19D205370/XD7904R/IRENE & YOUR REF: SMC2970S -PRI - Acc Inv: SMC 2970 S & XD 7904 R ON 11 NOVEMBER 2019

Dear Irene,

Please conduct PRS –SMC2970R soonest possible.

File with officer-in-charge Irene Tay –DID- 6389 6192

Regards

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

Fax (65) 6224 7175 / 6224 7478

Email : claimsdept@sg.cntaiping.com

Website:www.sg.cntaiping.com

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: bonnie kwok [<mailto:litigation@bonniekwok.com>]
Sent: Tuesday, 12 November, 2019 5:43 PM
To: Claims Dept of CTI
Subject: PRI - Acc Inv: SMC 2970 S & XD 7904 R ON 11 NOVEMBER 2019

Dear Sir,

We refer to the above matter.

We hereby give you 2 days' notice to conduct a pre-repair inspection of vehicle SMC 2970 S at M/s Yee Auto Pte Ltd, 160 Sin Ming Drive #02-17 Sin Ming Autocity Singapore 575722. Contact number 6457 5768.

Regards,

June

BONNIE KWOK LLC

Advocates & Solicitors

101A Upper Cross Street

#08-12 People's Park Centre

Singapore 058358

TEL: 6536 6026

FAX: 6536 2279

email : litigation@bonniekwok.com

GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 6 pm and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other

defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

--

BONNIE KWOK LLC

Advocates & Solicitors
101A Upper Cross Street
#08-12 People's Park Centre
Singapore 058358
TEL: 6536 6026
FAX: 6536 2279
email : litigation@bonniekwok.com
GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 6 pm and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Denise Tay (LKKAuto)

From: yeeauto pteltd <yeeautopteltd@gmail.com>
Sent: Friday, 17 January 2020 3:35 PM
To: Denise Tay (LKKAuto)
Subject: Re: SMC 2970C / TP / DOA: 11.11.2019

Hi Sir,

We accept amount S\$13,200/- (bf GST) and 11 days.

Thanks & Regards

Ms Phang

Yee Auto Pte Ltd

160 Sin Ming Drive
#02-17 Sin Ming AutoCity
Singapore 575722
ROC & GST No.: 201719251W
email: yeeautopteltd@gmail.com
Contact No: 6457 2625 Fax: 6252 8459

On Fri, 17 Jan 2020 at 15:33, Denise Tay (LKKAuto) <denisetay@lkkauto.com> wrote:

Dear Ms Phang,

This can confirm?

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAuto)
Sent: Monday, 13 January 2020 11:31 AM
To: yeeautopteltd@gmail.com
Subject: SMC 2970C / TP / DOA: 11.11.2019

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Business
Owner ID: 2768

Vehicle Details

Vehicle No.: SMC29705
Vehicle to be Exported: No
Intended Deregistration Date: 15 Nov 2019
Vehicle Make: HONDA
Vehicle Model: SHUTTLE HYBRID 1.5 AUTO
Primary Colour: Silver
Manufacturing Year: 2018
Engine No.: LEB6552929
Chassis No.: GP71210632
Maximum Power Output: 101.0 kW (135 bhp)
Open Market Value: \$21,214.00
Original Registration Date: 28 Jun 2018
First Registration Date: 28 Jun 2018
Transfer Count: 0
Actual ARF Paid: \$5,000.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 27 Jun 2028
PARF Rebate Amount: \$3,750.00

Intended COE Rebate Details

COE Expiry Date: 27 Jun 2028
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$33,900.00
COE Rebate Amount: \$29,210.00
Total Rebate Amount: \$32,960.00

The information contained herein is correct as at 15 Nov 2019

OK

SIN MING AUTOCITY

Work Order: R007699
 Name: YEE AUTO PTE LTD
 License: SMC 2970 S
 Date: 14.11.19 15:57

BEFORE

Factory Japan 2019.0.1 : Honda : Shuttle : GK8
Thrust Line Alignment

Front : Left

Actual	Before	Specified Range
-0°48'		-1°00' 1°00'
5°00'		4°00' 6°00'
-0°01'		-0°09' 0°09'
13°28'		
12°40'		

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-2°25'		-1°00' 1°00'
5°00'		4°00' 6°00'
1°32'		-0°09' 0°09'
15°05'		
12°40'		

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
1°37'		-1°00' 1°00'
0°00'		
-1°37'		
1°32'		-0°17' 0°17'

Rear : Left

Actual	Before	Specified Range
-1°08'		-2°45' -0°45'
0°14'		0°00' 0°17'

Camber
 Toe

Rear : Right

Actual	Before	Specified Range
-3°26'		-2°45' -0°45'
1°07'		0°00' 0°17'

Rear

Cross Camber
 Total Toe
 Thrust Angle
 Axle Offset

Actual	Before	Specified Range
2°18'		-1°00' 1°00'
1°20'		0°00' 0°34'
-0°26'		
0mm		

SIN MING AUTOCITY

Work Order: R007851
 Name 2: YEE AUTO
 License: SMC 2970 S
 Technician: HUA
 Date: 6.12.19 16:02

AFTER

Factory Japan 2019.0.1 : Honda : Shuttle : GP7
 4-Wheel Total Alignment

Front : Left

Actual	Before	Specified Range
-0°26'	-0°32'	-1°00' 1°00'
4°55'	4°55'	4°00' 6°00'
0°01'	0°10'	-0°09' 0°09'
13°54'	14°00'	
13°28'	13°28'	
	0,0BAR	

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.
 Tire Pressure

Front : Right

Actual	Before	Specified Range
-0°01'	0°03'	-1°00' 1°00'
5°11'	5°11'	4°00' 6°00'
0°01'	-0°12'	-0°09' 0°09'
12°44'	12°41'	
12°44'	12°44'	
	0,0BAR	

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
-0°26'	-0°35'	-1°00' 1°00'
-0°16'	-0°16'	
1°10'	1°19'	
0°02'	0°03'	-0°17' 0°17'

Rear : Left

Actual	Before	Specified Range
-2°34'	-2°32'	-2°45' -0°45'
0°07'	0°08'	0°00' 0°17'
	0,0BAR	

Camber
 Toe
 Tire Pressure

Rear : Right

Actual	Before	Specified Range
-1°32'	-1°32'	-2°45' -0°45'
0°06'	0°09'	0°00' 0°17'
	0,0BAR	

Rear

Cross Camber
 Total Toe
 Thrust Angle
 Axle Offset

Actual	Before	Specified Range
-1°02'	-1°00'	-1°00' 1°00'
0°13'	0°16'	0°00' 0°34'
0°00'	0°00'	
0mm	0mm	



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopte ltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S : China Taiping Insurance (Singapore) Pte Ltd

3 Anson Road

#16-00 Springleaf Tower

Singapore 079909

Estimate No: ES1900115

Date: 13 Nov 2019

Policy No:

Veh Reg No: SMC2970S

Make/Model: HONDA SHUTTLE
HYBRID 1.5 AUTO

ATTN: Motor Claim Department

Your Ref No: -

Claim Type: Third Party

Accident Date: 11/11/2019

Chassis No: GP71210632

Engine No: LEB6552929

Reg. Date: 28/06/2018

Estimate Repair Cost to Vehicle No :SMC2970S

Description	U/Price	Quantity	List Price SS	Amount SS
Net Price				
1 FRONT TYRE 185/65/15	200.00	1 PC	200.00	200.00
2 FRONT TYRE RIM - RH	600.00	1 PC	600.00	600.00
3 REAR TYRE - RH	200.00	1 PC	200.00	200.00
4 REAR WHEEL RIM - RH	600.00	1 PC	600.00	600.00
5 REAR FENDER INNER SHIELD CLIP - RH	40.00	1 SET	40.00	40.00
6 REVERSE SENSORS	300.00	1 PC	300.00	300.00
			1,940.00	1,940.00
Spare Parts				
7 FRONT BONNET LOCK	298.70	1 PC	298.70	298.70
8 FRONT BUMPER 1050.00	1,185.30	1 PC	1,185.30	1,185.30
9 FRONT BUMPER CLIPS	64.00	1 SET	64.00	64.00
10 FRONT BUMPER SIDE RETAINER - LH	102.40	1 PC	102.40	102.40
11 FRONT BUMPER SIDE RETAINER - RH	102.40	1 PC	102.40	102.40
12 FRONT DOOR - RH 1055.30	1,135.90	1 PC	1,135.90	1,135.90
13 FRONT DOOR CENTRE PILLAR - RH	742.10	1 PC	742.10	742.10
14 FRONT DOOR CHANNEL - RH	92.40	1 PC	92.40	92.40
15 FRONT DOOR GLASS OUTER MOULDING - RH	187.70	1 PC	187.70	187.70
16 FRONT DOOR HINGE - LOWER	108.60	1 PC	108.60	108.60
17 FRONT DOOR HINGE - TOP 80.00	108.60	1 PC	108.60	108.60
18 FRONT DOOR LOCK - RH	372.80	1 PC	372.80	372.80
19 FRONT DOOR LOCKER PANEL STEP COVER - RH	198.50	1 PC	198.50	198.50
20 FRONT DOOR OUTER HANDLE - RH	147.70	1 PC	147.70	147.70
21 FRONT DOOR PILLAR - RH	628.60	1 PC	628.60	628.60
22 FRONT DOOR REGULATOR GEAR - RH	358.60	1 PC	358.60	358.60
23 FRONT DOOR REGULATOR GEAR MOTOR - RH	384.90	1 PC	384.90	384.90
24 FRONT DOOR SIDE MIRROR ASSY - RH 705.00	850.00	1 PC	850.00	850.00
25 FRONT DOOR STICKER - RH	56.50	1 PC	56.50	56.50
26 FRONT DOOR TRIM BOARD - RH	698.00	1 PC	698.00	698.00
27 FRONT DOOR WEATHERSTRIP - RH	179.50	1 PC	179.50	179.50
28 FRONT DRIVE SHAFT - RH	888.00	1 PC	888.00	888.00
29 FRONT FENDER - RH 435.10	598.60	1 PC	598.60	598.60
30 FRONT FENDER INNER SHIELD CLIPS	50.00	1 SET	50.00	50.00
31 FRONT FENDER LOGO 'HYBRID'	88.50	1 PC	88.50	88.50
32 FRONT FENDER SPLASH SHIELD - RH	178.10	1 PC	178.10	178.10
33 FRONT KNUCKLE ARM - RH 350.00	428.70	1 PC	428.70	428.70
34 FRONT LOWER ARM - RH 320.00	358.60	1 PC	358.60	358.60
35 FRONT STEERING RACK 1950	2,481.30	1 PC	2,481.30	2,481.30



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopte ltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S : China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 11/11/2019

Estimate No: ES1900115
Date: 13 Nov 2019
Policy No:
Veh Reg No: SMC2970S
Make/Model: HONDA SHUTTLE
HYBRID 1.5 AUTO
Chassis No: GP71210632
Engine No: LEB6552929
Reg. Date: 28/06/2018

Estimate Repair Cost to Vehicle No :SMC2970S

Description	U/Price	Quantity	List Price	Amount
			SS	SS
36 FRONT WHEEL BEARING - RH	198.00	1 PC	<i>2</i> 198.00	<i>2</i>
37 HEAD LAMP - RH	1,885.10	1 PC	<i>3</i> 1,885.10	<i>X</i>
38 HEAD LAMP LOWER BRACKET - RH	89.10	1 PC	<i>1</i> 89.10	<i>X</i>
39 REAR AXLE BEAM <i>950.00</i>	1,680.40	1 PC	<i>2</i> 1,680.40	<i>2</i>
40 REAR BUMPER SIDE RETAINER - LH	85.20	1 PC	<i>1</i> 85.20	<i>X</i>
41 REAR BUMPER SIDE RETAINER - RH	85.20	1 PC	<i>1</i> 85.20	<i>✓</i>
42 REAR DOOR - RH <i>899.50</i>	1,112.30	1 PC	<i>2</i> 1,112.30	<i>✓</i>
43 REAR DOOR CHECKER - RH	135.00	1 PC	<i>2</i> 135.00	<i>X</i>
44 REAR DOOR GLASS - RH <i>shattered</i>	490.90	1 PC	<i>1</i> 490.90	<i>✓</i>
45 REAR DOOR GLASS OUTER MOULDING - RH	185.50	1 PC	<i>2</i> 185.50	<i>✓</i>
46 REAR DOOR GLASS SOLAR FILM - RH	220.00	1 PC	<i>1</i> 220.00	<i>180.00</i>
47 REAR DOOR HINGE - RH (TOP)	105.00	1 PC	<i>1</i> 105.00	<i>X</i>
48 REAR DOOR INNER TRIM BOARD - RH <i>560.80</i>	798.00	1 PC	<i>1</i> 798.00	<i>2</i>
49 REAR DOOR LOCKER PANEL STEP COVER - RH	225.50	1 PC	<i>1</i> 225.50	<i>X</i>
50 REAR DOOR LOWER HINGE - RH	105.00	1 PC	<i>1</i> 105.00	<i>X</i>
51 REAR DOOR OUTER HANDLE - RH	166.40	1 PC	<i>1</i> 166.40	<i>X</i>
52 REAR DOOR PILLAR - RH	680.50	1 PC	<i>1</i> 680.50	<i>X</i>
53 REAR DOOR REGULATOR GEAR - RH	297.80	1 PC	<i>2</i> 297.80	<i>✓</i>
54 REAR DOOR REGULATOR GEAR MOTOR - RH	353.10	1 PC	<i>1</i> 353.10	<i>✓</i>
55 REAR DOOR RUBBER - RH	85.50	1 PC	<i>1</i> 85.50	<i>✓</i>
56 REAR DOOR RUBBER SENSOR	550.00	1 PC	<i>1</i> 550.00	<i>X</i>
57 REAR DOOR SPEAKER	205.10	1 PC	<i>1</i> 205.10	<i>X</i>
58 REAR DOOR STICKER	56.50	1 PC	<i>1</i> 56.50	<i>✓</i>
59 REAR DOOR WEATHERSTRIP - RH	179.50	1 PC	<i>1</i> 179.50	<i>X</i>
60 REAR KNUCKLE ARM - RH	480.60	1 PC	<i>2</i> 480.60	<i>2</i>
61 REAR SHOCK ABSORBER - RH	425.10	1 PC	<i>1</i> 425.10	<i>X</i>
62 REAR WHEEL BEARING - RH	285.50	1 PC	<i>2</i> 285.50	<i>2</i>
63 REAR FENDER - RH <i>1010.90</i>	1,259.50	1 PC	<i>2</i> 1,259.50	<i>✓</i>
64 REAR FENDER GALSS MOUNDING - RH	89.20	1 PC	<i>1</i> 89.20	<i>✓</i>
65 REAR FENDER GLASS SEALANT - RH	50.00	1 PC	<i>1</i> 50.00	<i>40.00</i>
66 REAR FENDER LOWER INNER SHIELD - RH	150.00	1 PC	<i>1</i> 150.00	<i>✓</i>
67 REAR AIR VENT - RH	60.50	1 PC	<i>1</i> 60.50	<i>X</i>
68 REAR BUMPER	1,122.50	1 PC	<i>1</i> 1,122.50	<i>✓</i>
69 REAR BUMPER CLIPS	40.00	1 SET	<i>1</i> 40.00	<i>✓</i>
70 REAR BUMPER TOW HOOK COVER	455.00	1 PC	<i>1</i> 455.00	<i>X</i>
71 REAR END PANEL	480.50	1 PC	<i>1</i> 480.50	<i>X</i>
72 REAR END PANEL LOWER INNER GARNISH	210.10	1 PC	<i>1</i> 210.10	<i>X</i>
73 REAR FENDER INNER TRIMBOARD - RH	485.00	1 PC	<i>1</i> 485.00	<i>X</i>
74 REAR TAILGATE <i>1250</i>	1,572.50	1 PC	<i>2</i> 1,572.50	<i>2</i>



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopteitd@gmail.com

Registration No: 201719251W GST No: 201719251W

M/S : China Taiping Insurance (Singapore) Pte Ltd

3 Anson Road

#16-00 Springleaf Tower

Singapore 079909

ATTN: Motor Claim Department

Your Ref No: -

Claim Type: Third Party

Accident Date: 11/11/2019

Estimate No: ES1900115

Date: 13 Nov 2019

Policy No:

Veh Reg No: SMC2970S

Make/Model: HONDA SHUTTLE
HYBRID 1.5 AUTO

Chassis No: GP71210632

Engine No: LEB6552929

Reg. Date: 28/06/2018

Estimate Repair Cost to Vehicle No :SMC2970S

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
75 REAR TAILGATE INNER TRIMBOARD	475.00	1 PC	475.00	X
76 REAR TAILGATE LOCK	265.10	1 PC	265.10	X
77 REAR TAILGATE WEATHERSTRIP	193.70	1 PC	193.70	X
78 REAR TAILLAMP PANEL - RH	185.00	1 PC	185.00	X
79 REAR WINDSCREEN MOULDINGS	110.50	1 PC	110.50	X
80 TAIL LAMP LH	685.50	1 PC	685.50	X
81 TAIL LAMP RH	685.50	1 PC	685.50	X
82 REAR BUMPER REFLECTOR - LH	195.00	1 PC	195.00	X
83 REAR BUMPER REFLECTOR - RH	195.00	1 PC	195.00	X
84 REAR END PANEL TOP GARNISH CLIPS	40.00	1 PC	40.00	X
85 REAR END PANEL TOP GARNISH	250.10	1 PC	250.10	X
86 REAR TAILGATE 'LOGO' EMBLEM	125.00	1 PC	125.00	X
87 REAR TAILGATE EMBLEM 'SHUTTLE'	95.50	1 PC	95.50	X
88 REAR BUZZER SENSOR	189.20	1 PC	189.20	X
89 REAR FENDER INNER PANEL - RH	1,150.50	1 PC	1,150.50	X
90 FRONT FENDER - RH, FRONT DOOR, REAR DOOR - RH, REAR FENDER - RH SOUNDPROOF	150.00	4 PC	600.00	X
			35,656.20	35,656.20
Labour				
91 COMPUTER DIAGNOSTIC RESET	300.00	1 PC	300.00	X
92 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	2,500.00	1 JOB	2,500.00	1200
93 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	2,200.00	1 JOB	2,200.00	1400
94 TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.	300.00	1 JOB	300.00	1200
95 TO REMOVE/REFIT REAR WINDSCREEN TO FACILITATE REPAIRS.	200.00	1 JOB	200.00	X
96 TO REMOVE/REFIT PASSENGER SEAT, FENDER GARNISHES TO FACILITTE REPAIRS.	250.00	1 JOB	250.00	1000
97 TO REMOVE/TRANSFER TAILGATE COMPONENTS.	150.00	1 PC	150.00	X
98 TO CHECK WIRING FUNCTIONS.	150.00	1 JOB	150.00	400
99 COMPUTER DIAGNOSTIC RESET	300.00	1 PC	300.00	X
100 WHEEL ALIGNMENT	120.00	1 T	120.00	800
101 TO TOW VEHICLE TO WORKSHOP.	120.00	1 JOB	120.00	7000
			6,590.00	6,590.00



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopte ltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S : China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 11/11/2019

Estimate No: ES1900115
Date: 13 Nov 2019
Policy No:
Veh Reg No: SMC2970S
Make/Model: HONDA SHUTTLE
HYBRID 1.5 AUTO
Chassis No: GP71210632
Engine No: LEB6552929
Reg. Date: 28/06/2018

Estimate Repair Cost to Vehicle No :SMC2970S

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
			Total	SS 44,186.20
			Add GST @ 7%	3,093.03
			Total Amount Payable	SS 47,279.23

TOTAL: SINGAPORE DOLLAR FORTY SEVEN THOUSAND TWO HUNDRED SEVENTY NINE AND CENTS TWENTY THREE ONLY

For Yee Auto Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary work(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer:

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119020209/KTF3N2

Date: 30/01/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN19266819000
Claimant Vehicle No :	SMC2970S	Insured Vehicle No :	XD7904R
Date of Loss:	11/11/2019	Nature of Claim:	TP
		Claim No:	SNM19D205370C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC2970S	Engine No:	LEB6552929
Make & Model:	HONDA SHUTTLE, 1.5 (A)	Chassis No:	GP71210632
Reg. Date:	28/06/2018 (Man. Year: 2018)	Odometer:	90560 km
Colour:	Metallic Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	37,596.20	13,479.76	24,116.44	64.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,590.00	3,040.00	3,550.00	53.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	44,186.20	16,519.76	27,666.44	62.61
Approved Total (Overridden) (S\$)		13,200.00		
(S\$)	44,186.20	13,200.00	30,986.20	70.13
+ GST 7.00/7.00% (S\$)	3,093.03	924.00	2,169.03	70.13
Nett Amount (S\$)	47,279.23	14,124.00	33,155.23	70.13

INSPECTION

Date of Assignment:	14/11/2019	Yee Auto Pte Ltd (HQ)
Date Inspected:	14/11/2019 Inspected At:	160 SIN MING DRIVE, #02-17 SIN MING AUTOCITY
Estimated Period of Repair:	11.0 days	Singapore 575722

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 30 Jan 2020)	
Parts:	N/A	HONDA SHUTTLE 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMC2970S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET LOCK	Repair	298.70 F	*- FL
2	1		*FRONT BUMPER	Buckled/Cracked	1,185.30 F	*1,050.00 FL
3	1		*SET FRONT BUMPER CLIPS	Necessary	64.00 F	*64.00 FL
4	1		*FRONT BUMPER SIDE RETAINER-LH	Serviceable	102.40 F	*- FL
5	1		*FRONT BUMPER SIDE RETAINER-RH	Necessary	102.40 F	*102.40 FL
6	1		*FRONT DOOR-RH	Bent	1,135.90 F	*1,055.30 FL
7	1		*FRONT DOOR CENTRE PILLAR-RH	Repair	742.10 F	*- FL
8	1		*FRONT DOOR CHANNEL-RH	Dented	92.40 F	*92.40 FL
9	1		*FRONT DOOR GLASS OUTER MOULDING-RH	Buckled	187.70 F	*187.70 FL
10	1		*FRONT DOOR HINGE-LOWER	Repair	108.60 F	*- FL
11	1		*FRONT DOOR HINGE-TOP	Bent	108.60 F	*80.00 FL
12	1		*FRONT DOOR LOCK-RH	Serviceable	372.80 F	*- FL
13	1		*FRONT DOOR LOCKER PANEL STEP COVER-RH	Serviceable	198.50 F	*- FL
14	1		*FRONT DOOR OUTER HANDLE-RH	Dented	147.70 F	*147.70 FL
15	1		*FRONT DOOR PILLAR-RH	Repair	628.60 F	*- FL
16	1		*FRONT DOOR REGULATOR GEAR-RH	Serviceable	358.60 F	*- FL
17	1		*FRONT DOOR REGULATOR GEAR MOTOR-RH	Serviceable	384.90 F	*- FL
18	1		*FRONT DOOR SIDE MIRROR ASSY-RH	Cracked	850.00 F	*705.00 FL
19	1		*FRONT DOOR STICKER-RH	Necessary	56.50 F	*56.50 FL
20	1		*FRONT DOOR TRIM BOARD-RH	Serviceable	698.00 F	*- FL
21	1		*FRONT DOOR WEATHERSTRIP-RH	Serviceable	179.50 F	*- FL
22	1		*FRONT DRIVE SHAFT-RH	Repair	888.00 F	*- FL
23	1		*FRONT FENDER-RH	Bent	598.60 F	*435.10 FL
24	1		*SET FRONT FENDER INNER SHIELD CLIPS	Necessary	50.00 F	*50.00 FL
25	1		*FRONT FENDER LOGO HYBRID	Cracked	88.50 F	*88.50 FL
26	1		*FRONT FENDER SPLASH SHIELD-RH	Distorted	178.10 F	*178.10 FL
27	1		*FRONT KNUCKLE ARM-RH	Bent	428.70 F	*350.00 FL
28	1		*FRONT LOWER ARM-RH	Distorted	358.60 F	*320.00 FL
29	1		*FRONT STEERING RACK	Bent/Jammed	2,481.30 F	*1,950.00 FL
30	1		*FRONT WHEEL BEARING-RH	Necessary	198.00 F	*198.00 FL
31	1		*HEAD LAMP-RH	Serviceable	1,885.10 F	*- FL
32	1		*HEAD LAMP LOWER BRACKET-RH	Serviceable	89.10 F	*- FL
33	1		*REAR AXLE BEAM	Bent	1,680.40 F	*950.00 FL
34	1		*REAR BUMPER SIDE RETAINER-LH	Serviceable	85.20 F	*- FL
35	1		*REAR BUMPER SIDE RETAINER-RH	Distorted	85.20 F	*85.20 FL
36	1		*REAR DOOR-RH	Bent	1,112.30 F	*899.50 FL
37	1		*REAR DOOR CHECKER-RH	Serviceable	135.00 F	*- FL
38	1		*REAR DOOR GLASS-RH	Shattered	490.90 F	*490.90 FL
39	1		*REAR DOOR GLASS OUTER MOULDING-RH	Bent	185.50 F	*185.50 FL
40	1		*REAR DOOR HINGE-RH (TOP)	Repair	105.00 F	*- FL
41	1		*REAR DOOR INNER TRIM BOARD-RH	Mtg Cracked	798.00 F	*560.80 FL
42	1		*REAR DOOR LOCKER PANEL STEP COVER-RH	Serviceable	225.50 F	*- FL
43	1		*REAR DOOR LOWER HINGE-RH	Repair	105.00 F	*- FL
44	1		*REAR DOOR OUTER HANDLE-RH	Repair	166.40 F	*- FL
45	1		*REAR DOOR PILLAR-RH	Repair	680.50 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	1		*REAR DOOR REGULATOR GEAR-RH	Bent	297.80 F	*297.80 FL
47	1		*REAR DOOR REGULATOR GEAR MOTOR-RH	Jammed	353.10 F	*353.10 FL
48	1		*REAR DOOR RUBBER-RH	Cut	85.50 F	*85.50 FL
49	1		*REAR DOOR RUBBER SENSOR	Serviceable	550.00 F	*- FL
50	1		*REAR DOOR SPEAKER	Serviceable	205.10 F	*- FL
51	1		*REAR DOOR STICKER	Necessary	56.50 F	*56.50 FL
52	1		*REAR DOOR WEATHERSTRIP-RH	Serviceable	179.50 F	*- FL
53	1		*REAR KNUCKLE ARM-RH	Bent	480.60 F	*480.60 FL
54	1		*REAR SHOCK ABSORBER-RH	Serviceable	425.10 F	*- FL
55	1		*REAR WHEEL BEARING-RH	Serviceable	285.50 F	*- FL
56	1		*REAR FENDER-RH	Bent	1,259.50 F	*1,010.90 FL
57	1		*REAR FENDER GLASS MOULDING-RH	Necessary	89.20 F	*89.20 FL
58	1		*REAR FENDER LOWER INNER SHIELD-RH	Distorted	150.00 F	*150.00 FL
59	1		*REAR AIR VENT-RH	Serviceable	60.50 F	*- FL
60	1		*REAR BUMPER	Buckled	1,122.50 F	*1,122.50 FL
61	1		*SET REAR BUMPER CLIPS	Necessary	40.00 F	*40.00 FL
62	1		*REAR BUMPER TOW HOOK COVER	Serviceable	455.00 F	*- FL
63	1		*REAR END PANEL	Repair	480.50 F	*- FL
64	1		*REAR END PANEL LOWER INNER GARNISH	Serviceable	210.10 F	*- FL
65	1		*REAR FENDER INNER TRIMBOARD-RH	Serviceable	485.00 F	*- FL
66	1		*REAR TAILGATE	Bent	1,572.50 F	*1,250.00 FL
67	1		*REAR TAILGATE INNER TRIMBOARD	Serviceable	475.00 F	*- FL
68	1		*REAR TAILGATE LOCK	Repair	265.10 F	*- FL
69	1		*REAR TAILGATE WEATHERSTRIP	Serviceable	193.70 F	*- FL
70	1		*REAR TAILLAMP PANEL-RH	Repair	185.00 F	*- FL
71	1		*REAR WINDSCREEN MOULDING	Necessary	110.50 F	*110.50 FL
72	1		*TAIL LAMP LH	Serviceable	685.50 F	*- FL
73	1		*TAIL LAMP RH	Serviceable	685.50 F	*- FL
74	1		*REAR BUMPER REFLECTOR-LH	No such part	195.00 F	*- FL
75	1		*REAR BUMPER REFLECTOR-RH	No such part	195.00 F	*- FL
76	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	40.00 F	*- FL
77	1		*REAR END PANEL TOP GARNISH	Serviceable	250.10 F	*- FL
78	1		*REAR TAILGATE LOGO EMBLEM	Necessary	125.00 F	*125.00 FL
79	1		*REAR TAILGATE EMBLEM SHUTTLE	Necessary	95.50 F	*95.50 FL
80	1		*REAR BUZZER SENSOR	Serviceable	189.20 F	*- FL
81	1		*REAR FENDER INNER PANEL-RH	Repair	1,150.50 F	*- FL
82	4		*FRONT FENDER-RH FRONT DOOR,REAR DOOR-RH,REAR FENDER-RH SOUNDPROOF	Not Necessary	600.00 F	*- FL
83	1		*FRONT TYRE 185/65/15 (80%)	Punctured	200.00 FS	*160.00 FS
84	1		*FRONT TYRE RIM-RH	Dented	600.00 FS	*350.00 FS
85	1		*REAR TYRE-RH	Serviceable	200.00 FS	*- FS
86	1		*REAR WHEEL RIM-RH	Dented	600.00 FS	*350.00 FS
87	1		*SET REAR FENDER INNER SHIELD CLIP-RH	Necessary	40.00 FS	*40.00 FS
88	1		*REVERSE SENSORS	Serviceable	300.00 FS	*- FS
89	1		*REAR DOOR GLASS SOLAR FILM-RH	Necessary	220.00 FS	*100.00 FS
90	1		*REAR FENDER GLASS SEALANT-RH	Necessary	50.00 FS	*40.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	37,596.20	16,589.70
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	3,109.94
Total Parts (\$\$)	37,596.20	13,479.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	COMPUTER DIAGNOSTIC RESET	New	300.00	0.00
2	TO DISMANTLE & REPLACE DAMAGED PARTS,PANEL BEAT WHERE NECESSARY	New	2,500.00	1,200.00
3	TO PUTTY,APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION	New	2,200.00	1,400.00
4	TO APPLY RUST-PROOFING ON REPAIRED,REPLACED PANEL	New	300.00	120.00
5	TO REMOVE/REFIT REAR WINDSCREEN TO FACILITATE REPAIRS	New	200.00	0.00
6	TO REMOVE/REFIT PASSENGER SEAT,FENDER GARNISHES TO FACILITATE REPAIRS	New	250.00	100.00
7	TO REMOVE/TRANSFER TAILGATE COMPONENTS	New	150.00	0.00
8	TO CHECK WIRING FUNCTIONS	New	150.00	40.00
9	COMPUTER DIAGNOSTIC RESET	New	300.00	0.00
10	WHEEL ALIGNMENT	New	120.00	80.00
11	TO TOW VEHICLE TO WORKSHOP	New	120.00	100.00
Gross Labour Cost (\$\$)			6,590.00	3,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >