

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SJE 6443X
TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000
ATTN: Motor Claim Department

FAX: 64153727

Estimate No: ES1992247/YISHUN

Date: 14 Nov 2019

Policy No: DMPCSN3024581906

Veh Reg No: SJE6443X

Make/Model: HYUNDAI I30 (FD) 1.6
DOHC AUTO

Chassis No: KMHDC51DR9U094316

Engine No: G4FC8U412047

Reg. Date: 02/05/2008

WS Ref: TP/AIG/YS

Claim Type: Third Party

Accident Date: 13/11/2019

TP Veh Reg No: SBQ9900E

Not Notified

11 Nov 87

Primary After Paint

5 days

Estimate Repair Cost to Vehicle No :SJE6443X

PAGE:1/1

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
List Price				
1 FRONT BUMPER	435.00	1 PC	Bu 435.00	✓
2 FRONT BUMPER REINFORCEMENT	254.00	1 PC	254.00	7
3 FRONT BUMPER CENTRE LOWER GRILLE	53.20	1 PC	Net 53.20	✓
4 FRONT BUMPER RH FOG LAMP	141.70	1 PC	141.70	7
5 FRONT BUMPER RH RETAINER	25.90	1 PC	Dit 25.90	✓
6 FRONT BUMPER CLIPS	3.50	6 PCS	21.00	✓
7 HEADLAMPS	606.20	2 PCS	1,212.40	✓
8 BONNET	1,885.60	1 PC	Bu 1,885.60	✓
9 BONNET RH HINGE	48.80	1 PC	48.80	7
10 BONNET INNER RUBBER	40.00	1 PC	40.00	✓
11 FRT SUPPORT PANEL	863.90	1 PC	Bu/cm 863.90	✓
12 FRONT GRILLE	82.10	1 PC	cm 82.10	✓
13 AIR-CON CONDENSER	990.90	1 PC	990.90	7
14 FRONT RH FENDER	559.00	1 PC	Bu 1 Bu 559.00	✓
			6,613.50	
			Less 20%	1,322.70
				5,290.80
Special Net				
15 FRONT NUMBER PLATE	35.00	1 PC	CM 35.00	✓
			35.00	35.00
Labour				
16 REMOVE & REFIX FRT BUMPER ASSY,GRILLE,HEADLAMPS,FOG LAMPS,FRT FENDERS,RADIATOR & MOTOR,FRT SUPPORT PANEL,KNOCK & REPAIR FRT LH FENDER,FRT RH FENDER INNER PANEL & REALIGN THE SAME	800.00	1 LA	800.00	6501
17 REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS	100.00	1 LA	100.00	✓
18 PUTTY & RESPRAY ON FRT BUMPER,BONNET,HINGE,FRT FENDERS	800.00	1 LA	800.00	7201
			1,700.00	1,700.00

Total S\$ 7,025.80

Add GST @ 7% 491.81

Total Amount Payable S\$ 7,517.61

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE